Engine - Continental Motors - TSIO-360-GB

S/N 309034

| AD# | Applicable S.B. # & Subject | Date & Hours @ Comp. | Method of Compliance | One Time | Recurring | Next Comp. @ Hrs/Date | Authorized Signature & Number |
|--------------|---|----------------------------|-----------------------------|----------|-----------|-----------------------------|--|
| 81-13-10 R1 | Engine oil pump drive shaft | | PCW See Log Entry | × | T | | Doran Pedri A&P3205413IA |
| 81-23-02 | Oil filter adapter gasket | | N/A by S/N | × | | | Doran Pedri A&P3205413IA |
| 88-03-06 | Oil filter | _ | N/A by P/N | × | | | Doran Pedri A&P3205413IA |
| 91-19-03 | Champion oil filter | | N/A by Date Code | × | | | Doran Pedri A&P3205413IA |
| 92-04-09 | Rocker shaft | 4/9/03 1170.7 | PCW See Log Entry | × | | | Doran Pedri A&P3205413IA |
| 93-10-02 | Cylinder valve retainer | 4/9/03 1170.7 | PCW See Log Entry | × | | | Doran Pedri A&P3205413IA |
| 94-14-12 | Low octane detonation | | Superceded by AD 95-21-15 | × | | | Doran Pedri A&P3205413IA |
| 95-08-10 | Turbocharger check valves | 4/9/03 1170.7 | PCW See Log Entry | x | | | Doran Pedri A&P3205413IA |
| 95-21-15 | Engine teardown and analytical inspect. | | N/A by N# | x | | | Doran Pedri A&P3205413IA |
| 97-26-17 | CORRECTION - Crankshaft fatigue cracks | 4/9/03 1170.7 | PCW See Log Entry | | x | REMOVAL | Doran Pedri A&P3205413IA |
| 98-19-02 | PMA piston pin | 4/9/03 1170.7 | PCW See Log Entry | x | | | Doran Pedri |
| PL2000-08-51 | Crankshaft connecting rod journal fracture | | Superceded by AD 2000-23-21 | | x | | A&P3205413IA Doran Pedri |
| PL2000-11-51 | Possible engine failure | | Superceded by AD 2002-13-04 | x | | | A&P3205413iA Doran Pedri |
| 2000-23-21 | Fracture of the crankshaft connecting rod journal | 4/9/03 1170.7 | PCW See Log Entry | × | | | A&P3205413IA Doran Pedri |
| 2002-13-04 | CORRECTION - Prevent engine failure and loss of control of the airplane | | N/A not installed | × | | 0 | A&P3205413IA Doran Pedri A&P3205413IA |
| 2009-24-51 | To address rapid wear on the face of hydraulic lifters | | Superceded by AD 2009-24-52 | | x | | Doran Pedri |
| 009-24-52 | To address rapid wear on the face of hydraulic lifters | | Superceded by AD 2010-11-04 | | x | 1 | A&P3205413IA Doran Pedri |
| 010-11-04 | To prevent excessive hydraulic lifter wear | | N/A by Date | | x | | A&P3205413IA Doran Pedri |
| 2011-26-07 | To prevent engine failure due to migration of the magneto impulse coupling stop pin | | N/A by Model Installed | | x | | A&P3205413IA Doran Pedri A&P3205413IA |
| 2012-03-06 | | 8/10/81 223.8 | N/A by Model Installed | | x | | Doran Pedri A&P3205413IA |

FROM;
BLUE HORIZON AVIATION
4141 JERRY L MAYGRADEN RD,
PENSACOLA, FL 32504

Airframe - Mooney - M-20K

S/N 25-0026

| AD# | Applicable S.B. # & Subject | Date & Hours @ Comp. | Method of Compliance | One Time | Recurring | Next Comp. @ Hrs/Date | Authorized Signature & Number |
|------------|---|----------------------------|----------------------|----------|-----------|-----------------------------|-------------------------------------|
| 75-23-04 | Dukes gear actuator | - | N/A by P/N | | x | | Doran Pedri A&P3205413IA |
| 80-02-12 | Fuselage tubular structure | 2/2/80 | PCW | x | | | Doran Pedri A&P3205413IA |
| 85-24-03 | Water entrapment in fuel tanks | 7/9/86 | PCW | x | | _ | Doran Pedri A&P3205413IA |
| 88-25-11 | Baggage door | 7/20/89 | PCW | × | | | Doran Pedri A&P3205413IA |
| 95-17-06 | Exhaust system cracks | | N/A not installed | | х | | Doran Pedri A&P3205413IA |
| 95-18-12 | Fuel selector valve | 7/21/97 | PCW | x | | À | Doran Pedri A&P3205413IA |
| 98-21-26 | MLG leg bracket | | N/A by S/N | x | | | Doran Pedri A&P3205413IA |
| 98-24-11 | To detect and correct cracked aileron control links | 11/14/03 | PCW | | x | | Doran Pedri A&P3205413IA |
| 2012-05-09 | To address failure of the tail pitch trim assembly | 11 Dec 2012 | C/W by Inspection | x | | | Doran Pedri A&P3205413IA |

Propeller - McCauley - 2A34C216

S/N 812547

| AD# | Applicable S.B. # & Subject | Date & Hours @ Comp. | Method of Compliance | One Time | | Next Comp. @ Hrs/Date | Authorized Signature & Number |
|-------------|--|----------------------------|----------------------|----------|-----------|-----------------------------|-------------------------------------|
| 82-27-02 R1 | Propeller blade shank failure | 8/17/97 | PCW | x | | | Doran Pedri A&P3205413IA |
| 2003-13-17 | Detect unsafe conditions that could result in separation of a propeller blade | | N/A not by T&W | × | | | Doran Pedri A&P3205413IA |
| 2005-14-11 | Prevent blade failure that could result in separation of a propeller blade | - i sl | N/A not by SCP | x | 21 = 1 | | Doran Pedri A&P3205413IA |
| 2006-24-07 | To detect unsafe conditions that could result in a propeller blade separating from the hub and loss of control of the airplane | | N/A not by CSE | × | | | Doran Pedri A&P3205413IA |

Appliance - Air Filter - Paper Induction

Appliance - Governors - McCauley

Appliance - Ignition Switches - Bendix

Appliance - Oil Filters - Champion

Appliance - Pumps Vacuum - Airborne

Appliance - Turbochargers - Rajay

Appliance - GPS - Garmin GNS 430

Appliance - Magnetos - TCM (formerly Bendix) S-20 series

| AD# | Applicable S.B. # & Subject | Date & Hours @ Comp. | Method of Compliance | One Time | Recurring | Next Comp. @ Hrs/Date | Authorized Signature & Number |
|-------------|--|----------------------------|-----------------------------|----------|-----------|-----------------------------|-------------------------------------|
| 64-01-01 | Airborne vacuum pumps | | N/A by M/N | х | | | Doran Pedri A&P3205413IA |
| 65-02-03 | Rajay turbocharger cracks | | N/A not installed | | х | | Doran Pedri A&P3205413IA |
| 73-07-04 | Bendix Magnetos | | Superceded by AD 94-01-03 | x | | | Doran Pedri A&P3205413IA |
| 74-26-09 | Bendix magnetos | | N/A by S/N | × | | | Doran Pedri A&P3205413IA |
| 75-12-07 | McCauley governors | | N/A by M/N | х | | | Doran Pedri A&P3205413IA |
| 76-07-12 | Bendix switches | | N/A by Date | | х | | Doran Pedri A&P3205413IA |
| 76-16-02 | Airborne pumps | | N/A by M/N | х | | | Doran Pedri A&P3205413IA |
| 77-12-05 R1 | Champion oil filters | | N/A by Date Code | х | | | Doran Pedri A&P3205413IA |
| 78-09-07 R3 | Bendix magnetos | | Superceded by AD 96-12-07 | | x | | Doran Pedri A&P3205413IA |
| 79-13-08 | Airborne dry air pumps | | N/A by S/N | x | | | Doran Pedri A&P3205413IA |
| 32-20-01 | Bendix magnetos | | N/A by S/N | × | | | Doran Pedri A&P3205413IA |
| 32-27-03 | Rajay turbochargers | | N/A by P/N | | x | | Doran Pedri A&P3205413IA |
| 34-26-02 | Paper induction air filters | 10/6/10 1937.4 | PCW See Log Entry | | x | 2437 4 | Doran Pedri A&P3205413IA |
| 36-01-06 | Airborne dry air pumps | | N/A by M/N | × | | | Doran Pedri A&P3205413IA |
| 4-01-03 R2 | Teledyne/Bendix magnetos | | N/A by S/N | × | | | Doran Pedri A&P3205413IA |
| 4-06-09 | Teledyne/Bendix magnetos | | N/A by Date Code | × | | | Doran Pedri A&P3205413IA |
| 96-12-07 | Prevent magneto failure and subsequent engine failure | | Superceded by AD 2005-12-06 | | x | | Doran Pedri A&P3205413IA |
| 98-23-01 | Flexible coupling | | N/A not installed | × | | | Doran Pedri A&P3205413IA |
| 2001-23-17 | Prevent external noise to the GNS 430 units course deviation indicator (CDI) | | N/A by P/N | × | | | Doran Pedri A&P3205413IA |
| 2005-12-06 | Prevent failure of the magneto impulse coupling assembly | 1 | N/A by M/N Engine | | x | | Doran Pedri A&P3205413IA |