



CESCOM 20 - Projected Maintenance Due

Owner: **CANNON SECURITY PRODUCTS, INC.**

Aircraft Model: **525 - CJ1+**

Aircraft Serial: **525-0605**

Unit: **0605** Reg No: **N800PF**

Airworthiness: **04-Jan-2006**

Print Date: **07-Nov-2024 4:58PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 1	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 2	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
AIR COND	936.1		02-Oct-2024	.75	0.33	37.13		113	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
C270001	TRIM TAB ACTUATOR LUBRICATION (WITHOUT GREASE FITTINGS) TASK 12-21-01-610									
							12 MTH			New Req
SB FJ44-77-013	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK									
R11										New Req
E1				RECOMMENDED			MPI			
SB FJ44-77-013	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK									
R11										New Req
E2				RECOMMENDED			MPI			

Overdue Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
052601	PERFORM FIRE EXTINGUISHER 30 DAY CHECK									
		KLAS					30		12-Oct-2024	-26 d
					DAYS 12-Sep-2024					
					HRS 2333.1					
					LDG 1805					
										Over Due
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
		KLAS					3		31-Oct-2024	-7 d
					MTH 26-Jul-2024					
					HRS 2319.2					
					LDG 1797					
										Over Due
351002	COPILOT OXYGEN MASK	MC-10-16-101								
COPILOT		KDAL		77129			72	50	31-Oct-2024	-7 d
					MTH 15-Dec-2022					
					HRS 2079.4					
					LDG 1584					
										Over Due



CESCOM 20 - Projected Maintenance Due

Owner: **CANNON SECURITY PRODUCTS, INC.**

Aircraft Model: **525 - CJ1+**

Aircraft Serial: **525-0605**

Unit: **0605** Reg No: **N800PF**

Airworthiness: **04-Jan-2006**

Print Date: **07-Nov-2024 4:58PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 1	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 2	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
AIR COND	936.1		02-Oct-2024	.75	0.33	37.13		113	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
12-22-01-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH	KLAS		DAYS 12-Aug-2024 HRS 2319.2 LDG 1797		90		10-Nov-2024	3 d
A243301 0512009	LEAD ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) NOTE: THE INSPECTION SCHEDULE MAY BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED, BASED ON OPERATIONS. TASK 24-33-00-720	KLAS	RG-380E/44LA5 41092282	MTH 26-Jul-2024 HRS 2319.2 LDG 1797		4 200		30-Nov-2024 2519.2	23 d 182
801101 LEFT ENGINE	STARTER/GENERATOR 9912686-1	HND	MG94D-1 096B	MTH 09-Jun-2015 HRS 1354.1 LDG 928		1000	0	2354.1	16.9
5-12-08 0512008	INSPECTION DOCUMENT 08	KDAL		MTH 15-Dec-2022 HRS 2079.4 LDG 1584		24 300		31-Dec-2024 2379.4	1 m 24 d 42.2
5-12-12 0512012	INSPECTION DOCUMENT 12 (14 CFR 91.207)	KLAS		MTH 15-Feb-2024 HRS 2258.4 LDG 1770	-62	12		31-Dec-2024	1 m 24 d
5-12-21 0512021	INSPECTION DOCUMENT 21	KDAL		MTH 15-Dec-2022 HRS 2079.4 LDG 1584		24 600		31-Dec-2024 2679.4	1 m 24 d 342.2
5-12-MP	INSPECTION DOCUMENT MP	KLAS		MTH 15-Feb-2024 HRS 2258.4 LDG 1770	-62	12 250		31-Dec-2024 2508.4	1 m 24 d 171.2
B262201 COCKPIT 0512016	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER	KLAS	C352 F-95367559	MTH 15-Feb-2024	-62	12		31-Dec-2024	1 m 24 d
350004 0512005	HYDROSTATIC TEST OXYGEN BOTTLE (DOT SP-10945)		176276-50 1079800410	MTH 02-Jan-2020		60		31-Jan-2025	2 m 24 d
5-12-36	INSPECTION DOCUMENT 36	KLAS		MTH 26-Jul-2024 HRS 2319.2 LDG 1797		6		31-Jan-2025	2 m 24 d
12-22-01-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH	KLAS		DAYS 12-Aug-2024		90		08-Feb-2025	3 m 1 d
052100	INSPECT INSPECTION ENVIROSYSTEMS 12 MO	KLAS		MTH 15-Feb-2024 HRS 2258.4 LDG 1770		12		28-Feb-2025	3 m 21 d
5-12-02 0512002	INSPECTION DOCUMENT 02	KLAS		MTH 15-Feb-2024 HRS 2258.4 LDG 1770		12		28-Feb-2025	3 m 21 d
5-12-33 0512033	INSPECTION DOCUMENT 33	KLAS		MTH 15-Feb-2024 HRS 2258.4 LDG 1770		12 300		28-Feb-2025 2558.4	3 m 21 d 221.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-066 R06	CARBON RING SEAL AND BEARING HOUSING - REPLACE			HRS MSC				(3000)3000	662.8
E1			RECOMMENDED						
SB FJ44-72-066 R06	CARBON RING SEAL AND BEARING HOUSING - REPLACE			HRS MSC				(3000)3000	662.8
E2			RECOMMENDED						



CESCOM 20 - Projected Maintenance Due

Owner: **CANNON SECURITY PRODUCTS, INC.**

Aircraft Model: **525 - CJ1+**

Aircraft Serial: **525-0605**

Unit: **0605** Reg No: **N800PF**

Airworthiness: **04-Jan-2006**

Print Date: **07-Nov-2024 4:58PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 1	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 2	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
AIR COND	936.1		02-Oct-2024	.75	0.33	37.13		113	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-72-135 R01 E1	IDENTIFICATION PLATE - REPLACE				MTH HRS MSC				(3000)3000	662.8
		MANDATORY								
							DUE			
SB FJ44-72-135 R01 E2	IDENTIFICATION PLATE - REPLACE				MTH HRS MSC				(3000)3000	662.8
		MANDATORY								
							DUE			
SB FJ44-72-150 R03 E1	LP REAR BEARING SEAL RETAINER - REPLACE				MTH HRS MSC				(3000)3000	662.8
		RECOMMENDED					MPI			
SB FJ44-72-150 R03 E2	LP REAR BEARING SEAL RETAINER - REPLACE				MTH HRS MSC				(3000)3000	662.8
		RECOMMENDED					MPI			
SB FJ44-73-042 R05 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE				HRS MSC				(3000)3000	662.8
		RECOMMENDED					-			
SB FJ44-73-042 R05 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE				HRS MSC				(3000)3000	662.8
		RECOMMENDED					-			
SB FJ44-79-013 R05 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE				MTH HRS MSC				(3000)3000	662.8
		RECOMMENDED					-			
SB FJ44-79-013 R05 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE				MTH HRS MSC				(3000)3000	662.8
		RECOMMENDED					-			
SB FJ44-72-076 R02 E1	IP COMPRESSOR STATOR - REWORK				MTH HRS MSC				(5000)5000	2662.8
		OPTIONAL					CSI			
SB FJ44-72-076 R02 E2	IP COMPRESSOR STATOR - REWORK				MTH HRS MSC				(5000)5000	2662.8
		OPTIONAL					CSI			
SB FJ44-72-103 R02 E1	LP SHAFT ASSEMBLY - IDENTIFICATION				MTH HRS MSC				(5000)5000	2662.8
		RECOMMENDED					-			
SB FJ44-72-103 R02 E2	LP SHAFT ASSEMBLY - IDENTIFICATION				MTH HRS MSC				(5000)5000	2662.8
		RECOMMENDED					-			
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE				HRS MSC				(5000)5000	2662.8
		RECOMMENDED					DUE			
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE				HRS MSC				(5000)5000	2662.8
		RECOMMENDED					DUE			
SB FJ44-72-110 E1	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE				HRS MSC				(5000)5000	2662.8
		MANDATORY					DUE			
SB FJ44-72-110 E2	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE				HRS MSC				(5000)5000	2662.8
		MANDATORY					DUE			
SB FJ44-72-131 R02 E1	1ST LP TURBINE NOZZLE - REPLACE				MTH HRS MSC				(5000)5000	2662.8
		RECOMMENDED					DUE			
SB FJ44-72-131 R02 E2	1ST LP TURBINE NOZZLE - REPLACE				MTH HRS MSC				(5000)5000	2662.8
		RECOMMENDED					DUE			
SB FJ44-72-133 R02 E1	REPLACE 1ST LP TURBINE NOZZLE				HRS MSC				(5000)5000	2662.8
		RECOMMENDED					CSI			



CESCOM 20 - Projected Maintenance Due

Owner: **CANNON SECURITY PRODUCTS, INC.**

Aircraft Model: **525 - CJ1+**

Aircraft Serial: **525-0605**

Unit: **0605** Reg No: **N800PF**

Airworthiness: **04-Jan-2006**

Print Date: **07-Nov-2024 4:58PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 1	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
ENG 2	2337.2	1808	02-Oct-2024	.28	0.66	74.28	37	113	3
AIR COND	936.1		02-Oct-2024	.75	0.33	37.13		113	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-72-133 R02 E2	REPLACE 1ST LP TURBINE NOZZLE				HRS MSC				(5000)5000	2662.8
				RECOMMENDED			CSI			
SB FJ44-72-140 R01 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION				MTH HRS MSC				(5000)5000	2662.8
				RECOMMENDED			CSI			
SB FJ44-72-140 R01 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION				MTH HRS MSC				(5000)5000	2662.8
				RECOMMENDED			CSI			
SB FJ44-72-143 R02 E1	BLEED VALVE SHAFT - REPLACE				MTH HRS MSC				(5000)5000	2662.8
				RECOMMENDED			CSI			
SB FJ44-72-143 R02 E2	BLEED VALVE SHAFT - REPLACE				MTH HRS MSC				(5000)5000	2662.8
				RECOMMENDED			CSI			
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE				MTH HRS MSC				(5000)5000	2662.8
				MANDATORY			MPI			
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE				MTH HRS MSC				(5000)5000	2662.8
				MANDATORY			MPI			
SB WI-73-1009 R05 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE				HRS MSC				(5000)5000	2662.8
				RECOMMENDED			CSI			
SB WI-73-1009 R05 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE				HRS MSC				(5000)5000	2662.8
				RECOMMENDED			CSI			
SB WI-75-1001 R02 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH HRS MSC				(5000)5000	2662.8
				RECOMMENDED			-			
SB WI-75-1001 R02 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH HRS MSC				(5000)5000	2662.8
				RECOMMENDED			-			
SB 525-27-26 R01	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION				MTH MSC					
				RECOMMENDED			-			
SB 525-27-28	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION				MTH MSC					
				RECOMMENDED			-			

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2013-08-05 PARA (H)	REPLACE AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES									
		KSAT			MTH					
				MANDATORY	HRS					
					LDG					
					ACH					
							500		1175	238.9
	COMPLIED WITH AD2013-08-05 PARA (H); REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES. FREON SYSTEM HOURS ARE 675.0 HOURS.									