1990 DASSAULT FALCON 900B
Serial Number: 900-92
N316FF

AIRFRAME:

13,983.7	Total Time Since New
5,798	Landings

APU: Honeywell GTCP36-150(F)
5,946.2 TTSN

ENGINES: Honeywell TFE731-5BR-1C – MSP GOLD – 5,000 TBO

	Engine #1	Engine #2	Engine #3
TTSN	13,759	13,703	13,759
Cycles	5,541	5,510	5,541
SMPI	391	392	391
SCZI	391	392	391

AVIONICS:

Dual Collins ADF-60B	Dual Bendix/King KTR-953 w/SELCAL
Dual Honeywell FZ-800 w/controller	Dual Collins VIR-32 w/FM immunity
Dual Honeywell ED-800/Pro Line II/Honeywell	Sperry AA-300
Dual Collins VHF-22D w/8.33 spacing	AirCell ST-3100 Iridium
Fairchild A100A	Honeywell LSZ-850
Dual Collins DME	AlliedSignal Mark V EGPWS
Honeywell 5-tube	Collins TTR-921 TCAS-II w/change 7.1
Dual Honeywell ED-800	Dual Collins TDR-94D
Dual Honeywell NZ-2000 6.1 Software	Honeywell Primus 870
Fairchild GNSSU GPS	

ADDITIONAL EQUIPMENT:

AlliedSignal Mark V EGPWS	Dual Honeywell EFIS
Dual Honeywell Servo Drives	Honeywell Remote Controller
Dual Honeywell Vertical Speed Indicators	Dual Honeywell Air Data Computers
Dual Honeywell V-Bar Attitude Indicators	Honeywell Dataloader
Dual Honeywell Mach Airspeed Indicators	Triple Honeywell Inertial Reference Units
ELT	Triple Honeywell Mode Select Units
Dual Honeywell Avisor Displays	Dual Collins VOR/ILS/MKR
Honeywell Multi-function Display	Dual Honeywell Navigation Computers
Dual Honeywell Reversionary Controllers	WAAS/LPV

INTERIOR:

13 Passenger Interior	Microwave
Maintenance Runner	Oven
DVD Player	GOGO Avance L3 Wifi – Installed 2022

AVAILABLE IMMEDIATELY, MAKE OFFER, CONTACT BRIAN BARTUNEK (407)748-0288

Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aircraft Marketing & Sales, LLC. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.