

1995 Learjet 31A 104 **N278TT**

AIRFRAME: (7,488 CSN) 8,750.6 Total Time Since New

ENGINES: Honeywell TFFE731-2-3B (4,200 hr. Inspection Complied at 8,297)

Left SN: P99319 Right SN: P99321 8,414.7 TTSN 8,414.7 TTSN 117 SOH 117 SOH

AVIONICS:

Collins DME-442 King KRA- 405B

Dual Collins VHF-22D w/ 8.33 spacing Universal UNS-1M 23XX

Dual Bendix King VN-411B **Dual Audio System** Honeywell AHRS **Dual Compass System**

Collins Marker Beacon Dual Bendix/King MST-70B Mode S (SSR)

Bendix King 4-tube Bendix TCAS ANT- 67A ADF CTL Dichroic KCP 420 Auto Pilot Bendix KHF- 950 Fairchild F1000

RDR 2000

ADDITIONAL:

Gogo High-Speed Data/ Wi-Fi Airframe Maintenance Program Freon A/C Engine Maintenance Program Anti- Icing System Dee Howard Thrust Reversers

Winglets Cockpit Voice Recorder

Single-Point Refueling Traffic Collision Avoidance System

Emergency Locator Transmitter Honeywell Weather Radar

INTERIOR: Executive 7 Passenger Configuration (Refinished in 2021)

Two- tone Burnt Orange and White diamond stitching, football leather seating. Sheep skin pilot seats. Embroidered logo in head rest, forward double club, dual aft forward-facing single seats, and belted lav with privacy curtain. Forward galley with high-gloss medium wood veneer cabinetry. Neutral pattern carpeting.

EXTERIOR: (Refinished in 2021)

Snow White & Deep Blue Pearl w/Crimson Red Accents.

MAINTENANCE:

Maintenance Program (100% enrolled JSSI) Up to date Status Reports 12 Year Inspection Due 2031

AVAILABLE IMMEDIATELY, MAKE OFFER, CONTACT STEWART MILLER 205-493-2413







































