

Aircraft Highlights

- Fully enrolled on Programs
- L5 WiFi
- FANS 1/A, CPDLC
- Primus Elite DU-885AF w/Synthetic Vision
- Tailwind 500 Satellite TV System





2

Aircraft Summary

Aircraft Type Gulfstream GIVSP

Year of Manufacture 2001

Airframe Details

Total Airframe Time (hrs) 10,030

Total Airframe Cycles 5,396

Engine Details

Engine Model	Rolls Royce T	AY611-8
Engine Serial Numbers	18013	18014
Total Time Since New (hrs)	9,938	9,854
Total Cycles	5,326	5,284
Time Since Overhaul	3,339	2,200

APU Details

APU Model Honeywell GTCP36-150(G)

APU Serial Number P-870-C

Total Time Since New (hrs) 5,928



Aircraft Summary

Programs

Rolls Royce Corporate Care

Hourly Rate: \$406.62 per Engine

Minimum Utilization: 400 Hours

APU – Honeywell MSP

Hourly Rate: \$167.99

Minimum Utilization: 250 Hours

Honeywell Avionics/Mechanical (HAPP/MPP)

Hourly Rate: \$285.48

Minimum Utilization: 400 Hours

Collins CASP

Hourly Rate: \$132.10


Minimum Utilization: 400 Hours

Corporate Jet Support Briteparts

Hourly Rate: \$168.13

Minimum Utilization: 400 Hours







Avionics Summary

Avionics

- Honeywell Primus Elite
- Honeywell DU-885 Liquid Crystal Displays
- Triple Collins VHF-422D w/8.33 KHz spacing
- Dual Collins HF-9034 w/5 channel SELCAL
- Dual Honeywell NZ-2000 w/6.1.1 software
- Dual Honeywell CD-830 Control Display Units
- Dual Honeywell HG-2021 GPS
- SAT Iridium & VHF AFIS
- Dual Collins TDR-94D w/Flight ID & Enhanced Surveillance

All specifications are subject to verification upon inspection.

Availability subject to prior lease, sale, or withdrawal from the market without notice.

- Triple Honeywell LASEREF IV
- Dual Honeywell SPZ-8400 IFCS
- Fairchild FA2100 CVR
- Honeywell Primus 880 Color Weather Radar

- FANS over Iridium Datalink
- Dual Collins VIR-432 w/FM Immunity Navigation Radios
- Dual Collins DME-442
- Dual Collins ADF-462
- Fairchild FA2100 FDR
- Dual Honeywell SPZ-8400 IFCS Flight Director
- Dual Honeywell RT-300 Radar Altimeter
- Honeywell Mark V EGPWS TAWS
- Honeywell TCAS-2000 TCAS II w/change 7
- DU-885AF Version 2.03 w/XM Weather



Equipment & Inspection Status

Additional Features

- Avance L5 Wi Fi
- FANS 1/A, CPDLC
- Whelan Boombeam Taxi & Landing Lights (HID)
- DPI Labs SmartLink Cabin Management System
- Securaplane External Tail Camera
- Dual 60Hz Cabin Converters
- Tailwind 500 Satellite TV System

Inspection Status

Inspection	Last	Next
1C	March 2025	March 2026
2C	July 2024	July 2026
3C	August 2023	August 2026
4C	July 2024	July 2028
6C	August 2023	August 2029
8C	July 2022	July 2030
12C	July 2017	July 2029
16C	July 2017	July 2033



Cosmetic Summary

Interior

- Neutral Gray Seating for Thirteen (13) Passengers
- Forward 4 place club, Mid-Cabin Left Side 2 Place
 Club w/Right Side 2 Place 74-inch berthable Divan, Aft
 Left side 4 place double club conference group.
- Aft Lav
- Forward Crew Lav
- 7 Cabin Monitors
- 2018 Refurb

Exterior

Matterhorn White w/Blue & Gray Stripes

New Paint June 2015 at West Star





















































HODKINSON SINCE 1981 SDL-YYC