

Falcon 50 Aircraft Type

Year of Manufacture 1989

Airframe Details

Total Airframe Time (hrs) 11,513

Total Airframe Cycles 6,616

APU

APU Model Honeywell GTCP 36-100(A)

APU Serial Number P199

Total Time Since New (hrs) 6,235.4

Time Remaining to HSI 1,429.1

Engine Details

Engine Model	Honeywell TFE-731-3-1C		
Engine Program	EAP		
Program Cost	\$366.10/engine/hour		
Engine Serial Numbers	P76645	P76675	P76648
Total Time Since New (hrs)	10,506.6	13,803.0	10,876.6
Total Cycles Since New	6,091	9,889	6,295
Time Since MPI (hrs)	1,111.3	385.2	1,384.3
Time Since CZI (hrs)	2,506.8	3,224.0	2,879.8



Avionics

- Dual UNS-1Lw GPS/FMS with WAAS/LPV (1000.8)
- Triple Collins VHF-22D/B w/8.33 Spacing
- Dual Collins VIR-32 Nav w/FM Immunity
- Dual Collins ADF-60A
- Dual Collins DME-42
- Dual Honeywell Laseref II IRS
- Collins FCC-86D Flight Control System
- Collins ALT-55B Radio Altimeter
- Collins EFD-86 Five Screen EFIS
- Honeywell Mark V EGPWS w/Windshear
- Dual Collins TDR-94D Enhanced Mode S Transponders w/ADS-B Out

- Fairchild A100A CVR
- Artex ELT C406-N 406MHz
- Collins RTA-858 Weather Radar
- Collins TTR-920 TCAS II (MOPS 7.0)
- Dual Bendix King KTR-953 HF Radios
- Honeywell AFIS DMU
- Honeywell N1 DEEC's



Additional Features

- LED Taxi Light Installation
- Dual Davtron M877 Clocks
- Concorde RG390E Lead Acid Main Batteries
- Veryon Maintenance Tracking
- RVSM SB F50-246 Compliant

4





Interior

Nine (9) Passenger Interior

- The forward cabin features four (4) executive club seating area.
- The Aft cabin features a three (3) place divan opposite single aft facing club (2).
- Cockpit Jump Seat
- Forward Galley
- Galley Microwave
- 110 V Cabin Outlets with USB Ports
- Aft Lavatory
- Refurbished March 2016 at Standard Aero

All specifications are subject to verification upon inspection.

Availability subject to prior lease, sale, or withdrawal from the market without notice.

Entertainment & Communications

- Flight Displays Cabin Entertainment w/Cabin Monitor
- Rockwell Collins Airshow 400
- GoGo ATG 5000 WiFi

Exterior


- Repainted in March 2016 at Standard Aero
- Overall White with Blue and Gold stripes





Maintenance Status

Inspections	Due (Hrs)	
1B Inspection	373.0 Hours	
2B Inspection	2,102.1 Hours	
3B Inspection	602.1 Hours	
4B Inspection	5,102.1 Hours	
12 Month	October 2025	
24 Month	October 2026	
36 Month	October 2027	
1C/3C Inspection	October 2030	
2C/4C Inspection	October 2036	
Landing Gear Overhaul	October 2036	















































HODKINSON SINCE 1981 SDL-YYC