



2009 Bombardier Global 5000

SN: 9295/REG: N410AT





2009 Bombardier Global 5000

SN: 9295/REG: N410AT

Preface:

Risk Mondial Aviation & Recovery (RMAVI) has been appointed to manage, market, and support the sale of this asset. All information presented in this brochure is based on current documentation and inspections conducted under RMAVI's custody of the aircraft.

This is a government-authorized asset sale. The aircraft will be sold as-is, where-is, through an approved auction process, with no pre-purchase flights or inspections. Interested parties are encouraged to review all material carefully and contact RMAVI directly for inquiries or viewing coordination.



2009 Bombardier Global 5000

SN: 9295
REG: N410AT

+1 (954)-684-4680
info@rmavi.us
rmavi.us

HIGHLIGHTS

Only 2,798 Total Airframe Hours — One of the the lowest time Global 5000 currently available for sale.

Preservation & Maintenance at Bombardier Hartford Service Center.

Maximum Takeoff Weight (MTOW): 93,500 lbs.

13-passenger VIP interior – completed December 2022

Previously enrolled on Smart Parts, Corporate Care, and MSP Gold (paused February 2023)

Long-Range Fuel Capability 5,000 Nautical Miles – equipped with single-point refueling

AIRFRAME

Total Time:	2,798
Total Landings:	955
Condition:	GOOD

ENGINES

Manufacturer: Rolls-Royce

Model: BR710A2-20

Fire Detection & Fire Bottles: Installed

Overhaul Status: Not due for overhaul

Engine Serial Numbers & Total Time:

Left Engine: SN: 12703

ETT: 2,798 | Cycles: 955

Right Engine: SN: 12702

ETT: 2,798 | Cycles: 955

Information, specifications, and images are for reference only and subject to buyer verification. Aircraft availability may change without notice. Purchaser is responsible for confirming all details through inspection.



2009 Bombardier Global 5000

SN: 9295
REG: N410AT

+1 (954)-684-4680
Info@rmavi.us
rmavi.us

APU

Manufacturer/Model: Honeywell RE-220 (GX)

Serial Number: P-419 / WE3800714-1

Hours Since New: 2,861

APU cycles: 2,535

Program: Enrolled in Honeywell MSP Gold (paused Feb 2023)

AVIONICS

Suite: Honeywell Primus NZ2000

Dual Honeywell RCZ-833K w/8.33 spacing

Dual Honeywell RCZ-851 DME & ADF

Triple Honeywell NZ-2000 FMS

Honeywell DU-870 6-tube EFIS

Allied Signal SSCVR & SSFDR

Dual Honeywell GPS-550

Dual Collins HF-9031A

Honeywell LASEREF IV IRS

Dual Honeywell RNZ-851 Nav Radios

Dual Collins ALT-4000 Radar Altimeter

Collins SRT-2100 SATCOM

Honeywell Mark V EGPWS

Honeywell TCAS-2000

Honeywell WU-880 Weather Radar

Dual Honeywell Transponders

Information, specifications, and images are for reference only and subject to buyer verification. Aircraft availability may change without notice. Purchaser is responsible for confirming all details through inspection.



2009 Bombardier Global 5000

SN: 9295
REG: N410AT

+1 (954)-684-4680
Info@rmavi.us
rmavi.us

MAINTENANCE

Service Facility: Bombardier Hartford Service Center, in Hartford, Connecticut

Inspections:

15/30/60-month repeat inspections — completed by Bombardier at Bombardier Hartford Service Center (1/2025)

120/180-month repeat inspections — completed by Bombardier at Bombardier Hartford Service Center (1/2025)

Corrosion Remediation:

A known issue for the Global 5000 model, it was completed at Bombardier Hartford Service Center (1/2025). With the work already performed to standard, this is not considered a detractor to the aircraft's value.

Aircraft Logs:

Full, complete, and verified logbooks available onboard.

Additional Features:

ADS-B Out

HUD/EVS (Batch 3.4)

KA-Band Satellite Internet

Information, specifications, and images are for reference only and subject to buyer verification. Aircraft availability may change without notice. Purchaser is responsible for confirming all details through inspection.



2009 Bombardier Global 5000

SN: 9295
REG: N410AT

+1 (954)-684-4680

Info@rmavi.us

rmavi.us

INTERIOR

Completed: December 2022

Configuration: 13-passenger VIP layout

Forward VIP galley and lavatory

4 single executive club seats

4-seat conference group

Aft stateroom: Divan + 2 club seats

Rear lavatory with wardrobe/storage

Pressurized cabin, factory cockpit layout

Windows and instrument glass in excellent condition

EXTERIOR

Overall white paint completed December 2022 (Ft. Lauderdale)

Condition: Good – clean canvas for customization

Windows: Good – minor cosmetic scratches only

Tires: Fair

Brakes & Anti-Skid System: Good & Operational

Information, specifications, and images are for reference only and subject to buyer verification. Aircraft availability may change without notice. Purchaser is responsible for confirming all details through inspection.

Global 5000 Video Walkthrough



[Desktop Link to Video](#)



Information, specifications, and images are for reference only and subject to buyer verification. Aircraft availability may change without notice. Purchaser is responsible for confirming all details through inspection.

























Forward Lavatory



Aft Lavatory













