

**Alabama Aircraft Mgmt.
171 CR 491 Valley Head, AL 35989
256-996-0004**

**Fort Payne Municipal Airport
Fort Payne, AL (4A9)**

Date:3/15/25

Hobbs: 1495.0

RHEngTT:6122.5

TCS: 6122

SN PCE-10002

Performed event 1&2 inspection I/A/W Piper Pa31T MM, Pratt&Whitney MM and M.O.R.E. Insptection Program. Inboard igniter not functional, found bad igniter lead, replaced with new lead PN CH53399-04, tested good. Lubricated engine controls and cables. Adjusted idle for proper idle speed. Test ran engine, check good.

James D Newsome 3235957A&P