



DueList Report

HONDAJET HA-420

S/N 42000089 N562DH

OWNER: SOUTHERN UTAH AERO, LLC
ADDRESS: 520 E TABERNACLE STREET
ST GEORGE UT 84770

OPERATOR: SOUTHERN UTAH AERO, LLC
ADDRESS: 520 E TABERNACLE STREET
ST GEORGE UT 84770

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: JAKE SALINAS
EMAIL: JSALINAS@CAMPSYSTEMS.COM

+1-316-928-7883 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PROJECTED: 6 MOS. to 06-FEB-2025

AIRCRAFT SERIAL/REGNO: 42000089/N562DH MODEL: HONDAJET HA-420 MANUFACTURER: HONDA AIRCRAFT COMPANY, INC.

CERTIFICATION DATE: 26-DEC-2017

LAST ACTUALS:
634.8 A/C HRS as of 01-JUL-2024
594 AFL as of 01-JUL-2024

PROJECTED:
816.28
775

ENGINE NO. 1 SERIAL/PART: 883291/HJ1-17201-120-003 MODEL: HF120-H1A MANUFACTURER: GE HONDA AERO ENGINES

INSTALLED ON: 02-NOV-2017
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
634.8 ENG. HRS as of 01-JUL-2024
594 ENC as of 01-JUL-2024

PROJECTED:
816.28
775

ENGINE NO. 2 SERIAL/PART: 883290/HJ1-17201-120-004 MODEL: HF120-H1A MANUFACTURER: GE HONDA AERO ENGINES

INSTALLED ON: 02-NOV-2017
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
634.8 ENG. HRS as of 01-JUL-2024
594 ENC as of 01-JUL-2024

PROJECTED:
816.28
775



New Requirement/Flagged Items

Operator Review and Action Required

Model: HONDAJET HA-420 Serial: 42000089 RegNo: N562DH HRS: 634.8 AFL: 594 As Of: 01-Jul-2024 Operator: SOUTHERN UTAH AERO, LLC

Report Date: 06-Aug-2024

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
SB 420-52-006			DOORS - CABIN MAIN ENTRY DOOR HINGE TO FUSELAGE FASTENER - REPLACEMENT, SERVICE BULLETIN				Bulletin ATA:52
		MOS		26-Dec-17	_____		MANDATORY
		HRS			_____		
		AFL	T:9000	0	_____	9000 *	

NEW REQUIREMENT ADDED ON 23-JUL-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.

REF: BULLETINS

Name: _____

Signature: _____

Cert.# _____

Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HONDAJET HA-420 Serial: 42000089 RegNo: N562DH HRS: 634.8 AFL: 594
As Of: 01-Jul-2024 Operator: SOUTHERN UTAH AERO, LLC

Report Date: 06-Aug-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
70-31-00-970-801		NO. 1 ENGINE - PERFORMANCE CHECK - MONITOR AND RECORD SPECIFIED ENGINE DATA						
	MOS	1		17-May-24	17-Jun-24		OVD	Service ATA:70
	HRS			632.3				
	ENC			591				
	REF:							
70-31-00-970-801		NO. 2 ENGINE - PERFORMANCE CHECK - MONITOR AND RECORD SPECIFIED ENGINE DATA						
	MOS	1		17-May-24	17-Jun-24		OVD	Service ATA:70
	HRS			632.3				
	ENC			591				
	REF:							
SL SL-420-53-001		AIRFRAME LIFE EXTENSION SERVICE BULLETINS, SERVICE LETTER						
	MOS							Bulletin ATA:53
	HRS	T:600			600 (M)		OVD	
	AFL							
	REF: BULLETINS							
24CA2430013		NO. 1 MAIN SHIP (LEAD ACID) BATTERY MAIN SHIP (LEAD ACID) BATTERY CAPACITY CHECK						
PN:RG-390ES	MOS	6 (+1m/-1m)	Adj:-39d	17-May-24	09-Oct-24	09-Nov-24	64 d (+31)	Service ATA:24 09-Oct-2024
SN:41111979	HRS			632.3				
	AFL			591				
	REF:							
25HA2563062		EMERGENCY LOCATOR TRANSMITTER SELF-TEST (ELT) P/N S182X502-XX, S185X501-XX						
PN:S1851501-01	MOS	6 (+30d/-30d)	Adj:-39d	17-May-24	09-Oct-24	08-Nov-24	64 d (+30)	Service ATA:25 09-Oct-2024
SN:LX1100462637	HRS			632.3				
	AFL			591				
	REF: CMM 25-63-08, AMM 25-60-01							
26HA2620101		FWD HANDHELD FIRE EXTINGUISHER VISUAL INSPECTION P/N RT A1200 OR 337TS (OPTIONAL) (F.S. 140.70 LEFT SIDE)						
PN:RT A1200	MOS	12 (+30d/-30d)		09-Oct-23	09-Oct-24	08-Nov-24	64 d (+30)	Service ATA:26 09-Oct-2024
SN:Y-501142	HRS			569.2				
	AFL			542				
	REF: ALIM INTRO							
12HA1221102		LUBRICATE LEFT MAIN LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION						
	MOS			09-Oct-23				Service ATA:12 29-Oct-2024
	HRS	150 (+10%/-10%)		569.2	719.2	734.2	84.4 (+15)	
	AFL			542				
	REF: AMM 12-21-12							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HONDAJET HA-420 Serial: 42000089 RegNo: N562DH HRS: 634.8 AFL: 594
As Of: 01-Jul-2024 Operator: SOUTHERN UTAH AERO, LLC

Report Date: 06-Aug-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
12HA1221102		LUBRICATE NOSE LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION						Service ATA:12
	MOS			09-Oct-23				29-Oct-2024
	HRS	150 (+10%/-10%)		569.2	719.2	734.2	84.4 (+15)	
	AFL			542				
REF: AMM 12-21-12								
12HA1221102		LUBRICATE RIGHT MAIN LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION						Service ATA:12
	MOS			09-Oct-23				29-Oct-2024
	HRS	150 (+10%/-10%)		569.2	719.2	734.2	84.4 (+15)	
	AFL			542				
REF: AMM 12-21-12								
26HA2600104		FIRE DETECTOR AND FIRE SUPPRESSION BOTTLE INDICATIONS - FUNCTIONAL TEST						Service ATA:26
	MOS			09-Oct-23				29-Oct-2024
	HRS	150		569.2	719.2		84.4	
	AFL			542				
REF: AMM 26-00-01								
Disposition: AIRWORTHINESS								
REF: AMM 26-00-01								
24CA2430013		NO. 2 MAIN SHIP (LEAD ACID) BATTERY MAIN SHIP (LEAD ACID) BATTERY CAPACITY CHECK						Service ATA:24
PN:RG-390ES	MOS	6 (+1m/-1m)		17-May-24	17-Nov-24	17-Dec-24	103 d (+30)	17-Nov-2024
SN:41340529	HRS			632.3				
	AFL			591				
REF:								
25HA2560102		EMERGENCY LOCATOR TRANSMITTER FUNCTIONAL TEST. P/N S185X501-XX (KIT S1840510-02)						Service ATA:25
PN:S1851501-01	MOS	12 (+30d/-30d)	Adj:-155d	17-May-24	13-Dec-24	12-Jan-25	129 d (+30)	13-Dec-2024
SN:LX1100462637	HRS			632.3				
	AFL			591				
REF: AMM 25-60-01								
34HA3410106		STANDBY AIR DATA SYSTEM - FUNCTIONAL TEST						Service ATA:34
PN:100564-100-000	MOS			09-Jan-20				19-Dec-2024
SN:1001094	HRS	600		169.5	769.5		134.7	
	AFL			179				
REF: AMM 34-00-02								
31CA3131004		REPLACE - 1605-01-00 CVR/FDR COMPONENT BATTERY (7905012 DK120/90)						Component ATA:31
PN:PN	MOS	84	TSN:0	26-Dec-17	26-Dec-24		142 d	26-Dec-2024
SN:UNKNOWN	HRS		TSN:0	0				
	AFL		TSN:0	0				
Disposition: LIFE LIMIT								
REF: GENERIC NO REF								



Due List Report

Model: HONDAJET HA-420 Serial: 42000089 RegNo: N562DH HRS: 634.8 AFL: 594
As Of: 01-Jul-2024 Operator: SOUTHERN UTAH AERO, LLC

Report Date: 06-Aug-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
32CA3241463		LEFT MAIN WHEEL ASSEMBLY P/N 90006365 - PERFORM VISUAL AND NDT INSPECTION						Service	ATA:32
	MOS		TAC:0	26-Dec-17				10-Jan-2025	
	HRS		TAC:0	0					
	AFL	750		0	750		156		
REF: CMM 32-41-46, AMM 32-44-01									
32CA3241464		RIGHT MAIN WHEEL ASSEMBLY P/N 90006365 - PERFORM VISUAL AND NDT INSPECTION						Service	ATA:32
	MOS		TAC:0	26-Dec-17				10-Jan-2025	
	HRS		TAC:0	0					
	AFL	750		0	750		156		
REF: CMM 32-41-46, AMM 32-44-01									
32CA3241474		NOSE WHEEL ASSEMBLY P/N 90006367 - VISUAL AND NDT INSPECTION						Service	ATA:32
	MOS		TAC:0	26-Dec-17				10-Jan-2025	
	HRS		TAC:0	0					
	AFL	750		0	750		156		
REF: CMM 32-46-45, AMM 32-44-01									