



CESCOM 20 - Projected Maintenance Due

Owner: **FLEXFLIGHT APS**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0444**
 Unit: **0444** Reg No: **OY-JSW**
 Airworthiness: **04-Sep-2009**
 Print Date: **29-Oct-2024 4:25PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4620:45	3323	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 1	4563:33	3284	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 2	4620:45	3327	27-Oct-2024	0:37	1.64	300:47	181	183	6
AIR COND	1157:54		27-Oct-2024	0:10	0.99	180:28		183	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
E083-241001 E1	REVIEW FJ44-3A/-3A-24 LMM REV 60			MTH MSC						New Req
E083-241001 E2	REVIEW FJ44-3A/-3A-24 LMM REV 60			MTH MSC						New Req

Overdue Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
256006	INFANT LIFE VEST	A316101A00RFD 30027-076	MTH HRS LDG MSC	31-Jul-2024 4564:28 3277					01-Sep-2024	-1 m 28 d Over Due
256006 --	INFANT LIFE VEST	A316101A00RFD 30027-074	MTH HRS LDG MSC	31-Jul-2024 4564:28 3277					01-Sep-2024	-1 m 28 d Over Due
FXT-7	PERFORM EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE		MTH MSC	10-Sep-2021			12 ADMIN		16-Sep-2024	-1 m 13 d Over Due
052001 E1	FJ44 CHECK 1		MTH HRS LDG	28-Jul-2023 4292:37 3068			300		(4535:25)4592:37	-28:08 Over Due
052001 E2	FJ44 CHECK 1		MTH HRS LDG	28-Jul-2023 4292:37 3068			300		(4592:37)4592:37	-28:08 Over Due
5-12-01 0512001	INSPECTION DOCUMENT 1 EKBI		MTH HRS LDG	28-Jul-2023 4292:37 3068			300		4592:37	-28:08 Over Due
5-12-08 0512008	INSPECTION DOCUMENT 8 EKBI		MTH HRS LDG	28-Jul-2023 4292:37 3068			24 300		31-Jul-2025 4592:37	9 m 2 d -28:08 Over Due

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-21 0512021	INSPECTION DOCUMENT 21 EKBI		MTH HRS LDG	12-Oct-2022 4061:36 2903			24 600		31-Oct-2024 4661:36	2 d 40:51
5-12-26	INSPECTION DOCUMENT 26		MTH HRS LDG	26-Apr-2024 4440:30 3181			6		31-Oct-2024	2 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)		MTH HRS LDG	02-Aug-2024 4564:28 3277			3		30-Nov-2024	1 m 1 d
FAA 2024-15-09	GUST LOCK/DAMPER SYSTEM - INSTALL PLACARDS ON THE LEFT-HAND INBOARD EDGE OF THE TAMARACK ACTIVE CAMBER SURFACE (TACS) AND REVISING THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE		MTH HRS				6 MTH 60 HRS		22-Apr-2025 4680	5 m 24 d 59:15

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **FLEXFLIGHT APS**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0444**
 Unit: **0444** Reg No: **OY-JSW**
 Airworthiness: **04-Sep-2009**
 Print Date: **29-Oct-2024 4:25PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4620:45	3323	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 1	4563:33	3284	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 2	4620:45	3327	27-Oct-2024	0:37	1.64	300:47	181	183	6
AIR COND	1157:54		27-Oct-2024	0:10	0.99	180:28		183	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
4-12-MC <i>05120MC</i>	INSPECTION DOCUMENT MC	DUS			MTH 27-Sep-2021 HRS 3502:03 LDG 2522		1200		4702:03	81:18
D243201 <i>0512017</i>	NICKEL-CADMIUM BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK NOTE: THE INSPECTION INTERVAL CAN BE ADJUSTED AFTER THE AVERAGE BATTERY WATER DECREASE PER CELL IS FOUND. REFER TO THE BATTERY SERVICING TABLE. TASK 24-32-00-720									
				9914058-6 12301888	MTH 25-Jan-2024 HRS 4406:25 LDG 3152		400		4806:25	185:40
056005	AIRCRAFT WEIGHINGOPS 1.605 EKOD				MTH 05-Feb-2021 HRS 3247:17 LDG 2340		48		28-Feb-2025	3 m 30 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
					MTH 02-Aug-2024		3		28-Feb-2025	3 m 30 d
4-12-MA <i>05120MA</i>	INSPECTION DOCUMENT MA				MTH 02-Aug-2024 HRS 4564:28 LDG 3277		300		4864:28	243:43
5-12-24 <i>0512024</i>	INSPECTION DOCUMENT 24				MTH 02-Aug-2024 HRS 4564:28 LDG 3277		12 300		31-Aug-2025 4864:28	10 m 2 d 243:43
A256002	EMERGENCY LOCATOR TRANSMITTER DETAILED INSPECTION TASK 25-60-00-210									
				453-5060 05907	MTH 25-Apr-2024 HRS 4440:30 LDG 3181	-49	12		31-Mar-2025	5 m 2 d
80-10-00-960 RIGHT ENGINE	RIGHT STARTER-GENERATOR RESTORATION									
				300SGL129Q 5342XL2	MTH 21-Jul-2022 HRS 3879:28 LDG 2788		1000		4879:28	258:43
052002 E1	FJ44 CHECK 2				MTH 28-Jul-2023 HRS 4292:37 LDG 3068		600		(4835:25)4892:37	271:52
052002 E2	FJ44 CHECK 2				MTH 28-Jul-2023 HRS 4292:37 LDG 3068		600		(4892:37)4892:37	271:52
4-12-MN	INSPECTION DOCUMENT MN				MTH 02-Aug-2024 HRS 4564:28 LDG 3277		12 330		31-Aug-2025 4894:28	10 m 2 d 273:43
215027	EVAPORATOR COIL ASSEMBLY (INSPECT REFRIGERANT PLUMBING FOR LEAKAGE INSPECT COIL FINS FOR CLEANLINES AND DAMAGELNSPECT COLD AIR DUCTLNG FOR LEAKING CRACKS OR DAMAGE)									
					MTH 26-Apr-2024 HRS 4440:30 LDG 3181		12		30-Apr-2025	6 m 1 d
215028	EVAPORATOR HOUSING ASSEMBLY /SHROUD ASSEMBLY / ESCUTCHEON/ WATER DEFLECTOR (INSPECT SEAM BETWEEN SHROUD ASSEMBLY AND ESCUTCHEON FOR SIGNS OF SEPARATION AND CONDENSATE LEAKAGE,INSPECT FOR CLEANLINES AND DAMAGE/INTEGRITY. INSPECT CONDENSATE DRAIN, MAKING SURE HOLE IS CLEAR AND SECURE)									
					MTH 26-Apr-2024 HRS 4440:30 LDG 3181		12		30-Apr-2025	6 m 1 d
215029	BLOWER ASSEMBLY /BLOWER MOTOR /BLOWER WHEEL /BLOWER SCROLL (INSPECT FOR CLEANLINES AND DAMAGE/INTEGRITYVERIFY THAT BLOWER WHEEL IS CLEAN AND OPERATES VIBRATION FREE. MOTOR BRUSH INSPECTION (FWD EVAPORATOR1134300-3 ONLY))									
					MTH 26-Apr-2024 HRS 4440:30 LDG 3181 ACH 1082:50		12 1000		30-Apr-2025 2082:50	6 m 1 d 924:56
215030	EXPANSION VALVE (INSPECT FOR CLEANLINES AND DAMAGE/INTEGRITY)									
					MTH 26-Apr-2024 HRS 4440:30 LDG 3181		12		30-Apr-2025	6 m 1 d



CESCOM 20 - Projected Maintenance Due

Owner: **FLEXFLIGHT APS**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0444**
 Unit: **0444** Reg No: **OY-JSW**
 Airworthiness: **04-Sep-2009**
 Print Date: **29-Oct-2024 4:25PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4620:45	3323	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 1	4563:33	3284	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 2	4620:45	3327	27-Oct-2024	0:37	1.64	300:47	181	183	6
AIR COND	1157:54		27-Oct-2024	0:10	0.99	180:28		183	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)									
		MTH								
		RECOMMENDED	HRS						(5000)5057:12	436:27
			MSC				DUE			
SB FJ44-72-133 R01 E1	REPLACE 1ST LP TURBINE NOZZLE									
		MTH								
		RECOMMENDED	HRS						(5000)5057:12	436:27
			MSC				DUE			
SB FJ44-72-140 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION									
		HRS							(5000)5057:12	436:27
		MANDATORY	MSC				DUE			
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE									
		MTH								
		MANDATORY	HRS				4526		(5000)5057:12	436:27
			MSC				HRS			
This service document is MANDATORY and should be complied with during the first scheduled Compressor Section Inspection (CSI) or subsequent Major Periodic Inspection (MPI).										
SB FJ44-79-012 R01 E1	OIL - LUBE OIL COOLER - REWORK OR REPLACE									
		MTH								
		RECOMMENDED	HRS						(5000)5057:12	436:27
			MSC				DUE			
SB WI-72-1034 E1	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK									
		MTH								
		MANDATORY	HRS				4526		(5000)5057:12	436:27
			MSC				HRS			
							MPI			
This service document is MANDATORY and should be complied with at the next Major Periodic Inspection (MPI).										
SB WI-73-1009 R04 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
		MTH								
		RECOMMENDED	HRS				4526		(5000)5057:12	436:27
			MSC				HRS			
							CSI			
This service document is RECOMMENDED and should be complied with when material is available during the next scheduled Compressor Section Inspection.										
SB FJ44-72-154 R01 E2	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)									
		MTH								
		RECOMMENDED	HRS						(7026)7026	2405:15
			MSC				-			
SB FJ44-72-154 R01 E1	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)									
		MTH								
		RECOMMENDED	HRS						(6969)7026:12	2405:27
			MSC				-			
SB WI-72-1037 R01 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE									
		MTH								
		RECOMMENDED	HRS				4469		(7635:08)7635:08	3014:23
			MSC				HRS			
							CSI			
SB WI-72-1034 R01 E2	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK									
		MTH								
		MANDATORY	HRS				4526		(7692:08)7692:08	3071:23
			MSC				HRS			
							MPI			
SB WI-72-1034 R01 E1	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK									
		MTH								
		MANDATORY	HRS				4469		(7635:08)7692:20	3071:35
			MSC				HRS			
							MPI			
SB WI-72-1037 R01 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE									
		MTH								
		RECOMMENDED	HRS				4469		(7635:08)7692:20	3071:35
			MSC				HRS			
							CSI			
SB WI-72-1041 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE									
		MTH								
		RECOMMENDED	HRS				4526		(7692:08)7749:20	3128:35
			MSC				HRS			
							MPI			



CESCOM 20 - Projected Maintenance Due

Owner: **FLEXFLIGHT APS**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0444**
 Unit: **0444** Reg No: **OY-JSW**
 Airworthiness: **04-Sep-2009**
 Print Date: **29-Oct-2024 4:25PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4620:45	3323	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 1	4563:33	3284	27-Oct-2024	0:37	1.64	300:47	181	183	6
ENG 2	4620:45	3327	27-Oct-2024	0:37	1.64	300:47	181	183	6
AIR COND	1157:54		27-Oct-2024	0:10	0.99	180:28		183	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2024-15-09	GUST LOCK/DAMPER SYSTEM - INSTALL PLACARDS ON THE LEFT-HAND INBOARD EDGE OF THE TAMARACK ACTIVE CAMBER SURFACE (TACS) AND REVISING THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE									
										MSC
										MANDATORY