



CESCOM 20 - Projected Maintenance Due

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **25-Jun-2025 10:43AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	1606:16	1106	07-Jun-2025	0:36	0.66	124:16	93	189	6
ENG 1	1606:16	1106	07-Jun-2025	0:36	0.66	124:16	93	189	6
ENG 2	1606:16	1106	07-Jun-2025	0:36	0.66	124:16	93	189	6
AIR COND	497:12		07-Jun-2025	0:54	0.33	62:07		189	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FXT-7	PERFORM 1ST EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE									
				MTH	08-Oct-2024		36		11-Oct-2025	3 m 16 d
				HRS	1427:29					
				LDG	980					
FXT-8	PERFORM 2ND EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE									
				MTH			36 MTH		11-Oct-2025	3 m 16 d
B243603	LEAD ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) NOTE: THE INSPECTION SCHEDULE MAY BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED, BASED ON OPERATIONS. TASK 24-36-15-720									
	EKBI	RG-380E/44LA5 -	MTH	07-Jun-2025			4		31-Oct-2025	4 m 6 d
		S3597-8	HRS	1606:16			200		1806:16	200
		41238130	LDG	1104						
5-12-08	INSPECTION DOCUMENT 08			MTH	19-Sep-2024		24		30-Sep-2026	15 m 5 d
	UNK		HRS	1411:13			300		1711:13	104:57
			LDG	965						
5-12-36	INSPECTION DOCUMENT 36			MTH	07-Jun-2025		6		31-Dec-2025	6 m 6 d
	EKBI		HRS	1606:16						
			LDG	1104						



CESCOM 20 - Projected Maintenance Due

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **25-Jun-2025 10:43AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	1606:16	1106	07-Jun-2025	0:36	0.66	124:16	93	189	6
ENG 1	1606:16	1106	07-Jun-2025	0:36	0.66	124:16	93	189	6
ENG 2	1606:16	1106	07-Jun-2025	0:36	0.66	124:16	93	189	6
AIR COND	497:12		07-Jun-2025	0:54	0.33	62:07		189	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH						
E1				HRS					(3500)3500	1893:44
				RECOMMENDED	MSC		-			
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH						
E2				HRS					(3500)3500	1893:44
				RECOMMENDED	MSC		-			
SB WI-73-1040 R02 ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH						
E1				HRS					(8000)8000	6393:44
				MSC			DUE			
SB WI-73-1040 R02 ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH						
E2				HRS					(8000)8000	6393:44
				MSC			DUE			
SB 525-27-26	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION			MTH						
				RECOMMENDED	MSC		-			
SB 525-27-26 R01	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION			MTH						
				RECOMMENDED	MSC		-			
SB 525-27-28	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION			MTH						
				RECOMMENDED	MSC		-			
SL 525-21-06	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT			MTH						
				RECOMMENDED	MSC		-			
SL 525-23-08 R01	COMMUNICATIONS - GARMIN GMA 36 MODIFICATION LEVEL VERIFICATION			MTH						
				RECOMMENDED	MSC		-			
SL 525-23-09	COMMUNICATIONS - LINK 2000+ CPDLC AND VHF ACARS CONFIGURATION VERIFICATION			MTH						
				RECOMMENDED	MSC		-			
SL 525-26-01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE ORIENTATION VERIFICATION			MTH						
				RECOMMENDED	MSC		-			
SL 525-27-11	FLIGHT CONTROLS - CONTROL WHEEL ADAPTER AND SHAFT INSPECTION			MTH						
				RECOMMENDED	MSC		-			
SL 525-34-38	NAVIGATION - STORMSCOPE PROCESSOR MODIFICATION (MOD) LEVEL INSPECTION			MTH						
				RECOMMENDED	MSC		-			
SL 525-52-04	DOORS - MAIN CABIN DOOR GROMMET INSTALLATION			MTH						
				RECOMMENDED	MSC		-			
SL 525-53-12	FUSELAGE - CONTROL PEDESTAL WIRE HARNESS ANCHOR VERIFICATION			MTH						
				RECOMMENDED	MSC		-			
SL 525-71-08	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL			MTH						
				RECOMMENDED	MSC		-			
SL 525-71-08 R01	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL			MTH						
				RECOMMENDED	MSC		-			
SL 525-71-08 R02	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL			MTH						
				RECOMMENDED	MSC		-			