



DueList Report

FALCON 900

S/N 157 N328JL

OWNER: LAMON AVIATION, LLC
ADDRESS: 132 LEE DUGGAN DR. STE 3
TX 77498

OPERATOR: LAMON AVIATION, LLC
ADDRESS: 132 LEE DUGGAN DR. STE 3
TX 77498

OPERATOR: JET LINK AVIATION, LLC
ADDRESS: 132 LEE DUGAN DR
SUGAR LAND TX

CAMO: JET LINK AVIATION, LLC
ADDRESS: 132 LEE DUGAN DR
SUGAR LAND TX

OFFICE:
FAX:

OFFICE:
FAX:

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: FALCON ANALYST
EMAIL: ESIMPSON@CAMPSYSTEMS.COM

877-411-2267 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PROJECTED: 3 MOS. to 26-NOV-2025

AIRCRAFT	SERIAL / REGNO: 157/N328JL	MODEL: FALCON 900	MANUFACTURER: DASSAULT AVIATION S.A.
CERTIFICATION DATE: 02-FEB-1996		LAST ACTUALS: 8560.9 A/C HRS as of 10-AUG-2025 5069 AFL as of 10-AUG-2025 6488.4 APH as of 10-AUG-2025	PROJECTED: 8621.38 5099 6549
APU	SERIAL / PART: P-276/3800188-2	MODEL: GTCP36-150(F)	MANUFACTURER: HONEYWELL
INSTALLED ON: 07-OCT-2024		LAST ACTUALS: 6488.4 APU HRS as of 10-AUG-2025 APUS as of 03-MAR-2025	PROJECTED: 6548.88 0
6368.8 APU HRS 8507.6 A/C HRS APUS			
ENGINE NO. 1	SERIAL / PART: P-101280/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 01-JUN-2017		LAST ACTUALS: 8271.4 ENG. HRS as of 10-AUG-2025 4930 ENC as of 10-AUG-2025	PROJECTED: 8331.88 4981
6449.4 ENG. HRS 6742.8 A/C HRS 3739 ENC			
ENGINE NO. 2	SERIAL / PART: P-101279/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 11-MAR-2020		LAST ACTUALS: 8437.2 ENG. HRS as of 10-AUG-2025 5021 ENC as of 10-AUG-2025	PROJECTED: 8497.68 5072
7418 ENG. HRS 7541.7 A/C HRS 4343 ENC			
ENGINE NO. 3	SERIAL / PART: P-101282/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 17-NOV-2017		LAST ACTUALS: 8364.4 ENG. HRS as of 10-AUG-2025 4887 ENC as of 10-AUG-2025	PROJECTED: 8424.88 4938
6727.4 ENG. HRS 6923.9 A/C HRS 3810 ENC			



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
SB F900-388 REV 04		WINGS - WING TANK MODIFICATION, SERVICE BULLETIN						Bulletin ATA:57
	MOS	T:150		EFF	19-Apr-24 * (M)		OVD	
	HRS							
	AFL							
Disposition: MANDATORY		REF: BULLETINS						
26-20-13-960-801-02		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R3WB)						Service ATA:26
PN:861375	MOS	60		02-Sep-20	02-Sep-25		7 d	02-Sep-2025
SN:NSN	HRS							
	AFL							
Disposition: SCRAP		REF: AMM 26-20-13-960-801						
32-20-00-640-801-01		LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG LEG (3GF)						Service ATA:32
	MOS	8 (+1m)	Adj:-197d	29-Jul-25	13-Sep-25	13-Oct-25	18 d (+30)	13-Sep-2025
	HRS			8559.4				
	AFL	400		5068	5468		399	
		REF: AMM 32-20-00-640-801						
32-10-00-640-801-01		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND DOORS						Service ATA:32
	MOS	8 (+1m)	Adj:-196d	29-Jul-25	14-Sep-25	14-Oct-25	19 d (+30)	14-Sep-2025
	HRS			8559.4				
	AFL	400		5068	5468		399	
		REF: AMM 32-10-00-640-801						
32-10-00-640-801-02		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND DOORS						Service ATA:32
	MOS	8 (+1m)	Adj:-196d	29-Jul-25	14-Sep-25	14-Oct-25	19 d (+30)	14-Sep-2025
	HRS			8559.4				
	AFL	400		5068	5468		399	
		REF: AMM 32-10-00-640-801						
32-00-00-700-801-01		CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	20 d (+30)	15-Sep-2025
	HRS			8507.6				
	AFL			5038				
		REF: AMM 32-00-00-700-801						
32-00-00-700-801-02		CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	20 d (+30)	15-Sep-2025
	HRS			8507.6				
	AFL			5038				
		REF: AMM 32-00-00-700-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-00-00-700-801-03		CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	20 d (+30)	15-Sep-2025
	HRS			8507.6				
	AFL			5038				
		REF: AMM 32-00-00-700-801						
28-30-00-680-803-01		DRAINING OF THE GRAVITY DEFUELING LINE						Service ATA:28
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	34 d (+5)	29-Sep-2025
	HRS			8559.4				
	AFL			5068				
		REF: AMM 28-30-00-680-803						
		WO#: NOV 2022						
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS						Service ATA:28
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	34 d (+5)	29-Sep-2025
	HRS			8559.4				
	AFL			5068				
		REF: AMM 28-30-00-680-804						
		WO#: NOV 2022						
32-44-00-780-801-01		PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES						Service ATA:32
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	34 d (+5)	29-Sep-2025
	HRS			8559.4				
	AFL			5068				
		REF: AMM 32-44-00-780-801						
		WO#: NOV 2022						
05-08-00-200-800-05		12 M/800 FH INSPECTION						Package ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS	800 (+40)		8507.6	9307.6	9347.6	746.7 (+40)	
	AFL			5038				
		REF: GENERIC NO REF						
05-08-00-200-800-15		12 M INSPECTION						Package ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
		REF: GENERIC NO REF						
05-60-00-200-801-01		BASIC INSPECTION						Service ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS	400 (+40)		8507.6	8907.6	8947.6	346.7 (+40)	
	AFL			5038				
		REF: AMM 05-60-00-200-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
05-60-00-200-801-03		BASIC INSPECTION - GROUND SERVICING CHECKS						Service ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS	400 (+40)		8507.6	8907.6	8947.6	346.7 (+40)	
	AFL			5038				
		REF: AMM 05-60-00-200-801						
24-32-09-610-801-02		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)						Service ATA:24
PN:135687	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:3505	HRS			8507.6				
	AFL			5038				
		REF: AMM 24-32-09-610-801						
24-32-09-610-801-03		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)						Service ATA:24
PN:804747	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:1026	HRS			8507.6				
	AFL			5038				
		REF: AMM 24-32-09-610-801						
24-32-09-610-801-04		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 BATTERY (32FP)						Service ATA:24
PN:135687	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:5127	HRS			8507.6				
	AFL			5038				
		REF: AMM 24-32-09-610-801						
24-32-09-610-801-05		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC)						Service ATA:24
PN:804747	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:2017	HRS			8507.6				
	AFL			5038				
		REF: AMM 24-32-09-610-801						
25-61-00-200-881-01		INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)						Service ATA:25
	MOS	12		07-Oct-24	07-Oct-25		42 d	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 1						
253A05 ^U		EQUIPMENT AUDIT (TPED'S) (ST11071SC) (DOC# L60-CA001)						Service ATA:25
	MOS	12		07-Oct-24	07-Oct-25		42 d	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
		REF:						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
26-20-15-720-801-01		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:Y-649043	HRS			8507.6				
	AFL			5038				
REF: AMM 26-20-15-720-801								WO#: NOV 2022
26-20-15-720-801-02		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:Y-439906	HRS			8507.6				
	AFL			5038				
REF: AMM 26-20-15-720-801								WO#: NOV 2022
26-20-15-720-801-03		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:Y-547480	HRS			8507.6				
	AFL			5038				
REF: AMM 26-20-15-720-801								WO#: NOV 2022
33-50-05-350-803-01		RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT)						Service ATA:33
PN:P2-07-0025-001	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:UNKNOWN	HRS			8507.6				
	AFL			5038				
REF: AMM 33-50-05-350-803								
345A12 ^U		EQUIPMENT INSPECTION AVANCE L5 BROADBAND SYSTEM (DOC#1038081)						Service ATA:34
	MOS	12		07-Oct-24	07-Oct-25		42 d	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
REF:								
35-30-05-210-801-01		GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						Service ATA:35
PN:894-20330	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	42 d (+11)	07-Oct-2025
SN:P09081020	HRS			8507.6				
	AFL			5038				
REF: AMM 35-30-05-210-801								
38-10-00-670-801-01		STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION						Service ATA:38
	MOS	6 (+1m)	Adj:-.114d	29-Jul-25	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8559.4				
	AFL			5068				
REF: AMM 38-10-00-670-801								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
53-10-00-200-808-01C	INSPECTION OF THE NLG BAY (CPCP)							Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-10-00-200-808					
53-40-00-200-804-01C	INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)							Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-40-00-200-804					
53-40-00-200-804-02C	INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)							Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-40-00-200-804					
53-50-00-210-804-02C	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)							Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-50-00-210-804					
54-00-00-210-810-01C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ) (CPCP)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
	APH							
Disposition: CPCP			REF: AMM 54-00-00-210-810					
54-00-00-210-810-02C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ) (CPCP)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	42 d (+31)	07-Oct-2025
	HRS			8507.6				
	AFL			5038				
	APH							
Disposition: CPCP			REF: AMM 54-00-00-210-810					
32-44-00-250-801-03	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R535GC)							Service ATA:32
PN:C20180120-2	MOS			30-Sep-21				13-Oct-2025
SN:F1106	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	16 (+12)	
			REF: AMM 32-44-00-250-801					

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-44-00-250-801-04		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R540GC)						Service ATA:32
PN:C20180400	MOS			30-Sep-21				13-Oct-2025
SN:02606	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	16 (+12)	
REF: AMM 32-44-00-250-801								
26-20-13-960-801-01		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		62 d	27-Oct-2025
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-03		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)						Service ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		62 d	27-Oct-2025
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-04		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT RH PERCUSSION CARTRIDGE (R4WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		62 d	27-Oct-2025
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-05		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L5WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		62 d	27-Oct-2025
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-06		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)						Service ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		62 d	27-Oct-2025
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
26-20-13-960-801-07		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT LH PERCUSSION CARTRIDGE (L6WB)						Service ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		62 d	27-Oct-2025
SN:N/A	HRS							
	AFL							
Disposition: SCRAP		REF: AMM 26-20-13-960-801						
26-20-13-960-801-08		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		62 d	27-Oct-2025
SN:N/A	HRS							
	AFL							
Disposition: SCRAP		REF: AMM 26-20-13-960-801						
25-62-01-720-801-02		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)						Service ATA:25
PN:DK120/90	MOS	25 (+3%)		10-Oct-23	10-Nov-25	02-Dec-25	76 d (+22)	10-Nov-2025
SN:AT123547	HRS			8437.6				
	AFL			4993				
		REF: AMM 25-62-01-720-801						
26-20-15-790-801-01		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		79 d	13-Nov-2025
SN:Y-649043	HRS			0				
	AFL			0				
		REF: AMM 26-20-15-790-801						
26-20-15-790-801-02		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		79 d	13-Nov-2025
SN:Y-439906	HRS			7627.5				
	AFL			4445				
		REF: AMM 26-20-15-790-801						
26-20-15-790-801-03		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		79 d	13-Nov-2025
SN:Y-547480	HRS			7627.5				
	AFL			4445				
		REF: AMM 26-20-15-790-801						
760130		NO. 1 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			03-Jul-25				16-Nov-2025
	HRS			8266.2				
	ENC	50		4926	(4976)5115		46	
		REF: MSC CAMP EHM ADENDUM, LMM 76-10-03						

WO#: NOV 2022

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 10-Aug-2025 Operator: LAMON AVIATION, LLC

Report Date: 26-Aug-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
760130	NO. 2 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS			03-Jul-25				16-Nov-2025
	HRS			8432				
	ENC	50		5017	(5067)5115		46	
REF: MSC CAMP EHM ADENDUM, LMM 76-10-03								WO#: NOV 2022
760130	NO. 3 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS			03-Jul-25				16-Nov-2025
	HRS			8359.2				
	ENC	50		4883	(4933)5115		46	
REF: MSC CAMP EHM ADENDUM, LMM 76-10-03								WO#: NOV 2022
27-40-01-210-802-01	VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)							Service ATA:27
PN:021121-11	MOS	72 (+3%)		25-Nov-19	25-Nov-25	29-Jan-26	91 d (+65)	25-Nov-2025
SN:141	HRS			7516.2				
	AFL	3750 (+3%)		4372	8122	8234.5	3053 (+112.5)	
REF: AMM 27-40-01-210-802								