



| | | | |
|-------------------------------|-------------------------|---------------------------|---|
| ANALYST: JOSE BRITO | 1-631-619-4578 (DIRECT) | 800-787-9749 (EFAX-CARDS) | PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY). |
| EMAIL: JBRITO@CAMPSYSTEMS.COM | +1-631-588-3200 (MAIN) | 631-980-4222 (FAX) | |
| | WWW.CAMPSYSTEMS.COM | | |

| | | | |
|----------|---------------------------------|----------------|-------------------------------------|
| AIRCRAFT | SERIAL/REGNO: 443/N552TC | MODEL: PC-12 | MANUFACTURER: PILATUS AIRCRAFT LTDX |
| | CERTIFICATION DATE: 10-DEC-2001 | LAST ACTUALS: | |
| | | 4684.5 A/C HRS | as of 01-NOV-2024 |
| | | 3180 AFL | as of 01-NOV-2024 |
| | | 896.1 ACH | as of 14-JUN-2021 |

| | | | |
|--------------|---------------------------------|-----------------|--|
| ENGINE NO. 1 | SERIAL/PART: PCE-PR0309/3042200 | MODEL: PT6A-67B | MANUFACTURER: PRATT & WHITNEY CANADA CORP. |
| | INSTALLED ON: 23-APR-2019 | LAST ACTUALS: | |
| | 3299.5 ENG. HRS | 4659.4 ENG. HRS | as of 01-NOV-2024 |
| | 2285 ENC | 3157 ENC | as of 01-NOV-2024 |
| | 0 A/C HRS | | |

| | | | |
|-----------------|---|---------------------------------------|----------------------------|
| PROPELLER NO. 1 | SERIAL/PART: 110361/MTV-27-1-N-C-F-R(P) | MODEL: MTV-27-1-N-C-F-R(P)/CFR260-65A | MANUFACTURER: MT-PROPELLER |
| | INSTALLED ON: 13-AUG-2019 | LAST ACTUALS: | |
| | 1569.7 PROP HRS | 2885.6 PROP HRS | as of 01-NOV-2024 |
| | 0 PRC | | |
| | 3368.5 A/C HRS | | |



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|--------------------------|---------|---------------------------|--|
| ATA 00 - INFORMATION | | | | | | | | | | | |
| 00-00/121 ^S | CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED | | | | | | | | Service | ATA:00 | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | | | | PKG:15 ,16,17,18,19,20,21 | |
| 00-00/122 ^S | CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH | | | | | | | | Service | ATA:00 | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | | | | PROC. REF: GENERIC NO REF | |
| | | | | | | | | | | PKG:15 ,16,17,18,19,20,21 | |
| 00-00/481 ^S | CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION | | | | | | | | Service | ATA:00 | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | | | | PROC. REF: GENERIC NO REF | |
| | | | | | | | | | | PKG:15 ,16,17,18,19,20,21 | |
| E072-180821 | NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2 | | | | | | | | Service | ATA:00 | |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | | |
| | HRS | | | | | | | | | | |
| | ENC | | | | | | | | | | |
| | | | | | | | | | | PROC. REF: RCF E072 | |
| E072-230410 | NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 57.0 | | | | | | | | Service | ATA:00 | |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | | |
| | HRS | | | | | | | | | | |
| | ENC | | | | | | | | | | |
| | | | | | | | | | | PROC. REF: RCF E072 | |
| PC12-180524 | REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36 | | | | | | | | Service | ATA:00 | |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | | |
| | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| | | | | | | | | | | PROC. REF: RCF PC12 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|----------------------|--|-----------|----------|----------|------------------------|-----------|-----------|--------------------------|-----|----------------|
| ATA 00 - INFORMATION | | | | | | | | | | |
| PC12-181129 | REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 37 | | | | | | | | | Service ATA:00 |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | |
| | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| | PROC. REF: RCF PC12 | | | | | | | | | |
| PC12-190517 | REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 38 | | | | | | | | | Service ATA:00 |
| | MOS/MSC | 10-Dec-01 | - | | | | | REQUIREMENT CHANGE FORMS | | |
| | HRS | 0 | | | | | | | | |
| | AFL | 0 | | | | | | | | |
| | PROC. REF: RCF PC12 | | | | | | | | | |
| PC12-200515 | REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 39 | | | | | | | | | Service ATA:00 |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | |
| | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| | PROC. REF: RCF PC12 | | | | | | | | | |
| PC12-201130 | REVIEW PC-12, PC-12/45, PC-12/47 AIRCRAFT MAINTENANCE MANUAL REVISION 40 | | | | | | | | | Service ATA:00 |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | |
| | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| | PROC. REF: RCF PC12 | | | | | | | | | |
| PC12-210716 | REVIEW PC-12, PC-12/45, PC-12/47 AIRCRAFT MAINTENANCE MANUAL REVISION 41 | | | | | | | | | Service ATA:00 |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | |
| | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| | PROC. REF: RCF PC12 | | | | | | | | | |
| PC12-220829 | REVIEW PC-12, PC-12/45, PC-12/47 AIRCRAFT MAINTENANCE MANUAL REVISION 44 | | | | | | | | | Service ATA:00 |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | |
| | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| | PROC. REF: RCF PC12 | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|

ATA 00 - INFORMATION

| | | | | | | | | | | |
|---------------------|--|-----|---|--|--|--|--|--------------------------|---------|--------|
| PC12-230116 | REVIEW PC-12, PC-12/45, PC-12/47 AIRCRAFT MAINTENANCE MANUAL REVISION 45 | | | | | | | | Service | ATA:00 |
| | MOS/MSC | EFF | - | | | | | REQUIREMENT CHANGE FORMS | | |
| | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: RCF PC12 | | | | | | | | | | |

ATA 04 - LIMITATIONS

| | | | | | | | | | | |
|---------------------------|----------------------------|-----------|-------|-------|-------|--|---------|------------|-----------|--------|
| 040001 | AIRCRAFT LIMIT OF VALIDITY | | | | | | | | Component | ATA:04 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 50000 | TSN 0 | 50000 | | 45315.5 | | | |
| | AFL | 0 | 60000 | TSN 0 | 60000 | | 56820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

| | | | | | | | | | | |
|---------------------------|--|-----------|-------|-------|-------|--|---------|------------|-----------|--------|
| 040005 | AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY | | | | | | | | Component | ATA:04 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 35000 | TSN 0 | 35000 | | 30315.5 | | | |
| | AFL | 0 | 43000 | TSN 0 | 43000 | | 39820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

| | | | | | | | | | | |
|---------------------------|---|-----------|-------|-------|-------|--|---------|------------|-----------|--------|
| 040005 | AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY | | | | | | | | Component | ATA:04 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 35000 | TSN 0 | 35000 | | 30315.5 | | | |
| | AFL | 0 | 43000 | TSN 0 | 43000 | | 39820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

ATA 05 - TIME LIMITS/MAINTENANCE CHECKS

| | | | | | | | | | | |
|-------------------------|--|-----------|-------|--|-------|--|---------|--|---------|--------|
| 050001 | SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID) | | | | | | | | Service | ATA:05 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | 25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | 30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 05-10-30 | | | | | | | | | | |

| | | | | | | | | | | |
|------------------------------------|-----------------------------------|-----------|----|--|---------------|--|--------|--|---------|--------|
| 050005 | AIRCRAFT REGISTRATION - FAR 47.40 | | | | | | | | Service | ATA:05 |
| | MOS | 02-Oct-12 | 84 | | 31-Oct-28 (M) | | 1450 d | | | |
| | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: GENERIC NO REF, FAR FAR | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS | | | | | | | | | | |
| 050010 | SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION | | | | | | | | | Service ATA:05 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | 25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | 30000 | | 30000 | | 26820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 05200A | JOB SET UP / CLOSE UP PACKAGE | | | | | | | | | Package ATA:05 |
| | MOS/MS | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-A-05-20-00-00A-913A-A | | | | | | | | | | |
| 05401A | 300 HOUR INSPECTION | | | | | | | | | Package ATA:05 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4601.3 | 300 | | 4901.3 | | 216.8 | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-A-05-40-01-01A-000B-A | | | | | | | | | | |
| 05402A | 300 HOUR OR 12 MONTHS INSPECTION | | | | | | | | | Package ATA:05 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | 300 | | 4901.3 | | 216.8 | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-A-05-40-01-02A-000B-A | | | | | | | | | | |
| 05403A | 600 HOUR INSPECTION | | | | | | | | | Package ATA:05 |
| | MOS | 11-Jul-23 | | | | | | | | |
| | HRS | 4413.3 | 600 | | 5013.3 | | 328.8 | | | |
| | AFL | 2995 | | | | | | | | |
| PROC. REF: AMM 12-A-05-40-01-03A-000B-A | | | | | | | | | | |
| 05404A | 600 HOUR OR 12 MONTHS INSPECTION | | | | | | | | | Package ATA:05 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | 600 | | 5201.3 | | 516.8 | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-A-05-40-01-04A-000B-A | | | | | | | | | | |
| 05405A | 1200 HOUR OR 12 MONTHS INSPECTION | | | | | | | | | Package ATA:05 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | 1200 | | 5801.3 | | 1116.8 | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-A-05-40-01-05A-000B-A | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS | | | | | | | | | | |
| 05406A | 2400 HOUR OR 24 MONTHS INSPECTION | | | | | | | | | Package ATA:05 |
| | MOS | 06-Jun-24 | 24 | | 06-Jun-26 | | 572 d | | | |
| | HRS | 4601.3 | 2400 | | 7001.3 | | 2316.8 | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-A-05-40-01-06A-000B-A | | | | | | | | | | PKG:21 |
| 057010 | NO. 1 ENGINE - MINOR INSPECTION | | | | | | | | | Package ATA:05 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 72-00-00, EMM 72-00-00 | | | | | | | | | | PKG:2 |
| ATA 06 - DIMENSIONS AND AREAS | | | | | | | | | | |
| 06-00/582 ^S | ACCESS PANEL, ENGINE: 41AT, 42AB, 42AT - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:19 |
| 06-00/583 ^S | ACCESS PANEL, ENGINE: 41AT, 42AB, 42AT - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:19 |
| 06-00/592 ^S | ACCESS PANEL, ENGINE: 42AT - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:16 |
| 06-00/593 ^S | ACCESS PANEL, ENGINE: 42AT - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:16 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-------------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 06 - DIMENSIONS AND AREAS | | | | | | | | | | |
| 06-00/594 ^S | ACCESS PANEL, FUSELAGE: 11BL, 21PZ - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:17 |
| 06-00/595 ^S | ACCESS PANEL, FUSELAGE: 11BL, 21PZ - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:17 |
| 06-00/596 ^S | ACCESS PANEL, EMPENNAGE: 31AB, 32AB, 33ET - OPEN OR REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:17 |
| 06-00/597 ^S | ACCESS PANEL, EMPENNAGE: 31AB, 32AB, 33ET - CLOSE OR INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:17 |
| 06-00/598 ^S | ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:17 |
| 06-00/599 ^S | ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:17 |
| 06-00/602 ^S | ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 11-Jul-23 | | | | | | | | |
| | HRS | 4413.3 | 600 | | | | | | | |
| | AFL | 2995 | | | | | | | | |
| PROC. REF: AMM 06-20-00 | | | | | | | | | | PKG:18 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-------------------------------|---|-----------|----------|----------|-------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 06 - DIMENSIONS AND AREAS | | | | | | | | | | |
| 06-00/603 ^S | ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 11-Jul-23 | | | | | | | | |
| | HRS | 4413.3 | 600 | | | | | | | |
| | AFL | 2995 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:18 |
| 06-00/610 ^S | ACCESS PANEL, EMPENNAGE: 31AB, 31AL, 31AR, 32AB, 32BL, 32BR, 32AL, 32CL, 32CT,32DL, 32DR, 32BT, 33DT, 33ET, 34DT - OPEN OR REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |
| 06-00/611 ^S | ACCESS PANEL, EMPENNAGE: 31AB, 31AL, 31AR, 32AB, 32BL, 32BR, 32AL, 32CL, 32CT,32DL, 32DR, 32BT, 33DT, 33ET, 34DT - CLOSE OR INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |
| 06-00/612 ^S | ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |
| 06-00/613 ^S | ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |
| 06-00/620 ^S | ACCESS PANEL, WING: 51AB, 51BB, 61AB, 61BB - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 |
| 06-00/621 ^S | ACCESS PANEL, WING: 51AB, 51BB, 61AB, 61BB - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-------------------------------|--|-----------|----------|----------|-------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 06 - DIMENSIONS AND AREAS | | | | | | | | | | |
| 06-00/622 ^S | ACCESS PANELS, FUSELAGE: 11BR, 12BZ, 12EZ, 12HZ, 21OZ - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:16 |
| 06-00/623 ^S | ACCESS PANELS, FUSELAGE: 11BR, 12BZ, 12EZ, 12HZ, 21OZ - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:16 |
| 06-00/624 ^S | ACCESS PANEL, FUSELAGE: 11AL, 12EL, 21PZ - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:19 |
| 06-00/625 ^S | ACCESS PANEL, FUSELAGE: 11AL, 12EL, 21PZ - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:19 |
| 06-00/626 ^S | ACCESS PANEL, WING: 52NB - REMOVE AND EXAMINE | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:19 |
| 06-00/627 ^S | ACCESS PANEL, WING: 52NB - INSTALL | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:19 |
| 06-00/628 ^S | ACCESS PANEL,FUSELAGE: 11AR, 11BR, 11BL, 12AL, 12AR, 12AB, 12EL, 12HZ, 12JZ, 12MZ, 11BZ, 12AZ, 12BZ, 12DZ, 12GZ,12BL, 12BR, 12EZ, 12ER, 12KZ, 12CZ, 12FZ, 12IZ, 12LZ, 21JZ, 21OZ, 21GZ, 21HZ, 22TZ, 22PZ, 22UZ - OPEN OR REMOVE. EXAMINE AND MAKE SURE THAT ACCESS PANEL DRAIN HOLES ARE CLEAR | | | | | | | | | Service ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-------------------------------|------|---|----------|----------|-------------------------|-----------|-----------|-------------|---------|----------|
| ATA 06 - DIMENSIONS AND AREAS | | | | | | | | | | |
| 06-00/629 ^S | | ACCESS PANEL,FUSELAGE: 11AR, 11BR, 11BL, 12AL, 12AR, 12AB, 12EL, 12HZ, 12JZ, 12MZ, 11BZ, 12AZ, 12BZ, 12DZ, 12GZ,12BL, 12BR, 12EZ, 12ER, 12KZ, 12CZ, 12FZ, 12IZ, 12LZ, 21JZ, 21QZ, 21GZ, 21HZ, 22TZ, 22PZ, 22UZ - CLOSE OR INSTALL | | | | | | | Service | ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |
| 06-00/630 ^S | | ACCESS PANEL, WING: 51AB, 51BB, 51JB, 51LB, 52MB, 52NB, 52OB, 52KB, 51MB, 51NB, 52TB, 52SB, 52RB, 52PB, 51KB, 61AB, 61BB, 62KB, 62MB, 62NB, 62OB, 62SB, 62RB, 62PB, 61KB, 61MB, 61NB, 62TB - REMOVE AND EXAMINE | | | | | | | Service | ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |
| 06-00/631 ^S | | ACCESS PANEL, WING: 51AB, 51BB, 51JB, 51LB, 52MB, 52NB, 52OB, 52KB, 51MB, 51NB, 52TB, 52SB, 52RB, 52PB, 51KB, 61AB, 61BB, 62KB, 62MB, 62NB, 62OB, 62SB, 62RB, 62PB, 61KB, 61MB, 61NB, 62TB - INSTALL | | | | | | | Service | ATA:06 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:20 |
| 06-00/632 ^S | | ACCESS PANEL,FUSELAGE: 11AL, 11AZ, 11BL, 11CZ, 12EL, 12ER, 12EZ, 21JZ - OPEN OR REMOVE. EXAMINE AND MAKE SURE THAT ACCESS PANEL DRAIN HOLES ARE CLEAR | | | | | | | Service | ATA:06 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 |
| 06-00/633 ^S | | ACCESS PANEL,FUSELAGE: 11AL, 11AZ, 11BL, 11CZ, 12EL, 12ER, 12EZ, 21JZ - CLOSE OR INSTALL | | | | | | | Service | ATA:06 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 |
| 06-00/634 ^S | | ACCESS PANEL, EMPENNAGE: 31AB, 32AB,32CT, 33ET - OPEN OR REMOVE AND EXAMINE | | | | | | | Service | ATA:06 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|---------|---------------------------|--|
| ATA 06 - DIMENSIONS AND AREAS | | | | | | | | | | | |
| 06-00/635 ^S | ACCESS PANEL, EMPENNAGE: 31AB, 32AB,32CT, 33ET - INSTALL | | | | | | | | Service | ATA:06 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 | |
| 06-00/636 ^S | ACCESS PANEL, ENGINE: 42AT - REMOVE AND EXAMINE | | | | | | | | Service | ATA:06 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 | |
| 06-00/637 ^S | ACCESS PANEL, ENGINE: 42AT - INSTALL | | | | | | | | Service | ATA:06 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | PROC. REF: AMM 06-20-00 | | | | | PKG:21 | |
| ATA 07 - LIFTING AND SHORING | | | | | | | | | | | |
| 07-10/160 ^S | LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION | | | | | | | | Service | ATA:07 | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | PROC. REF: AMM 07-10-00 | | | | | PKG:15 ,16,17,18,19,20,21 | |
| 07-10/161 ^S | LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND | | | | | | | | Service | ATA:07 | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | PROC. REF: AMM 07-10-00 | | | | | PKG:15 ,16,17,18,19,20,21 | |
| ATA 10 - PARKING, MOORING, STORE AND RET TO SERV | | | | | | | | | | | |
| 10-10/428 ^S | EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY. | | | | | | | | Service | ATA:10 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | PROC. REF: GENERIC NO REF | | | | | PKG:17 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|

ATA 11 - PLACARDS AND MARKINGS

| | | | | | | | | | | |
|------------------------|--|-----------|------|--|---|--|--|--|---------|--------|
| 11-00/220 ^S | EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY | | | | | | | | Service | ATA:11 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 11-00-00, AMM 11-00-00, AMM 11-20-00, AMM 11-20-00, AMM 11-30-00 | | | | | PKG:20 |

ATA 12 - SERVICING

| | | | | | | | | | | |
|------------------------|--|-----------|-----|--|---------------------------------------|--|--|--|---------|---------------------------|
| 12-20/124 ^S | WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS | | | | | | | | Service | ATA:12 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 12-20-01, AMM 12-20-01 | | | | | PKG:15 ,16,17,18,19,20,21 |
| 12-20/125 ^S | CLEAN WINDSHIELDS AND WINDOWS | | | | | | | | Service | ATA:12 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 12-20-02 | | | | | PKG:15 ,16,17,18,19,20,21 |
| 12-20/126 ^S | CLEAN COCKPIT AND CABIN | | | | | | | | Service | ATA:12 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | PROC. REF: AMM 12-20-03 | | | | | PKG:15 ,16,17,18,19,20,21 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--|--|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 20 - STANDARD PRACTICES - AIRFRAME | | | | | | | | | | |
| 00-00/45A | PERFORM CORROSION INSPECTION (INTERNAL) | | | | | | | | | Service ATA:20 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | | | | | | | | |
| WC#: 20.010 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 20-40-00 | | | | | | | | | | |
| 00-00/45B | PERFORM CORROSION INSPECTION (EXTERNAL) | | | | | | | | | Service ATA:20 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | | | | | | | | |
| WC#: 20.011 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 20-40-00 | | | | | | | | | | |
| 00-00/45C | CORROSION INSPECT (AND ONLY APPLICABLE IF IN SEVERE CLIMATIC CONDITION) | | | | | | | | | Service ATA:20 |
| | MOS/MSC | | A/R | | | | | | | |
| | HRS | | | | | | | | | |
| WC#: 20.015 | AFL | | | | | | | | | |
| PROC. REF: AMM 20-40-00 | | | | | | | | | | |
| ATA 21 - AIR CONDITIONING | | | | | | | | | | |
| 21-20/127 ^S | OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN | | | | | | | | | Service ATA:21 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 21-20/221 ^S | EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT | | | | | | | | | Service ATA:21 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 |
| 21-30/46 | FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM | | | | | | | | | Service ATA:21 |
| | MOS | 18-Jun-21 | 48 | | 18-Jun-25 | | 219 d | | | |
| | HRS | 3764.8 | 4800 | | 8564.8 | | 3880.3 | | | |
| WC#: 21.040 | AFL | 2572 | | | | | | | | |
| PROC. REF: AMM 21-30-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|----------------------------------|--|-----------|----------|----------|------------------------|-------------------------|-----------|-------------|---------|----------|
| ATA 21 - AIR CONDITIONING | | | | | | | | | | |
| 21-30/47 ^S | CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE AND OUTFLOW VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND PROPER SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN | | | | | | | | Service | ATA:21 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| WC#: 21.030 | AFL | 3132 | | | | | | | | |
| | | | | | | PROC. REF: AMM 21-30-01 | | | | |
| 21-30/48 | FUNCTIONAL TEST CABIN ALTITUDE SWITCH | | | | | | | | Service | ATA:21 |
| | MOS | 11-Jul-23 | 60 | | 11-Jul-28 | | 1338 d | | | |
| | HRS | 4413 | | | | | | | | |
| WC#: 21.010 | AFL | 2995 | | | | | | | | |
| | | | | | | PROC. REF: AMM 21-30-07 | | | | |
| 21-30/49 | FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH | | | | | | | | Service | ATA:21 |
| | MOS | 11-Jul-23 | 60 | | 11-Jul-28 | | 1338 d | | | |
| | HRS | 4413 | | | | | | | | |
| WC#: 21.020 | AFL | 2995 | | | | | | | | |
| | | | | | | PROC. REF: AMM 21-30-08 | | | | |
| 21-40/128 ^S | OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH | | | | | | | | Service | ATA:21 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | | PROC. REF: AMM 21-40-11 | | | | |
| 21-40/50 ^S | CLEAN WATER SEPARATOR CONDENSER | | | | | | | | Service | ATA:21 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| WC#: 21.080 | AFL | 3132 | | | | | | | | |
| | | | | | | PROC. REF: AMM 21-40-02 | | | | |
| 21-40/51 | FUNCTIONAL TEST OVERTEMPERATURE SWITCH | | | | | | | | Service | ATA:21 |
| | MOS | 06-Jun-22 | 60 | | 06-Jun-27 | | 937 d | | | |
| | HRS | 4063.5 | 4800 | | 8863.5 | | 4179 | | | |
| WC#: 21.130 | AFL | | | | | | | | | |
| | | | | | | PROC. REF: AMM 21-40-06 | | | | |
| 21-40/52 | FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH | | | | | | | | Service | ATA:21 |
| | MOS | 06-Jun-22 | 60 | | 06-Jun-27 | | 937 d | | | |
| | HRS | 4063.5 | 4800 | | 8863.5 | | 4179 | | | |
| WC#: 21.120 | AFL | | | | | | | | | |
| | | | | | | PROC. REF: AMM 21-60-05 | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|----------------------------------|------|--|----------|----------|------------------------|-----------|---------------------------|-------------|---------|----------|--|
| ATA 21 - AIR CONDITIONING | | | | | | | | | | | |
| 21-40/53 ^S | | OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 101-320 WITHOUT A MODIFIED AUXILIARY HEATING SYSTEM) | | | | | | | Service | ATA:21 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 21-40-09 | | | PKG:20 | |
| 21-40/54 ^S | | OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM) | | | | | | | Service | ATA:21 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 21-40-00 | | | PKG:20 | |
| 21-40/55 ^S | | RE-OIL AIR CONDITIONING COLD AIR UNIT | | | | | | | Service | ATA:21 | |
| | MOS | 11-Jul-23 | | | | | | | | | |
| | HRS | 4413.3 | 600 | | | | | | | | |
| WC#: 21.060 | AFL | 2995 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 21-40-01 | | | PKG:18 | |
| 21-40/56 ^S | | INSPECT/CHECK HEAT EXCHANGER MATRIX | | | | | | | Service | ATA:21 | |
| | MOS | 11-Jul-23 | | | | | | | | | |
| | HRS | 4413.3 | 600 | | | | | | | | |
| WC#: 21.070 | AFL | 2995 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 21-40-01 | | | PKG:18 | |
| 21-50/223 ^S | | EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT | | | | | | | Service | ATA:21 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: GENERIC NO REF | | | PKG:20 | |
| 21-50/433 | | CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED) | | | | | | | Service | ATA:21 | |
| PN:PN | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | | |
| SN:UNKNOWN | HRS | 4601.3 | 300 | | 4901.3 | | 216.8 | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: GENERIC NO REF | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|
| ATA 21 - AIR CONDITIONING | | | | | | | | | | |
| 21-50/461 INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED) Service ATA:21 | | | | | | | | | | |
| PN:PN | MOS/MSC | 10-Dec-01 | N/A | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | | | | | | | |
| | AFL | 0 | | | | | | | | |
| | ACH | | | | | | | | | |
| PROC. REF: AMM 21-50-03 | | | | | | | | | | |
| 21-50/462 CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED) Service ATA:21 | | | | | | | | | | |
| PN:PN | MOS/MSC | 10-Dec-01 | N/A | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | | | | | | | |
| | AFL | 0 | | | | | | | | |
| | ACH | | | | | | | | | |
| PROC. REF: AMM 21-50-00, AMM 21-50-00 | | | | | | | | | | |
| 21-50/58 INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED) Service ATA:21 | | | | | | | | | | |
| PN:PN | MOS | 18-Jun-18 | | | | | | | | |
| SN:UNKNOWN | HRS | 3146.6 | | | | | | | | |
| WC#: 21.110 | AFL | 2198 | | | | | | | | |
| | ACH | 759.2 | 500 | | 1259.2 | | 363.1 | | | |
| PROC. REF: AMM 21-50-03 | | | | | | | | | | |
| 21-50/59 CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED) Service ATA:21 | | | | | | | | | | |
| PN:PN | MOS | 18-Jun-18 | | | | | | | | |
| SN:UNKNOWN | HRS | 3146.6 | | | | | | | | |
| WC#: 21.100 | AFL | 2198 | | | | | | | | |
| | ACH | 759.2 | 500 | | 1259.2 | | 363.1 | | | |
| PROC. REF: AMM 21-50-00, AMM 21-50-00 | | | | | | | | | | |
| 210040 TEMPCONTROL VALVE Component ATA:21 | | | | | | | | | | |
| PN:6031C000-001 | MOS/MSC | 08-May-12 | O/C | TSR 0 | | | | | | |
| SN:1310 | HRS | 1284.3 | | TSR 0 | | | | | | |
| WC#: 21.310 | AFL | 876 | | TSR 0 | | | | | | |
| PROC. REF: AMM 21-60-01, AMM 21-60-01 | | | | | | | | | | |
| 210045 AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE Component ATA:21 | | | | | | | | | | |
| PN:PN | MOS/MSC | 10-Dec-01 | O/C | TSN 0 | | | | | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | |
| WC#: 21.380 | AFL | 0 | | TSN 0 | | | | | | |
| PROC. REF: AMM 21-50-01, AMM 21-50-01 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|----------------------------------|--|-----|-----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 21 - AIR CONDITIONING | | | | | | | | | | |
| 210046 | VAPOR CYCLE COMPRESSOR MOTOR | | | | | | | | | Component ATA:21 |
| PN:PN-UNKNOWN | MOS/MSC | | 15-May-08 | O/C | TSO 3 | | | | | |
| SN:495 | HRS | | 1003.4 | | TSO 0 | | | | | |
| | AFL | | | | TSO 0 | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 210095 | CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR | | | | | | | | | Component ATA:21 |
| PN:965.23.23.202 | MOS/MSC | | 06-Jun-22 | O/C | TSR 162 | | | | | |
| SN:1023705 | HRS | | 4063.5 | | TSR 2977.4 | | | | | |
| WC#: 21.245 | AFL | | | | | | | | | |
| PROC. REF: AMM 21-30-06 | | | | | | | | | | |
| 210105 | CABIN DIFFERENTIAL PRESSURE SWITCH | | | | | | | | | Component ATA:21 |
| PN:P105651 | MOS/MSC | | 11-Jul-23 | O/C | TSN 0 | | | | | |
| SN:1102094 | HRS | | 4413 | | TSN 0 | | | | | |
| WC#: 21.330 | AFL | | 2995 | | TSN 0 | | | | | |
| PROC. REF: AMM 21-30-08 | | | | | | | | | | |
| 210110 | CABIN PX SWITCH | | | | | | | | | Component ATA:21 |
| PN:965.23.21.533 | MOS/MSC | | 29-Dec-08 | O/C | TSR 0 | | | | | |
| SN:1010110 | HRS | | 1086.1 | | TSR 0 | | | | | |
| WC#: 21.360 | AFL | | 740 | | TSR 0 | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| ATA 22 - AUTO FLIGHT | | | | | | | | | | |
| 22-10/233 ^S | EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES | | | | | | | | | Service ATA:22 |
| | MOS | | 06-Jun-24 | 24 | | | | | | |
| | HRS | | 4601.3 | 2400 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 22-10/60 ^S | SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK | | | | | | | | | Service ATA:22 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 22-10-00 | | | | | | | | | | |
| 22-10/60 ^S | SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK | | | | | | | | | Service ATA:22 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 22-10-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 22 - AUTO FLIGHT | | | | | | | | | | |
| 22-10/60 ^S | SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK | | | | | | | | | Service ATA:22 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 22-10-00 | | | | | | | | | | PKG:20 |
| 22-10/60 ^S | SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK | | | | | | | | | Service ATA:22 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| WC#: 22.010 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 22-10-00 | | | | | | | | | | PKG:20 |
| 22-20/129 ^S | EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS | | | | | | | | | Service ATA:22 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 22-20-02 | | | | | | | | | | PKG:17 |
| 22-20/130 ^S | CHECK STICK PUSHER SYSTEM | | | | | | | | | Service ATA:22 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 22-20-00 | | | | | | | | | | PKG:16 |
| 22-20/226 ^S | FUNCTIONAL TEST STICK PUSHER SYSTEM | | | | | | | | | Service ATA:22 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 22-20-00 | | | | | | | | | | PKG:20 |
| 220005 | AUTOPILOT MODE CONTROL | | | | | | | | | Component ATA:22 |
| PN:065-0086-17 | MOS/MSC | 18-Jan-10 | O/C | | | | | | | |
| SN:2079 | HRS | 1175.3 | | | | | | | | |
| WC#: 22.160 | AFL | 828 | | | | | | | | |
| PROC. REF: AMM 22-10-05 | | | | | | | | | | |
| 220070 | STICK PUSHER COMPUTER | | | | | | | | | Component ATA:22 |
| PN:975.44.23.104 | MOS/MSC | 18-Jan-10 | O/C | TSR 0 | | | | | | |
| SN:120159 | HRS | 1175.3 | | TSR 0 | | | | | | |
| WC#: 22.170 | AFL | 828 | | TSR 0 | | | | | | |
| PROC. REF: AMM 22-20-01 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|---------|---|-----------|----------|------------------------|-----------|-----------|-------------|-----------|----------|--|
| ATA 23 - COMMUNICATIONS | | | | | | | | | | | |
| 230030 | | AUDIO SELECTOR | | | | | | | Component | ATA:23 | |
| PN:011-00401-10 | MOS/MSC | | 01-Jul-14 | O/C | | | | | | | |
| SN:96265007 | HRS | | 1890.9 | | | | | | | | |
| WC#: 23.040 | AFL | | | | | | | | | | |
| PROC. REF: AMM 23-50-01 | | | | | | | | | | | |
| ATA 24 - ELECTRICAL POWER | | | | | | | | | | | |
| 24-20/227 ^S | | OPERATIONAL TEST AC ELECTRICAL SYSTEM | | | | | | | Service | ATA:24 | |
| | MOS | | 06-Jun-24 | 12 | | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | | |
| | AFL | | 3132 | | | | | | | | |
| PROC. REF: AMM 24-20-00 | | | | | | | | | | | |
| PKG:20 | | | | | | | | | | | |
| 24-30/131 ^S | | EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT | | | | | | | Service | ATA:24 | |
| | MOS | | 06-Jun-24 | 12 | | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | | |
| | AFL | | 3132 | | | | | | | | |
| PROC. REF: AMM 24-30-03, AMM 24-30-03 | | | | | | | | | | | |
| PKG:17 | | | | | | | | | | | |
| 24-30/132 ^S | | EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED) | | | | | | | Service | ATA:24 | |
| | MOS | | 06-Jun-24 | 12 | | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | | |
| | AFL | | 3132 | | | | | | | | |
| PROC. REF: AMM 24-30-00, AMM 24-30-00 | | | | | | | | | | | |
| PKG:17 | | | | | | | | | | | |
| 24-30/19 | | STARTER GENERATOR | | | | | | | Component | ATA:24 | |
| PN:23085-029 | MOS | | 11-Jul-23 | | TSN 84, TSO 1 | | | OVERHAUL | | | |
| SN:P1158 | HRS | | 4413 | 1000 | TSN 1925.1, TSO 0 5413 | | 728.5 | | | | |
| WC#: 24.020 | AFL | | 2995 | | TSN 1204, TSO 0 | | | | | | |
| PROC. REF: AMM 24-30-01 | | | | | | | | | | | |
| 24-30/20 | | GENERATOR 2 DRIVE ASSEMBLY AFT BEARING | | | | | | | Component | ATA:24 | |
| PN:PN | MOS | | 10-Dec-01 | | TSN 0 | | | DISCARD | | | |
| SN:UNKNOWN | HRS | | 0 | 10000 | TSN 0 | 10000 | 5315.5 | | | | |
| WC#: 24.040 | AFL | | 0 | | TSN 0 | | | | | | |
| PROC. REF: AMM 24-30-04 | | | | | | | | | | | |
| 24-30/21 | | GENERATOR 2 DRIVE ASSEMBLY AFT BEARING | | | | | | | Component | ATA:24 | |
| PN:940.83.08.902 | MOS | | 18-Jun-21 | | TSN 0 | | | DISCARD | | | |
| SN:UNKNOWN | HRS | | 3764.8 | 3000 | TSN 0 | 6764.8 | 2080.3 | | | | |
| | AFL | | 2572 | | TSN 0 | | | | | | |
| PROC. REF: AMM 24-30-04 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|--------|---|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|--------|
| ATA 24 - ELECTRICAL POWER | | | | | | | | | | | |
| 24-30/228 ^S | | OPERATIONAL TEST EXTERNAL POWER | | | | | | | | Service | ATA:24 |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 24-30-00, AMM 24-30-00 | | | | | | | | | | PKG:21 | |
| 24-30/482 ^S | | BRUSH CHECK STARTER GENERATOR BRUSHES (P/N 978.91.23.407, 978.91.23.408 AND 978.91.23.409) | | | | | | | | Service | ATA:24 |
| PN:23085-029 | MOS | 11-Jul-23 | | | | | | | | | |
| SN:P1158 | HRS | 4413.3 | 600 | | | | | | | | |
| | AFL | 2995 | | | | | | | | | |
| PROC. REF: AMM 24-30-01 | | | | | | | | | | PKG:18 | |
| 24-30/61 ^S | | BRUSH CHECK STARTER GENERATOR BRUSHES (ALL P/N'S EXCEPT 978.91.23.407, 978.91.23.408 AND 978.91.23.409) | | | | | | | | Service | ATA:24 |
| PN:23085-029 | MOS | 06-Jun-24 | | | | | | | | | |
| SN:P1158 | HRS | 4601.3 | 300 | | | | | | | | |
| WC#: 24.020 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 24-30-01 | | | | | | | | | | PKG:16 | |
| 24-30/62 | | EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS | | | | | | | | Service | ATA:24 |
| | MOS | 11-Jul-23 | 24 | | 11-Jul-25 | | 242 d | | | | |
| | HRS | 4413 | | | | | | | | | |
| WC#: 24.210 | AFL | 2995 | | | | | | | | | |
| PROC. REF: AMM 24-30-00 | | | | | | | | | | | |
| 24-30/63 ^S | | INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES | | | | | | | | Service | ATA:24 |
| PN:PN | MOS | 06-Jun-24 | | | | | | | | | |
| SN:UNKNOWN | HRS | 4601.3 | 300 | | | | | | | | |
| WC#: 24.030 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 24-30-02 | | | | | | | | | | PKG:16 | |
| 24-30/64 ^S | | INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES | | | | | | | | Service | ATA:24 |
| PN:PN | MOS | 11-Jul-23 | | | | | | | | | |
| SN:UNKNOWN | HRS | 4413.3 | 600 | | | | | | | | |
| | AFL | 2995 | | | | | | | | | |
| PROC. REF: AMM 24-30-02 | | | | | | | | | | PKG:18 | |
| 24-30/65 | | INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING | | | | | | | | Service | ATA:24 |
| | MOS/MS | | N/A | | | | | | | | |
| | HRS | | | | | | | | | | |
| WC#: 24.030 | AFL | | | | | | | | | | |
| PROC. REF: AMM 24-30-04 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|----------------------------------|--------|--|----------|----------|------------------------|-----------|-----------|-------------|-----|-----------|--------|
| ATA 24 - ELECTRICAL POWER | | | | | | | | | | | |
| 24-30/66 | | INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING | | | | | | | | Service | ATA:24 |
| | MOS | 18-Jun-18 | | | | | | | | | |
| | HRS | 3146.6 | 1800 | | 4946.6 | | 262.1 | | | | |
| | AFL | 2198 | | | | | | | | | |
| PROC. REF: AMM 24-30-04 | | | | | | | | | | | |
| 24-30/69 | | REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY | | | | | | | | Service | ATA:24 |
| PN:RG-380E/44 | MOS | 06-Jun-24 | 6 | | 06-Dec-24 | | 25 d | | | | |
| SN:70017717 | HRS | 4601.3 | 600 | | 5201.3 | | 516.8 | | | | |
| WC#: 24.010 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 24-30-07 | | | | | | | | | | | |
| 24-30/69 | | REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY | | | | | | | | Service | ATA:24 |
| PN:RG-380E/44 | MOS | 06-Jun-24 | 6 | | 06-Dec-24 | | 25 d | | | | |
| SN:70020791 | HRS | 4601.3 | 600 | | 5201.3 | | 516.8 | | | | |
| WC#: 24.010 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 24-30-07 | | | | | | | | | | | |
| 24-40/229 ^S | | EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE | | | | | | | | Service | ATA:24 |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 | |
| 24-60/133 ^S | | EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS | | | | | | | | Service | ATA:24 |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 | |
| 240065 | | OVERHEAD PANEL | | | | | | | | Component | ATA:24 |
| PN:972.81.32.102 | MOS/MS | 06-Apr-11 | O/C | | | | | | | | |
| SN:JWPIL336 | HRS | | | | | | | | | | |
| WC#: 24.190 | AFL | | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 240073 | | VOLTAGE/CURRENT INDICATOR | | | | | | | | Component | ATA:24 |
| PN:988.21.16.104 | MOS/MS | 09-May-13 | O/C | TSN 0 | | | | | | | |
| SN:130458 | HRS | 1517.6 | | TSN 0 | | | | | | | |
| | AFL | 1046 | | TSN 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|-------------------------|-----|-----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 24 - ELECTRICAL POWER | | | | | | | | | | |
| 240135 | NO. 1 LEAD ACID BATTERY | | | | | | | | | Component ATA:24 |
| PN:RG-380E/44 | MOS/MSC | | 23-Sep-22 | O/C | | | | | | |
| SN:70017717 | HRS | | 4195.3 | | | | | | | |
| WC#: 24.010 | AFL | | | | | | | | | |
| PROC. REF: AMM 24-30-07 | | | | | | | | | | |
| 240140 | NO. 2 LEAD ACID BATTERY | | | | | | | | | Component ATA:24 |
| PN:RG-380E/44 | MOS/MSC | | 23-Sep-22 | O/C | TSN 0 | | | | | |
| SN:70020791 | HRS | | 4195.3 | | TSN 0 | | | | | |
| WC#: 24.010 | AFL | | | | TSN 0 | | | | | |
| PROC. REF: AMM 24-30-07 | | | | | | | | | | |
| 243045 | GENERATOR 2 | | | | | | | | | Component ATA:24 |
| PN:PN | MOS/MSC | | 10-Dec-01 | O/C | TSN 0 | | | | | |
| SN:UNKNOWN | HRS | | 0 | | TSN 0 | | | | | |
| WC#: 24.030 | AFL | | 0 | | TSN 0 | | | | | |
| PROC. REF: AMM 24-30-02, AMM 24-30-02 | | | | | | | | | | |
| 243100 | NO. 1 NICAD BATTERY | | | | | | | | | Component ATA:24 |
| PN:PN | MOS/MSC | | 10-Dec-01 | O/C | TSN 0 | | | | | |
| SN:NOT INSTALLED | HRS | | 0 | | TSN 0 | | | | | |
| WC#: 24.060 | AFL | | 0 | | TSN 0 | | | | | |
| PROC. REF: AMM 24-30-07 | | | | | | | | | | |
| 243105 | NO. 2 NICAD BATTERY | | | | | | | | | Component ATA:24 |
| PN:PN | MOS/MSC | | 10-Dec-01 | O/C | TSN 0 | | | | | |
| SN:NOT INSTALLED | HRS | | 0 | | TSN 0 | | | | | |
| WC#: 24.060 | AFL | | 0 | | TSN 0 | | | | | |
| PROC. REF: AMM 24-30-07 | | | | | | | | | | |
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | |
| 25-10/134 ^S | EXAMINE CREW SEAT BELTS | | | | | | | | | Service ATA:25 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| | | | | | | | | | | PKG:17 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|---------|--|----------|----------|------------------------|-----------|-----------|-------------|-----------|---------------------------|--|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | | |
| 25-10/135 ^S | | EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED | | | | | | | Service | ATA:25 | |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:16 | |
| 25-10/294 | | CO-PILOT SEAT BELT | | | | | | | Component | ATA:25 | |
| PN:1-10-875301 | MOS/MSC | 13-Dec-13 | O/C | | TSO 0 | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | | TSO 0 | | | | | | |
| | AFL | | | | TSO 0 | | | | | | |
| PROC. REF: AMM 25-10-02 | | | | | | | | | | | |
| 25-10/294 | | CREW SEAT BELTS | | | | | | | Component | ATA:25 | |
| PN:PN-UNKNOWN | MOS/MSC | 13-Dec-13 | O/C | | TSO 0 | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | | TSO 0 | | | | | | |
| WC#: 25.030 | AFL | | | | TSO 0 | | | | | | |
| PROC. REF: AMM 25-10-02 | | | | | | | | | | | |
| 25-10/294 | | PILOT SEAT BELT | | | | | | | Component | ATA:25 | |
| PN:1-10-570301 | MOS/MSC | 13-Dec-13 | O/C | | TSO 0 | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | | TSO 0 | | | | | | |
| | AFL | | | | TSO 0 | | | | | | |
| PROC. REF: AMM 25-10-02 | | | | | | | | | | | |
| 25-10/296 ^S | | REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION | | | | | | | Service | ATA:25 | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 25-10-05, AMM 25-10-01 | | | | | | | | | | PKG:15 ,16,17,18,19,20,21 | |
| 25-10/297 ^S | | INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION | | | | | | | Service | ATA:25 | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 25-10-05, AMM 25-10-01 | | | | | | | | | | PKG:15 ,16,17,18,19,20,21 | |
| 25-10/300 ^S | | REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. | | | | | | | Service | ATA:25 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 25-10-05, AMM 25-10-01 | | | | | | | | | | PKG:20 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|--------------------------------|---------|---|----------|----------|------------------------|-----------|-----------|-------------|-----------|----------|--|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | | |
| 25-20/136 ^S | | EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS | | | | | | | Service | ATA:25 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 | |
| 25-20/137 ^S | | EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT | | | | | | | Service | ATA:25 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |
| 25-20/295 | | NO. 1 PASSENGER SEAT BELT | | | | | | | Component | ATA:25 | |
| PN:5-02-024723 | MOS/MSC | 13-Dec-13 | O/C | TSO 0 | | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | TSO 0 | | | | | | | |
| | AFL | | | TSO 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 25-20/295 | | NO. 2 PASSENGER SEAT BELT | | | | | | | Component | ATA:25 | |
| PN:5-02-024723 | MOS/MSC | 13-Dec-13 | O/C | TSO 0 | | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | TSO 0 | | | | | | | |
| | AFL | | | TSO 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 25-20/295 | | NO. 3 PASSENGER SEAT BELT | | | | | | | Component | ATA:25 | |
| PN:5-02-024723 | MOS/MSC | 13-Dec-13 | O/C | TSO 0 | | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | TSO 0 | | | | | | | |
| | AFL | | | TSO 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 25-20/295 | | NO. 4 PASSENGER SEAT BELT | | | | | | | Component | ATA:25 | |
| PN:5-02-024723 | MOS/MSC | 13-Dec-13 | O/C | TSO 0 | | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | TSO 0 | | | | | | | |
| | AFL | | | TSO 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 25-20/295 | | NO. 5 PASSENGER SEAT BELT | | | | | | | Component | ATA:25 | |
| PN:5-02-024723 | MOS/MSC | 13-Dec-13 | O/C | TSO 0 | | | | | | | |
| SN:UNKNOWN | HRS | 1740.4 | | TSO 0 | | | | | | | |
| | AFL | | | TSO 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---|-----|-----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | |
| 25-20/295 | NO. 6 PASSENGER SEAT BELT | | | | | | | | | Component ATA:25 |
| PN:5-02-024723 | MOS/MSC | | 13-Dec-13 | O/C | TSO 0 | | | | | |
| SN:UNKNOWN | HRS | | 1740.4 | | TSO 0 | | | | | |
| | AFL | | | | TSO 0 | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 25-20/295 | PASSENGER SEAT BELTS | | | | | | | | | Component ATA:25 |
| PN:5-02-024723 | MOS/MSC | | 13-Dec-13 | O/C | TSO 0 | | | | | |
| SN:UNKNOWN | HRS | | 1740.4 | | TSO 0 | | | | | |
| WC#: 25.010 | AFL | | | | TSO 0 | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 25-20/298 ^S | REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION | | | | | | | | | Service ATA:25 |
| | MOS/MSC | | 06-Jun-24 | A/R | | | | | | |
| | HRS | | 4601.3 | | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 25-22-01, AMM 25-20-01, AMM 25-21-01 | | | | | | | | | | |
| 25-20/299 ^S | INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION | | | | | | | | | Service ATA:25 |
| | MOS/MSC | | 06-Jun-24 | A/R | | | | | | |
| | HRS | | 4601.3 | | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 25-22-01, AMM 25-20-01, AMM 25-21-01 | | | | | | | | | | |
| 25-20/302 ^S | EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS). | | | | | | | | | Service ATA:25 |
| | MOS | | 06-Jun-24 | | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 25-60/231 ^S | OPERATIONAL TEST ELT | | | | | | | | | Service ATA:25 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 25-63-10, AMM 25-63-00, AMM 25-63-20, AMM 25-63-30 | | | | | | | | | | |
| 25-60/232 ^S | EXAMINE ELT INSTALLATION | | | | | | | | | Service ATA:25 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--------------------------------|----------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | |
| 25-62/642 | EXAMINE COPILOTS LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201C | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| SN:24031320011 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-62/642 | EXAMINE NO. 1 LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201 | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| SN:24022290007 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-62/642 | EXAMINE NO. 2 LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201 | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| SN:24022290008 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-62/642 | EXAMINE NO. 3 LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201 | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| SN:24022290009 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-62/642 | EXAMINE NO. 4 LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201 | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| SN:24022290010 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-62/642 | EXAMINE NO. 5 LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201 | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| SN:24022290011 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-62/642 | EXAMINE NO. 6 LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201 | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| SN:24022290012 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|--------------------------------|------|----------------------------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|--------|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | | |
| 25-62/642 | | EXAMINE PILOTS LIFE VEST | | | | | | | | Service | ATA:25 |
| PN:P01074-201C | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | | |
| SN:24031320010 | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| 25-62/643 | | DISCARD COPILOTS LIFE VEST | | | | | | | | Service | ATA:25 |
| PN:P01074-201C | MOS | | 120 | | 01-Mar-34 (M) | | 3397 d | DISCARD | | | |
| SN:24031320011 | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| 25-62/643 | | DISCARD NO. 1 LIFE VEST | | | | | | | | Service | ATA:25 |
| PN:P01074-201 | MOS | | 120 | | 01-Feb-34 (M) | | 3369 d | DISCARD | | | |
| SN:24022290007 | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| 25-62/643 | | DISCARD NO. 2 LIFE VEST | | | | | | | | Service | ATA:25 |
| PN:P01074-201 | MOS | | 120 | | 01-Feb-34 (M) | | 3369 d | DISCARD | | | |
| SN:24022290008 | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| 25-62/643 | | DISCARD NO. 3 LIFE VEST | | | | | | | | Service | ATA:25 |
| PN:P01074-201 | MOS | | 120 | | 01-Feb-34 (M) | | 3369 d | DISCARD | | | |
| SN:24022290009 | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| 25-62/643 | | DISCARD NO. 4 LIFE VEST | | | | | | | | Service | ATA:25 |
| PN:P01074-201 | MOS | | 120 | | 01-Feb-34 (M) | | 3369 d | DISCARD | | | |
| SN:24022290010 | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| 25-62/643 | | DISCARD NO. 5 LIFE VEST | | | | | | | | Service | ATA:25 |
| PN:P01074-201 | MOS | | 120 | | 01-Feb-34 (M) | | 3369 d | DISCARD | | | |
| SN:24022290011 | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--|--|-----------|----------|-----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | |
| 25-62/643 | DISCARD NO. 6 LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201 | MOS | | 120 | | 01-Feb-34 (M) | | 3369 d | DISCARD | | |
| SN:24022290012 | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-62/643 | DISCARD PILOTS LIFE VEST | | | | | | | | | Service ATA:25 |
| PN:P01074-201C | MOS | | 120 | | 01-Mar-34 (M) | | 3397 d | DISCARD | | |
| SN:24031320010 | HRS | | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | |
| 25-63/23 | EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY | | | | | | | | | Component ATA:25 |
| PN:PN | MOS/MSC | 13-Oct-20 | DUE | TSN 0 | 01-May-27 (M) | | 901 d | DISCARD | | |
| SN:UNKNOWN | HRS | 3612.7 | | TSN 0 | | | | | | |
| WC#: 25.020 | AFL | 2504 | | TSN 0 | | | | | | |
| Expiry Date: : 01-May-27 PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 250010 | EMERGENCY LOCATOR TRANSMITTER | | | | | | | | | Component ATA:25 |
| PN:S1821502-02 | MOS/MSC | 06-Jun-24 | O/C | TSR 44 | | | | | | |
| SN:J092-0048 | HRS | 4601.3 | | TSR 988.6 | | | | | | |
| WC#: 25.050 | AFL | 3132 | | TSR 628 | | | | | | |
| PROC. REF: AMM 25-63-01 | | | | | | | | | | |
| 251010 | PILOT SEAT BACKREST TUBES | | | | | | | | | Component ATA:25 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 5000 | TSN 0 | 5000 | | 315.5 | | | |
| WC#: 25.060 | AFL | 0 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 251015 | COPILOT SEAT BACKREST TUBES | | | | | | | | | Component ATA:25 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 5000 | TSN 0 | 5000 | | 315.5 | | | |
| | AFL | 0 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 258010 | PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION | | | | | | | | | Service ATA:25 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | | | | | | | | |
| WC#: 25.085 | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF, FAR 91.207 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|--------------------------------|---------|-------------------|----------|----------|------------------------|-----------|-----------|-------------|-----|-----------|--------|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | | |
| PC12A256CA110 | | PILOT LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201C | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24031320010 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| PC12A256CA120 | | COPILOT LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201C | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24031320011 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| PC12A256CA210 | | NO. 1 LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201 | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24022290007 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| PC12A256CA220 | | NO. 2 LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201 | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24022290008 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| PC12A256CA230 | | NO. 3 LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201 | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24022290009 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| PC12A256CA240 | | NO. 4 LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201 | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24022290010 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| PC12A256CA250 | | NO. 5 LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201 | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24022290011 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|---------|--|----------|-------------------------|------------------------|-----------|------------|-------------|-----|-----------|--------|
| ATA 25 - EQUIPMENT/FURNISHINGS | | | | | | | | | | | |
| PC12A256CA260 | | NO. 6 LIFE VEST | | | | | | | | Component | ATA:25 |
| PN:P01074-201 | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:24022290012 | HRS | 4601.3 | TSN 0 | | | | | | | | |
| | AFL | 3132 | TSN 0 | | | | | | | | |
| PROC. REF: AMM 25-62-00 | | | | | | | | | | | |
| ATA 26 - FIRE PROTECTION | | | | | | | | | | | |
| 26-20/2 | | CABIN FIRE EXTINGUISHER | | | | | | | | Component | ATA:26 |
| PN:PN | MOS/MSC | N/A | | | | | | | | | |
| SN:UNKNOWN | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| PROC. REF: AMM 26-20-02 | | | | | | | | | | | |
| 26-20/2 | | COCKPIT FIRE EXTINGUISHER | | | | | | | | Component | ATA:26 |
| PN:C352TS | MOS | 18-Jan-19 | 120 | 01-Mar-28 | | 1206 d | LIFE LIMIT | | | | |
| SN:E-92812692 | HRS | 3272.7 | TSN 0 | | | | | | | | |
| WC#: 26.010 | AFL | 2286 | TSN 0 | | | | | | | | |
| Manufacture Date:: 01-Mar-18 | | | | PROC. REF: AMM 26-20-01 | | | | | | | |
| 26-20/24 | | CONTENTS CHECK CABIN FIRE EXTINGUISHER | | | | | | | | Service | ATA:26 |
| PN:PN | MOS/MSC | 10-Dec-01 | N/A | | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | | | | | | | | |
| | AFL | 0 | | | | | | | | | |
| PROC. REF: AMM 26-20-00 | | | | | | | | | | | |
| 26-20/24 | | CONTENTS CHECK COCKPIT FIRE EXTINGUISHER | | | | | | | | Service | ATA:26 |
| PN:C352TS | MOS | 06-Jun-24 | 12 | 06-Jun-25 | | 207 d | | | | | |
| SN:E-92812692 | HRS | 4601.3 | | | | | | | | | |
| WC#: 26.010 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 26-20-00 | | | | | | | | | | | |
| 262001 ^U | | PORTABLE FIRE EXTINGUISHER | | | | | | | | Component | ATA:26 |
| PN:C352 | MOS | 06-Jun-24 | 72 | 06-Jun-30 (M) | | 2033 d | | | | | |
| SN:E-92812692 | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-00/138 ^S | | OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | |
| 27-00/402 | EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 27-00/71 | EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES | | | | | | | | | Service ATA:27 |
| | MOS | 06-Jun-22 | 60 | | 06-Jun-27 | | 937 d | | | |
| | HRS | 4063.5 | 4800 | | 8863.5 | | 4179 | | | |
| WC#: 27.010 | AFL | | | | | | | | | |
| PROC. REF: AMM 27-00-00 | | | | | | | | | | |
| 27-10/139 ^S | EXAMINE AILERON LH AND RH AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC TEMPORARY (MAT. NO. P10-001) | | | | | | | | | Service ATA:27 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 27-10/234 ^S | EXAMINE AILERON LH AND RH RODS AND LEVERS | | | | | | | | | Service ATA:27 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 27-10/235 ^S | EXAMINE AILERON ELECTRICAL BONDING STRAPS | | | | | | | | | Service ATA:27 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 27-10/236 ^S | AILERON CONTROL SYSTEM - INSPECTION/ CHECK | | | | | | | | | Service ATA:27 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 27-10-00 | | | | | | | | | | |
| 27-10/237 ^S | CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999 | | | | | | | | | Service ATA:27 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 27-10-00, AMM 27-10-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--------------------------|--|-----------|----------|----------|------------------------|---|-----------|---------------|-----|----------------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | |
| 27-10/238 ^S | FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999 | | | | | | | | | Service ATA:27 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | | PROC. REF: AMM 27-10-00, AMM 27-10-00 | | | | |
| 27-10/394 | EXAMINE - AILERON CONTROL SYSTEM | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 27-10-00 | | | | |
| 27-10/395 | EDDY CURRENT INSPECTION AILERON CABLE SEGMENT | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 27-10-09 | | | | |
| 27-10/396 | EDDY CURRENT INSPECTION - AILERON CONTROL RODS | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 27-00-01 | | | | |
| 27-10/397 | MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 27-00-01 | | | | |
| 27-10/398 | EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 27-10-08, AMM 27-10-08, AMM 27-10-08 | | | | |
| 27-10/400 | EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 57-60-06 | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|------|---|----------|----------|------------------------|-----------|-----------|---------------|-----------|----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-10/400 | | EDDY CURRENT INSPECTION LEFT WING - AILERON HINGE POINTS | | | | | | | Service | ATA:27 | |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 57-60-06 | | | | | | | | | | | |
| 27-10/444 | | AILERON FLIGHT CONTROL CABLES | | | | | | | Component | ATA:27 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-10-01 | | | | | | | | | | | |
| 27-10/445 | | AUTOPILOT CONTROL CABLE | | | | | | | Component | ATA:27 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-10-02 | | | | | | | | | | | |
| 27-10/470 ^S | | LUBRICATE AILERON CONTROL SYSTEM BEARING | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-10-00 | | | | | | | | | | PKG:20 | |
| 27-15/239 ^S | | FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999 | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-15-00, AMM 27-15-00 | | | | | | | | | | PKG:21 | |
| 27-20/140 ^S | | INSPECT/CHECK RUDDER | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 55-40-00 | | | | | | | | | | PKG:17 | |
| 27-20/240 ^S | | EXAMINE RUDDER STATIC DISCHARGERS | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|------|---|----------|----------|------------------------|-----------|-----------|-------------|---------|----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-20/241 ^S | | RUDDER CONTROL SYSTEM - INSPECTION/ CHECK | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-20-00, AMM 27-20-04 | | | | | | | | | | PKG:20 | |
| 27-20/242 ^S | | EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM, MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 20-31-00 | | | | | | | | | | PKG:20 | |
| 27-20/243 ^S | | CHECK RUDDER CABLE TENSION | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-20-00, AMM 27-20-00 | | | | | | | | | | PKG:20 | |
| 27-20/244 ^S | | FUNCTIONAL TEST RUDDER | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-20-00, AMM 27-20-00 | | | | | | | | | | PKG:21 | |
| 27-20/245 ^S | | FUNCTIONAL TEST RUDDER TRIM | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-25-00 | | | | | | | | | | PKG:21 | |
| 27-20/246 ^S | | EXAMINE RUDDER ELECTRICAL BONDING STRAPS | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|--------------------------|---------|--|----------|----------|------------------------|-----------|-----------|---------------|-----|-----------|--------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-20/374 | | EXAMINE - RUDDER CONTROL SYSTEM | | | | | | | | Service | ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 27-20-00 | | | | | | | | | | | |
| 27-20/376 | | EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT | | | | | | | | Service | ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 27-20-05 | | | | | | | | | | | |
| 27-20/431 | | CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER) | | | | | | | | Service | ATA:27 |
| PN:PN | MOS/MSC | | A/R | | | | | | | | |
| SN:UNKNOWN | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| PROC. REF: AMM 27-20-00 | | | | | | | | | | | |
| 27-20/431 | | CHECK R/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER) | | | | | | | | Service | ATA:27 |
| PN:PN | MOS/MSC | | A/R | | | | | | | | |
| SN:UNKNOWN | HRS | | | | | | | | | | |
| | AFL | | | | | | | | | | |
| PROC. REF: AMM 27-20-00 | | | | | | | | | | | |
| 27-20/446 | | RUDDER FLIGHT CONTROL CABLES | | | | | | | | Component | ATA:27 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-20-01 | | | | | | | | | | | |
| 27-20/447 | | RUDDER AUTOPILOT CONTROL CABLES | | | | | | | | Component | ATA:27 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-20-02 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|------|---|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|--------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-20/575 | | REPLACE RUDDER BELLCRANK | | | | | | | | Service | ATA:27 |
| PN:PN | MOS | 10-Dec-01 | | | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | | 20000 | | 15315.5 | | | | |
| | AFL | 0 | 27000 | | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-20-04 | | | | | | | | | | | |
| 27-30/141 ^S | | EXAMINE ELEVATORS | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | 12 | | | | | | | |
| | HRS | 4601.3 | | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:17 | | | | | | | | | | | |
| 27-30/247 ^S | | EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | 12 | | | | | | | |
| | HRS | 4601.3 | | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:20 | | | | | | | | | | | |
| 27-30/248 ^S | | EXAMINE ELEVATOR STATIC DISCHARGERS | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | 24 | | | | | | | |
| | HRS | 4601.3 | | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:21 | | | | | | | | | | | |
| 27-30/249 ^S | | ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | 12 | | | | | | | |
| | HRS | 4601.3 | | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-30-00 | | | | | | | | | | | |
| PKG:20 | | | | | | | | | | | |
| 27-30/250 ^S | | CHECK ELEVATOR CABLE TENSION | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | 12 | | | | | | | |
| | HRS | 4601.3 | | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-30-00 | | | | | | | | | | | |
| PKG:20 | | | | | | | | | | | |
| 27-30/251 ^S | | FUNCTIONAL TEST ELEVATOR | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | 24 | | | | | | | |
| | HRS | 4601.3 | | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-30-00 | | | | | | | | | | | |
| PKG:21 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----------|----------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | |
| 27-30/334 | CHECK ELEVATOR CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR) | | | | | | | | Service | ATA:27 |
| PN:PN | MOS/MSC | 18-Jan-10 | A/R | | | | | | | |
| SN:UNKNOWN | HRS | 1175.3 | | | | | | | | |
| WC#: 27.150 | AFL | 828 | | | | | | | | |
| PROC. REF: AMM 27-30-00 | | | | | | | | | | |
| 27-30/363 | EXAMINE - ELEVATOR CONTROL SYSTEM | | | | | | | | Service | ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 27-30-00 | | | | | | | | | | |
| 27-30/364 | EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS | | | | | | | | Service | ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 27-00-01 | | | | | | | | | | |
| 27-30/365 | MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS | | | | | | | | Service | ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 27-00-01 | | | | | | | | | | |
| 27-30/366 | EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER | | | | | | | | Service | ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 27-30-05 | | | | | | | | | | |
| 27-30/448 | ELEVATOR FLIGHT CONTROL CABLES | | | | | | | | Component | ATA:27 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | |
| PROC. REF: AMM 27-30-01 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|---------|---|----------|----------|------------------------|-----------|-----------|---------------|-----------|----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-30/449 | | ELEVATOR AUTOPILOT CONTROL CABLES | | | | | | | Component | ATA:27 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-30-02 | | | | | | | | | | | |
| 27-30/450 | | STICK PUSHER CABLES | | | | | | | Component | ATA:27 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 27-30/514 ^S | | EXAMINE ELEVATOR STOPS | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 55-20-01 | | | | | | | | | | | |
| 27-40/1 | | FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | AIRWORTHINESS | | | |
| | HRS | 4601.3 | 3000 | | 7601.3 | | 2916.8 | | | | |
| WC#: 27.021 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-40-00 | | | | | | | | | | | |
| 27-40/142 ^S | | OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-40-00 | | | | | | | | | | | |
| 27-40/25 | | PITCH TRIM ACTUATOR OVERHAUL | | | | | | | Component | ATA:27 | |
| PN:129-1-1100-02 | MOS/MSC | 12-Dec-19 | O/C | TSO 0 | | | | | | | |
| SN:690 | HRS | 3433.3 | | TSO 0 | | | | | | | |
| WC#: 27.020 | AFL | 2379 | | TSO 0 | | | | | | | |
| PROC. REF: AMM 27-40-01 | | | | | | | | | | | |
| 27-40/252 ^S | | INSPECTION/CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-40-01 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------|---------|---|----------|--------------------|------------------------|-----------|-----------|---------------|-----|---------------------------|--------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-40/26 | | OVERHAUL PITCH TRIM ACTUATOR | | | | | | | | Service | ATA:27 |
| PN:129-1-1100-02 | MOS | 12-Dec-19 | 84 | | 12-Dec-26 | | 761 d | OVERHAUL | | | |
| SN:690 | HRS | 3433.3 | 3400 | | 6833.3 | | 2148.8 | | | | |
| | AFL | 2379 | | | | | | | | | |
| PROC. REF: AMM 27-40-01 | | | | | | | | | | | |
| 27-40/291^S | | OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-40-00 | | | | | | | | | | PKG:16 | |
| 27-40/292^S | | FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-40-00 | | | | | | | | | | PKG:20 | |
| 27-40/3 | | PITCH TRIM ACTUATOR | | | | | | | | Component | ATA:27 |
| PN:129-1-1100-02 | MOS | 12-Dec-19 | | TSO 0 | | | | AIRWORTHINESS | | | |
| SN:690 | HRS | 3433.3 | 20000 | TSN 11655.3, TSO 0 | 23433.3 | | 18748.8 | | | | |
| WC#: 27.011 | AFL | 2379 | 27000 | TSN 12181, TSO 0 | 29379 | | 26199 | | | | |
| PROC. REF: AMM 27-40-01 | | | | | | | | | | | |
| 27-40/307 | | PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS | | | | | | | | Component | ATA:27 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 10000 | TSN 0 | 10000 | | 5315.5 | | | | |
| WC#: 27.036 | AFL | 0 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 27-40-02 | | | | | | | | | | | |
| 27-50/143^S | | LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION | | | | | | | | Service | ATA:27 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:15 ,16,17,18,19,20,21 | |
| 27-50/144^S | | EXAMINE FLAPS AND FLAP SUPPORT MECHANISM | | | | | | | | Service | ATA:27 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|---------|---|----------|---------------------------|------------------------|-----------|-----------|-------------|-----------|----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-50/253 ^S | | EXAMINE FLAPS ELECTRICAL BONDING STRAPS | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |
| 27-50/254 ^S | | EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |
| 27-50/255 ^S | | FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999 | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-50-00, AMM 27-50-00 | | | | | | | | | | PKG:20 | |
| 27-50/27 | | FLAP POWER DRIVE UNIT | | | | | | | Component | ATA:27 | |
| PN:PN | MOS/MSC | 10-Dec-01 | N/A | TSN 0 | | | | OVERHAUL | | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | | |
| WC#: 27.030 | AFL | 0 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01 | | | | | | | | | | | |
| 27-50/28 | | FLAP POWER DRIVE UNIT | | | | | | | Component | ATA:27 | |
| PN:978.73.20.003 | MOS | 06-Jun-24 | | TSO 2 | | | | OVERHAUL | | | |
| SN:0692 | HRS | 4601.3 | 10000 | TSN 2968.5, TSO 0 14601.3 | | | 9916.8 | | | | |
| | AFL | 3132 | 13500 | TSN 3449, TSO 0 16632 | | | 13452 | | | | |
| PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01 | | | | | | | | | | | |
| 27-50/30 | | OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | 10-Dec-01 | | | | | | OVERHAUL | | | |
| SN:1387 | HRS | 0 | 5000 | | 5000 | | 315.5 | | | | |
| WC#: 27.040 | AFL | 0 | 7000 | | 7000 | | 3820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/30 | | OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | 10-Dec-01 | | | | | | OVERHAUL | | | |
| SN:1044 | HRS | 0 | 5000 | | 5000 | | 315.5 | | | | |
| WC#: 27.040 | AFL | 0 | 7000 | | 7000 | | 3820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|------|---|----------|----------|------------------------|-----------|-----------|---------------|-----|-----------|--------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-50/30 | | OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | | Service | ATA:27 |
| PN:978.73.20.309 | MOS | 10-Dec-01 | | | | | | OVERHAUL | | | |
| SN:0131 | HRS | 0 | 5000 | | 5000 | | 315.5 | | | | |
| WC#: 27.050 | AFL | 0 | 7000 | | 7000 | | 3820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/30 | | OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | | Service | ATA:27 |
| PN:978.73.20.309 | MOS | 10-Dec-01 | | | | | | OVERHAUL | | | |
| SN:1409 | HRS | 0 | 5000 | | 5000 | | 315.5 | | | | |
| WC#: 27.050 | AFL | 0 | 7000 | | 7000 | | 3820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/31 | | LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT | | | | | | | | Component | ATA:27 |
| PN:945.02.02.203 | MOS | 10-Dec-01 | | TSN 0 | | | | DISCARD | | | |
| SN:UNKNOWN | HRS | 0 | 10000 | TSN 0 | 10000 | | 5315.5 | | | | |
| WC#: 27.060 | AFL | 0 | 13500 | TSN 0 | 13500 | | 10320 | | | | |
| PROC. REF: AMM 27-50-02, AMM 27-50-02 | | | | | | | | | | | |
| 27-50/31 | | LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT | | | | | | | | Component | ATA:27 |
| PN:945.02.02.203 | MOS | 10-Dec-01 | | TSN 0 | | | | DISCARD | | | |
| SN:UNKNOWN | HRS | 0 | 10000 | TSN 0 | 10000 | | 5315.5 | | | | |
| WC#: 27.060 | AFL | 0 | 13500 | TSN 0 | 13500 | | 10320 | | | | |
| PROC. REF: AMM 27-50-02, AMM 27-50-02 | | | | | | | | | | | |
| 27-50/31 | | RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT | | | | | | | | Component | ATA:27 |
| PN:945.02.02.203 | MOS | 10-Dec-01 | | TSN 0 | | | | DISCARD | | | |
| SN:UNKNOWN | HRS | 0 | 10000 | TSN 0 | 10000 | | 5315.5 | | | | |
| WC#: 27.070 | AFL | 0 | 13500 | TSN 0 | 13500 | | 10320 | | | | |
| PROC. REF: AMM 27-50-02, AMM 27-50-02 | | | | | | | | | | | |
| 27-50/31 | | RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT | | | | | | | | Component | ATA:27 |
| PN:945.02.02.203 | MOS | 10-Dec-01 | | TSN 0 | | | | DISCARD | | | |
| SN:UNKNOWN | HRS | 0 | 10000 | TSN 0 | 10000 | | 5315.5 | | | | |
| WC#: 27.070 | AFL | 0 | 13500 | TSN 0 | 13500 | | 10320 | | | | |
| PROC. REF: AMM 27-50-02, AMM 27-50-02 | | | | | | | | | | | |
| 27-50/386 | | EXAMINE - FLAP MECHANISM | | | | | | | | Service | ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | | |
| PROC. REF: AMM 27-51-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | |
| 27-50/387 | EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED) | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| | PROC. REF: AMM 27-51-00 | | | | | | | | | |
| 27-50/388 | EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED) | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| | PROC. REF: AMM 27-51-01, AMM 27-51-02, AMM 27-51-03 | | | | | | | | | |
| 27-50/389 | EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| | PROC. REF: AMM 27-51-01, AMM 27-51-02, AMM 27-51-03 | | | | | | | | | |
| 27-50/389 | EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| | PROC. REF: AMM 27-51-01, AMM 27-51-02, AMM 27-51-03 | | | | | | | | | |
| 27-50/390 | EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| | PROC. REF: AMM 27-51-01, AMM 27-51-02, AMM 27-51-03 | | | | | | | | | |
| 27-50/390 | EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FLTTINGS | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| | PROC. REF: AMM 27-51-01, AMM 27-51-02, AMM 27-51-03 | | | | | | | | | |
| 27-50/391 | EDDY CURRENT INSPECTION - FLAP AFT LINKS | | | | | | | | | Service ATA:27 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| | PROC. REF: AMM 27-51-01, AMM 27-51-02, AMM 27-51-03 | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|------|--|----------|------------|------------------------|-----------|-----------|---------------|-----------|----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-50/392 | | EDDY CURRENT INSPECTION - FLAP BELLCRANKS | | | | | | | Service | ATA:27 | |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | | |
| PROC. REF: AMM 27-51-01, AMM 27-51-02, AMM 27-51-03 | | | | | | | | | | | |
| 27-50/4 | | LEFT INBOARD FLAP ACTUATOR | | | | | | | Component | ATA:27 | |
| PN:978.73.20.309 | MOS | 13-May-17 | | | | | | AIRWORTHINESS | | | |
| SN:1387 | HRS | 2832.9 | 20000 | TSN 2832.9 | 20000 | | 15315.5 | | | | |
| WC#: 27.040 | AFL | 1973 | 27000 | TSN 1973 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/4 | | LEFT OUTBOARD FLAP ACTUATOR | | | | | | | Component | ATA:27 | |
| PN:978.73.20.309 | MOS | 13-May-17 | | | | | | AIRWORTHINESS | | | |
| SN:1044 | HRS | 2832.9 | 20000 | TSN 2832.9 | 20000 | | 15315.5 | | | | |
| WC#: 27.040 | AFL | 1973 | 27000 | TSN 1973 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/4 | | RIGHT INBOARD FLAP ACTUATOR | | | | | | | Component | ATA:27 | |
| PN:978.73.20.309 | MOS | 13-May-17 | | | | | | AIRWORTHINESS | | | |
| SN:0131 | HRS | 2832.9 | 20000 | TSN 2832.9 | 20000 | | 15315.5 | | | | |
| WC#: 27.050 | AFL | 1973 | 27000 | TSN 1973 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/4 | | RIGHT OUTBOARD FLAP ACTUATOR | | | | | | | Component | ATA:27 | |
| PN:978.73.20.309 | MOS | 13-May-17 | | | | | | AIRWORTHINESS | | | |
| SN:1409 | HRS | 2832.9 | 20000 | TSN 2832.9 | 20000 | | 15315.5 | | | | |
| WC#: 27.050 | AFL | 1973 | 27000 | TSN 1973 | 27000 | | 23820 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/414 | | LEFT HAND FLAP | | | | | | | Component | ATA:27 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 25000 | TSN 0 | 25000 | | 20315.5 | | | | |
| WC#: 57.060 | AFL | 0 | 30000 | TSN 0 | 30000 | | 26820 | | | | |
| PROC. REF: AMM 27-50-00, AMM 27-50-00, AMM 57-50-01 | | | | | | | | | | | |
| 27-50/414 | | RIGHT HAND FLAP | | | | | | | Component | ATA:27 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | 25000 | TSN 0 | 25000 | | 20315.5 | | | | |
| WC#: 57.060 | AFL | 0 | 30000 | TSN 0 | 30000 | | 26820 | | | | |
| PROC. REF: AMM 27-50-00, AMM 27-50-00, AMM 57-50-01 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---------|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | |
| 27-50/437 PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS Service ATA:27 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | AIRWORTHINESS | | |
| | HRS | 4601.3 | 600 | | 5201.3 | | 516.8 | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 27-51-00 | | | | | | | | | | |
| 27-50/443^S SERVICE FLAP UP AND DOWN LIMIT SWITCHES Service ATA:27 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-20-07 | | | | | | | | | | |
| 27-50/451 FLAP TENSION RODS Component ATA:27 | | | | | | | | | | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | | 15315.5 | | | |
| | AFL | 0 | 27000 | TSN 0 | 27000 | | 23820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 27-50/475^S RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION Service ATA:27 | | | | | | | | | | |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| PKG:15 ,16,17,18,19,20,21 | | | | | | | | | | |
| 27-50/72 REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE Service ATA:27 | | | | | | | | | | |
| PN:945.02.02.203 | MOS/MSC | | O/C | | | | | | | |
| SN:UNKNOWN | HRS | | | | | | | | | |
| WC#: 27.060 | AFL | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | |
| 27-50/72 REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE Service ATA:27 | | | | | | | | | | |
| PN:945.02.02.203 | MOS/MSC | | O/C | | | | | | | |
| SN:UNKNOWN | HRS | | | | | | | | | |
| WC#: 27.060 | AFL | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | |
| 27-50/72 REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE Service ATA:27 | | | | | | | | | | |
| PN:945.02.02.203 | MOS/MSC | | O/C | | | | | | | |
| SN:UNKNOWN | HRS | | | | | | | | | |
| WC#: 27.070 | AFL | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|--------------------------|---------|--|----------|----------|------------------------|-----------|-----------|-------------|---------|----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-50/72 | | REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE | | | | | | | Service | ATA:27 | |
| PN:945.02.02.203 | MOS/MSC | | O/C | | | | | | | | |
| SN:UNKNOWN | HRS | | | | | | | | | | |
| WC#: 27.070 | AFL | | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | | |
| 27-50/73 ^S | | LUBRICATE LEFT INBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | 18-Jun-21 | N/A | | | | | | | | |
| SN:1387 | HRS | 3764.8 | | | | | | | | | |
| WC#: 27.040 | AFL | 2572 | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | PKG:17 | |
| 27-50/73 ^S | | LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | 18-Jun-21 | N/A | | | | | | | | |
| SN:1044 | HRS | 3764.8 | | | | | | | | | |
| WC#: 27.040 | AFL | 2572 | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | PKG:17 | |
| 27-50/73 ^S | | LUBRICATE RIGHT INBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | 18-Jun-21 | N/A | | | | | | | | |
| SN:0131 | HRS | 3764.8 | | | | | | | | | |
| WC#: 27.050 | AFL | 2572 | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | PKG:17 | |
| 27-50/73 ^S | | LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | 18-Jun-21 | N/A | | | | | | | | |
| SN:1409 | HRS | 3764.8 | | | | | | | | | |
| WC#: 27.050 | AFL | 2572 | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | PKG:17 | |
| 27-50/74 ^S | | LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | 06-Jun-24 | 12 | | | | | | | | |
| SN:1387 | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | PKG:17 | |
| 27-50/74 ^S | | LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | 06-Jun-24 | 12 | | | | | | | | |
| SN:1044 | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | PKG:17 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------|---------|---|-----------|----------|------------------------|-----------|-------------------------|-------------|---------|----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-50/74 ^S | | LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | | 06-Jun-24 | 12 | | | | | | | |
| SN:0131 | HRS | | 4601.3 | 300 | | | | | | | |
| | AFL | | 3132 | | | | | | | | |
| | | | | | | | PROC. REF: AMM 27-50-00 | | | PKG:17 | |
| 27-50/74 ^S | | LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | | 06-Jun-24 | 12 | | | | | | | |
| SN:1409 | HRS | | 4601.3 | 300 | | | | | | | |
| | AFL | | 3132 | | | | | | | | |
| | | | | | | | PROC. REF: AMM 27-50-00 | | | PKG:17 | |
| 27-50/75 | | BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | | | N/A | | | | | | | |
| SN:1387 | HRS | | | | | | | | | | |
| WC#: 27.040 | AFL | | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 27-50-03 | | | | |
| 27-50/75 | | BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | | | N/A | | | | | | | |
| SN:1044 | HRS | | | | | | | | | | |
| WC#: 27.040 | AFL | | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 27-50-03 | | | | |
| 27-50/75 | | BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | | | N/A | | | | | | | |
| SN:0131 | HRS | | | | | | | | | | |
| WC#: 27.050 | AFL | | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 27-50-03 | | | | |
| 27-50/75 | | BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (WHITE COLORED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS/MSC | | | N/A | | | | | | | |
| SN:1409 | HRS | | | | | | | | | | |
| WC#: 27.050 | AFL | | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 27-50-03 | | | | |
| 27-50/76 | | BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | | 11-Jul-23 | 24 | 11-Jul-25 | | 242 d | | | | |
| SN:1387 | HRS | | 4413 | 2400 | 6813 | | 2128.5 | | | | |
| | AFL | | 2995 | 3200 | 6195 | | 3015 | | | | |
| | | | | | | | PROC. REF: AMM 27-50-03 | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------|---------|---|----------|----------|------------------------|-----------|-----------|-------------|-----------|-----------|--|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 27-50/76 | | BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | 11-Jul-23 | 24 | | 11-Jul-25 | | 242 d | | | | |
| SN:1044 | HRS | 4413 | 2400 | | 6813 | | 2128.5 | | | | |
| | AFL | 2995 | 3200 | | 6195 | | 3015 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/76 | | BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | 11-Jul-23 | 24 | | 11-Jul-25 | | 242 d | | | | |
| SN:0131 | HRS | 4413 | 2400 | | 6813 | | 2128.5 | | | | |
| | AFL | 2995 | 3200 | | 6195 | | 3015 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/76 | | BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) | | | | | | | Service | ATA:27 | |
| PN:978.73.20.309 | MOS | 11-Jul-23 | 24 | | 11-Jul-25 | | 242 d | | | | |
| SN:1409 | HRS | 4413 | 2400 | | 6813 | | 2128.5 | | | | |
| | AFL | 2995 | 3200 | | 6195 | | 3015 | | | | |
| PROC. REF: AMM 27-50-03 | | | | | | | | | | | |
| 27-50/77^S | | PERFORM FLAP ELECTRICAL SYSTEM MAINTENANCE PRACTICES TESTS (MSN101 - 400 PRE SB27-013) | | | | | | | Service | ATA:27 | |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| WC#: 27.080 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 27-50-00 | | | | | | | | | | PKG:16,18 | |
| 270015 | | ELEVATOR LH ASSY | | | | | | | Component | ATA:27 | |
| PN:555.20.12.039 | MOS/MSC | 25-Jan-06 | O/C | TSN 0 | | | | | | | |
| SN:619 | HRS | 575.7 | | TSN 0 | | | | | | | |
| | AFL | | | TSN 0 | | | | | | | |
| PROC. REF: AMM 55-20-01 | | | | | | | | | | | |
| 270033 | | RUDDER ASSY | | | | | | | Component | ATA:27 | |
| PN:555.40.12.038 | MOS/MSC | 25-Jan-06 | O/C | TSN 0 | | | | | | | |
| SN:617A | HRS | 575.7 | | TSN 0 | | | | | | | |
| | AFL | | | TSN 0 | | | | | | | |
| PROC. REF: AMM 55-40-01 | | | | | | | | | | | |
| 270035 | | FLAP CONTROL AND WARNING (FCWU) UNIT | | | | | | | Component | ATA:27 | |
| PN:978.73.20.016 | MOS/MSC | 08-Apr-11 | O/C | | | | | | | | |
| SN:108923 | HRS | | | | | | | | | | |
| WC#: 27.130 | AFL | | | | | | | | | | |
| PROC. REF: AMM 27-50-05 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------|---------|---|----------|----------|------------------------|-----------|-----------|-------------|-----|-----------|--------|
| ATA 27 - FLIGHT CONTROLS | | | | | | | | | | | |
| 270040 | | RUDDER BELLCRANK | | | | | | | | Component | ATA:27 |
| PN:PN | MOS/MSC | 10-Dec-01 | H/T | TSN 0 | | | | LIFE LIMIT | | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | | |
| | AFL | 0 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 27-20-04 | | | | | | | | | | | |
| 270120 | | R/H RUDDER CONTROL CABLE | | | | | | | | Component | ATA:27 |
| PN:PN | MOS/MSC | 10-Dec-01 | O/C | TSN 0 | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | | |
| | AFL | 0 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 27-20-01 | | | | | | | | | | | |
| 270121 | | L/H RUDDER CONTROL CABLE | | | | | | | | Component | ATA:27 |
| PN:PN | MOS/MSC | 10-Dec-01 | O/C | TSN 0 | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | | |
| | AFL | 0 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 27-20-01 | | | | | | | | | | | |
| 270130 | | ELEVATOR CONTROL CABLE | | | | | | | | Component | ATA:27 |
| PN:PN | MOS/MSC | 10-Dec-01 | O/C | TSN 0 | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | | |
| | AFL | 0 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 27-30-01 | | | | | | | | | | | |
| ATA 28 - FUEL | | | | | | | | | | | |
| 28-10/145 ^S | | EXAMINE FUEL TANK FILLER CAPS | | | | | | | | Service | ATA:28 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:17 | | | | | | | | | | | |
| 28-10/146 ^S | | EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER | | | | | | | | Service | ATA:28 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 28-10-02 | | | | | | | | | | | |
| PKG:17 | | | | | | | | | | | |
| 28-10/306 | | OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE | | | | | | | | Service | ATA:28 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4601.3 | 2400 | | 7001.3 | | 2316.8 | | | | |
| WC#: 28.029 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 28-10-01 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|------------------------|------|---|----------|----------|------------------------|-----------|---------------------------------------|-------------|-----------|----------|--|
| ATA 28 - FUEL | | | | | | | | | | | |
| 28-20/147 ^S | | OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR | | | | | | | Service | ATA:28 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 28-20-07 | | | PKG:17 | |
| 28-20/148 ^S | | REMOVE/CLEAN FUEL FILTER ELEMENT | | | | | | | Service | ATA:28 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 28-20-01, AMM 28-20-01 | | | PKG:17 | |
| 28-20/149 ^S | | OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N) | | | | | | | Service | ATA:28 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: GENERIC NO REF | | | PKG:19 | |
| 28-20/150 ^S | | EXAMINE ENGINE DRIVEN PUMP | | | | | | | Service | ATA:28 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: GENERIC NO REF | | | PKG:17 | |
| 28-20/256 ^S | | EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH THOSE ACCESS PANELS OPEN / REMOVED IN THIS INSPECTION PACKAGE | | | | | | | Service | ATA:28 | |
| | MOS | 06-Jun-24 | 24 | | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: GENERIC NO REF | | | PKG:21 | |
| 28-20/32 | | ACCESSORY GEARBOX FUEL PUMP | | | | | | | Component | ATA:28 | |
| PN:RG9570R1/M | MOS | 23-Apr-19 | | TSO 0 | | | | OVERHAUL | | | |
| SN:B4257 | HRS | 3299.5 | 3500 | TSO 0 | 6799.5 | | 2115 | | | | |
| WC#: 28.010 | AFL | 2308 | | TSO 0 | | | | | | | |
| | | | | | | | PROC. REF: AMM 28-20-03 | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----------|----------|
| ATA 28 - FUEL | | | | | | | | | | |
| 28-40/78 | OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM | | | | | | | | Service | ATA:28 |
| | MOS | 06-Jun-22 | 48 | | 06-Jun-26 | | 572 d | | | |
| | HRS | 4063.5 | 1200 | | 5263.5 | | 579 | | | |
| WC#: 28.020 | AFL | | | | | | | | | |
| PROC. REF: AMM 28-40-00, AMM 28-40-00 | | | | | | | | | | |
| 280010 | FUEL FLOW TRANSMITTER | | | | | | | | Component | ATA:28 |
| PN:TFF2905-50 | MOS/MSC | 13-Aug-19 | O/C | TSN 6 | | | | | | |
| SN:AAR0212 | HRS | 3368.5 | | TSN 0 | | | | | | |
| WC#: 28.130 | AFL | 2360 | | TSN 0 | | | | | | |
| PROC. REF: AMM 73-30-01 | | | | | | | | | | |
| ATA 29 - HYDRAULIC POWER | | | | | | | | | | |
| 29-10/151 ^S | RETURN LINE FILTER DIHERENTIAL PRESSURE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE | | | | | | | | Service | ATA:29 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 29-10-04 | | | | | | | | | | PKG:19 |
| 29-10/152 ^S | CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY | | | | | | | | Service | ATA:29 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 29-00-00, AMM 29-00-00 | | | | | | | | | | PKG:17 |
| 29-10/153 ^S | CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY. | | | | | | | | Service | ATA:29 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 29-00-00, AMM 29-00-00 | | | | | | | | | | PKG:17 |
| 29-10/257 ^S | EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED | | | | | | | | Service | ATA:29 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|
| ATA 29 - HYDRAULIC POWER | | | | | | | | | | |
| 29-10/258 ^S CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) Service ATA:29 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 29-10-02 | | | | | | | | | | PKG:20 |
| 29-10/259 ^S REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL Service ATA:29 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 29-10/418 NITROGEN ACCUMULATOR Component ATA:29 | | | | | | | | | | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 25000 | TSN 0 | 25000 | | 20315.5 | | | |
| WC#: 29.020 | AFL | 0 | 30000 | TSN 0 | 30000 | | 26820 | | | |
| PROC. REF: AMM 29-10-02 | | | | | | | | | | |
| 29-10/471 ^S CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292) Service ATA:29 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 29-10-02 | | | | | | | | | | PKG:21 |
| 290005 LANDING GEAR STEER SELECTOR VALVE Component ATA:29 | | | | | | | | | | |
| PN:960.30.01.273 | MOS/MSC | 11-Jul-23 | O/C | TSO 3 | | | | | | |
| SN:0014ABC | HRS | 4413 | | TSO 0 | | | | | | |
| WC#: 29.040 | AFL | 2995 | | TSO 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 290015 PRESSURE GAGE SWITCH Component ATA:29 | | | | | | | | | | |
| PN:973.81.14.307 | MOS/MSC | 18-Feb-15 | O/C | TSN 0 | | | | | | |
| SN:UNKNOWN | HRS | | | TSN 0 | | | | | | |
| WC#: 29.050 | AFL | | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| ATA 30 - ICE AND RAIN PROTECTION | | | | | | | | | | |
| 30-10/154 ^S INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS Service ATA:30 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---|-----|-----------|----------|------------------------|-----------|-----------|-------------|-----|----------------|
| ATA 30 - ICE AND RAIN PROTECTION | | | | | | | | | | |
| PROC. REF: AMM 30-10-00 | | | | | | | | | | PKG:17 |
| 30-10/155 ^S | OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999 | | | | | | | | | Service ATA:30 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 600 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 30-20-00, AMM 30-20-00 | | | | | | | | | | PKG:19 |
| 30-10/260 ^S | FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM | | | | | | | | | Service ATA:30 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 30-10-00 | | | | | | | | | | PKG:20 |
| 30-10/79 | APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1 | | | | | | | | | Service ATA:30 |
| | MOS | | 06-Jun-24 | 6 | 06-Dec-24 | | 25 d | | | |
| | HRS | | 4601.3 | | | | | | | |
| WC#: 30.010 | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 30-20/156 ^S | EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS | | | | | | | | | Service ATA:30 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 30-20/261 ^S | EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 | | | | | | | | | Service ATA:30 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 30-30/157 ^S | OPERATIONAL TEST PROBES DE-ICE SYSTEM | | | | | | | | | Service ATA:30 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 600 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 30-30-10, AMM 30-30-20, AMM 30-30-20 | | | | | | | | | | PKG:19 |
| 30-40/262 ^S | OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM | | | | | | | | | Service ATA:30 |
| | MOS | | 06-Jun-24 | 24 | | | | | | |
| | HRS | | 4601.3 | 2400 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 30-40-00, AMM 30-40-00 | | | | | | | | | | PKG:21 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|--|---------|--|----------|----------|------------------------|-----------|---------------------------------------|-------------|-----------|----------|--|
| ATA 30 - ICE AND RAIN PROTECTION | | | | | | | | | | | |
| 30-60/158 ^S | | INSPECTION/CHECK PROPELLER DE-ICE SYSTEM | | | | | | | Service | ATA:30 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 30-60-00 | | | PKG:19 | |
| 30-60/159 ^S | | OPERATIONAL TEST PROPELLER DE-ICE SYSTEM | | | | | | | Service | ATA:30 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 30-60-00, AMM 30-60-00 | | | PKG:19 | |
| 300005 | | PROP DE-ICE TIMER/ CONTROLLER | | | | | | | Component | ATA:30 | |
| PN:4E3163-2 | MOS/MSC | 29-Aug-14 | O/C | | TSO 0 | | | | | | |
| SN:U0236 | HRS | 1972.2 | | | TSO 0 | | | | | | |
| WC#: 30.140 | AFL | | | | TSO 0 | | | | | | |
| | | | | | | | PROC. REF: AMM 30-60-01 | | | | |
| 300105 | | RH OUTBD-WING DE-ICER BOOT | | | | | | | Component | ATA:30 | |
| PN:P27-7D5221-24 | MOS/MSC | 25-Jun-19 | O/C | | TSN 0 | | | | | | |
| SN:NET6330 | HRS | 3329.6 | | | TSN 0 | | | | | | |
| WC#: 30.050 | AFL | 2328 | | | TSN 0 | | | | | | |
| | | | | | | | PROC. REF: AMM 30-14-01 | | | | |
| ATA 31 - INDICATING/RECORDING SYSTEMS | | | | | | | | | | | |
| 31-50/34 | | CAWS & CACU CLOCK BATTERY | | | | | | | Component | ATA:31 | |
| PN:PN | MOS | 06-Jun-24 | 24 | | 06-Jun-26 (M) | | 572 d | DISCARD | | | |
| SN:UNKNOWN | HRS | 4601.3 | | | | | | | | | |
| WC#: 31.010 | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 31-50-03 | | | | |
| ATA 32 - LANDING GEAR | | | | | | | | | | | |
| 32-10/162 ^S | | LUBRICATE MAIN LANDING GEAR | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 12-20-04 | | | PKG:19 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 32 - LANDING GEAR | | | | | | | | | | |
| 32-10/163 ^S | EXAMINE MAIN LANDING GEAR LEGS | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:19 |
| 32-10/164 ^S | EXAMINE MAIN LANDING GEAR COMPARTMENTS | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:19 |
| 32-10/165 ^S | CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 32-10-00 | | | | | | | | | | PKG:19 |
| 32-10/263 ^S | EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 32-10/264 ^S | REMOVE MAIN LANDING GEAR LEFT AND RIGHT AXLE BOLT (PRE SB 32-006) AND EXAMINE. REPLACE IF DAMAGED. INSTALL A SERVICEABLE BOLT. | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:19 |
| 32-10/347 | OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK | | | | | | | | | Service ATA:32 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| 32-10/347 | OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK | | | | | | | | | Service ATA:32 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 32 - LANDING GEAR | | | | | | | | | | |
| 32-10/436 | EXAMINE MAIN LANDING GEAR SHOCK ABSORBER TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS. | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 32-10-00 | | | | | | | | | | |
| 32-10/438 | EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-22 | 72 | | 06-Jun-28 | | 1303 d | | | |
| | HRS | 4063.5 | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: AMM 32-10-00 | | | | | | | | | | |
| 32-10/438 | EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-22 | 72 | | 06-Jun-28 | | 1303 d | | | |
| | HRS | 4063.5 | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: AMM 32-10-00 | | | | | | | | | | |
| 32-10/644 | OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING (HYDRAULIC LANDING GEAR) | | | | | | | | | Service ATA:32 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:20000 | | 20000 | | 15315.5 | | | |
| | AFL | 0 | T:27000 | | 27000 | | 23820 | | | |
| 32-10/644 | OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING (HYDRAULIC LANDING GEAR) | | | | | | | | | Service ATA:32 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:20000 | | 20000 | | 15315.5 | | | |
| | AFL | 0 | T:27000 | | 27000 | | 23820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 32-10/80 | LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS | | | | | | | | | Service ATA:32 |
| PN:40-424 | MOS/MSC | 06-Jun-24 | 12 / T/C | | 06-Jun-25 | | 207 d | | | |
| SN:2164/2187 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-20-06 | | | | | | | | | | |
| 32-10/80 | LUBRICATE NOSE WHEEL BEARINGS | | | | | | | | | Service ATA:32 |
| PN:3-1501 | MOS/MSC | 06-Jun-24 | 12 / T/C | | 06-Jun-25 | | 207 d | | | |
| SN:1259 | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-20-06 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|---------|---|----------|----------|------------------------|-----------|-----------|-------------|---------|----------|--|
| ATA 32 - LANDING GEAR | | | | | | | | | | | |
| 32-10/80 | | LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS | | | | | | | Service | ATA:32 | |
| PN:40-424 | MOS/MSC | 06-Jun-24 | 12 / T/C | | 06-Jun-25 | | 207 d | | | | |
| SN:2163/2186 | HRS | 4601.3 | | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 12-20-06 | | | | | | | | | | | |
| 32-10/81 | | INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | | |
| | HRS | 4601.3 | 2400 | | 7001.3 | | 2316.8 | | | | |
| WC#: 32.010 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 32-10-00 | | | | | | | | | | | |
| 32-20/166 ^S | | CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 32-20-00 | | | | | | | | | | | |
| 32-20/167 ^S | | LUBRICATE NOSE LANDING GEAR | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 12-20-04 | | | | | | | | | | | |
| 32-20/168 ^S | | EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 32-20/169 ^S | | EXAMINE NOSE LANDING GEAR COMPARTMENT | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 32-20/265 ^S | | EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|------------------------|---------|---|----------|----------|------------------------|-----------|---------------------------------------|---------------|-----------|----------|--|
| ATA 32 - LANDING GEAR | | | | | | | | | | | |
| 32-20/266 ^S | | REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 32-20-03, AMM 32-20-03 | | | PKG:20 | |
| 32-20/305 ^S | | EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING | | | | | | | Service | ATA:32 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM GENERIC | | | PKG:20 | |
| 32-20/335 | | NOSE LANDING GEAR TORQUE TUBE | | | | | | | Component | ATA:32 | |
| PN:532.50.12.064 | MOS/MSC | 08-May-12 | O/C | | | | | | | | |
| SN:UNKNOWN | HRS | 1284.3 | | | | | | | | | |
| WC#: 32.175 | AFL | 876 | | | | | | | | | |
| | | | | | | | PROC. REF: AMM 32-50-03 | | | | |
| 32-20/336 | | INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT DRAG LINK | | | | | | | Service | ATA:32 | |
| | MOS | 11-Jul-23 | | | | | | AIRWORTHINESS | | | |
| | HRS | 4413 | 300 | | 4713 | | 28.5 | | | | |
| WC#: 32.180 | AFL | 2995 | 400 | | 3395 | | 215 | | | | |
| | | | | | | | PROC. REF: AMM 32-20-06 | | | | |
| 32-20/403 | | NOSE LANDING GEAR | | | | | | | Component | ATA:32 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | OVERHAUL | | | |
| SN:UNKNOWN | HRS | 0 | T:25000 | TSN 0 | 25000 | | 20315.5 | | | | |
| | AFL | 0 | T:30000 | TSN 0 | 30000 | | 26820 | | | | |
| | | | | | | | PROC. REF: GENERIC NO REF | | | | |
| 32-20/410 | | NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK | | | | | | | Component | ATA:32 | |
| PN:532.20.12.296 | MOS/MSC | 06-Jun-24 | H/T | TSN 0 | | | | | | | |
| SN:UNKNOWN | HRS | 4601.3 | | TSN 0 | | | | | | | |
| | AFL | 3132 | | TSN 0 | | | | | | | |
| 32-20/416 | | NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK (EXCEPT FOR P/N 532.2012.140) - REPLACE | | | | | | | Service | ATA:32 | |
| | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| | HRS | 0 | 25000 | TSN 0 | 25000 | | 20315.5 | | | | |
| | AFL | 0 | 30000 | TSN 0 | 30000 | | 26820 | | | | |
| | | | | | | | PROC. REF: AMM 32-20-05 | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|-----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 32 - LANDING GEAR | | | | | | | | | | |
| 32-20/532 | NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK (P/N 532.20.12.140, PRE SB 32-014) - REPLACE | | | | | | | | | Service ATA:32 |
| | MOS/MSC | 06-Jun-24 | N/A | TSN 0 | | | | | | |
| | HRS | 4601.3 | | TSN 0 | | | | | | |
| WC#: 32.020 | AFL | 3132 | | TSN 0 | | | | | | |
| PROC. REF: AMM 32-20-05 | | | | | | | | | | |
| 32-30/170 ^S | FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 32-30-00 | | | | | | | | | | PKG:20 |
| 32-30/417 | LEFT HAND MAIN LANDING GEAR ACTUATOR | | | | | | | | | Component ATA:32 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 25000 | TSN 0 | | 25000 | 20315.5 | | | |
| WC#: 32.040 | AFL | 0 | 30000 | TSN 0 | | 30000 | 26820 | | | |
| PROC. REF: AMM 32-30-01 | | | | | | | | | | |
| 32-30/417 | RIGHT HAND MAIN LANDING GEAR ACTUATOR | | | | | | | | | Component ATA:32 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 25000 | TSN 0 | | 25000 | 20315.5 | | | |
| WC#: 32.040 | AFL | 0 | 30000 | TSN 0 | | 30000 | 26820 | | | |
| PROC. REF: AMM 32-30-01 | | | | | | | | | | |
| 32-30/442 | EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-22 | 72 | 06-Jun-28 | | | 1303 d | | | |
| | HRS | 4063.5 | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: AMM 32-10-00 | | | | | | | | | | |
| 32-30/442 | EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS | | | | | | | | | Service ATA:32 |
| | MOS | 06-Jun-22 | 72 | 06-Jun-28 | | | 1303 d | | | |
| | HRS | 4063.5 | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: AMM 32-10-00 | | | | | | | | | | |
| 32-30/518 | LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE | | | | | | | | | Service ATA:32 |
| | MOS | 18-Jun-21 | 60 | 18-Jun-26 | | | 584 d | REPLACE | | |
| | HRS | 3764.8 | | | | | | | | |
| | AFL | 2572 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|------|-----------|----------|----------|--|-----------|-----------|-------------|-----|----------------|
| ATA 32 - LANDING GEAR | | | | | | | | | | |
| 32-30/518 | | | | | RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE | | | | | Service ATA:32 |
| | MOS | 18-Jun-21 | 60 | | 18-Jun-26 | | 584 d | REPLACE | | |
| | HRS | 3764.8 | | | | | | | | |
| | AFL | 2572 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 32-40/171 ^S | | | | | EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 32-40/172 ^S | | | | | EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-10-04 | | | | | | | | | | |
| 32-40/173 ^S | | | | | EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 32-40/174 ^S | | | | | EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-10-04 | | | | | | | | | | |
| 32-40/175 ^S | | | | | EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING. | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 32-40/176 ^S | | | | | CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY | | | | | Service ATA:32 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 12-10-02 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|---------|--|------------|----------|------------------------|-----------|-----------|-------------|-----|-----------|--------|
| ATA 32 - LANDING GEAR | | | | | | | | | | | |
| 32-50/404 | | EXAMINE NOSE LANDING GEAR STEERING MECHANISM | | | | | | | | Service | ATA:32 |
| | MOS | 10-Dec-01 | | | | | | | | | |
| | HRS | 0 | T:32500 | 32500 | | 27815.5 | | | | | |
| | AFL | 0 | T:42000 | 42000 | | 38820 | | | | | |
| PROC. REF: AMM 32-50-00 | | | | | | | | | | | |
| 320020 | | NOSE WHEEL | | | | | | | | Component | ATA:32 |
| PN:3-1501 | MOS/MSC | 14-Apr-21 | O/C | TSN 122 | | | | | | | |
| SN:1259 | HRS | 3697.4 | TSN 2446.5 | | | | | | | | |
| WC#: 32.150 | AFL | 2545 | TSN 1686 | | | | | | | | |
| PROC. REF: AMM 32-40-02 | | | | | | | | | | | |
| 320021 | | NOSE LANDING GEAR TIRE | | | | | | | | Component | ATA:32 |
| PN:021-327-0 | MOS/MSC | 14-Apr-21 | O/C | TSN 0 | | | | | | | |
| SN:8089S00129 | HRS | 3697.4 | TSN 0 | | | | | | | | |
| WC#: 32.155 | AFL | 2545 | TSN 0 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 320022 | | LEFT MAIN LANDING GEAR WHEEL | | | | | | | | Component | ATA:32 |
| PN:40-424 | MOS/MSC | 11-Feb-11 | O/C | | | | | | | | |
| SN:2164/2187 | HRS | 1250.9 | | | | | | | | | |
| WC#: 32.160 | AFL | 859 | | | | | | | | | |
| PROC. REF: AMM 32-40-01 | | | | | | | | | | | |
| 320023 | | LEFT MAIN LANDING GEAR TIRE | | | | | | | | Component | ATA:32 |
| PN:025-350-0 | MOS/MSC | 06-Jun-22 | O/C | | | | | | | | |
| SN:1055T00257 | HRS | 4063.5 | | | | | | | | | |
| WC#: 32.160 | AFL | | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 320024 | | RIGHT MAIN LANDING GEAR WHEEL | | | | | | | | Component | ATA:32 |
| PN:40-424 | MOS/MSC | 11-Feb-11 | O/C | | | | | | | | |
| SN:2163/2186 | HRS | 1250.9 | | | | | | | | | |
| WC#: 32.165 | AFL | 859 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 320026 | | RIGHT MAIN LANDING GEAR TIRE | | | | | | | | Component | ATA:32 |
| PN:025-350-0 | MOS/MSC | 06-Jun-22 | O/C | | | | | | | | |
| SN:1055T00264 | HRS | 4063.5 | | | | | | | | | |
| WC#: 32.165 | AFL | | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---------|-----|-----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 32 - LANDING GEAR | | | | | | | | | | |
| 320074 NOSE LANDING GEAR ACTUATOR | | | | | | | | | | Component ATA:32 |
| PN:960.30.01.111 | MOS/MSC | | 26-Apr-04 | O/C | TSO 0 | | | | | |
| SN:0065 | HRS | | 362.9 | | TSO 0 | | | | | |
| WC#: 29.060 | AFL | | | | TSO 0 | | | | | |
| PROC. REF: AMM 32-30-02 | | | | | | | | | | |
| 320075 LH BRAKE ASSY | | | | | | | | | | Component ATA:32 |
| PN:30-244 | MOS/MSC | | 06-Jun-22 | O/C | TSO 0 | | | | | |
| SN:1389 | HRS | | 4063.5 | | TSO 0 | | | | | |
| WC#: 32.050 | AFL | | | | TSO 0 | | | | | |
| PROC. REF: AMM 32-40-03, AMM 32-40-03 | | | | | | | | | | |
| 320080 RH BRAKE ASSY | | | | | | | | | | Component ATA:32 |
| PN:30-244 | MOS/MSC | | 06-Jun-22 | O/C | TSO 0 | | | | | |
| SN:3835 | HRS | | 4063.5 | | TSO 0 | | | | | |
| WC#: 32.050 | AFL | | | | TSO 0 | | | | | |
| PROC. REF: AMM 32-40-03, AMM 32-40-03 | | | | | | | | | | |
| ATA 33 - LIGHTS | | | | | | | | | | |
| 33-40/177^S OPERATIONAL TEST EXTERIOR LIGHTING | | | | | | | | | | Service ATA:33 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 33-40-00, AMM 33-40-00 | | | | | | | | | | |
| 33-41/178^S EXAMINE LANDING LIGHTS | | | | | | | | | | Service ATA:33 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 33-41-01 | | | | | | | | | | |
| 33-42/179^S EXAMINE TAXI LIGHTS | | | | | | | | | | Service ATA:33 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 33-42-01 | | | | | | | | | | |
| 33-43/180^S EXAMINE NAVIGATION AND STROBE LIGHTS | | | | | | | | | | Service ATA:33 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 33 - LIGHTS | | | | | | | | | | |
| 33-44/181 ^S | EXAMINE RECOGNITION LIGHTS (IF INSTALLED) | | | | | | | | | Service ATA:33 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 33-46/182 ^S | EXAMINE BEACON LIGHTS (IF INSTALLED) | | | | | | | | | Service ATA:33 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 330035 | LH WING POWER SUPPLY UNIT | | | | | | | | | Component ATA:33 |
| PN:972.87.87.164 | MOS/MSC | 05-Oct-22 | O/C | TSN 0 | | | | | | |
| SN:236775-68-13 | HRS | | | TSN 0 | | | | | | |
| WC#: 33.070 | AFL | 2856 | | TSN 0 | | | | | | |
| PROC. REF: AMM 33-43-03 | | | | | | | | | | |
| 330040 | LEFT WING TIP WARNING LIGHT ASSEMBLY | | | | | | | | | Component ATA:33 |
| PN:972.87.87.322 | MOS/MSC | 05-Oct-22 | O/C | TSN 0 | | | | | | |
| SN:238359-6-12 | HRS | | | TSN 0 | | | | | | |
| WC#: 33.030 | AFL | 2856 | | TSN 0 | | | | | | |
| PROC. REF: AMM 33-44-01 | | | | | | | | | | |
| 330050 | RIGHT WING TIP WARNING LIGHT ASSEMBLY | | | | | | | | | Component ATA:33 |
| PN:03-2201-0002 | MOS/MSC | 18-Jan-10 | O/C | TSN 0 | | | | | | |
| SN:40350 | HRS | 1175.3 | | TSN 0 | | | | | | |
| WC#: 33.030 | AFL | 828 | | TSN 0 | | | | | | |
| PROC. REF: AMM 33-44-01 | | | | | | | | | | |
| 330065 | NAVIGATION (FC), LED WHITE LIGHT | | | | | | | | | Component ATA:33 |
| PN:972.87.87.184 | MOS/MSC | 26-Jun-15 | O/C | | | | | | | |
| SN:UNKNOWN | HRS | 2190.3 | | | | | | | | |
| WC#: 33.060 | AFL | 1561 | | | | | | | | |
| PROC. REF: AMM 33-43-04 | | | | | | | | | | |
| ATA 34 - NAVIGATION | | | | | | | | | | |
| 34-00/183 ^S | EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS | | | | | | | | | Service ATA:34 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|------|-----------|--|----------|------------------------|-----------|-----------|-------------|---------|----------|--------|
| ATA 34 - NAVIGATION | | | | | | | | | | | |
| 34-00/184 ^S | | | EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT | | | | | | Service | | ATA:34 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 | |
| 34-11/185 ^S | | | EXAMINE PITOT TUBE | | | | | | Service | | ATA:34 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 | |
| 34-11/186 ^S | | | EXAMINE STATIC PORTS | | | | | | Service | | ATA:34 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 | |
| 34-11/268 ^S | | | DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM | | | | | | Service | | ATA:34 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 34-11-00, AMM 34-11-10, AMM 34-11-20 | | | | | | | | | | PKG:20 | |
| 34-11/82 | | | LEAK CHECK STATIC SYSTEM | | | | | | Service | | ATA:34 |
| | MOS | 06-Jun-24 | 24 | | 06-Jun-26 | | 572 d | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| WC#: 34.010 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 30-30-21, AMM 34-11-10, AMM 34-11-20 | | | | | | | | | | | |
| 34-14/83 | | | CALIBRATION CHECK ALTIMETER | | | | | | Service | | ATA:34 |
| | MOS | 06-Jun-24 | 24 | | 06-Jun-26 | | 572 d | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| WC#: 34.020 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 34-14-00, AMM 34-14-10, AMM 34-14-20 | | | | | | | | | | | |
| 34-21/84 | | | SWING CHECK STANDBY MAGNETIC COMPASS | | | | | | Service | | ATA:34 |
| | MOS | 11-Jul-23 | 24 | | 11-Jul-25 | | 242 d | | | | |
| | HRS | 4413 | | | | | | | | | |
| WC#: 34.030 | AFL | 2995 | | | | | | | | | |
| PROC. REF: AMM 34-21-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---------|-----------|----------|----------|--|-----------|-----------|-------------|-----|------------------|
| ATA 34 - NAVIGATION | | | | | | | | | | |
| 34-25/85 ^S | | | | | CHECK SWING ATTITUDE HEADING REFERENCE SYSTEM (AHRS) | | | | | Service ATA:34 |
| | MOS | | 24 | | | | | | | |
| | HRS | | | | | | | | | |
| WC#: 34.040 | AFL | | | | | | | | | |
| PROC. REF: AMM 34-25-00 | | | | | | | | | | |
| 34-54/86 | | | | | FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) | | | | | Service ATA:34 |
| | MOS | 06-Jun-24 | 24 | | 06-Jun-26 | | 572 d | | | |
| | HRS | 4601.3 | | | | | | | | |
| WC#: 34.050 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 34-54-00, AMM 34-54-00, AMM 34-54-10, AMM 34-54-10 | | | | | | | | | | |
| 340005 | | | | | PILOT ALTIMETER | | | | | Component ATA:34 |
| PN:70256N02D02 | MOS/MSC | 08-May-12 | O/C | | | | | | | |
| SN:07090849D | HRS | 1284.3 | | | | | | | | |
| WC#: 31.020 | AFL | 876 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 340006 | | | | | COPILOT ALTIMETER | | | | | Component ATA:34 |
| PN:70256N02D02 | MOS/MSC | 08-May-12 | O/C | | | | | | | |
| SN:07090850D | HRS | 1284.3 | | | | | | | | |
| WC#: 31.120 | AFL | 876 | | | | | | | | |
| PROC. REF: AMM 34-14-12 | | | | | | | | | | |
| 340007 | | | | | NO. 1 TRANSPONDER | | | | | Component ATA:34 |
| PN:011-03302-00 | MOS/MSC | 12-Aug-16 | O/C | | | | | | | |
| SN:3EG001770 | HRS | 2525.1 | | | | | | | | |
| WC#: 34.140 | AFL | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 340026 | | | | | STAND-BY ALTIMETER | | | | | Component ATA:34 |
| PN:5035P-P | MOS/MSC | 08-May-12 | O/C | | | | | | | |
| SN:46887 | HRS | 1284.3 | | | | | | | | |
| WC#: 31.020 | AFL | 876 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 340080 | | | | | NO. 2 TRANSPONDER | | | | | Component ATA:34 |
| PN:06601144-0201 | MOS/MSC | 08-May-12 | O/C | | | | | | | |
| SN:30572 | HRS | 1284.3 | | | | | | | | |
| WC#: 34.080 | AFL | 876 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 34 - NAVIGATION | | | | | | | | | | |
| 340097 | GARMIN FLIGHT STREAM 210 TRANSCEIVER | | | | | | | | | Component ATA:34 |
| PN:011-03257-40 | MOS/MSC | 01-Mar-16 | O/C | | | | | | | |
| SN:3RE003915 | HRS | 2370.6 | | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 340110 | NO. 1 CAL PROM AHRS,LCR-92 UNIT | | | | | | | | | Component ATA:34 |
| PN:985.99.11.823 | MOS/MSC | 29-Dec-08 | O/C | TSN 0 | | | | | | |
| SN:10545 | HRS | 1086.1 | | TSN 0 | | | | | | |
| WC#: 34.390 | AFL | 740 | | TSN 0 | | | | | | |
| PROC. REF: AMM 34-25-01 | | | | | | | | | | |
| 340111 | AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU | | | | | | | | | Component ATA:34 |
| PN:124210-2022 | MOS/MSC | 13-Sep-13 | O/C | | | | | | | |
| SN:1083 | HRS | 1673 | | | | | | | | |
| WC#: 34.060 | AFL | | | | | | | | | |
| PROC. REF: AMM 34-25-01 | | | | | | | | | | |
| 340153 | SG465 EFIS MFD SYMBOL GENERATOR | | | | | | | | | Component ATA:34 |
| PN:066-04021-1111 | MOS/MSC | 29-Dec-08 | O/C | TSR 0 | | | | | | |
| SN:5828 | HRS | 1086.1 | | TSR 0 | | | | | | |
| | AFL | 740 | | TSR 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 340215 | AHRS NO2 AHRU,LCR-92,WSYNCHR,124210-2022 UNIT | | | | | | | | | Component ATA:34 |
| PN:12410-2011 | MOS/MSC | 26-Dec-03 | O/C | | | | | | | |
| SN:9104 | HRS | 307.9 | | | | | | | | |
| WC#: 34.320 | AFL | | | | | | | | | |
| PROC. REF: AMM 34-25-01 | | | | | | | | | | |
| 340235 | AOA SENSOR RH UNIT | | | | | | | | | Component ATA:34 |
| PN:0012AC12 | MOS/MSC | 04-Aug-17 | O/C | TSR 0 | | | | | | |
| SN:0989 | HRS | 2923.9 | | TSR 0 | | | | | | |
| WC#: 34.330 | AFL | 2034 | | TSR 0 | | | | | | |
| PROC. REF: AMM 22-20-02 | | | | | | | | | | |
| 340250 | OUTSIDE AIR TEMPERATURE PROBE | | | | | | | | | Component ATA:34 |
| PN:534.13.12.054 | MOS/MSC | 25-Feb-14 | O/C | TSN 0 | | | | | | |
| SN:UNKNOWN | HRS | 1801.7 | | TSN 0 | | | | | | |
| WC#: 34.250 | AFL | | | TSN 0 | | | | | | |
| PROC. REF: AMM 34-13-12 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--|--|-----|-----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 34 - NAVIGATION | | | | | | | | | | |
| 340305 | GTN 750 GA-37 GPS/WAAS/XM ANTENNA | | | | | | | | | Component ATA:34 |
| PN:CI420-1 | MOS/MSC | | 14-Nov-07 | O/C | | | | | | |
| SN:172288 | HRS | | 891.9 | | | | | | | |
| | AFL | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 341005 | LH AOA PLATE TEMP CONTROLLER | | | | | | | | | Component ATA:34 |
| PN:975.44.21.417 | MOS/MSC | | 07-Nov-03 | O/C | | | | | | |
| SN:U0628 | HRS | | 275.2 | | | | | | | |
| WC#: 30.170 | AFL | | 196 | | | | | | | |
| PROC. REF: AMM 30-30-21 | | | | | | | | | | |
| ATA 35 - OXYGEN | | | | | | | | | | |
| 35-10/187 ^S | CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED | | | | | | | | | Service ATA:35 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 35-10/188 ^S | CHECK OXYGEN SYSTEM CONTENTS | | | | | | | | | Service ATA:35 |
| | MOS | | 06-Jun-24 | | | | | | | |
| | HRS | | 4601.3 | 300 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:16 |
| 35-10/269 ^S | EXAMINE OXYGEN PIPELINES AND EQUIPMENT | | | | | | | | | Service ATA:35 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 35-10/270 ^S | OPERATIONAL TEST OXYGEN SYSTEM | | | | | | | | | Service ATA:35 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: AMM 35-00-00 | | | | | | | | | | PKG:20 |
| 35-10/6 | OXYGEN BOTTLE | | | | | | | | | Component ATA:35 |
| PN:957.12.12.211 | MOS | | 06-Jun-22 | 180 | TSN 0 | 01-Aug-36 | 4281 d | DISCARD | | |
| SN:C21070256 | HRS | | 4063.5 | | TSN 0 | | | | | |
| WC#: 35.010 | AFL | | | | TSN 0 | | | | | |
| Manufacture Date:: 01-Aug-21 PROC. REF: AMM 35-10-01 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|--|---------|--|----------|----------|------------------------|-----------|-----------|-------------|-----------|----------|--|
| ATA 35 - OXYGEN | | | | | | | | | | | |
| 35-10/7 | | HYDROSTATIC TEST OXYGEN BOTTLE | | | | | | | Service | ATA:35 | |
| PN:957.12.12.211 | MOS | 01-Aug-21 | 60 | | 01-Aug-26 | | 628 d | | | | |
| SN:C21070256 | HRS | | | | | | | | | | |
| WC#: 35.010 | AFL | | | | | | | | | | |
| HydroCheck Date: : 01-Aug-21 PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 35-20/87 | | INSPECTION/CHECK PASSENGER OXYGEN MASKS | | | | | | | Service | ATA:35 | |
| | MOS | 06-Jun-24 | 36 | | 06-Jun-27 | | 937 d | | | | |
| | HRS | 4601.3 | | | | | | | | | |
| WC#: 35.010 | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 35-20-00 | | | | | | | | | | | |
| 350025 | | COPILOT QUICK DONNING MASK-REGULATOR ASSY | | | | | | | Component | ATA:35 | |
| PN:MC10-06-125 | MOS/MSC | 06-Jun-24 | O/C | TSN 0 | | | | | | | |
| SN:B199794 | HRS | 4601.3 | | TSN 0 | | | | | | | |
| WC#: 35.040 | AFL | 3132 | | TSN 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| ATA 52 - DOORS | | | | | | | | | | | |
| 52-10/189 ^S | | CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK | | | | | | | Service | ATA:52 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:19 | | | | | | | | | | | |
| 52-10/190 ^S | | EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS | | | | | | | Service | ATA:52 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:19 | | | | | | | | | | | |
| 52-10/191 ^S | | MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE | | | | | | | Service | ATA:52 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:19 | | | | | | | | | | | |
| 52-10/192 ^S | | EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT | | | | | | | Service | ATA:52 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:19 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|------|-----------|---|----------|------------------------|-----------|-----------|---------------|---------|----------|--|
| ATA 52 - DOORS | | | | | | | | | | | |
| 52-10/271 ^S | | | EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS | | | | | | Service | ATA:52 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |
| 52-10/348 | | | EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR | | | | | | Service | ATA:52 | |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 52-10-00 | | | | | | | | | | | |
| 52-10/405 | | | EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE | | | | | | Service | ATA:52 | |
| | MOS | 10-Dec-01 | | | | | | | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 52-00-01 | | | | | | | | | | | |
| 52-10/406 | | | EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SKIN | | | | | | Service | ATA:52 | |
| | MOS | 10-Dec-01 | | | | | | | | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | | |
| PROC. REF: AMM 52-10-01 | | | | | | | | | | | |
| 52-10/472 | | | EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SHOOT BOLT FITTING ONLY IF SB 52-007 PART C IS DONE | | | | | | Service | ATA:52 | |
| | MOS | | | | | | | | | | |
| | HRS | EFF | 3000 | | 5190.7 * | | 506.2 | | | | |
| | AFL | EFF | 3600 | | 3600 * | | 420 | | | | |
| PROC. REF: AMM 52-10-06 | | | | | | | | | | | |
| 52-10/88 | | | EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED | | | | | | Service | ATA:52 | |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | | |
| WC#: 52.010 | AFL | 2328 | | | | | | | | | |
| PROC. REF: AMM 25-21-03, AMM 25-22-03, AMM 52-10-00 | | | | | | | | | | | |
| 52-20/272 ^S | | | EXAMINE EMERGENCY DOOR (DOOR REMOVED) | | | | | | Service | ATA:52 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|------|-----------|--|----------|------------------------|-----------|-----------|---------------|-----|----------|--------|
| ATA 52 - DOORS | | | | | | | | | | | |
| 52-20/273 ^S | | | CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK | | | | | | | Service | ATA:52 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |
| 52-20/349 | | | EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR | | | | | | | Service | ATA:52 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 52-20-00 | | | | | | | | | | | |
| 52-30/193 ^S | | | CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK | | | | | | | Service | ATA:52 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:19 | |
| 52-30/194 ^S | | | EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS | | | | | | | Service | ATA:52 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 52-30-00 | | | | | | | | | | PKG:19 | |
| 52-30/195 ^S | | | EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT | | | | | | | Service | ATA:52 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:19 | |
| 52-30/274 ^S | | | EXAMINE CARGO DOOR | | | | | | | Service | ATA:52 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |
| 52-30/350 | | | EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR | | | | | | | Service | ATA:52 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 52-30-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|---------|--|----------|----------|------------------------|-----------|-----------|---------------|-----|-----------|--------|
| ATA 52 - DOORS | | | | | | | | | | | |
| 52-30/407 | | EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE | | | | | | | | Service | ATA:52 |
| | MOS | 10-Dec-01 | | | | | | | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 52-30-00 | | | | | | | | | | | |
| 52-30/408 | | EDDY CURRENT INSPECTION CARGO DOOR SKIN | | | | | | | | Service | ATA:52 |
| | MOS | 10-Dec-01 | | | | | | | | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | | |
| PROC. REF: AMM 52-30-01 | | | | | | | | | | | |
| 52-30/8 | | CARGO DOOR LOWER LUG (QTY 3) FITTINGS | | | | | | | | Component | ATA:52 |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | AIRWORTHINESS | | | |
| SN:UNKNOWN | HRS | 0 | 13000 | TSN 0 | 13000 | | 8315.5 | | | | |
| WC#: 52.020 | AFL | 0 | 17000 | TSN 0 | 17000 | | 13820 | | | | |
| PROC. REF: AMM 52-30-07 | | | | | | | | | | | |
| 52-30/89 | | EXAMINE CARGO DOOR WITH TRIM REMOVED.EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM | | | | | | | | Service | ATA:52 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | | |
| WC#: 52.030 | AFL | 2328 | | | | | | | | | |
| PROC. REF: AMM 52-30-00, AMM 25-21-03, AMM 25-22-03 | | | | | | | | | | | |
| 52-70/275 ^S | | OPERATIONAL TEST DOOR WARNING SYSTEM | | | | | | | | Service | ATA:52 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 52-70-00 | | | | | | | | | | | |
| 523006 | | CARGO DOOR GAS STRUT | | | | | | | | Component | ATA:52 |
| PN:552.30.12.427 | MOS/MSC | 11-Jan-17 | O/C | TSN 0 | | | | | | | |
| SN:UNKNOWN | HRS | 2704.5 | | TSN 0 | | | | | | | |
| | AFL | 1913 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 52-30-06 | | | | | | | | | | | |
| ATA 53 - FUSELAGE | | | | | | | | | | | |
| 53-00/196 ^S | | EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS. | | | | | | | | Service | ATA:53 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|--|-----|-----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 53 - FUSELAGE | | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 53-00/276 ^S | EXAMINE REAR PRESSURE BULKHEAD | | | | | | | | | Service ATA:53 |
| | MOS | | 06-Jun-24 | | 12 | | | | | |
| | HRS | | 4601.3 | | 1200 | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 53-00/277 ^S | EXAMINE FLOOR PANELS TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH FLOOR PANELS REMOVED | | | | | | | | | Service ATA:53 |
| | MOS | | 06-Jun-24 | | 12 | | | | | |
| | HRS | | 4601.3 | | 1200 | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 53-00/278 ^S | EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION | | | | | | | | | Service ATA:53 |
| | MOS | | 06-Jun-24 | | 24 | | | | | |
| | HRS | | 4601.3 | | 2400 | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 |
| 53-00/279 ^S | EXAMINE BAGGAGE COMPARTMENT | | | | | | | | | Service ATA:53 |
| | MOS | | 06-Jun-24 | | 24 | | | | | |
| | HRS | | 4601.3 | | 2400 | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 |
| 53-00/280 ^S | EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION | | | | | | | | | Service ATA:53 |
| | MOS | | 06-Jun-24 | | 12 | | | | | |
| | HRS | | 4601.3 | | 1200 | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 53-00/324 | STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009) | | | | | | | | | Service ATA:53 |
| | MOS | | 10-Dec-01 | | | | | AIRWORTHINESS | | |
| | HRS | | 0 | | 25000 | | 25000 | 20315.5 | | |
| | AFL | | 0 | | 30000 | | 30000 | 26820 | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|------------------------|--|-----------|----------|----------|------------------------|-------------------------|-----------|---------------|-----|----------------|
| ATA 53 - FUSELAGE | | | | | | | | | | |
| 53-00/337 ^S | INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24 | | | | | | | | | Service ATA:53 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| | | | | | | PROC. REF: AMM 53-20-02 | | | | |
| 53-00/351 | EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10 | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 53-10-06 | | | | |
| 53-00/352 | EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16 | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 53-10-00 | | | | |
| 53-00/353 | EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36 | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 53-20-00 | | | | |
| 53-00/354 | EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43 | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 53-30-00 | | | | |
| 53-00/355 | EXAMINE - ANTENNA STRUCTURE | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| | | | | | | PROC. REF: AMM 53-00-00 | | | | |
| 53-00/356 | EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:28300 | | 28300 | | 23615.5 | | | |
| | AFL | 0 | T:37000 | | 37000 | | 33820 | | | |
| | | | | | | PROC. REF: AMM 53-00-00 | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 53 - FUSELAGE | | | | | | | | | | |
| 53-00/357 | EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 53-00-00 | | | | | | | | | | |
| 53-00/359 | EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| PROC. REF: AMM 57-00-03 | | | | | | | | | | |
| 53-00/360 | EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| PROC. REF: AMM 53-20-02 | | | | | | | | | | |
| 53-00/361 | EDDY CURRENT INSPECTION FRAMES 41 AND 43 STABILIZER ATTACHMENT | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-30-03, AMM 53-30-02 | | | | | | | | | | |
| 53-00/419 | EDDY CURRENT INSPECTION FRAME 40 | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-30-03, AMM 53-30-02 | | | | | | | | | | |
| 53-00/9 | STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (PRE SB 04-009) | | | | | | | | | Service ATA:53 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 20000 | | 20000 | | 15315.5 | | | |
| WC#: 53.010 | AFL | 0 | 27000 | | 27000 | | 23820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 53-00/90 | EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED) | | | | | | | | | Service ATA:53 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| WC#: 53.030 | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-----------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|---------|----------|
| ATA 53 - FUSELAGE | | | | | | | | | | |
| 53-00/91 | EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED) | | | | | | | | Service | ATA:53 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| WC#: 53.040 | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 53-00/92 | EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED | | | | | | | | Service | ATA:53 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| WC#: 53.070 | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 53-00/93 | EXAMINE STRUCTURE AROUND WINDOWS | | | | | | | | Service | ATA:53 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| WC#: 53.050 | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 53-00/94 | EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES | | | | | | | | Service | ATA:53 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| WC#: 53.060 | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| ATA 55 - STABILIZERS | | | | | | | | | | |
| 55-00/10 | STRUCTURAL LIMITATION TAIL STRUCTURE (PRE SB 04-009) | | | | | | | | Service | ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 20000 | | 20000 | | 15315.5 | | | |
| | AFL | 0 | 27000 | | 27000 | | 23820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 55-00/325 | STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009) | | | | | | | | Service | ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | 30000 | | 30000 | | 26820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 55 - STABILIZERS | | | | | | | | | | |
| 55-10/197 ^S | EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE | | | | | | | | | Service ATA:55 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 55-10/319 ^S | INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT | | | | | | | | | Service ATA:55 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 55-00-00 | | | | | | | | | | PKG:20 |
| 55-10/415 | HORIZONTAL STABILIZER | | | | | | | | | Component ATA:55 |
| PN:PN | MOS | 10-Dec-01 | | | | | | LIFE LIMIT | | |
| SN:UNKNOWN | HRS | 0 | 25000 | TSN 0 | 25000 | | 20315.5 | | | |
| | AFL | 0 | 30000 | TSN 0 | 30000 | | 26820 | | | |
| | ACH | | | | | | | | | |
| PROC. REF: AMM 55-10-01 | | | | | | | | | | |
| 55-10/638 | HORIZONTAL STABBILIZER - EXAMINE WITH BOROSCOPE | | | | | | | | | Service ATA:55 |
| | MOS | 11-Jul-23 | 120 | | 11-Jul-33 | | 3164 d | | | |
| | HRS | 4413 | 10000 | | 14413 | | 9728.5 | | | |
| | AFL | 2995 | | | | | | | | |
| PROC. REF: AMM 55-10-01 | | | | | | | | | | |
| 55-10/640 | INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT BOLTS (P/N 555.10.12.139) | | | | | | | | | Service ATA:55 |
| | MOS/MSC | 10-Dec-01 | N/A | | | | | | | |
| | HRS | 0 | | | | | | | | |
| | AFL | 0 | | | | | | | | |
| PROC. REF: AMM 55-00-00 | | | | | | | | | | |
| 55-10/641 | INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT BOLTS (P/N 555.10.12.158 AND 555.10.12.178) | | | | | | | | | Service ATA:55 |
| | MOS | 11-Jul-23 | 120 | | 11-Jul-33 | | 3164 d | | | |
| | HRS | 4413 | | | | | | | | |
| | AFL | 2995 | | | | | | | | |
| PROC. REF: AMM 55-00-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 55 - STABILIZERS | | | | | | | | | | |
| 55-10/96 | EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED) | | | | | | | | | Service ATA:55 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 55-20/362 | EXAMINE LEFT ELEVATOR | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-20-00 | | | | | | | | | | |
| 55-20/362 | EXAMINE RIGHT ELEVATOR | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-20-00 | | | | | | | | | | |
| 55-20/367 | EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-20-01 | | | | | | | | | | |
| 55-20/368 | EDDY CURRENT INSPECTION - LEFT ELEVATOR HINGES | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-20-01 | | | | | | | | | | |
| 55-20/368 | EDDY CURRENT INSPECTION - RIGHT ELEVATOR HINGES | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-20-01 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|-----------------------------|------|-----------|----------|--|------------------------|-----------|-----------|---------------|---------|----------|--------|
| ATA 55 - STABILIZERS | | | | | | | | | | | |
| 55-30/198 ^S | | | | EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE | | | | | Service | ATA:55 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | PROC. REF: AMM 55-00-01 | | | | | | | PKG:17 |
| 55-30/199 ^S | | | | EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002. | | | | | Service | ATA:55 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | PROC. REF: GENERIC NO REF | | | | | | | PKG:17 |
| 55-30/281 ^S | | | | EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS | | | | | Service | ATA:55 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| | | | | PROC. REF: GENERIC NO REF | | | | | | | PKG:20 |
| 55-30/369 | | | | EXAMINE - VERTICAL STABILIZER | | | | | Service | ATA:55 | |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| | | | | PROC. REF: AMM 55-30-00 | | | | | | | |
| 55-30/370 | | | | EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE | | | | | Service | ATA:55 | |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| | | | | PROC. REF: AMM 55-30-03, AMM 53-30-02 | | | | | | | |
| 55-30/371 | | | | EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER | | | | | Service | ATA:55 | |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| | | | | PROC. REF: AMM 55-00-00 | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-----------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 55 - STABILIZERS | | | | | | | | | | |
| 55-30/372 | EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-30-02 | | | | | | | | | | |
| 55-30/420 | EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40 | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-30-03 | | | | | | | | | | |
| 55-40/373 | EXAMINE - RUDDER | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-40-00 | | | | | | | | | | |
| 55-40/377 | EDDY CURRENT INSPECTION - RUDDER HINGES | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-40-05 | | | | | | | | | | |
| 55-40/410 | EXAMINE RUDDER TRIM TAB | | | | | | | | | Service ATA:55 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 55-40-04 | | | | | | | | | | |
| ATA 56 - WINDOWS | | | | | | | | | | |
| 56-11/14 | REPLACE LEFT HAND WINDSHIELD ASSEMBLY (INNER LAMINATION CRACKED) | | | | | | | | | Service ATA:56 |
| PN:PN | MOS/MSC | 10-Dec-01 | A/R | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | | | | | | | |
| | AFL | 0 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|---------|---|----------|----------|------------------------|-----------|-----------|---------------|---------|----------|--|
| ATA 56 - WINDOWS | | | | | | | | | | | |
| 56-11/14 | | REPLACE RIGHT HAND WINDSHIELD ASSEMBLY (INNER LAMINATION CRACKED) | | | | | | | Service | ATA:56 | |
| PN:PN | MOS/MSC | 10-Dec-01 | A/R | | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | | | | | | | | |
| | AFL | 0 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 56-11/15 | | LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) | | | | | | | Service | ATA:56 | |
| PN:PN | MOS/MSC | 10-Dec-01 | A/R | | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | | | | | | | | |
| | AFL | 0 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 56-11/15 | | RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) | | | | | | | Service | ATA:56 | |
| PN:PN | MOS/MSC | 10-Dec-01 | A/R | | | | | | | | |
| SN:UNKNOWN | HRS | 0 | | | | | | | | | |
| | AFL | 0 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 56-11/200 ^S | | EXAMINE WINDSHIELD LH AND RH | | | | | | | Service | ATA:56 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 56-00-00 | | | | | | | | | | PKG:17 | |
| 56-11/332 | | INSPECTION/CHECK COCKPIT SIDE WINDOWS | | | | | | | Service | ATA:56 | |
| | MOS | 06-Jun-22 | 120 | | 06-Jun-24 | | 2764 d | | | | |
| | HRS | 4063.5 | 11000 | | 15063.5 | | 10379 | | | | |
| WC#: 56.100 | AFL | | | | | | | | | | |
| PROC. REF: AMM 56-11-02 | | | | | | | | | | | |
| 56-11/378 | | EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS | | | | | | | Service | ATA:56 | |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | | |
| PROC. REF: AMM 53-10-16, AMM 56-11-01, AMM 56-11-02 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--|---|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----------|----------|
| ATA 56 - WINDOWS | | | | | | | | | | |
| 56-11/517 ^S | COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND | | | | | | | | Service | ATA:56 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF, AMM GENERIC | | | | | | | | | | PKG:20 |
| 56-20/201 ^S | EXAMINE COCKPIT AND CABIN WINDOWS | | | | | | | | Service | ATA:56 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 56-00-00 | | | | | | | | | | PKG:17 |
| 561010 | LEFT HAND WINDSHIELD ASSEMBLY | | | | | | | | Component | ATA:56 |
| PN:PN | MOS/MSC | 10-Dec-01 | O/C | TSN 0 | | | | AIRWORTHINESS | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | |
| WC#: 56.010 | AFL | 0 | | TSN 0 | | | | | | |
| PROC. REF: AMM 56-11-01 | | | | | | | | | | |
| 561011 | RIGHT HAND WINDSHIELD ASSEMBLY | | | | | | | | Component | ATA:56 |
| PN:PN | MOS/MSC | 10-Dec-01 | O/C | TSN 0 | | | | AIRWORTHINESS | | |
| SN:UNKNOWN | HRS | 0 | | TSN 0 | | | | | | |
| WC#: 56.010 | AFL | 0 | | TSN 0 | | | | | | |
| PROC. REF: AMM 56-11-01 | | | | | | | | | | |
| ATA 57 - WINGS | | | | | | | | | | |
| 57-00/11 | STRUCTURAL LIMITATION LEFT WING STRUCTURE | | | | | | | | Service | ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 20000 | | 20000 | | 15315.5 | | | |
| WC#: 57.010 | AFL | 0 | 27000 | | 27000 | | 23820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 57-00/11 | STRUCTURAL LIMITATION RIGHT WING STRUCTURE | | | | | | | | Service | ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 20000 | | 20000 | | 15315.5 | | | |
| WC#: 57.010 | AFL | 0 | 27000 | | 27000 | | 23820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 57-00/202 ^S | EXAMINE WING EXTERNAL SURFACES | | | | | | | | Service | ATA:57 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 57 - WINGS | | | | | | | | | | |
| 57-00/282 ^S | EXAMINE WING TIP STATIC DISCHARGERS | | | | | | | | | Service ATA:57 |
| | MOS | 06-Jun-24 | 24 | | | | | | | |
| | HRS | 4601.3 | 2400 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:21 |
| 57-00/283 ^S | EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH ACCESS PANELS REMOVED | | | | | | | | | Service ATA:57 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 57-00/284 ^S | EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE | | | | | | | | | Service ATA:57 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 57-00/326 | STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009) | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | 30000 | | 30000 | | 26820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 57-00/326 | STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009) | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | 30000 | | 30000 | | 26820 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 57-00/379 | EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| PROC. REF: AMM 57-00-00 | | | | | | | | | | |
| 57-00/379 | EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| PROC. REF: AMM 57-00-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 57 - WINGS | | | | | | | | | | |
| 57-00/380 | EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:30000 | | 30000 | | 25315.5 | | | |
| | AFL | 0 | T:39000 | | 39000 | | 35820 | | | |
| PROC. REF: AMM 57-00-03, AMM 57-00-03 | | | | | | | | | | |
| 57-00/382 | EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |
| 57-00/382 | EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |
| 57-00/383 | EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |
| 57-00/383 | EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |
| 57-00/384 | EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-05 | | | | | | | | | | |
| 57-00/384 | EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-05 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 57 - WINGS | | | | | | | | | | |
| 57-00/385 | EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |
| 57-00/385 | EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |
| 57-00/412 | EXAMINE WING TIPS | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 57-33-00 | | | | | | | | | | |
| 57-00/413 | EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-01 | | | | | | | | | | |
| 57-00/413 | EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | T:25000 | | 25000 | | 20315.5 | | | |
| | AFL | 0 | T:30000 | | 30000 | | 26820 | | | |
| PROC. REF: AMM 57-20-01 | | | | | | | | | | |
| 57-00/427 | EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 16000 | | 16000 | | 11315.5 | | | |
| | AFL | 0 | 22500 | | 22500 | | 19320 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |
| 57-00/427 | EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6 | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 16000 | | 16000 | | 11315.5 | | | |
| | AFL | 0 | 22500 | | 22500 | | 19320 | | | |
| PROC. REF: AMM 57-20-10 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|------------------|
| ATA 57 - WINGS | | | | | | | | | | |
| 57-00/97 | EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED) | | | | | | | | | Service ATA:57 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| WC#: 57.020 | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 57-00/98 | EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS) | | | | | | | | | Service ATA:57 |
| | MOS | 25-Jun-19 | 72 | | 25-Jun-25 | | 226 d | | | |
| | HRS | 3329.6 | 6000 | | 9329.6 | | 4645.1 | | | |
| WC#: 57.030 | AFL | 2328 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 57-00/99 | EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED | | | | | | | | | Service ATA:57 |
| | MOS | 06-Jun-22 | 120 | | 06-Jun-32 | | 2764 d | | | |
| | HRS | 4063.5 | 11000 | | 15063.5 | | 10379 | | | |
| WC#: 57.040 | AFL | | | | | | | | | |
| PROC. REF: AMM 57-00-00 | | | | | | | | | | |
| 57-60/393 | EXAMINE LEFT WING AILERON | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 57-60-00 | | | | | | | | | | |
| 57-60/411 | EXAMINE AILERON TRIM TAB | | | | | | | | | Service ATA:57 |
| | MOS | 10-Dec-01 | | | | | | | | |
| | HRS | 0 | T:32500 | | 32500 | | 27815.5 | | | |
| | AFL | 0 | T:42000 | | 42000 | | 38820 | | | |
| PROC. REF: AMM 57-60-04 | | | | | | | | | | |
| 570010 | AILERON RH 10A SERIE ASSY | | | | | | | | | Component ATA:57 |
| PN:557.05.12.014 | MOS/MSC | 25-Jan-06 | O/C | TSN 0 | | | | | | |
| SN:592 | HRS | 575.7 | | TSN 0 | | | | | | |
| WC#: 57.050 | AFL | | | TSN 0 | | | | | | |
| PROC. REF: AMM 57-60-01 | | | | | | | | | | |
| 570025 | AILERON LH 10A SERIE ASSY | | | | | | | | | Component ATA:57 |
| PN:557.05.12.011 | MOS/MSC | 25-Jan-06 | O/C | TSN 0 | | | | | | |
| SN:471 | HRS | 575.7 | | TSN 0 | | | | | | |
| WC#: 57.050 | AFL | | | TSN 0 | | | | | | |
| PROC. REF: AMM 57-60-01 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|--|-----|-----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 57 - WINGS | | | | | | | | | | |
| 570282 | WING STATIC DISCHARGER | | | | | | | | | Component ATA:57 |
| PN:984.78.81.408 | MOS/MSC | | 25-Jan-06 | O/C | TSN 0 | | | | | |
| SN:UNKNOWN | HRS | | 575.7 | | TSN 0 | | | | | |
| | AFL | | | | TSN 0 | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| ATA 61 - PROPELLERS/PROPULSORS | | | | | | | | | | |
| 61-10/37 | NO. 1 PROPELLER - OVERHAUL | | | | | | | | | Service ATA:61 |
| | MOS | | 25-Jun-19 | 72 | 25-Jun-25 | | 226 d | OVERHAUL | | |
| | HRS | | 1542.5 | 4500 | (6042.5) 7841.4 | | 3156.9 | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 61-20/286 ^S | EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS | | | | | | | | | Service ATA:61 |
| | MOS | | 06-Jun-24 | 12 | | | | | | |
| | HRS | | 4601.3 | 1200 | | | | | | |
| | AFL | | 3132 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 |
| 610060 | NO. 1 PROPELLER - OIL ACCUMULATOR | | | | | | | | | Component ATA:61 |
| PN:PN | MOS/MSC | | 25-Jun-19 | N/A | | | | | | |
| SN:UNKNOWN | HRS | | 1542.5 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 610100 | NO. 1 PROPELLER - ACCOMPLISH INSPECTION | | | | | | | | | Service ATA:61 |
| | MOS | | 06-Jun-24 | 12 | 06-Jun-25 | | 207 d | | | |
| | HRS | | 2802.4 | 150 | (2952.4) 4751.3 | | 66.8 | | | |
| PROC. REF: OIM 61-00-83 | | | | | | | | | | |
| 610400 | NO. 1 PROPELLER - PERFORM PROPELLER BALANCE | | | | | | | | | Service ATA:61 |
| | MOS/MSC | | 25-Jun-19 | A/R | | | | | | |
| | HRS | | 1542.5 | | | | | | | |
| PROC. REF: OIM 61-00-83 | | | | | | | | | | |
| 611501 | NO. 1 PROPELLER - NO. 1 BLADE | | | | | | | | | Component ATA:61 |
| PN:UNKN | MOS/MSC | | 25-Jun-19 | O/C | TSN 666, TSO 0 | | | | | |
| SN:ABF-40159 | HRS | | 1542.5 | | TSO 0 | | | | | |
| PROC. REF: OIM 61-00-83, OIM 61-00-83 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|---|-----------|-----------------|--------------------------------------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 61 - PROPELLERS/PROPULSORS | | | | | | | | | | |
| 611502 | NO. 1 PROPELLER - NO. 2 BLADE | | | | | | | | | Component ATA:61 |
| PN:UNKN | MOS/MSC | 25-Jun-19 | O/C | TSN 666, TSO 0 | | | | | | |
| SN:ABF-40160 | HRS | 1542.5 | TSO 0 | | | | | | | |
| PROC. REF: OIM 61-00-83, OIM 61-00-83 | | | | | | | | | | |
| 611503 | NO. 1 PROPELLER - NO. 3 BLADE | | | | | | | | | Component ATA:61 |
| PN:UNKN | MOS/MSC | 25-Jun-19 | O/C | TSN 666, TSO 0 | | | | | | |
| SN:ABF-40161 | HRS | 1542.5 | TSO 0 | | | | | | | |
| PROC. REF: OIM 61-00-83, OIM 61-00-83 | | | | | | | | | | |
| 611504 | NO. 1 PROPELLER - NO. 4 BLADE | | | | | | | | | Component ATA:61 |
| PN:UNKN | MOS/MSC | 25-Jun-19 | O/C | TSN 666, TSO 0 | | | | | | |
| SN:ABF-40162 | HRS | 1542.5 | TSO 0 | | | | | | | |
| PROC. REF: OIM 61-00-83, OIM 61-00-83 | | | | | | | | | | |
| 611505 | NO. 1 PROPELLER - NO. 5 BLADE | | | | | | | | | Component ATA:61 |
| PN:UNKN | MOS/MSC | 25-Jun-19 | O/C | TSN 666, TSO 0 | | | | | | |
| SN:ABF-40163 | HRS | 1542.5 | TSO 0 | | | | | | | |
| PROC. REF: OIM 61-00-83, OIM 61-00-83 | | | | | | | | | | |
| 612010 | NO. 1 ENGINE - PROPELLER GOVERNOR | | | | | | | | | Component ATA:61 |
| PN:3049558-01 | MOS | 23-Apr-19 | TSN 208, TSO 0 | | | OVERHAUL | | | | |
| SN:13107793 | HRS | 3272.5 | 3500 | TSN 3272.5, TSO 0 (6772.5) 6797.6 | | | 2113.1 | | | |
| | ENC | 2285 | TSN 2285, TSO 0 | | | | | | | |
| PROC. REF: EMM 61-20-00 | | | | | | | | | | |
| 612020 | NO. 1 ENGINE - OVERSPEED GOVERNOR | | | | | | | | | Component ATA:61 |
| PN:3037685 | MOS | 23-Apr-19 | TSN 208, TSO 0 | | | OVERHAUL | | | | |
| SN:13098218 | HRS | 3272.5 | 3500 | TSN 3272.5, TSO 0 (6772.5) 6797.6 | | | 2113.1 | | | |
| | ENC | 2285 | TSN 2285, TSO 0 | | | | | | | |
| PROC. REF: EMM 61-20-00 | | | | | | | | | | |
| 617010 | NO. 1 PROPELLER - REPLACE SEALS (IF STORED FOR LONGER THAN 24 MONTHS) | | | | | | | | | Component ATA:61 |
| PN:PN | MOS/MSC | 25-Jun-19 | A/R | | | | | | | |
| SN:UNKNOWN | HRS | 1542.5 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 619010 | NO. 1 PROPELLER - BETA/OIL TRANSFER TUBE | | | | | | | | | Component ATA:61 |
| PN:PN | MOS/MSC | 25-Jun-19 | N/A | | | | | | | |
| SN:UNKNOWN | HRS | 1542.5 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|---|-----------|----------|----------|------------------------|---------------|-----------|-------------|-----|------------------|
| ATA 61 - PROPELLERS/PROPULSORS | | | | | | | | | | |
| 61PR1 | NO. 1 PROPELLER | | | | | | | | | Component ATA:61 |
| PN:MTV-27-1-N-C-F-R(P) | MOS/MSC | 13-Aug-19 | PP/C | | | | | | | |
| SN:110361 | HRS | 3368.5 | | | TSN 1569.7, TSO 27.2 | | | | | |
| WC#: 61.PR1 | AFL | | | | | | | | | |
| PROC. REF: AMM 61-10-01 | | | | | | | | | | |
| ATA 71 - POWER PLANT | | | | | | | | | | |
| 71-00/101 ^S | OPERATIONAL TEST POWER PLANT TORQUE LIMITER | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| WC#: 71.010 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 71-00-00 | | | | | | | | | | |
| 71-00/102 ^S | OPERATIONAL TEST POWER PLANT PERFORMANCE | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 71-00-00 | | | | | | | | | | |
| 71-00/106 ^S | CLEAN OIL PRESSURE TRANSDUCER ELECTRICAL CONNECTOR | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| WC#: 71.020 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 71-00-03 | | | | | | | | | | |
| 71-00/107 ^S | CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| WC#: 71.030 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 71-00-03 | | | | | | | | | | |
| 71-00/16 | ENGINE (PRE SB 04-009) MOUNTING FRAME | | | | | | | | | Component ATA:71 |
| PN:PN | MOS | 10-Dec-01 | | | TSN 0 | AIRWORTHINESS | | | | |
| SN:UNKNOWN | HRS | 0 | 20000 | TSN 0 | 20000 | 15315.5 | | | | |
| WC#: 71.050 | AFL | 0 | 27000 | TSN 0 | 27000 | 23820 | | | | |
| PROC. REF: AMM 71-00-05 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 71 - POWER PLANT | | | | | | | | | | |
| 71-00/17 | REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS | | | | | | | | | Service ATA:71 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | 11000 | | 11000 | | 6315.5 | | | |
| WC#: 71.050 | AFL | 0 | | | | | | | | |
| PROC. REF: AMM 71-00-04 | | | | | | | | | | |
| 71-00/204 ^S | DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 71-00-00 | | | | | | | | | | |
| PKG:15 ,16,17,18,19,20,21 | | | | | | | | | | |
| 71-00/205 ^S | EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| PKG:20 | | | | | | | | | | |
| 71-00/206 | EXAMINE POWER PLANT AND ACCESSORIES REFER TO P&WC EMM 72-00-00 PERIODIC INSPECTION | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 18-Jun-18 | A/R | | | | | | | |
| | HRS | 3146.6 | | | | | | | | |
| | AFL | 2198 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 71-00/209 ^S | EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS) | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| PKG:17 | | | | | | | | | | |
| 71-00/287 ^S | DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 71-00-00 | | | | | | | | | | |
| PKG:15 ,16,17,18,19,20,21 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|------|---|----------|----------|------------------------|-----------|-----------|---------------|-----------|----------|--|
| ATA 71 - POWER PLANT | | | | | | | | | | | |
| 71-00/301 ^S | | EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME | | | | | | | Service | ATA:71 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM GENERIC | | | | | | PKG:20 | | | | | |
| 71-00/327 | | ENGINE (POST SB 04-009) MOUNTING FRAME | | | | | | | Component | ATA:71 | |
| PN:PN | MOS | 10-Dec-01 | | TSN 0 | | | | AIRWORTHINESS | | | |
| SN:UNKNOWN | HRS | 0 | 25000 | TSN 0 | 25000 | | 20315.5 | | | | |
| | AFL | 0 | 30000 | TSN 0 | 30000 | | 26820 | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 71-00/38 | | LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY | | | | | | | Component | ATA:71 | |
| PN:944.81.21.409 | MOS | 23-Apr-19 | | TSN 0 | | | | OVERHAUL | | | |
| SN:UNKNOWN | HRS | 3299.5 | 3500 | TSN 0 | 6799.5 | | 2115 | | | | |
| WC#: 71.063 | AFL | 2308 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 71-00-01 | | | | | | | | | | | |
| 71-00/38 | | LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY | | | | | | | Component | ATA:71 | |
| PN:944.81.21.409 | MOS | 23-Apr-19 | | TSN 0 | | | | OVERHAUL | | | |
| SN:10917 | HRS | 3299.5 | 3500 | TSN 0 | 6799.5 | | 2115 | | | | |
| WC#: 71.064 | AFL | 2308 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 71-00-01 | | | | | | | | | | | |
| 71-00/38 | | UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY | | | | | | | Component | ATA:71 | |
| PN:944.81.21.409 | MOS | 23-Apr-19 | | TSN 0 | | | | OVERHAUL | | | |
| SN:10897 | HRS | 3299.5 | 3500 | TSN 0 | 6799.5 | | 2115 | | | | |
| WC#: 71.061 | AFL | 2308 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 71-00-01 | | | | | | | | | | | |
| 71-00/38 | | UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY | | | | | | | Component | ATA:71 | |
| PN:944.81.21.409 | MOS | 23-Apr-19 | | TSN 0 | | | | OVERHAUL | | | |
| SN:10896 | HRS | 3299.5 | 3500 | TSN 0 | 6799.5 | | 2115 | | | | |
| WC#: 71.060 | AFL | 2308 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 71-00-01 | | | | | | | | | | | |
| 71-00/38 | | UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY | | | | | | | Component | ATA:71 | |
| PN:944.81.21.409 | MOS | 23-Apr-19 | | TSN 0 | | | | OVERHAUL | | | |
| SN:10901 | HRS | 3299.5 | 3500 | TSN 0 | 6799.5 | | 2115 | | | | |
| WC#: 71.062 | AFL | 2308 | | TSN 0 | | | | | | | |
| PROC. REF: AMM 71-00-01 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|---------------|-----|----------------|
| ATA 71 - POWER PLANT | | | | | | | | | | |
| 71-00/401 | MAGNETIC PARTICLE INSPECT - ENGINE MOUNT | | | | | | | | | Service ATA:71 |
| | MOS | 10-Dec-01 | | | | | | AIRWORTHINESS | | |
| | HRS | 0 | T:26600 | | 26600 | | 21915.5 | | | |
| | AFL | 0 | T:35000 | | 35000 | | 31820 | | | |
| PROC. REF: AMM 71-00-05 | | | | | | | | | | |
| 71-00/476 ^S | REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| PKG:15 ,16,17,18,19,20,21 | | | | | | | | | | |
| 71-10/207 ^S | OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001 | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| PKG:15 ,16,17,18,19,20,21 | | | | | | | | | | |
| 71-10/208 ^S | CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4601.3 | | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| PKG:15 ,16,17,18,19,20,21 | | | | | | | | | | |
| 71-10/476 ^U | REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 10-Dec-01 | A/R | | | | | | | |
| | HRS | 0 | | | | | | | | |
| | AFL | 0 | | | | | | | | |
| 710011 | NO. 1 ENGINE - OVERHAUL | | | | | | | | | Service ATA:71 |
| | MOS | 23-Apr-19 | | | | | | OVERHAUL | | |
| | HRS | 3274.4 | 3500 | | (6774.4) 6799.5 | | 2115 | | | |
| | ENC | 2285 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 710019 ^S | NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 72-30-05 | | | | | | | | | | |
| PKG:2 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|-------------------------|---------|-----------|---|----------|------------------------|-----------|-----------|-------------|-----|----------|----------------|
| ATA 71 - POWER PLANT | | | | | | | | | | | |
| 710021 | | | NO. 1 ENGINE - HOT SECTION INSPECTION | | | | | | | | Service ATA:71 |
| | MOS | 23-Apr-19 | | | | | | | | | |
| | HRS | 3274.4 | 2000 | | (5274.4) 5299.5 | | 615 | | | | |
| | ENC | 2285 | | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | | |
| 710031 | | | NO. 1 ENGINE - BORESCOPE HOT SECTION | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 400 | | (4976.2) 5001.3 | | 316.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | | |
| 710041 | | | NO. 1 ENGINE - INSPECT POWER TURBINE BLADES | | | | | | | | Service ATA:71 |
| | MOS/MSC | 23-Apr-19 | N/A | | | | | | | | |
| | HRS | 3274.4 | | | | | | | | | |
| | ENC | 2285 | | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | | |
| 710050 | | | NO. 1 ENGINE - COMPRESSOR DESALINATION WASH | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 71-00-00 | | | | | | | | | | | |
| 710051 | | | NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 71-00-00 | | | | | | | | | | | |
| 710052 | | | NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH | | | | | | | | Service ATA:71 |
| | MOS/MSC | 06-Jun-22 | A/R | | | | | | | | |
| | HRS | 4035.5 | | | | | | | | | |
| | ENC | | | | | | | | | | |
| PROC. REF: EMM 71-00-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|-------------------------|--|-----------|----------|----------|--------------------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 71 - POWER PLANT | | | | | | | | | | |
| 710061 | NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM) | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 06-Jun-24 | A/R | | | | | | | |
| | HRS | 4576.2 | | | | | | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | |
| 710070 ^S | NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION | | | | | | | | | Service ATA:71 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 71-00-00 | | | | | | | | | | |
| 710100 | NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE | | | | | | | | | Service ATA:71 |
| | MOS/MSC | 01-Dec-01 | A/R | | | | | | | |
| | HRS | 0 | | | | | | | | |
| | ENC | 0 | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | |
| 71EN1 | NO. 1 ENGINE | | | | | | | | | Component ATA:71 |
| PN:PT6A-67B | MOS/MSC | 23-Apr-19 | E/C | | TSO 0 | | | | | |
| SN:PCE-PR0309 | HRS | 3299.5 | | | TSN 3299.5, TSO 0 | | | | | |
| WC#: 71.EN1 | AFL | 2308 | | | TSO 0 | | | | | |
| PROC. REF: AMM 71-00-01 | | | | | | | | | | |
| ATA 72 - ENGINE | | | | | | | | | | |
| 720010 | NO. 1 ENGINE - GAS GENERATOR MODULE | | | | | | | | | Component ATA:72 |
| PN:PN | MOS | 23-Apr-19 | | | TSN 208, TSO 0 | | | OVERHAUL | | |
| SN:UNKNOWN | HRS | 3272.5 | 3500 | | TSN 3272.5, TSO 0 (6772.5) 6797.6 | | 2113.1 | | | |
| | ENC | 2285 | | | TSN 2295, TSO 0 | | | | | |
| PROC. REF: EMM 72-30-04 | | | | | | | | | | |
| 720022 | NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL | | | | | | | | | Service ATA:72 |
| | MOS/MSC | 23-Apr-19 | BF/F | | | | | | | |
| | HRS | 3274.4 | | | | | | | | |
| | ENC | 2285 | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------------------|---------|-----------|--|----------|------------------------|-----------|-----------|-------------|-----|----------|----------------|
| ATA 72 - ENGINE | | | | | | | | | | | |
| 720023 | | | NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP | | | | | | | | Service ATA:72 |
| | MOS/MSC | 23-Apr-19 | BF/F | | | | | | | | |
| | HRS | 3274.4 | | | | | | | | | |
| | ENC | 2285 | | | | | | | | | |
| PROC. REF: EMM 72-60-00 | | | | | | | | | | | |
| 720030 ^S | | | NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT | | | | | | | | Service ATA:72 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:2 | | | | | | | | | | | |
| 720040 ^S | | | NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION | | | | | | | | Service ATA:72 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:2 | | | | | | | | | | | |
| 720050 ^S | | | NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES | | | | | | | | Service ATA:72 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:2 | | | | | | | | | | | |
| 720070 ^S | | | NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE | | | | | | | | Service ATA:72 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:2 | | | | | | | | | | | |
| 721100 | | | NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS | | | | | | | | Service ATA:72 |
| | MOS/MSC | 23-Apr-19 | BF/F | | | | | | | | |
| | HRS | 3274.4 | | | | | | | | | |
| | ENC | 2285 | | | | | | | | | |
| PROC. REF: EMM 72-11-00 | | | | | | | | | | | |
| 722010 ^S | | | NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS | | | | | | | | Service ATA:72 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 72-20-00, EMM 72-20-00 | | | | | | | | | | | |
| PKG:2 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|--------|--|----------|----------|------------------------|-----------|-----------|-------------|-----------|----------|--|
| ATA 72 - ENGINE | | | | | | | | | | | |
| 722020 ^S | | NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITHBORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACEAREAS AND STRUTS FOR CORROSION | | | | | | | Service | ATA:72 | |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 72-20-00 | | | | | | | | | | PKG:2 | |
| 723010 | | NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR | | | | | | | Component | ATA:72 | |
| PN:3039001 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:TX1A0530 | HRS | 0 | | TSN 0 | | | | | | | |
| | ENC | 0 | | TSN 0 | (24000) 24023 (M) | | 20843 | | | | |
| | ACCCYC | 0 | | 24000 | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 723020 | | NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT | | | | | | | Component | ATA:72 | |
| PN:3043063 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:A000XKBE | HRS | 0 | | TSN 0 | | | | | | | |
| | ENC | 0 | | TSN 0 | (24000) 24023 (M) | | 20843 | | | | |
| | ACCCYC | 0 | | 24000 | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 723026 ^S | | NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION | | | | | | | Service | ATA:72 | |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 72-30-04 | | | | | | | | | | PKG:2 | |
| 723030 | | NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR | | | | | | | Component | ATA:72 | |
| PN:3040952 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:TX1A0490 | HRS | 0 | | TSN 0 | | | | | | | |
| | ENC | 0 | | TSN 0 | (24000) 24023 (M) | | 20843 | | | | |
| | ACCCYC | 0 | | 24000 | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|---------|-----------|--|----------|------------------------|-----------|-----------|-------------------------------------|-----|----------|------------------|
| ATA 72 - ENGINE | | | | | | | | | | | |
| 723036 ^S | | | NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS | | | | | | | | Service ATA:72 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 72-30-04, EMM 72-30-01, EMM 72-30-02 | | | | | | | | | | PKG:2 | |
| 723040 | | | NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR | | | | | | | | Component ATA:72 |
| PN:3040933 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:TX1A0442 | HRS | 0 | | TSN 0 | | | | | | | |
| | ENC | 0 | | TSN 0 | (24000) 24023 (M) | | 20843 | | | | |
| | ACCCYC | 0 | 24000 | TSN 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 723050 | | | NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR | | | | | | | | Component ATA:72 |
| PN:3040944 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:TX1A0434 | HRS | 0 | | TSN 0 | | | | | | | |
| | ENC | 0 | | TSN 0 | (24000) 24023 (M) | | 20843 | | | | |
| | ACCCYC | 0 | 24000 | TSN 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 723060 | | | NO. 1 ENGINE - CENTRIFUGAL IMPELLER | | | | | | | | Component ATA:72 |
| PN:3036898 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | | |
| SN:TX1A0513 | HRS | 0 | | TSN 0 | | | | | | | |
| | ENC | 0 | | TSN 0 | (24000) 24023 (M) | | 20843 | | | | |
| | ACCCYC | 0 | 24000 | TSN 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 723070 | | | NO. 1 ENGINE - PERFORMANCE DETERIORATION | | | | | | | | Service ATA:72 |
| | MOS/MSC | 23-Apr-19 | A/R | | | | | UNSCHEDULED MAINTENANCE CHECK | | | |
| | HRS | 3274.4 | | | | | | | | | |
| | ENC | 2285 | | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 724060 | NO. 1 ENGINE - HIGH TORQUE INDICATION AT LOW POWER | | | | | | | | | Service ATA:72 |
| | MOS/MS | 01-Dec-01 | A/R | | | | | | | |
| | HRS | 0 | | | | | | | | |
| | ENC | 0 | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | |
| 725010 | NO. 1 ENGINE - COMPRESSOR TURBINE DISK | | | | | | | | | Component ATA:72 |
| PN:3053740-01 | MOS | 29-Dec-08 | | | | | | LIFE LIMIT | | |
| SN:A000YW64 | HRS | 1086.1 | | | | | | | | |
| | ENC | 740 | | TSN 740 | (8000) 8023 (M) | | 4843 | | | |
| | ACCCYC | 0 | 8000 | TSN 740 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725020 | NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES | | | | | | | | | Service ATA:72 |
| | MOS | 23-Apr-19 | | | | | | LIFE LIMIT | | |
| | HRS | 3274.4 | 5000 | | (8274.4) 8299.5 | | 3615 | | | |
| | ENC | 2285 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725026 ^S | NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION | | | | | | | | | Service ATA:72 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 72-50-05 | | | | | | | | | | PKG:2 |
| 725030 | NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK | | | | | | | | | Component ATA:72 |
| PN:3037312 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:A00102BA | HRS | 0 | | TSN 0 | | | | | | |
| | ENC | 0 | | TSN 0 | (15000) 15023 (M) | | 11843 | | | |
| | ACCCYC | 0 | 15000 | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725040 | NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK | | | | | | | | | Component ATA:72 |
| PN:3037313 | MOS | 01-Dec-01 | | TSN 0 | | | | LIFE LIMIT | | |
| SN:A0010CFX | HRS | 0 | | TSN 0 | | | | | | |
| | ENC | 0 | | TSN 0 | (15000) 15023 (M) | | 11843 | | | |
| | ACCCYC | 0 | 15000 | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|--|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 725122 | NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B764 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725123 | NO. 1 ENGINE - NO. 2 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B785 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725124 | NO. 1 ENGINE - NO. 3 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B789 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725125 | NO. 1 ENGINE - NO. 4 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B798 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725126 | NO. 1 ENGINE - NO. 5 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B799 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725127 | NO. 1 ENGINE - NO. 6 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B807 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725128 | NO. 1 ENGINE - NO. 7 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B835 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 725129 | NO. 1 ENGINE - NO. 8 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B927 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725130 | NO. 1 ENGINE - NO. 9 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B973 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725131 | NO. 1 ENGINE - NO. 10 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B980 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725132 | NO. 1 ENGINE - NO. 11 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B982 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725133 | NO. 1 ENGINE - NO. 12 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B984 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725134 | NO. 1 ENGINE - NO. 13 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG02B991 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725135 | NO. 1 ENGINE - NO. 14 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B005 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 725136 | NO. 1 ENGINE - NO. 15 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B009 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725137 | NO. 1 ENGINE - NO. 16 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B011 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725138 | NO. 1 ENGINE - NO. 17 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B014 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725139 | NO. 1 ENGINE - NO. 18 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B020 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725140 | NO. 1 ENGINE - NO. 19 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B025 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725141 | NO. 1 ENGINE - NO. 20 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B028 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725142 | NO. 1 ENGINE - NO. 21 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B087 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 725143 | NO. 1 ENGINE - NO. 22 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B294 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725144 | NO. 1 ENGINE - NO. 23 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B353 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725145 | NO. 1 ENGINE - NO. 24 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B358 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725146 | NO. 1 ENGINE - NO. 25 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B359 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725147 | NO. 1 ENGINE - NO. 26 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B399 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725148 | NO. 1 ENGINE - NO. 27 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B413 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725149 | NO. 1 ENGINE - NO. 28 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B422 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 725150 | NO. 1 ENGINE - NO. 29 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG03B449 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725151 | NO. 1 ENGINE - NO. 30 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG13B967 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725152 | NO. 1 ENGINE - NO. 31 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG13B972 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725153 | NO. 1 ENGINE - NO. 32 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG19B780 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725154 | NO. 1 ENGINE - NO. 33 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG20B363 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725155 | NO. 1 ENGINE - NO. 34 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG20B380 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725156 | NO. 1 ENGINE - NO. 35 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG20B381 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 725157 | NO. 1 ENGINE - NO. 36 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG20B384 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725158 | NO. 1 ENGINE - NO. 37 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG20B390 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725159 | NO. 1 ENGINE - NO. 38 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG20B429 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725160 | NO. 1 ENGINE - NO. 39 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG21B295 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725161 | NO. 1 ENGINE - NO. 40 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG21B307 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725162 | NO. 1 ENGINE - NO. 41 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG21B444 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 725163 | NO. 1 ENGINE - NO. 42 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG81A827 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---------------------------------------|--|-----------|----------|-------------------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 72 - ENGINE | | | | | | | | | | |
| 725164 | NO. 1 ENGINE - NO. 43 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE | | | | | | | | | Component ATA:72 |
| PN:3056693-01 | MOS/MSC | 03-Apr-19 | H/T | TSN 0 | | | | | | |
| SN:CG90A203 | HRS | 3274.4 | | TSN 0 | | | | | | |
| | ENC | 2285 | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 726020 | NO. 1 ENGINE - POWER SECTION MODULE | | | | | | | | | Component ATA:72 |
| PN:PN | MOS | 23-Apr-19 | | TSN 208, TSO 0 | | | | OVERHAUL | | |
| SN:UNKNOWN | HRS | 3272.5 | 3500 | TSN 3272.5, TSO 0 | | (6772.5) | 2113.1 | | | |
| | | | | | | 6797.6 | | | | |
| | ENC | 2285 | | TSN 2295, TSO 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 726030 | NO. 1 ENGINE - ELECTRICAL FILLER CAP AND INDICATOR, OIL-LEVEL | | | | | | | | | Component ATA:72 |
| PN:3045457-01 | MOS/MSC | 03-Apr-20 | O/C | TSO 0 | | | | | | |
| SN:AB0259 | HRS | 3274.4 | | TSO 0 | | | | | | |
| | ENC | 2285 | | TSO 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| ATA 73 - ENGINE FUEL AND CONTROL | | | | | | | | | | |
| 731010 | NO. 1 ENGINE - FUEL PUMP | | | | | | | | | Component ATA:73 |
| PN:825601-5 | MOS | 23-Apr-19 | | TSO 0 | | | | OVERHAUL | | |
| SN:1957 | HRS | 3272.5 | 3500 | TSO 0 | | (6772.5) | 2113.1 | | | |
| | | | | | | 6797.6 | | | | |
| | ENC | 2285 | | TSO 0 | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | |
| 731015 | NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) | | | | | | | | | Service ATA:73 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4576.2 | 400 | | | (4976.2) | 316.8 | | | |
| | | | | | | 5001.3 | | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 73-11-05, EMM 71-00-00 | | | | | | | | | | |
| 731025 | NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) | | | | | | | | | Service ATA:73 |
| | MOS/MSC | 23-Apr-19 | N/A | | | | | | | |
| | HRS | 3274.4 | | | | | | | | |
| | ENC | 2285 | | | | | | | | |
| PROC. REF: EMM 73-11-05 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|----------------------------------|---|-----|-----------|----------|--|-----------|-----------|-------------|-----|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL | | | | | | | | | | |
| 731030 | NO. 1 ENGINE - OVERTORQUE LIMITER | | | | | | | | | Component ATA:73 |
| PN:3055748-01 | MOS | | 23-Apr-19 | | TSN 208, TSO 0 | | | OVERHAUL | | |
| SN:C50360 | HRS | | 3272.5 | 3500 | TSN 3272.5, TSO 0 (6772.5) 6797.6 (M) | | 2113.1 | | | |
| | ENC | | 2285 | | TSN 2285, TSO 0 | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | |
| 731031 ^S | NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE | | | | | | | | | Service ATA:73 |
| | MOS | | 06-Jun-24 | | | | | | | |
| | HRS | | 4576.2 | 300 | | | | | | |
| | ENC | | 3109 | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | |
| 731035 | NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION | | | | | | | | | Service ATA:73 |
| | MOS/MSC | | 01-Dec-01 | N/A | | | | | | |
| | HRS | | 0 | | | | | | | |
| | ENC | | 0 | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | |
| 731040 | NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN | | | | | | | | | Service ATA:73 |
| PN:825601-5 | MOS | | 06-Jun-24 | | | | | | | |
| SN:1957 | HRS | | 4576.2 | 600 | (5176.2) 5201.3 | | 516.8 | | | |
| | ENC | | 3109 | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | |
| 731045 ^S | NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION | | | | | | | | | Service ATA:73 |
| | MOS | | 06-Jun-24 | | | | | | | |
| | HRS | | 4576.2 | 300 | | | | | | |
| | ENC | | 3109 | | | | | | | |
| PROC. REF: EMM 73-10-01 | | | | | | | | | | |
| 731050 | NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION | | | | | | | | | Service ATA:73 |
| PN:825601-5 | MOS/MSC | | 23-Apr-19 | N/A | | | | | | |
| SN:1957 | HRS | | 3272.5 | | | | | | | |
| | ENC | | 2285 | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|----------------------------------|---------|-----------|--|-------------------|------------------------|-----------|-----------|-------------|-----|-----------|--------|
| ATA 73 - ENGINE FUEL AND CONTROL | | | | | | | | | | | |
| 731052 | | | NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. | | | | | | | Service | ATA:73 |
| | MOS/MSC | 23-Apr-19 | N/A | | | | | | | | |
| | HRS | 3272.5 | | | | | | | | | |
| | ENC | 2285 | | | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | | |
| 731055 | | | NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER | | | | | | | Service | ATA:73 |
| PN:PN | MOS | 06-Jun-24 | | | | | | REPLACE | | | |
| SN:UNKNOWN | HRS | 4576.2 | 600 | | (5176.2) 5201.3 | | 516.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | | |
| 731056 ^S | | | NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS | | | | | | | Service | ATA:73 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| PKG:2 | | | | | | | | | | | |
| 731060 | | | NO. 1 ENGINE - OIL TO FUEL HEATER | | | | | | | Component | ATA:73 |
| PN:3039259 | MOS | 23-Apr-19 | | TSN 208, TSO 0 | | | | OVERHAUL | | | |
| SN:WA17403 | HRS | 3272.5 | 3500 | TSN 3272.5, TSO 0 | (6772.5) 6797.6 | | 2113.1 | | | | |
| | ENC | 2285 | | TSN 2285, TSO 0 | | | | | | | |
| PROC. REF: EMM 73-10-01 | | | | | | | | | | | |
| 731065 | | | NO. 1 ENGINE - EXAMINE FILTER BOWL | | | | | | | Service | ATA:73 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 731070 | | | NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE | | | | | | | Component | ATA:73 |
| PN:3038472 | MOS | 23-Apr-19 | | TSN 208, TSO 0 | | | | OVERHAUL | | | |
| SN:2017 | HRS | 3272.5 | 3500 | TSN 3272.5, TSO 0 | (6772.5) 6797.6 | | 2113.1 | | | | |
| | ENC | 2285 | | TSN 2285, TSO 0 | | | | | | | |
| PROC. REF: EMM 73-10-04 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | | |
|----------------------------------|------|-----|--|----------|------------------------|--------------------|-----------|-------------|-----|----------|-----------|--------|
| ATA 73 - ENGINE FUEL AND CONTROL | | | | | | | | | | | | |
| 731085 ^S | | | NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE | | | | | | | | Service | ATA:73 |
| | MOS | | 06-Jun-24 | | | | | | | | | |
| | HRS | | 4576.2 | 300 | | | | | | | | |
| | ENC | | 3109 | | | | | | | | | |
| PROC. REF: EMM 73-10-06 | | | | | | | | | | PKG:2 | | |
| 731090 | | | NO. 1 ENGINE - FUEL CONTROL UNIT | | | | | | | | Component | ATA:73 |
| PN:8063-042-01 | MOS | | 23-Apr-19 | | TSO 0 | | | OVERHAUL | | | | |
| SN:13093666 | HRS | | 3272.5 | 3500 | TSN 3272.5, TSO 0 | (6772.5) 6797.6 | 2113.1 | | | | | |
| | ENC | | 2285 | | TSO 0 | | | | | | | |
| PROC. REF: EMM 73-20-00 | | | | | | | | | | | | |
| 731091 ^S | | | NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE | | | | | | | | Service | ATA:73 |
| | MOS | | 06-Jun-24 | | | | | | | | | |
| | HRS | | 4576.2 | 300 | | | | | | | | |
| | ENC | | 3109 | | | | | | | | | |
| PROC. REF: EMM 73-10-04 | | | | | | | | | | PKG:2 | | |
| 731095 | | | NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS | | | | | | | | Component | ATA:73 |
| PN:PN | MOS | | 23-Apr-19 | | TSN 0 | | | LIFE LIMIT | | | | |
| SN:UNKNOWN | HRS | | 3272.5 | 4000 | TSN 0 | (7272.5) 7297.6 | 2613.1 | | | | | |
| | ENC | | | | TSN 0 | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | | |
| 731100 | | | NO. 1 ENGINE - CLEAN P3 FILTER | | | | | | | | Service | ATA:73 |
| | MOS | | 06-Jun-24 | | | | | | | | | |
| | HRS | | 4576.2 | 300 | | (4876.2) 4901.3 | 216.8 | | | | | |
| | ENC | | 3109 | | | | | | | | | |
| PROC. REF: EMM 73-10-07 | | | | | | | | | | PKG:2 | | |
| 731150 ^S | | | NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION | | | | | | | | Service | ATA:73 |
| | MOS | | 06-Jun-24 | | | | | | | | | |
| | HRS | | 4576.2 | 300 | | | | | | | | |
| | ENC | | 3109 | | | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | PKG:2 | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL | | | | | | | | | | |
| 731155 | NO. 1 ENGINE - FUEL PUMP OUTLET FILTER | | | | | | | | | Component ATA:73 |
| PN:PN | MOS/MSC | 06-Jun-24 | H/T | | | | | | | |
| SN:UNKNOWN | HRS | 4576.2 | | | | | | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 73-10-02 | | | | | | | | | | |
| 732020 ^S | NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES | | | | | | | | | Service ATA:73 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4576.2 | 300 | | | | | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 73-20-00 | | | | | | | | | | |
| 733020 | NO. 1 ENGINE - REPLACE P3 FILTER | | | | | | | | | Service ATA:73 |
| | MOS | 08-Mar-23 | | | | | | | | |
| | HRS | 4292.8 | 900 | | (5192.8) 5217.9 | | 533.4 | | | |
| | ENC | 2921 | | | | | | | | |
| PROC. REF: EMM 73-10-07 | | | | | | | | | | |
| 733070 | NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY | | | | | | | | | Service ATA:73 |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | |
| | ENC | 3109 | | | | | | | | |
| PROC. REF: EMM 73-10-07, EMM 73-10-07 | | | | | | | | | | |
| ATA 74 - IGNITION | | | | | | | | | | |
| 74-00/288 ^S | OPERATIONAL TEST IGNITION SYSTEM | | | | | | | | | Service ATA:74 |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 74-00-00 | | | | | | | | | | |
| 740010 | NO. 1 ENGINE - IGNITION EXCITER | | | | | | | | | Component ATA:74 |
| PN:10-381550-4 | MOS | 23-Apr-19 | | TSO 0 | | | | OVERHAUL | | |
| SN:00135632 | HRS | 3272.5 | 3500 | TSO 0 | (6772.5) 6797.6 | | 2113.1 | | | |
| | ENC | 2262 | | TSO 0 | | | | | | |
| PROC. REF: EMM 74-10-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|---------|-----|---|----------|------------------------|--------------------|-----------|-------------|-----|-----------|--------|
| ATA 74 - IGNITION | | | | | | | | | | | |
| 740015 | | | NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION | | | | | | | Service | ATA:74 |
| | MOS | | 06-Jun-24 | | | | | | | | |
| | HRS | | 4576.2 | 400 | | (4976.2) 5001.3 | 316.8 | | | | |
| | ENC | | 3109 | | | | | | | | |
| PROC. REF: EMM 74-10-00 | | | | | | | | | | | |
| 740020 | | | NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG | | | | | | | Component | ATA:74 |
| PN:CH34055 | MOS/MSC | | 11-Dec-17 | O/C | | | | | | | |
| SN:UNKNOWN | HRS | | 3022.3 | | | | | | | | |
| | ENC | | 2117 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 740025 | | | NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION | | | | | | | Service | ATA:74 |
| | MOS | | 06-Jun-24 | | | | | | | | |
| | HRS | | 4576.2 | 400 | | (4976.2) 5001.3 | 316.8 | | | | |
| | ENC | | 3109 | | | | | | | | |
| PROC. REF: EMM 74-20-00 | | | | | | | | | | | |
| 740040 | | | NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG | | | | | | | Component | ATA:74 |
| PN:CH34055 | MOS/MSC | | 11-Dec-17 | O/C | | | | | | | |
| SN:UNKNOWN | HRS | | 3022.3 | | | | | | | | |
| | ENC | | 2117 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 742010 | | | NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION | | | | | | | Service | ATA:74 |
| | MOS | | 06-Jun-24 | | | | | | | | |
| | HRS | | 4576.2 | 400 | | (4976.2) 5001.3 | 316.8 | | | | |
| | ENC | | 3109 | | | | | | | | |
| PROC. REF: EMM 74-20-00 | | | | | | | | | | | |
| ATA 75 - AIR | | | | | | | | | | | |
| 750010 | | | NO. 1 ENGINE - COMPRESSOR BLEED VALVE | | | | | | | Component | ATA:75 |
| PN:3123532-01 | MOS | | 23-Apr-19 | | TSN 208, TSO 0 | | | OVERHAUL | | | |
| SN:44A824 | HRS | | 3272.5 | 3500 | TSN 3272.5, TSO 0 | (6772.5) 6797.6 | 2113.1 | | | | |
| | ENC | | 2285 | | TSN 2285, TSO 0 | | | | | | |
| PROC. REF: EMM 75-30-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|---|------|-----------|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|
| ATA 76 - ENGINE CONTROLS | | | | | | | | | | |
| 76-00/210^S EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT Service ATA:76 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:19 |
| 76-00/211^S MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM) Service ATA:76 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 76-00/212^S OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. Service ATA:76 | | | | | | | | | | |
| | MOS | 06-Jun-24 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 76-10-00 | | | | | | | | | | PKG:16 |
| 76-00/303^S OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE Service ATA:76 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 76-10-00, AMM 76-20-00 | | | | | | | | | | PKG:20 |
| 76-00/304^S EXAMINE COCKPIT CONTROL QUADRANT Service ATA:76 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | |
| | AFL | 3132 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 |
| 76-10/117 FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES Service ATA:76 | | | | | | | | | | |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | |
| | HRS | 4601.3 | 3000 | | 7601.3 | | 2916.8 | | | |
| WC#: 76.010 | AFL | 3132 | | | | | | | | |
| PROC. REF: AMM 76-10-02 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty |
|--------------------------|---|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------|----------|
| ATA 76 - ENGINE CONTROLS | | | | | | | | | | |
| 761011 | NO. 1 ENGINE - DEPENDING ON OPERATING CONDITIONS AND ENVIRONMENT, EXAMINE LINKAGES AT REGULAR INTERVALS | | | | | | | | Service | ATA:76 |
| | MOS | 11-Jul-23 | | | | | | | | |
| | HRS | 4385 | 300 | | (4685) 4710.1 | | 25.6 | | | |
| | ENC | 2978 | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---|---------|---|----------|----------|------------------------|-----------|-----------|-------------|-----|-----------|--------|
| ATA 77 - ENGINE INDICATING | | | | | | | | | | | |
| 77-00/213 ^S | | OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM | | | | | | | | Service | ATA:77 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 77-40-00, AMM 77-40-00, AMM 77-40-00 | | | | | | | | | | PKG:17 | |
| 770020 | | ACQ/DISPLAY UNIT | | | | | | | | Component | ATA:77 |
| PN:975.29.02.017 | MOS/MSC | 25-Oct-04 | O/C | | | | | | | | |
| SN:047 | HRS | 423 | | | TSN 282.3 | | | | | | |
| WC#: 77.020 | AFL | 272 | | | | | | | | | |
| PROC. REF: AMM 77-40-04, AMM 77-40-04 | | | | | | | | | | | |
| 771010 | | NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS | | | | | | | | Component | ATA:77 |
| PN:3043825-01 | MOS/MSC | 03-Apr-19 | O/C | | TSN 0 | | | | | | |
| SN:NRA104000 | HRS | 3274.4 | | | TSN 0 | | | | | | |
| | ENC | 2285 | | | TSN 0 | | | | | | |
| PROC. REF: EMM 77-20-01 | | | | | | | | | | | |
| 771020 | | NO. 1 ENGINE - T5 TERMINAL BLOCK | | | | | | | | Component | ATA:77 |
| PN:971.42.31.705 | MOS/MSC | 04-Apr-02 | O/C | | TSN 0 | | | | | | |
| SN:UNKNOWN | HRS | | | | TSN 0 | | | | | | |
| | ENC | | | | TSN 0 | | | | | | |
| PROC. REF: EMM 77-20-01 | | | | | | | | | | | |
| 772001 | | NO. 1 ENGINE - T5 POSITIVE TERMINAL BUS BAR | | | | | | | | Component | ATA:77 |
| PN:3109240-01 | MOS/MSC | 03-Apr-19 | O/C | | TSO 0 | | | | | | |
| SN:NR05115 | HRS | 3274.4 | | | TSO 0 | | | | | | |
| | ENC | 2285 | | | TSO 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 772002 | | NO. 1 ENGINE - T5 NEGATIVE TERMINAL BUS BAR | | | | | | | | Component | ATA:77 |
| PN:3109239-01 | MOS/MSC | 03-Apr-19 | O/C | | TSO 0 | | | | | | |
| SN:NR05124 | HRS | 3274.4 | | | TSO 0 | | | | | | |
| | ENC | 2285 | | | TSO 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| ATA 78 - EXHAUST | | | | | | | | | | | |
| 78-00/214 ^S | | EXAMINE EXHAUST STUBS | | | | | | | | Service | ATA:78 |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:17 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|--------|---|----------|----------|------------------------|-----------|-----------|-------------|-----------|----------|--|
| ATA 79 - OIL | | | | | | | | | | | |
| 79-00/215 ^S | | EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY. | | | | | | | Service | ATA:79 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 600 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 24-00-00 | | | | | | | | | | PKG:19 | |
| 79-20/289 ^S | | EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT | | | | | | | Service | ATA:79 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 1200 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:20 | |
| 79-20/290 ^S | | OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM | | | | | | | Service | ATA:79 | |
| | MOS | 06-Jun-24 | 12 | | | | | | | | |
| | HRS | 4601.3 | 300 | | | | | | | | |
| | AFL | 3132 | | | | | | | | | |
| PROC. REF: AMM 79-30-01 | | | | | | | | | | PKG:17 | |
| 79-20/43 | | OIL COOLER | | | | | | | Component | ATA:79 | |
| PN:968.32.14.102 | MOS | 23-Apr-19 | | TSO 0 | | | | OVERHAUL | | | |
| SN:T0391 | HRS | 3299.5 | 3500 | TSO 0 | 6799.5 | | 2115 | | | | |
| WC#: 79.010 | AFL | 2308 | | TSO 0 | | | | | | | |
| PROC. REF: AMM 79-20-02 | | | | | | | | | | | |
| 790021 | | NO. 1 ENGINE - SERVICING OF OIL SYSTEM | | | | | | | Service | ATA:79 | |
| | MOS/MS | 23-Apr-19 | A/R | | | | | DISCARD | | | |
| | HRS | 3274.4 | | | | | | | | | |
| | ENC | 2285 | | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |
| 790031 | | NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR | | | | | | | Service | ATA:79 | |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 79-20-02 | | | | | | | | | | PKG:2 | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|-------------------------|---------|--|----------|----------|------------------------|-----------|-----------|-------------|-----|----------|--------|
| ATA 79 - OIL | | | | | | | | | | | |
| 790040 | | NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR | | | | | | | | Service | ATA:79 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | | |
| | HRS | 4576.2 | 600 | | (5176.2) 5201.3 | | 516.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 79-20-02 | | | | | | | | | | | |
| 790050 | | NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT | | | | | | | | Service | ATA:79 |
| | MOS | 08-Mar-23 | | | | | | | | | |
| | HRS | 4292.8 | 900 | | (5192.8) 5217.9 | | 533.4 | | | | |
| | ENC | 2921 | | | | | | | | | |
| PROC. REF: EMM 79-20-02 | | | | | | | | | | | |
| 790060 | | NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN | | | | | | | | Service | ATA:79 |
| | MOS | 06-Jun-24 | | | | | | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 79-20-02 | | | | | | | | | | | |
| 790070 | | NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN | | | | | | | | Service | ATA:79 |
| | MOS | 08-Mar-23 | | | | | | | | | |
| | HRS | 4292.8 | 1000 | | (5292.8) 5317.9 | | 633.4 | | | | |
| | ENC | 2921 | | | | | | | | | |
| PROC. REF: EMM 72-60-00 | | | | | | | | | | | |
| 790080 | | NO. 1 ENGINE - PERFORM AN OIL SAMPLE | | | | | | | | Service | ATA:79 |
| | MOS/MSC | 18-Jun-21 | N/A | | | | | | | | |
| | HRS | 3736.8 | | | | | | | | | |
| | ENC | 2551 | | | | | | | | | |
| PROC. REF: EMM 79-20-02 | | | | | | | | | | | |
| 790081 | | NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING | | | | | | | | Service | ATA:79 |
| | MOS | 06-Jun-24 | 12 | | 06-Jun-25 | | 207 d | | | | |
| | HRS | 4576.2 | 300 | | (4876.2) 4901.3 | | 216.8 | | | | |
| | ENC | 3109 | | | | | | | | | |
| PROC. REF: EMM 72-00-00 | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12 Serial: 443 RegNo: N552TC HRS: 4684.5 AFL: 3180 As Of: 01-Nov-2024

11-Nov-2024 03:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | MOC | Warranty | |
|---------------------------|---------|-----|--|----------|------------------------|-----------|-----------|-------------|-----|----------|------------------|
| ATA 79 - OIL | | | | | | | | | | | |
| 790091 ^S | | | NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS | | | | | | | | Service ATA:79 |
| | MOS | | 06-Jun-24 | | | | | | | | |
| | HRS | | 4576.2 | | 300 | | | | | | |
| | ENC | | 3109 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:2 | |
| 790093 ^S | | | NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS | | | | | | | | Service ATA:79 |
| | MOS | | 06-Jun-24 | | | | | | | | |
| | HRS | | 4576.2 | | 300 | | | | | | |
| | ENC | | 3109 | | | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | PKG:2 | |
| 792030 | | | NO. 1 ENGINE - OIL PRESSURE TRANSDUCER | | | | | | | | Component ATA:79 |
| PN:975.21.15.214 | MOS/MSC | | 06-Aug-03 | O/C | TSN 0 | | | | | | |
| SN:6801-12-99 | HRS | | | | TSN 0 | | | | | | |
| | ENC | | | | TSN 0 | | | | | | |
| PROC. REF: GENERIC NO REF | | | | | | | | | | | |

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task