

# 2004 GULFSTREAM G-IV (G400)



**TOTAL TIME: 10,298 HOURS • LANDINGS: 4,814**

Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.

ACS-

## HIGHLIGHTS

---

14 CLUB SEAT CONFIGURATION

ENGINES ENROLLED ON RRCC

COLLINS AVIONICS ENROLLED ON CASP

HONEYWELL AVIONICS ENROLLED ON HAPP

AIRCELL ATG-5000 HIGH SPEED INTERNET

UPGRADED -150 APU

HEADS UP DISPLAY

ENHANCED FLIGHT VISION SYSTEM

ADS-B (OUT)/WAAS/LPV

AFT GALLEY

INTERIOR DONE 2022

## AIRFRAME

---

TOTAL TIME	10,298
LANDINGS	4,814
PROGRAM	None
ENTRY INTO SERVICE DATE	10/11/2004
CERTIFICATION DATE	30/06/2004
HOME BASE	Teterboro Airport (KTEB)

## ENGINES

---

MAKE/MODEL	Rolls Royce Tay 611-8	
SERIAL NO.	LEFT: 18207	RIGHT: 18194
TSN	LEFT: 10,167	RIGHT: 10,169
CSN	LEFT: 4,756	RIGHT: 4,758
PROGRAM	RRCC	

## APU

---

MAKE/MODEL	Honeywell GTCP-150 (G)
INSTALLED	2009
SERIAL NO.	P-975C
TSN	5,094
PROGRAM	None

Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.

## AVIONICS

<b>EFIS</b> (Electronic Flight Instrument System)	Honeywell DU-884 6-tube
<b>GPS</b> (Global Positioning System)	Dual Honeywell HG-2021
<b>DME</b> (Distance Measuring Equipment)	Dual Collins DME-442
<b>VHF COM</b> (Very High Frequency Communication)	Triple Collins VHF-422C (2), 422D (1)
<b>HF COM</b> (High Frequency Communication)	Dual Collins HF-9034A
<b>RADALT</b> (Radar Altimeter)	Dual Honeywell RT-300
<b>TCAS</b> (Traffic Collision Avoidance System)	Honeywell TCAS-2000 TCAS-II w/change 7.1
<b>AFIS</b> (Aerodrome Flight Information Service)	Honeywell VHF SATAFIS
<b>WRADAR</b> (Weather Radar)	Honeywell Primus 880
<b>XPNDR</b> (Transponder)	Dual Collins TDR-94D
<b>NAV</b> (Navigation Radios)	Dual Collins VIR-432
<b>GPWS</b> (Ground Proximity Warning System)	Honeywell Mark V EGPWS/RAAS
<b>FMS</b> (Flight Management System)	Triple Honeywell FMZ-2000 version 6.1 via ASC477A
<b>CDU</b> (Control Display Unit)	Triple HoneywellCDU-820
<b>IRS</b> (Inertial Reference System)	Triple Honeywell HG1075AE04
<b>CVR</b> (Cockpit Voice Recorder)	L3 FA2100
<b>FDR</b> (Flight Data Recorder)	L3 FA2100 (88-parameter)
<b>HUD</b> (Heads Up Display)	Honeywell HUD-2020
<b>EFVS</b> (Enhanced Flight Vision System)	Kollsman EFVS
<b>RTU</b> (Radio Tuning Units)	Dual Honeywell RTU-4220
<b>ADF</b> (Automatic Direction Finder)	Dual Honeywell ADF-462
<b>RMI</b> (Radio Magnetic Indicator)	Dual Litton BDI-303A
<b>ELT</b> (Emergency Locator Transmitter)	Artex C406-2

## COMPLIANCE

ADS-B (Out) Via Gulfstream ASC 502A	WAAS/LPV
8.33kHz Spacing	RNP 10
FM Immunity	B-RNAV (RNP-5)
Flight ID	NAT MNPS
RVSM	TCAS 7.1

## ADDITIONAL FEATURES

External Camera System w/3 Cameras

Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.

## INTERIOR

---

NUMBER OF PASSENGER SEATS	Fourteen (Certified)
GALLEY LOCATION	Aft
GALLEY EQUIPMENT	B/E Aerospace Convection Oven, Sharp Microwave Oven, Dual TIA Coffee Maker
CABIN CONFIGURATION	Fourteen Individual Captain's Chairs with Four Interchangeable Ottomans
LAVATORY LOCATION(S)	Aft
ADDITIONAL FEATURES	Interior done 2022

## EXTERIOR

---

LAST PAINT	2011
------------	------

## COMMUNICATIONS

---

Honeywell MCS-6000 SATCOM  
Aircell ATG-5000 High Speed Internet

## CABIN ENTERTAINMENT

---

Airshow Genesys  
Forward & Aft 17" Bulkhead Monitors  
Six Rosen Plug-In Monitors  
CD/DVD Players

## MAINTENANCE

---

Gulfstream CMP  
MSG-3

Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.



Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.



Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.



Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.