

1993 Challenger 601-3R **Registration: N144MH**

S/N: 5135

AIRFRAME:

Total Time: 8,582 Landings: 4,839

ENGINES: General Electric CF34-3A1

807049 Engine #1: Engine #2: 807048 Total Time: Total Time: 8,551 8,563 Cycles: 4,822 Cycles: 4,831

AUXILIARY POWER UNIT: Honeywell GTCP 36-150

MSP Gold

S/N: P-341 Total Time: 8,997

AVIONICS: Honeywell Primus II+ ADS-B WAAS LPV

Dual Honeywell NZ-2000 w/ 6.1 Software (WAAS) Global AFIS

Dual Honeywell 24-Channel GPS Honeywell SPZ-8000 IFCS Autopilot

Dual Honeywell RM8-855 with Flight ID Safe Flight Windshear System STC SA5753SW Honeywell Primus 880 Weather Radar Upgrade Safe Flight AOA STC SA776NE

Dual Honeywell HF's

Triple Honeywell HG-2001 LASERF III Dual Honeywell RCZ-833 Comms Dual Honeywell RNZ-850 w/ FM Immunity

Fairchild A100A CVR Honeywell RT-300 Radar Altimeter:

ICG ICS-200 Iridium w/ Dual Handsets Honeywell EDZ-815 & MDZ-815 5-Tube EFIS

Honeywell SPZ-8000 IFCS Honeywell Mark V EGPWS Class A

Dual Honeywell RCZ-833J Mode S Enhanced Surveillance Honeywell RT-910 TCAS-II w/ Change 7.1 SA1677GL

Honeywell KGS-200 GPS WAAS receiver

ADDITIONAL:

ADSB-Out XM Satellite Weather **Tail Flood Lighting Cockpit Sunvisors**

Landing & Taxi Pulse Lighting System Honeywell CG-130 LASERTRAK

Dual Honeywell CD-830 STC ST00818DE **EMTEQ LED Lighting**

Crew Electronic Flight Bags STC 02544CH-D Kannad 406 ELT

INTERIOR: Refurbished in 2019

Executive 8 Passenger in a Double Club Configuration in Tan Leather, Forward Galley w/Convection Oven, Microwave, Coffeemaker, 115-volt/60 Hz Power Outlets, Electric Window Shades, Airshow 400 w/DVD & CD Player, Dual Cabin Monitors, High- Gloss Walnut Burl Veneer Woodwork, Executive Writing Tables & a Private Enclosed AFT Lav.

EXTERIOR: Refurbished in 2019

Overall Chevron White & Red w/ Black Accents

CAMP Maintenance Tracking Fresh 10-year February 2023 Fresh 48 Month February 2025

Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aircraft Marketing & Sales, LLC. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.



































































