

2000 Learjet 45 PT-FLE | S/N 45-081 Located in Sao Paulo, SP- Brazil (CGH/SBSP)

AIRFRAME: Currently Flying 4,314 Total Time 3,808 Cycles ENGINES: TFE731-20AR-1B on Honeywell MSP S/N P116151 S/N P116152 **3.766 TSNEW** 4,314 TSNEW APU: Alliedsignal RE-100 P-137 on Honeywell MSP 8.554 **TSNEW** 3,442 Cycles **AVIONICS: ADSB OUT ADF:Honeywell Primus II** Flight Director: Honeywell Primus 1000 IFCS **AHRS: Dual Honeywell AHZ-800** Flight Phone: MagnaStar C-2000 Autopilot: Honeywell Primus 1000 IFCS w/dual FMS: Universal UNS-1C w/GPS **IC-600 computers Navigation Radios: Dual Honeywell RNZ-851 Avionics: Primus 1000 IFCS/Primus II** Radar Altimeter: Honeywell RT-300 **Communication Radios: Dual Honeywell RCZ-**TAWS: Bendix/King KGP-860 EGPWS 833 w/8.33 spacing **TCAS: Honeywell TCAS-II DME: Dual Honeywell Primus II Transponder: Dual Honeywell Primus II Mode S** EFIS: Honeywell 4-tube 8x7-inch **Honeywell Primus 660 color** Weather Radar: w/DU-870 & MFD

ADDITIONAL:

Thrus Reversers APU

INTERIOR:

Executive 8 Passenger Black Leather Seats

EXTERIOR: 2019

Overall Snow White w/Silver & Black Stripes and Black Lower

MAINTENANCE:

Complete logbooks Digital Maintenance Tracking Annual due May 2022 5 Year due January 2025 Phase A due 11/2022 Phase B due 3/2023 Forward Galley

Aft Lavatory RVSM

Phase C due 5/2023 Phase D due 4/2023

AVAILABLE IMMEDIATELY, MAKE OFFER, CONTACT TOM LELYO (941-216-1246) OR MARC BIUZZI (813-355-8585) Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Sales & Marketing, LLC. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase. IAMS | 8191 N. Tamiami Trail, suite 175 Sarasota, FL 34243 | T 941.355.5353 | F 941.827.2909 | www.intlams.com






















Marketing, LLC. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.















