

1985 Beechcraft Baron 58P Serial Number: TJ-486 Registration: N26HA TME/KTME/Houston Executive Airport, Houston, TX - U.S

AIRFRAME:

6,794 hours TTSN

ENGINE : Continental Aerospace Technologies TSIO-520-WB (Engines Replaced in 2013)	
Engine 1: 274030-R	Engine 2: 518476
552 TSMOH	552 TSMOH
TBO Interval: 1,600 hours	

PROP: McCauley- 3 Blade Metal- Constant Speed Propeller 1:

552 hrs SOH

AVIONICS:

Garmin G600 TXi EIS

Garmin GTN-650 Garmin GTN-750 GMA-35 GTX-33 ES

ADDITIONAL:

Dual Push-To-Talk Control-Wheels Bose System Yoke-Mounted Timer/Clock Long-Range Fuel, Cleveland Wheels & Brakes Ground Service Plug Spoilers GDL-69A GAD-43E ATT Gyro 2" Airspeed GA37 Ant.

Propeller 2:

552 hrs SOH

Polished Spinners Static Wicks Known Icing Wing-Tip Strobes ADSB Compliant Flightstream 210 (passengers)

INTERIOR: 2002 (Executive 4 Passenger- 2 Pilot)

Blue Leather Seating, Executive Writing Table

EXTERIOR: 2002

White w/high-gloss black & silver trim

MAINTENANCE: -Sold with a fresh Annual Inspection, Complete Logs Since New

AVAILABLE IMMEDIATELY, \$375,000.00 USD, CONTACT RYAN BOWNE (813)690-0465 (C)









AVAILABLE IMMEDIATELY, \$375,000.00 USD, CONTACT RYAN BOWNE (813)690-0465 (C) Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase. IAMI 8191 N. Tamiami Trail, suite 175 Sarasota, FL 34243 | T 941.355.5353 | F 941.827.2909 | www.intlams.com





Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.





Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.





Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.





Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.









Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.





Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.













Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase.













Specifications and descriptions are provided as introductory information. They do not constitute representations or warranties of International Aviation Marketing, Inc. Accordingly, you should rely on your own inspection of the aircraft prior to making any purchase or offer to purchase. IAMI 8191 N. Tamiami Trail, suite 175 Sarasota, FL 34243 | T 941.355.5353 | F 941.827.2909 | www.intlams.com