



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
4-12-MA <i>0512MA</i>	INSPECTION DOCUMENT MA ICT			MTH 05-Dec-2021 HRS 3327.4 LDG 2292		500		3827.4	179.9
4-12-MB	INSPECTION DOCUMENT MB			MTH 09-Oct-2006 HRS 0		15000		15000	11352.5
4-12-MC <i>0512MC</i>	INSPECTION DOCUMENT MC KMYF			MTH 21-Jul-2014 HRS 2010.6 LDG 1250		2000		4010.6	363.1
4-12-MD <i>0512MD</i>	INSPECTION DOCUMENT MD KICT			MTH 01-Feb-2019 HRS 2961.1 LDG 2072		1500		4461.1	813.6
4-12-ME <i>0512ME</i>	INSPECTION DOCUMENT ME (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) *CF			MTH 09-Oct-2006 LDG 0		5000			
32-20-00-250 NOSE LANDING GEAR	NOSE LANDING GEAR FORK AND PISTON ASSEMBLY (EDDY CURRENT OR DYE PENETRANT) SPECIAL DETAILED INSPECTION 6342350-4 SN-UNKNOWN			MTH 09-Oct-2006 LDG 0		5000		5000	2454
4-12-MF <i>0512MF</i>	INSPECTION DOCUMENT MF KIWA			MTH 03-Mar-2017 HRS 2440 LDG 1759 ACH 956.3		2500		4940	1292.5
4-12-MG <i>0512MG</i>	INSPECTION DOCUMENT MG *CF			MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
4-12-MH <i>0512MH</i>	INSPECTION DOCUMENT MH *CF			MTH 09-Oct-2006 HRS 0		5050		5050	1402.5
4-12-MI <i>0512MI</i>	INSPECTION DOCUMENT MI *CF			MTH 09-Oct-2006 HRS 0		6000		6000	2352.5
4-12-MJ <i>0512MJ</i>	INSPECTION DOCUMENT MJ KICT			MTH 01-Feb-2019 HRS 2961.1 LDG 2072		3000		5961.1	2313.6
4-12-MK	INSPECTION DOCUMENT MK PVU			MTH 03-Feb-2023 HRS 3554.1 LDG 2477		12 330		29-Feb-2024 3884.1	5 m 3 d 236.6
4-12-ML	INSPECTION DOCUMENT ML			HRS		9000		9000	5352.5
4-12-MO	INSPECTION DOCUMENT MO			MTH 09-Oct-2006 HRS 0		15000		15000	11352.5
4-12-MQ	INSPECTION DOCUMENT MQ			MTH 09-Oct-2006 HRS 0		15000		15000	11352.5
4-12-MR	INSPECTION DOCUMENT MR			MTH 09-Oct-2006 HRS 0		11500		11500	7852.5
4-12-MS	INSPECTION DOCUMENT MS			MTH 09-Oct-2006 HRS 0		12000		12000	8352.5
4-12-MT	INSPECTION DOCUMENT MT			HRS		7400		7400	3752.5
4-12-MU	INSPECTION DOCUMENT MU			MTH 09-Oct-2006 HRS 0		12000		12000	8352.5
4-12-MV	INSPECTION DOCUMENT MV			MTH 09-Oct-2006 HRS 0		9000		9000	5352.5
4-12-MW	INSPECTION DOCUMENT MW			MTH 09-Oct-2006 HRS 0		9000		9000	5352.5
4-12-MX	INSPECTION DOCUMENT MX			MTH 09-Oct-2006 HRS 0		6000		6000	2352.5
4-12-MY	INSPECTION DOCUMENT MY			MTH 09-Oct-2006 HRS 0		12000		12000	8352.5
4-12-MZ	INSPECTION DOCUMENT MZ			MTH 09-Oct-2006 HRS 0		24600		24600	20952.5



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052010B(L) LEFT	PERFORM WINDSHIELD PRISM INSPECTION	ICT		MTH HRS LDG	05-Dec-2021 3327.4 2292		24 300		31-Dec-2023 3627.4	3 m 5 d -20.1
Over Due										
052010B(R) RIGHT	PERFORM WINDSHIELD PRISM INSPECTION	ICT		MTH HRS LDG	05-Dec-2021 3327.4 2292		24 300		31-Dec-2023 3627.4	3 m 5 d -20.1
Over Due										
052300	VISUAL INSPECTION ROCKWELL COLLINS PRO LINE FUSION EDS WIRING ICA			MTH HRS LDG	27-Feb-2018 2770.4 1946		1200			
052301	AFT PRESS BULKHEAD PENETRATION ICA			MTH HRS LDG	27-Feb-2018 2770.4 1946		2500			
052302	GPS/XM ANTENNA 5000 HOURS ICA			MTH HRS LDG	27-Feb-2018 2770.4 1946		5000			
5-12-01 051201	INSPECTION DOCUMENT 1 KHMZ			MTH HRS LDG	03-Nov-2021 3317.2 2288		300		3617.2	-30.3
Over Due										
5-12-05 051205	INSPECTION DOCUMENT 5 PVU			MTH HRS LDG	03-Feb-2023 3554.1 2477		12		29-Feb-2024	5 m 3 d
B262002 CABIN 051219 : CABIN	CABIN PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK PVU			C352 Y-216193	MTH 03-Feb-2023		12		29-Feb-2024	5 m 3 d
B262002 COCKPIT 051219 : CKPT	COCKPIT PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK PVU			C352 Y-216160	MTH 03-Feb-2023		12		29-Feb-2024	5 m 3 d
B342100	CAPACITY TEST STANDBY GYRO POWER SUPPLY PS-855 (LEAD ACID) PVU			501-1712-01 80807	MTH HRS LDG		12		29-Feb-2024	5 m 3 d
5-12-06	INSPECTION DOCUMENT 6 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) KSBA			MTH HRS LDG	12-Jul-2023 3620 2528		24			
B237001	CVR RECORDER FUNCTIONAL CHECK KSBA			2100-1020-02 000390441	MTH HRS LDG		24		31-Jul-2025	22 m 5 d
5-12-07 051207	INSPECTION DOCUMENT 7 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS LDG	05-Dec-2021 3327.4 2292		36			
B236001	FUNCTIONAL CHECK STATIC DISCHARGE SYSTEM			MTH HRS LDG	05-Dec-2021 3327.4 2292		36		31-Dec-2024	15 m 5 d
5-12-08 051208	INSPECTION DOCUMENT 8 KSBA			MTH HRS LDG	14-Jun-2023 3600.2 2514		48		30-Jun-2027	45 m 4 d
5-12-09 051209	INSPECTION DOCUMENT 9 KICT			MTH HRS LDG	01-Feb-2019 2961.1 2072		72		28-Feb-2025	17 m 2 d
5-12-11 051211	INSPECTION DOCUMENT 11 KSBA			MTH HRS LDG	12-Jul-2023 3620 2528		12 300		31-Jul-2024 3920	10 m 5 d 272.5



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-12 051212	INSPECTION DOCUMENT 12	KSBA		MTH 12-Jul-2023 HRS 3620 LDG 2528		24 600		31-Jul-2025 4220	22 m 5 d 572.5
5-12-14 051214	INSPECTION DOCUMENT 14	KSBA		MTH 12-Jul-2023 HRS 3620 LDG 2528		24 1200		31-Jul-2025 4820	22 m 5 d 1172.5
5-12-16 051216	INSPECTION DOCUMENT 16	KSBA		MTH 14-Jun-2023 HRS 3600.2 LDG 2514		48 2400		30-Jun-2027 6000.2	45 m 4 d 2352.7
5-12-17 051217	INSPECTION DOCUMENT 17 (INTERVAL CFR 91.207) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			PVU					
				MTH 03-Feb-2023 HRS 3554.1 LDG 2477		12			
A256001	ELT TRANSMITTER DETAILED INSPECTION (INTERVAL CFR 91.207)	PVU	453-5060 02177	MTH 03-Feb-2023 HRS 3554.1 LDG 2477	-60	12		31-Dec-2023	3 m 5 d
B256001	OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (INTERVAL CFR 91.207)	PVU	453-5060 02177	MTH 03-Feb-2023 HRS 3554.1 LDG 2477	-60	12		31-Dec-2023	3 m 5 d
5-12-18	INSPECTION DOCUMENT 18 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			PVU					
				MTH 03-Feb-2023 HRS 3554.1 LDG 2477		24			
341055 NO. 1 051218 : L-ADC	NO. 1 AIR DATA COMPUTER CALIBRATION TEST	PVU	822-1109-014 2FW1J	MTH 01-Feb-2023		24		28-Feb-2025	17 m 2 d
341056 NO. 2 051218 : R-ADC	NO. 2 AIR DATA COMPUTER CALIBRATION TEST	PVU	822-1109-014 2FW9J	MTH 01-Feb-2023		24		28-Feb-2025	17 m 2 d
341057 STANDBY 051218 : STDBY	STANDBY AIR DATA COMPUTER CALIBRATION TEST	PVU	501-1890-04 1766	MTH 01-Feb-2023		24		28-Feb-2025	17 m 2 d
341060 051218 : RVSM	INSPECT RVSM SKIN WAVINESS	PVU		MTH 03-Feb-2023		24		28-Feb-2025	17 m 2 d
B341001 LEFT 051218 : L	FUNCTIONAL CHECK PITOT STATIC SYSTEM (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450)	PVU		MTH 01-Feb-2023		24		28-Feb-2025	17 m 2 d
B341001 RIGHT 051218 : R	FUNCTIONAL CHECK PITOT STATIC SYSTEM (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450)	PVU		MTH 01-Feb-2023		24		28-Feb-2025	17 m 2 d
B345001 NO. 1 051218 : 1	CALIBRATION CHECK TRANSPONDER (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450)	PVU	622-9201-501 2910V	MTH 01-Feb-2023		24		28-Feb-2025	17 m 2 d
B345001 NO. 2 051218 : 2	CALIBRATION CHECK TRANSPONDER (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450)	PVU	622-9210-008 2910P	MTH 01-Feb-2023		24		28-Feb-2025	17 m 2 d
5-12-22 051222	INSPECTION DOCUMENT 22	PVU		MTH 28-Jun-2022 HRS 3443 LDG 2382		36 1200		30-Jun-2025 4643	21 m 4 d 995.5
5-12-23 051223	INSPECTION DOCUMENT 23	KSBA		MTH 12-Jul-2023 HRS 3620 LDG 2528		24 300		31-Jul-2025 3920	22 m 5 d 272.5
5-12-24 051224	INSPECTION DOCUMENT 24 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 05-Mar-2021 HRS 3247.2 LDG 2241		36 1200			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
A561001	WINDSHIELD OPTICAL PRISM INSPECTION	KHMZ			MTH 05-Mar-2021 HRS 3247.2 LDG 2241		36 1200		31-Mar-2024 4447.2	6 m 5 d 799.7
5-12-29	INSPECTION DOCUMENT 29 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 09-Oct-2006 HRS 0 LDG 0		12 100			
5-12-32	INSPECTION DOCUMENT 32 (NDI INTERVAL) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 08-Oct-2018 HRS 2917.5 LDG 2043		T/C			
A324103 LEFT MAIN LANDING GEAR 051232 : L	LEFT MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)	PVU		3-1607-1 2684	MTH 28-Jun-2022 HRS 3443 LDG 2382		T/C			
A324103 NOSE LANDING GEAR 051232 : NOSE	NOSE MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)	KHMZ		3-1418 7266	MTH 31-Dec-2018 HRS 2952.5 LDG 2067		T/C			
A324103 RIGHT MAIN LANDING GEAR 051232 : R	RIGHT MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)	KHMZ		3-1607 0807	MTH 23-Apr-2020 HRS 3182.1 LDG 2192		T/C			
5-12-35	INSPECTION DOCUMENT 35 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 12-Jul-2023 HRS 3620 LDG 2528		4 200			
A243301 051235 : LEAD	CAPACITY CHECK BATTERY (LEAD ACID)	KSBA		RG-380E/44LA5 41138706	MTH 12-Jul-2023 HRS 3620 LDG 2528		4 200		30-Nov-2023 3820	2 m 4 d 172.5
5-12-38 051238	INSPECTION DOCUMENT 38 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 03-Feb-2023 HRS 3554.1 LDG 2477		6			
B342101	PS-855 (LEAD ACID) STANDBY GYRO BATTERY PACK PERIODIC TEST	PVU		501-1712-01 80807	MTH 03-Feb-2023 HRS 3554.1 LDG 2477		6		31-Aug-2023	-26 d
Over Due										
5-12-39	INSPECTION DOCUMENT 39				MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
5-12-40	INSPECTION DOCUMENT 40				MTH 31-Dec-2018 HRS 2952.5 LDG 2067		6			
5-12-41	INSPECTION DOCUMENT 41				MTH 05-May-2019 HRS 3000.7 LDG 2090 ACH 1163		500		1663	449.5
5-12-42	INSPECTION DOCUMENT 42						N/A			
5-12-43	INSPECTION DOCUMENT 43				MTH 06-Jan-2016 HRS 2243.1 LDG 1513		7200		9443.1	5795.6
052001 E1	FJ44 CHECK 1				MTH 03-Feb-2023 HRS 3554.1 LDG 2477	-36.6	300		(3817.5)3817.5	170



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052001 E2	FJ44 CHECK 1		MTH HRS 3554.1 LDG 2477	03-Feb-2023	-36.6	300		(3817.5)3817.5	170
052002 E1	FJ44 CHECK 2	KICT	MTH HRS 3222.1 LDG 2223	06-Oct-2020	-4.6	600		(3817.5)3817.5	170
052002 E2	FJ44 CHECK 2	KICT	MTH HRS 3222.1 LDG 2223	06-Oct-2020	-4.6	600		(3817.5)3817.5	170
052003 E1	FJ44 CHECK 3	KMKE	MTH HRS 2033 LDG 1264	20-Aug-2014		-			
052003 E2	FJ44 CHECK 3	MKE	MTH HRS 2033 LDG 1264	20-Aug-2014		-			
052004 E1	FJ44 CHECK 4		MTH HRS 0	09-Oct-2006		5000		(5000)5000	1352.5
052004 E2	FJ44 CHECK 4		MTH HRS 0	09-Oct-2006		5000		(5000)5000	1352.5
052005 E1	FJ44 CHECK 5		MTH HRS 0	09-Oct-2006		8000		(8000)8000	4352.5
052005 E2	FJ44 CHECK 5		MTH HRS 0	09-Oct-2006		8000		(8000)8000	4352.5
052006 E1	FJ44 CHECK 6		MTH HRS 0	09-Oct-2006		10000		(10000)10000	6352.5
052006 E2	FJ44 CHECK 6		MTH HRS 0	09-Oct-2006		10000		(10000)10000	6352.5
052007 E1	FJ44 CHECK 7		MTH HRS 0	09-Oct-2006		13000		(13000)13000	9352.5
052007 E2	FJ44 CHECK 7		MTH HRS 0	09-Oct-2006		13000		(13000)13000	9352.5
052008 E1	FJ44 CHECK 8		MTH HRS 0	09-Oct-2006		15000		(15000)15000	11352.5
052008 E2	FJ44 CHECK 8		MTH HRS 0	09-Oct-2006		15000		(15000)15000	11352.5
052009 E1	FJ44 CHECK 9		MTH HRS 0	09-Oct-2006		18000		(18000)18000	14352.5
052009 E2	FJ44 CHECK 9		MTH HRS 0	09-Oct-2006		18000		(18000)18000	14352.5
052010 E1	FJ44 CHECK 10		MTH HRS 0	09-Oct-2006		20000		(20000)20000	16352.5
052010 E2	FJ44 CHECK 10		MTH HRS 0	09-Oct-2006		20000		(20000)20000	16352.5
12-23-00-601	15 DAY HIGH EXPOSURE AREA WASH -AIRPLANE ZONE 1 WASH		DAYS			15			
12-23-00-602	45 DAY MEDIUM EXPOSURE AREA WASH -AIRPLANE ZONE 2 WASH		DAYS			45			
12-23-00-603	90 DAY LOW EXPOSURE AREA WASH -AIRPLANE ZONE 3 WASH		DAYS			90			
215018	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES ICT		MTH HRS 2562.3 LDG 1807 ACH 976.3	01-Jun-2017		800		1776.3	562.8



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262002A LEFT ENGINE NO.1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 14-Jul-2021		72		31-Jul-2027	46 m 5 d
262002A LEFT ENGINE NO.2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 14-Jul-2021		72		31-Jul-2027	46 m 5 d
262002A RIGHT ENGINE NO.1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 14-Jul-2021		72		31-Jul-2027	46 m 5 d
262002A RIGHT ENGINE NO.2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 14-Jul-2021		72		31-Jul-2027	46 m 5 d
262002B LEFT ENGINE NO.1	REPLACE LEFT ENGINE NO.1 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 01-Apr-2020		72		01-Apr-2026	30 m 6 d
262002B LEFT ENGINE NO.2	REPLACE LEFT ENGINE NO. 2 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 01-Apr-2020		72		01-Apr-2026	30 m 6 d
262002B RIGHT ENGINE NO.1	REPLACE RIGHT ENGINE NO.1 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 01-Apr-2020		72		01-Apr-2026	30 m 6 d
262002B RIGHT ENGINE NO.2	REPLACE RIGHT ENGINE NO.2 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KHMZ		13083-5 SN-UNKNOWN	MTH 01-Apr-2020		72		01-Apr-2026	30 m 6 d
A262002 CABIN <i>051209 : CABIN</i>	CABIN PORTABLE FIRE EXTINGUISHER SPECIAL DETAILED INSPECTION	KHMZ		C352 Y-216193	MTH 07-Dec-2020		72		31-Dec-2026	39 m 5 d
A262002 COCKPIT <i>051209 : CKPT</i>	COCKPIT PORTABLE FIRE EXTINGUISHER SPECIAL DETAILED INSPECTION	KHMZ		C352 Y-216160	MTH 07-Dec-2020		72		31-Dec-2026	39 m 5 d
D262001 LEFT <i>051220 : L</i>	LEFT ENGINE FIRE EXTINGUISHER BOTTLE RESTORATION (HYDROSTATIC TEST)	KHMZ		30401102-2 81948B1	MTH 06-May-2021		60		31-May-2026	32 m 5 d
D262001 RIGHT <i>051220 : R</i>	RIGHT ENGINE FIRE EXTINGUISHER BOTTLE RESTORATION (HYDROSTATIC TEST)	KHMZ		9912048-6 81949B1	MTH 06-May-2021		60		31-May-2026	32 m 5 d
D262003 CABIN <i>051210 : CABIN</i>	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER	*CF		C352 Y-216193	MTH 15-Dec-2012		144		31-Dec-2024	15 m 5 d
D262003 COCKPIT <i>051210 : CKPT</i>	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER			C352 Y-216160	MTH 15-Dec-2012 HRS 1564.1 LDG 931		144		31-Dec-2024	15 m 5 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)	KHMZ			MTH 04-May-2020 HRS 3182.1 LDG 2192		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH		A/R			
312001A LEFT	REPLACE DIGITAL CLOCK BATTERY	KSBA		M877A5V 12159	MTH 14-Jun-2023 HRS 3600.2 LDG 2514	-24	12		31-May-2024	8 m 5 d
B323101 <i>051207 : GEAR</i>	HYDROSTATIC TEST EMERGENCY PNEUMATIC STORAGE BOTTLE	PVU		40005320-2 4639	MTH 16-Jun-2022		36		30-Jun-2025	21 m 4 d
33-50-00-960 LEFT	AFT LEFT EMERGENCY LIGHTING BATTERY PACK RESTORATION			CBS28-1 4377M	MTH 28-Jun-2022 HRS 3443 LDG 2382		48		30-Jun-2026	33 m 4 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
33-50-00-960 RIGHT	FORWARD RIGHT EMERGENCY LIGHTING BATTERY PACK RESTORATION			CBS28-1 3900M	MTH 28-Jun-2022 HRS 3443 LDG 2382		48		30-Jun-2026	33 m 4 d
B351002 051225 : OXY	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER AND REGULATOR ASSEMBLY	KHMZ		176276-50 1102701901	MTH 01-May-2021		60		31-May-2026	32 m 5 d
571050 LEFT WING 045709	INSPECT MAIN SPAR, WS 183.50 *CF				MTH 09-Oct-2006 HRS 0	1	10000		10001	6353.5
571055 RIGHT WING 045709	INSPECT MAIN SPAR, WS 183.50 *CF				MTH 09-Oct-2006 HRS 0	1	10000		10001	6353.5
571080 LEFT WING 045705	INSPECT MAIN SPAR SPLICE, WS 132.00 *CF				MTH 09-Oct-2006 HRS 0	1	9500		9501	5853.5
571085 RIGHT WING 045705	INSPECT MAIN SPAR SPLICE, WS 132.00 *CF				MTH 09-Oct-2006 HRS 0	1	9500		9501	5853.5
712003 LEFT ENGINE AFT	LEFT ENGINE AFT ISOLATOR MOUNT (INSPECTION)			LM-605-SA11 LK1912	MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
712003 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK0403	MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
712003 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK0556	MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
712003 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT (INSPECTION)			LM-605-SA10 LK1905	MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
712003 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK0546	MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
712003 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK0524	MTH 09-Oct-2006 HRS 0		5000		5000	1352.5
710003 E1	RINSE DESALINIZATION	KHMZ			MTH 02-Jun-2021 HRS 3268.2 LDG 2260		A/R			
710003 E2	RINSE DESALINIZATION	KHMZ			MTH 02-Jun-2021 HRS 3268.2 LDG 2260		A/R			
710030 E1	POLISH FAN ROTOR				MTH 09-Oct-2006		A/R			
710030 E2	POLISH FAN ROTOR				MTH 09-Oct-2006		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211001 LEFT	PRESS SHUTOFF VALVE KICT			5253-00-3 3405B	MTH 27-Feb-2020 HRS 3172.5 LDG 2186		O/C	1 0 0		
211001 RIGHT	PRESS SHUTOFF VALVE KICT			5253-00-3 5314B	MTH 09-Sep-2019 HRS 3088.7 LDG 2140		O/C	0 0 0		
211002 LEFT	VARIABLE VALVE KIWA			2601-32 291	MTH 10-Jan-2012 HRS 1307.7 LDG 758		O/C			
211002 RIGHT	VARIABLE VALVE KIWA			2601-32 0288	MTH 10-Jan-2012 HRS 1307.7 LDG 758		O/C			
211003	HEAT PRESS EXCHANGER *CF			10905A 182	MTH 09-Oct-2006		O/C			
211005	EMER PRESS SHUTOFF VALVE 9912422-2 *CF			2601-23 0686	MTH 09-Oct-2006		O/C			
211006 NO.1	A/C CHECK VALVE 9912078-9 *CF			7125-320101 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
211006 NO.2	A/C CHECK VALVE 9912078-9 *CF			7125-320101 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
211006 NO.3	A/C CHECK VALVE 9912078-9 *CF			7125-320101 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
212001	BAGGAGE CMPT BLOWER *CF			0113-12 1039	MTH 09-Oct-2006		O/C			
212003	THERMO AIR DIST SWITCH ICT			1173T42-1 3973	MTH 08-Feb-2009 HRS 570		O/C	0		
212302	W/S AIR BLOWER MOTOR *CF			7003-200 1250	MTH 09-Oct-2006		O/C			
212303	BLDC MOTOR ASSEMBLY BLOWER			1133270-2 SN-UNKNOWN	MTH 09-Oct-2006		O/C	0		
213001	PRIMARY OUTFLOW VALVE 9912409-21 MCO			52771-339 858B	MTH 18-Jul-2011 HRS 1189.9 LDG 682		O/C	3 0 0		
213002	SEC OUTFLOW VALVE 9912409-22 *CF			52772-339 918B	MTH 09-Oct-2006		O/C			
213003	PRESSURIZATION CONTROLLER 9912409-13 *CF			52770-116 2493	MTH 09-Oct-2006		O/C			
213004 NO.1	SOLENOID BAGGAGE VALVE *CF			5060-00-1 3252	MTH 09-Oct-2006		O/C			
213004 NO.2	SOLENOID BAGGAGE VALVE *CF			5060-00-1 3190	MTH 09-Oct-2006		O/C			
213005	DIFF PRESS INDICATOR 3001J73 *CF			C668511-0106 23515	MTH 09-Oct-2006		O/C			
213008	MANUAL PRESSURE SWITCH 9912409-4 *CF			52773-001 1921	MTH 09-Oct-2006		O/C			
215000 AFT	EVAPORATOR BLOWER MOTOR MYF			1133210-7 0710	MTH 11-Jul-2008 ACH 155		O/C	0		
215000 FWD	EVAPORATOR BLOWER MOTOR KCOS			1260185-1 2223	MTH 05-Sep-2019 HRS 3087.6 LDG 2139		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0110**
 Unit: **0110** Reg No: **N716NS**
 Airworthiness: **09-Oct-2006**
 Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215001	FWD EVAPORATOR MODULE 9912583-9	IWA		1134300-3 919	MTH 08-Apr-2011 HRS 1130.4 LDG 643		O/C	1 0 0		
215002	AFT EVAPORATOR MODULE 9912583-10	LGB		1134820-15 383	MTH 04-Oct-2007 ACH 97		O/C	0		
215003	COMPRESSOR DRIVE MOTOR *CF			1134146-1 624A	MTH 09-Oct-2006		O/C			
215004	COMPRESSOR DRIVE ASSEMBLY 9912583-6	*CF		1134610-1 521	MTH 09-Oct-2006		O/C			
215005	CONDENSER ASSEMBLY 9912583-7	*CF		1134620-3 535	MTH 09-Oct-2006		O/C			
215006	BINARY SWITCH	IWA		1250232-10 1249	MTH 15-Nov-2010 HRS 996.7 LDG 564		O/C	0 0 0		
215007	DRYER ASSY RECEIVER 9912583-3	*CF		1134275-1 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
215008	COMPRESSOR ASSEMBLY *CF			1134130-5 527	MTH 09-Oct-2006		O/C			
215009	VANE AXIAL BLOWER ASSY KICT			1250435-10 1052	MTH 06-May-2019 HRS 3001.1 LDG 2091		O/C	0 0 0		
215010	A/C FLIGHT HOURMETER *CF			1250703-3 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
215011	AIR CONDITIONER DRIVE BELT *CF			225L100 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
216001	RAM AIR MOD VALVE KICT			27241287-24 11BA87	MTH 01-Feb-2019 HRS 2961.1 LDG 2072		O/C	0 0 0		
216002	TEMP CONTROLLER	ICT		1E58-7 2BE2	MTH 28-Apr-2010 HRS 891.7 LDG 500		O/C	0 0		
216003 AFT	CABIN TC007 SENSOR 9912085-3	ICT		27221274 12BB639	MTH 04-May-2007 HRS 150		O/C	0		
216003 FORWARD	COCKPIT UT006 SENSOR 9912085-3	*CF		27221274 6BB303	MTH 09-Oct-2006		O/C			
221002 AILERON	SERVO MOUNT SMT-65	*CF	1	622-5735-021 293YG	MTH 09-Oct-2006		O/C			
221002 ELEVATOR	SERVO MOUNT	*CF	1	622-5735-023 2945L	MTH 09-Oct-2006		O/C			
221002 RUDDER	SERVO MOUNT SMT-65	*CF	1	622-5735-022 293XJ	MTH 09-Oct-2006		O/C			
221003 AILERON	SERVO SVO-3000	*CF	2	822-1168-002 281TN	MTH 09-Oct-2006		O/C			
221003 ELEVATOR	SERVO SVO-3000	KICT	2	822-1168-001 294GW	MTH 26-Apr-2016 HRS 2284.6 LDG 1564		O/C	0 0 0		
221003 RUDDER	SERVO SVO-3000	*CF	2	822-1168-001 281TB	MTH 09-Oct-2006		O/C			
221004	AUTOPILOT PANEL	*CF	08	622-6208-223 27RDN	MTH 09-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0110**
 Unit: **0110** Reg No: **N716NS**
 Airworthiness: **09-Oct-2006**
 Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
230090	AEROWAVE BIAS-T --	KSDL		89000015-008 5123	MTH 28-Oct-2016 HRS 2403.7		O/C	0 0		
230091	AEROWAVE ACTIVE LGA ANTENNA	KSDL		89000015-009 5119	MTH 28-Oct-2016 HRS 2403.7		O/C	0 0		
230092	AEROWAVE HDU --	KSDL		90402045 351	MTH 28-Oct-2016 HRS 2403.7		O/C	0 0		
230093	AEROWAVE ESCM --	KSDL		1252-A-4120-01 958	MTH 28-Oct-2016 HRS 2403.7		O/C	0 0		
230094	AEROWAVE ROUTER --	KSDL		89000015-005 141	MTH 28-Oct-2016 HRS 2403.7		O/C	0 0		
231002	SWITCH AUDIO	KSDL		2TL1-2 NSN	MTH 31-Oct-2017 HRS 2687		O/C			
231006 NO.1	VHF COMM TRANSCEIVER VHF-4000	*CF		822-1468-102 26J7M	MTH 09-Oct-2006		O/C			
231006 NO.2	VHF COMM TRANSCEIVER VHF-4000	*CF		822-1468-102 277YF	MTH 09-Oct-2006		O/C			
231007 NO.1	COMM ANTENNA	KICT		VC10-126-1 0952	MTH 31-May-2018 HRS 2829.4 LDG 1987		O/C	0 0 0		
231007 NO.2	COMM ANTENNA	*CF		VFS10-90-2 5932	MTH 09-Oct-2006		O/C			
231012	AIRTEXT IRIDIUM PAXX TEXTING UNIT			15G25-2 20309	MTH 28-Jun-2022 HRS 3452.5 LDG 2389		O/C	0 0 0		
231013	IRIDIUM ANTENNA			S67-1575-409 904-2998	MTH 28-Jun-2022		O/C	0		
232007	AIRCELL FLITEFONE HANDSET --	KMYF		310-10595-002 1059511316	MTH 28-Mar-2016 HRS 2261 LDG 1548		O/C			
232009	SAT COM ANTENNA	*CF		15-10306-001 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
232011	AIRCRAFT PERSONALITY MODULE	LNK		822-2195-001 4D9252	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
235001	AUDIO AMPLIFIER	ICT		102025-2 1280806	MTH 23-Oct-2006 HRS 12		O/C	0		
235068 NO.1 345068 : 1	AUDIO CONTROL PANEL RADIO	KMYF		822-1861-230 1NTMR	MTH 02-Oct-2012 HRS 1449 LDG 855		O/C			
235068 NO.2 345068 : 2	AUDIO CONTROL PANEL RADIO	KMYF		822-1861-230 292VT	MTH 02-Oct-2012 HRS 1449 LDG 855		O/C			
237000	CVR LOCATOR BEACON			DK120 DR7697	MTH 29-Nov-2018 HRS 2937 LDG 2059		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
237000A	CVR LOCATOR BEACON BATTERY DK120 CODE B & D			810-2007/K SN-UNKNOWN	MTH 29-Nov-2018 HRS 2937 LDG 2059		72		31-Dec-2024	15 m 5 d
237001	CVR RECORDER	*CF	07	2100-1020-02 000390441	MTH 09-Oct-2006		O/C			
237002	CVR CONTROLLER	*CF	04	S251-1120-00 000391604	MTH 09-Oct-2006		O/C			
237003	CVR MICROPHONE	*CF		S055-0067-00 000387311	MTH 09-Oct-2006		O/C			
237004	IMPACT CVR SWITCH	*CF		6895-D-2-X-5-5 5916	MTH 09-Oct-2006		O/C			
243003 LEFT	GENERATOR CONTROL UNIT ICT			51525-001F P2346	MTH 24-Apr-2012 HRS 1401.4 LDG 822		O/C	1401.4 822		
243003 RIGHT	GENERATOR CONTROL UNIT ICT			51525-001F P2559	MTH 24-Apr-2012 HRS 1401.4 LDG 822		O/C	1401.4 822		
243004	BATTERY TEMP MONITOR- *CF			1529-1-1 4595	MTH 09-Oct-2006		O/C			
243006 LEFT	GEN LOAD AMMETER C662501-0107	SEE		MD130-7 E0611636	MTH 09-May-2012 HRS 1409.4 LDG 830		O/C	1409.4 830		
243006 RIGHT	GEN LOAD AMMETER C662501-0107	SEE		MD130-7 E0610544	MTH 09-May-2012 HRS 1409.4 LDG 830		O/C	1409.4 830		
243007	BATTERY S3597-8	KSBA		RG-380E/44LA5 41138706	MTH 12-Jul-2023 HRS 3620 LDG 2528		O/C			
243008	RELAY-BATTERY	*CF		A931F 39251	MTH 09-Oct-2006		O/C			
243011	DC POWER VOLTMETER C662502-0101	*CF		MD129-1 G0610096	MTH 09-Oct-2006		O/C			
245001 LEFT	START CONTROL PCB	LGB		6318038-1 0493	MTH 01-Aug-2007 HRS 219		O/C	0		
245001 RIGHT	START CONTROL PCB	*CF		6318038-1 0306	MTH 09-Oct-2006		O/C			
245002 LEFT	FUEL CONTROL PCB	*CF		6318037-6 0217	MTH 09-Oct-2006		O/C			
245002 RIGHT	FUEL CONTROL PCB	LGB		6318037-6 383	MTH 19-Sep-2007 HRS 243		O/C	0		
245003 LEFT	IGNITOR CNTRL PCB	*CF		6318396-6 215	MTH 09-Oct-2006		O/C			
245003 RIGHT	IGNITOR CNTRL PCB	*CF		6318396-6 216	MTH 09-Oct-2006		O/C			
245004 LEFT	ANTI ICE PCB	*CF		6318342-29 0338	MTH 09-Oct-2006		O/C			
245004 RIGHT	ANTI ICE PCB	*CF		6318342-29 0339	MTH 09-Oct-2006		O/C			
245006	ENVIRONMENTAL PCB ICT			6318358-15 0266	MTH 04-May-2007 HRS 150		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245007	HYDRAULIC PCB	*CF		6318035-7 154	MTH 09-Oct-2006		O/C			
245008	TRIM RELAY PCB	*CF		6518351-9 0718	MTH 09-Oct-2006		O/C			
245010	GEAR LOGIC 1 PCB	*CF		6318398-6 0159A	MTH 09-Oct-2006		O/C			
245011	FUEL FLOW PCB 9912417-3	*CF		85-230-2 0416136A	MTH 09-Oct-2006		O/C			
245012	SPEEDBRAKE PCB	*CF		6318034-6 0155	MTH 09-Oct-2006		O/C			
245014	GEAR LOGIC 2 PCB	*CF		6318399-11 0160A	MTH 09-Oct-2006		O/C			
245015	GEAR MONITOR PCB	KMYF		6318397-21 0564	MTH 15-Nov-2011 HRS 1272 LDG 734		O/C	0 0 0		
245016	TAIL DEICE CONTROL PCB	*CF		6318044-1 215	MTH 09-Oct-2006		O/C			
245017	TAIL DEICE MONITOR PCB	*CF		6318043-1 217B	MTH 09-Oct-2006		O/C			
245018	PRESSURIZATION PCB	DSH		6318349-15 0512	MTH 24-Jul-2012 HRS 1479 LDG 872		O/C	0 0 0		
245020	DETECTOR-OVERVOLTAGE	*CF		1645-1-3 3963	MTH 09-Oct-2006		O/C			
254098	TOILET MOTOR AND PUMP ASSEMBLY	KSDL		17200-382 10750	MTH 15-May-2021 HRS 3261.7 LDG 2256		O/C	0 0 0		
256001	ELT TRANSMITTER C406-N	LNK		453-5060 02177	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	2770.4 1946		
256002	ELT BEACON BATTERY PACK	KHMZ		452-0133 383251-019	MTH 14-Feb-2020 HRS 3168.2 LDG 2183		DUE DUE DUE DUE	0 0 0	30-Nov-2024	14 m 4 d
256003	REMOTE SWITCH	*CF		452-0010 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
256004	ELT ANTENNA C406-N	*CF		110-340 129413	MTH 09-Oct-2006		O/C			
256006 CO-PILOT	LIFE JACKET	KHMZ		P01074-207 970596	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										
256006 LAVATORY	LIFE JACKET --	KHMZ		P01074-207 20100440068	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		16-Oct-2030	84 m 20 d
256006 NO. 1	LIFE JACKET	KHMZ		P01074-207 970542	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256006 NO. 2	LIFE JACKET	KHMZ		P01074-207 970519	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										
256006 NO. 3	LIFE JACKET	KHMZ		P01074-207 970580	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										
256006 NO. 4	LIFE JACKET	KHMZ		P01074-207 970556	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										
256006 NO. 5	LIFE JACKET	KHMZ		P01074-207 970506	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										
256006 NO. 6	LIFE JACKET	KHMZ		P01074-207 970617	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										
256006 PILOT	LIFE JACKET	KHMZ		P01074-207 970551	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		09-Jul-2028	57 m 13 d
Expiration Date: 09-Jul-2028										
256006	SFS LIFE JACKET --	KHMZ		P01074-207 970515	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		DUE DUE DUE DUE		16-Oct-2030	84 m 20 d
261001 LEFT	ENGINE FIRE DETECTOR 9912416-1	*CF		3001-212-1004/455-9 207083	MTH 09-Oct-2006		O/C			
261001 RIGHT	ENGINE FIRE DETECTOR 9912416-1	*CF		3001-212-1004/455-9 207172	MTH 09-Oct-2006		O/C			
261002 AFT	SMOKE DETECTOR	*CF		473597-17 1009	MTH 09-Oct-2006		O/C			
261002 FORWARD	SMOKE DETECTOR	*CF		473597-17 1045	MTH 09-Oct-2006		O/C			
262001 LEFT	FIRE EXTINGUISHER BOTTLE 9912048-6	KHMZ		30401102-2 81948B1	MTH 14-Jul-2021 HRS 3277.3 LDG 2267		O/C	2 0 0		
262001 RIGHT	FIRE EXTINGUISHER BOTTLE KHMZ			9912048-6 81949B1	MTH 14-Jul-2021 HRS 3277.3 LDG 2267		O/C	2 0 0		
262002 LEFT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE KHMZ			13083-5 SN-UNKNOWN	MTH 14-Jul-2021 HRS 3277.3 LDG 2267		H/T H/T H/T H/T	14 0 0 0		
262002 LEFT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE KHMZ			13083-5 SN-UNKNOWN	MTH 14-Jul-2021 HRS 3277.3 LDG 2267		H/T H/T H/T H/T	14 0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
262002 RIGHT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE KHMZ	13083-5 SN-UNKNOWN	MTH 14-Jul-2021 HRS 3277.3 LDG 2267		H/T H/T H/T H/T	14 0 0 0		
262002 RIGHT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE KHMZ	13083-5 SN-UNKNOWN	MTH 14-Jul-2021 HRS 3277.3 LDG 2267		H/T H/T H/T H/T	14 0 0 0		
262003 CABIN	PORTABLE FIRE EXTINGUISHER UNK	C352 Y-216193	MTH 08-Oct-2019 HRS 3094.6 LDG 2147		O/C			
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER UNK	C352 Y-216160	MTH 08-Oct-2019 HRS 3094.6 LDG 2147		O/C			
270001 LEFT	SPEED BRAKE FILTER FITTING *CF	20666-6-250 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
270001 RIGHT	SPEED BRAKE FILTER FITTING *CF	20666-6-250 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
272001	RUDDER BIAS SHUTOFF VALVE *CF	5307-1 0932C	MTH 09-Oct-2006		O/C			
273001	CONTROL SHAKER *CF	201 7016	MTH 09-Oct-2006		O/C			
273002	ELEV TRIM SERVO *CF	4 44430-3548 T1129	MTH 09-Oct-2006		O/C			
273003	ACTUATOR MOUNT ASSEMBLY *CF	44575-3415 T1889	MTH 09-Oct-2006		O/C			
275001	SHUTOFF VALVE *CF	4083-1 604	MTH 09-Oct-2006		O/C			
275002 LEFT	FLAP ACTUATOR 9912365-6	*CF 2-8210-2 AA271P618	MTH 09-Oct-2006		O/C			
275002 RIGHT	FLAP ACTUATOR 9912365-6	*CF 2-8210-2 AA270P618	MTH 09-Oct-2006		O/C			
276001 LEFT	SPEED BRAKE ACTUATOR 9912375-5	*CF 2-8209-2 AAA252P617	MTH 09-Oct-2006		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912375-5	*CF 2-8209-2 AAA244P617	MTH 09-Oct-2006		O/C			
281001 LEFT	SURGE TANK FLOAT VALVE 9912016-2	*CF 35C10D 3671	MTH 09-Oct-2006		O/C			
281001 RIGHT	SURGE TANK FLOAT VALVE 9912016-2	*CF 35C10D 3614	MTH 09-Oct-2006		O/C			
282001 LEFT	FUEL BOOST PUMP 9912553-1	*CF 1C7-23 5BB74	MTH 09-Oct-2006		O/C			
282001 RIGHT	FUEL BOOST PUMP 9912553-1	*CF 1C7-23 5BB59	MTH 09-Oct-2006		O/C			
282002 LEFT AFT	EJECTOR FUEL AFT/SCAVENG PUMP 9912190-3	*CF RG45880 B1762	MTH 09-Oct-2006		O/C			
282002 LEFT FORWARD	EJECTOR FUEL FWD/SCAVENG PUMP 9912190-3	*CF RG45880 B1757	MTH 09-Oct-2006		O/C			
282002 RIGHT AFT	EJECTOR FUEL AFT/SCAVENG PUMP 9912190-3	*CF RG45880 B1768	MTH 09-Oct-2006		O/C			
282002 RIGHT FORWARD	EJECTOR FUEL FWD/SCAVENG PUMP 9912190-3	*CF RG45880 B1759	MTH 09-Oct-2006		O/C			
282004 LEFT	FUEL MOTOR VALVE 9912014-3	*CF EM9014-3 N/A	MTH 09-Oct-2006		O/C			
282004 RIGHT	FUEL MOTOR VALVE 9912014-3	*CF AV24B1507 AA80212	MTH 09-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0110**
 Unit: **0110** Reg No: **N716NS**
 Airworthiness: **09-Oct-2006**
 Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282005 LEFT	EJECTOR FUEL PRIMARY PUMP 9912190-2	*CF		RG45310 B9776	MTH 09-Oct-2006		O/C			
282005 RIGHT	EJECTOR FUEL PRIMARY PUMP 9912190-2	*CF		RG45310 B9780	MTH 09-Oct-2006		O/C			
282006	TRANSFER VALVE 9914103-6	*CF		ZSV57 06042614	MTH 09-Oct-2006		O/C			
284003	FUEL QTY SIGNAL CONDITIONER 9912619-1	*CF		10713B01Y01 06040218	MTH 09-Oct-2006		O/C			
284004 LEFT	#3 UL003 FUEL PROBE 9912589-3	*CF		10664T03Y00 MN03189	MTH 09-Oct-2006		O/C			
284004 RIGHT	#3 UR003 FUEL PROBE 9912589-3	*CF		10664T03Y00 MN02629	MTH 09-Oct-2006		O/C			
284005 LEFT	#4 UL004 FUEL PROBE 9912589-4	*CF		10664T04Y00 MN03430	MTH 09-Oct-2006		O/C			
284005 RIGHT	#4 UR004 FUEL PROBE 9912589-4	*CF		10664T04Y00 MN02920	MTH 09-Oct-2006		O/C			
284006 LEFT	#2 UL002 FUEL PROBE 9912589-2	*CF		10664T02Y00 MN03180	MTH 09-Oct-2006		O/C			
284006 RIGHT	#2 UR002 FUEL PROBE 9912589-2	*CF		10664T02Y00 MN03359	MTH 09-Oct-2006		O/C			
284007 LEFT	#1 UL001 FUEL PROBE 9912589-1	*CF		10664T01Y00 MN03367	MTH 09-Oct-2006		O/C			
284007 RIGHT	#1 UR001 FUEL PROBE 9912589-1	*CF		10664T01Y00 MN03365	MTH 09-Oct-2006		O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH 9912589-1	*CF		L16H-9 1560	MTH 09-Oct-2006		O/C			
284008 RIGHT	FUEL LOW LEVEL SWITCH KIWA			L16H-14 2181	MTH 15-Jan-2013 HRS 1569.8 LDG 936		O/C	0 0 0		
284010 LEFT	FUEL QUANTITY TRANSMITTER 9912556-6	*CF		10634T11Y00 MN03128	MTH 09-Oct-2006		O/C			
284010 RIGHT	FUEL QUANTITY TRANSMITTER 9912556-6	*CF		10634T11Y00 MN03130	MTH 09-Oct-2006		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 911	MTH 09-Oct-2006		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-6	SEE		24195-LAC 2168	MTH 13-Jan-2010 HRS 827		O/C	0		
291005	HYDRAULIC RESERVOIR ASSEMBLY 9912423-39	*CF		6317500-16 150	MTH 09-Oct-2006		O/C			
291006	LOADING VALVE 9912423-39	*CF		4134-4 0483M	MTH 09-Oct-2006		O/C			
291007	PRESSURE SWITCH GAUGE 9912373-4	*CF		GPP1250-58 0617805	MTH 09-Oct-2006		O/C			
291008	HYD MANIFOLD ASSEMBLY 9912423-47	*CF		8250-2 0196	MTH 09-Oct-2006		O/C			
291010 LEFT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 AA73729	MTH 09-Oct-2006		O/C			
291010 RIGHT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 AA75807	MTH 09-Oct-2006		O/C			
291011 LEFT	FLOW SWITCH VALVE 9912194-2	*CF		V10F14 1484	MTH 09-Oct-2006		O/C			
291011 RIGHT	FLOW SWITCH VALVE 9912194-2	HMZ		V10F14 403	MTH 20-Jul-2010 HRS 942.6 LDG 528		O/C	0 0 0		
291012	SPDBK DUMP VALVE 9912423-33	*CF		4082-6 630	MTH 09-Oct-2006		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291013	RELIEF, SYSTEM VALVE 9912423-46	ICT		2576-2 674C	MTH 02-Sep-2011 HRS 1225.4 LDG 700		O/C			
291014	VALVE-GEAR 9912423-44	*CF		4051-4 594	MTH 09-Oct-2006		O/C			
291016 LEFT	SPDBK CHECK VALVE 9912423-31	*CF		9505-1 1244	MTH 09-Oct-2006		O/C			
291016 RIGHT	SPDBK CHECK VALVE 9912423-31	*CF		9505-1 1245	MTH 09-Oct-2006		O/C			
291017	THERM REL VALVE 9912423-32	*CF		2577-1 640	MTH 09-Oct-2006		O/C			
291018	PNEUMATIC DUMP VALVE 9912423-34	*CF		9503-2 628	MTH 09-Oct-2006		O/C			
291020	SPEED BRAKE VALVE 9912423-30	*CF		4052-3 630	MTH 09-Oct-2006		O/C			
291021	FLAP VALVE 9912423-29	*CF		4052-4 633	MTH 09-Oct-2006		O/C			
291022	CHECK VALVE	*CF		CV02-193 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
291023	GEAR VALVE SOLENOID	*CF		4051-4 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
301002 LEFT	PRESSURE SWITCH	*CF		1106P55-1 3958A	MTH 09-Oct-2006		O/C			
301002 RIGHT	PRESSURE SWITCH	*CF		1106P55-1 3947A	MTH 09-Oct-2006		O/C			
301003 LEFT	ANTI-ICE PRESSURE REGULATING VALVE 9914710-3	*CF		1H148-1 5BB69	MTH 09-Oct-2006		O/C			
301003 RIGHT	ANTI-ICE PRESSURE REGULATING VALVE 9914710-3	*CF		1H148-1 6BB76	MTH 09-Oct-2006		O/C			
301004 LEFT	TEMPERATURE SWITCH	*CF		1050C F9307	MTH 09-Oct-2006		O/C			
301004 RIGHT	TEMPERATURE SWITCH	*CF		1050C F9299	MTH 09-Oct-2006		O/C			
301006 LEFT	HORIZONTAL STAB BOOT KICT			P25S-4D5244-15 NET3400	MTH 05-May-2019 HRS 3000.7 LDG 2090		O/C	0 0 0		
301006 RIGHT	HORIZONTAL STAB BOOT	*CF		29S-4D5244-16 MYLT050	MTH 09-Oct-2006		O/C			
301007	ENG BLEED SHUTOFF VALVE 9914552-2	*CF		2602-43 127	MTH 09-Oct-2006		O/C			
302001 LEFT	PRESS REG VALVE	*CF		5285-00-3 0869	MTH 09-Oct-2006		O/C			
302001 RIGHT	PRESS REG VALVE	*CF		5285-00-3 0860	MTH 09-Oct-2006		O/C			
302002 LEFT	INLET TEMP SWITCH	*CF		1173T0759 3545	MTH 09-Oct-2006		O/C			
302002 RIGHT	INLET TEMP SWITCH	*CF		1173T0759 3494	MTH 09-Oct-2006		O/C			
303002 LEFT	PITOT TUBE	*CF		PH1100-1-VBW C4199	MTH 09-Oct-2006		O/C			
303002 RIGHT	PITOT TUBE	*CF		PH1100-1-VBW C4784	MTH 09-Oct-2006		O/C			
303003 STANDBY	PITOT TUBE S2800-493	*CF		PH1100 C4479	MTH 09-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
304001	B/A TEMP MONITOR-			1169-1 3857	MTH 09-Oct-2006		O/C			
		*CF								
304002	HEAT EXCHANGER	*CF		10653A 9912041-3 1717	MTH 09-Oct-2006		O/C			
304003	PRESS REG VALVE	KIWA		1962-00-3 9912402-14 0679	MTH 08-Jan-2017 HRS 2448.4 LDG 1715		O/C			
304004 AFT	FLOORBD TF006 SENSOR	*CF		27221274 9912085-3 6BB339	MTH 09-Oct-2006		O/C			
304004 FORWARD	T/C TT002 SENSOR	*CF		27221274 9912085-3 6BB344	MTH 09-Oct-2006		O/C			
304005	TEMP CONTROLLER	*CF		1E58-1 9912085-6 2BB67	MTH 09-Oct-2006		O/C			
304006	TEMP CONTROL VALVE	*CF		27241287 9912085-1 7BA57	MTH 09-Oct-2006		O/C			
304007	ALCOHOL PUMP	*CF		476411E SN-UNKNOWN	MTH 09-Oct-2006		O/C			
304008 LEFT	W/S BLEED AIR VALVE	*CF		1403-25 BYLB50168 4177	MTH 09-Oct-2006		O/C			
304008 RIGHT	W/S BLEED AIR VALVE	*CF		1403-25 BYLB50168 4185	MTH 09-Oct-2006		O/C			
304009	PRESSURE SWITCH	*CF		1115P25 4349AB	MTH 09-Oct-2006		O/C			
304010 LEFT	T2 HEAT CURRENT SENSOR	*CF		76796-2 1415	MTH 09-Oct-2006		O/C			
304010 RIGHT	T2 HEAT CURRENT SENSOR	*CF		76796-2 1413	MTH 09-Oct-2006		O/C			
304011 LEFT	SOLENOID DEICE VALVE	*CF		3D2353-06 N062226	MTH 09-Oct-2006		O/C			
304011 RIGHT	SOLENOID DEICE VALVE	*CF		3D2353-06 N062419	MTH 09-Oct-2006		O/C			
312001 LEFT	DIGITAL CLOCK			M877A5V 12159	MTH 21-May-2019 HRS 3011.7 LDG 2097		O/C			
313001	FLIGHT HOURMETER	*CF		C664503-0104 85071 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
315002	ANNUNCIATOR PANEL	ICT		9912618-5 618000226	MTH 14-Aug-2007 HRS 223		O/C	223		
32-10-00-960 LEFT MAIN LANDING GEAR 321003 : L	LEFT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD	*CF		6341321-1 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		15000	0	15000	12454
32-10-00-960 RIGHT MAIN LANDING GEAR 321004 : R	RIGHT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD	*CF		6341321-2 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		15000	0	15000	12454
32-10-00-961 LEFT MAIN LANDING GEAR 321010 : L	LEFT TRAILING LINK AND AXLE ASSEMBLY DISCARD	*CF		6341341-1 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		15000	0	15000	12454
32-10-00-961 RIGHT MAIN LANDING GEAR 321010 : R	RIGHT TRAILING LINK AND AXLE ASSEMBLY DISCARD	*CF		6341341-2 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		15000	0	15000	12454



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
32-10-00-962 LEFT MAIN LANDING GEAR <i>321005 : L</i>	LEFT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD KICT			6341301-16 218	MTH 01-Feb-2019 HRS 2961.1 LDG 2072		15000	2072	15000	12454
32-10-00-962 RIGHT MAIN LANDING GEAR <i>321005 : R</i>	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD KICT			6341301-16 217	MTH 01-Feb-2019 HRS 2961.1 LDG 2072		15000	2072	15000	12454
32-20-00-960 NOSE LANDING GEAR <i>322005</i>	NOSE LANDING GEAR STRUT ASSEMBLY DISCARD *CF			6342350-6 93	MTH 09-Oct-2006 LDG 0		22500	0	22500	19954
32-20-00-961 NOSE LANDING GEAR <i>322004</i>	NOSE LANDING GEAR FORK AND PISTON ASSEMBLY DISCARD *CF			6342350-4 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		12500	0	12500	9954
32-31-01-960 NOSE LANDING GEAR <i>323004</i>	NOSE LANDING GEAR ACTUATOR ASSEMBLY DISCARD 9912370-7 *CF			2-8208-2 0097	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
32-31-02-960 LEFT MAIN LANDING GEAR <i>323001 : L</i>	LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD 9912573-3 *CF			2-8207-1 1210	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
32-31-02-960 RIGHT MAIN LANDING GEAR <i>323001 : R</i>	RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD 9912573-4 KICT			2-8207-2 0211	MTH 09-Sep-2019 HRS 3088.7 LDG 2140		12000	3000.7 2190	11950	9404
321001 LEFT	MAIN LANDING GEAR *CF			6341350-3 109	MTH 09-Oct-2006		O/C			
321001 RIGHT	MAIN LANDING GEAR *CF			6341350-4 109	MTH 09-Oct-2006		O/C			
321011 <i>321010</i>	ANTISKID CONTROL VALVE 9912621-3 *CF			39-913 221	MTH 09-Oct-2006		O/C			
322001 NOSE LANDING GEAR	SHIMMY DAMPER *CF			6343001-10 137	MTH 09-Oct-2006		O/C			
322002	NOSE LANDING GEAR ASSEMBLY *CF			6342350-5 -	MTH 09-Oct-2006		O/C			
322003	NLG FORK *CF			5542300-1 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
322006	NLG CYLINDER BRAZE ASSEMBLY *CF			5542100-3 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
323002 LEFT	UPLOCK MAIN GEAR *CF			6327504-6 1308	MTH 09-Oct-2006		O/C			
323002 RIGHT	UPLOCK MAIN GEAR *CF			6327504-6 1288	MTH 09-Oct-2006		O/C			
323005	NOSE LANDING GEAR UPLOCK ACTUATOR *CF			6327504-7 651	MTH 09-Oct-2006		O/C			
323006	HYD SHUTTLE VALVE *CF			98312 0875	MTH 09-Oct-2006		O/C			
323007 NO.1	SHUTTLE, REGEN VALVE 9914689-2 *CF			5128-6 213	MTH 09-Oct-2006		O/C			
323007 NO.2	SHUTTLE, REGEN VALVE 9914689-2 *CF			5128-6 244	MTH 09-Oct-2006		O/C			
323020	EMERGENCY PNEUMATIC STORAGE BOTTLE 9912368-2 PVU			40005320-2 4639	MTH 28-Jun-2022 HRS 3443 LDG 2382		288	199	31-Oct-2029	73 m 5 d

Manufacture Date: 01-Oct-2005

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323021	EMER GEAR BOTTLE GAUGE *CF			19940932-1 020533	MTH 09-Oct-2006		O/C			
324001 LEFT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912561-5	PVU		3-1607-1 2684	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C			
324001 RIGHT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912561-4	PVU		3-1607 0807	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C			
324002 NOSE LANDING GEAR	WHEEL ASSEMBLY 9912622-1	PVU		3-1418 7266	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C	42 490.5 315		
324003 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR TIRE 9912622-1	PVU		026-618-0 1203P00078	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C	0 0 0		
324003 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR TIRE 9912622-1	KSBA		026-618-0 3144P00001	MTH 12-Jul-2023 HRS 3620 LDG 2528		O/C	0 0 0		
324004 NOSE LANDING GEAR	TIRE 9914070-1	PVU		031-613-8 1236T00420	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C	0 0 0		
324005 LEFT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912617-2	KHMZ		2-1695 1089	MTH 31-Oct-2019 HRS 3109 LDG 2154		O/C	0 0 0		
324005 RIGHT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912617-2	KHMZ		2-1695 0251	MTH 31-Oct-2019 HRS 3109 LDG 2154		O/C	0 0 0		
324101	BRK ANTISKID/METERING VALVE 9912621-2 *CF			32-107-1 222	MTH 09-Oct-2006		O/C			
324102 LEFT	ANTISKID TRANSDUCER 9912305-2 *CF			40-955 7806	MTH 09-Oct-2006		O/C			
324102 RIGHT	ANTISKID TRANSDUCER 9912305-2 *CF			40-955 7814	MTH 09-Oct-2006		O/C			
324103	DIG ANTISKID CNTRL BOX 9912621-1 *CF			142-103 225	MTH 09-Oct-2006		O/C			
324104	BRAKE PRESSURE SWITCH *CF			GPP1250-69 0343T	MTH 09-Oct-2006		O/C			
324105	PARKING BRAKE VALVE 9912388-1 *CF			95853 1152A	MTH 09-Oct-2006		O/C			
324106	HYDRAULIC PUMP MOTOR *CF			MP50B1 3347	MTH 09-Oct-2006		O/C			
324107	BRAKE ANTISKID ACCUMULATOR *CF			57C57663 0617117	MTH 09-Oct-2006		O/C			
324108	LOW PRESSURE SWITCH *CF			GPP1250-79 0618133	MTH 09-Oct-2006		O/C			
324109	BRAKE PRESSURE PUMP 9912364-2 *CF			640929 1934	MTH 09-Oct-2006		O/C			
324110	EMERGENCY BRAKE VALVE 9912387-3 ICT			878208-03 V345	MTH 04-Dec-2006 HRS 40		O/C	0		
324111	FAULT DISPLAY UNIT 9912305-9 *CF			42-92750 1825A	MTH 09-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324113	THERMAL RELIEF VALVE *CF	1785-3 0134	MTH 09-Oct-2006		O/C			
324204	BRAKE HYDRAULIC PACK ASSEMBLY FILTER ELEMENT DISCARD (REPLACE) TASK# 32-42-05-960 ICT	9912372-1 N/A	MTH 05-Dec-2021 HRS 3327.4 LDG 2292		36 1200	0 0 0	31-Dec-2024 4527.4	15 m 5 d 879.9
324205	BRAKE RESERVOIR AIR FILTER AND BRAKE RESERVOIR SUPPLY LINE FILTER DISCARD (REPLACE) TASK# 32-42-04-960 ICT	AN6237-1 NSN	MTH 05-Dec-2021 HRS 3327.4 LDG 2292		36 1200	0 0 0	31-Dec-2024 4527.4	15 m 5 d 879.9
326001 LEFT	MLG UPLOCK SWITCH *CF	65-430087 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
326001 NOSE	NLG UPLOCK SWITCH *CF	65-430087 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
326001 RIGHT	MLG UPLOCK SWITCH *CF	65-430087 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
331001 LEFT	LIGHT UB001 DIMMER *CF	273-1 206190456	MTH 09-Oct-2006		O/C			
331001 RIGHT	LIGHT UB002 DIMMER *CF	273-1 206190455	MTH 09-Oct-2006		O/C			
331002	EL PANEL INVERTER *CF	EM2044-1 5205A	MTH 09-Oct-2006		O/C			
331003	INDIRECT LIGHTING CONTROL BOX *CF	CLC500-01 500000985	MTH 09-Oct-2006		O/C			
334001	GROUND REC LIGHT *CF	90033-13 016873	MTH 09-Oct-2006		O/C			
334002	PULSE LIGHT CONTROL *CF	2401C TR855	MTH 09-Oct-2006		O/C			
334003 LEFT	COLLISION POWER SUPPLY KIWA	04-1502-1408 28866013	MTH 08-Jan-2017 HRS 2448.4 LDG 1715		O/C	0 0 0		
334003 RIGHT	COLLISION POWER SUPPLY *CF	04-1502-1408 26623	MTH 09-Oct-2006		O/C			
334004 LEFT	LANDING LAMP HOUSING *CF	50033025-1 1974	MTH 09-Oct-2006		O/C			
334004 RIGHT	LANDING LAMP HOUSING *CF	50033025-1 1961	MTH 09-Oct-2006		O/C			
334005 LEFT	ANTI-COLLISION LIGHT ASSEMBLY KSDL	03-1302-1003 37871	MTH 17-Jan-2017 HRS 2461.1 LDG 1722		O/C	0 0 0		
334005 RIGHT	ANTI-COLLISION LIGHT ASSEMBLY *CF	03-1302-1004 27233	MTH 09-Oct-2006		O/C			
334006 LEFT	FLOOD TAIL LIGHT ASSEMBLY *CF	01-0770966-00 014730A	MTH 09-Oct-2006		O/C			
335000 LEFT	AFT LEFT EMERGENCY LIGHTING BATTERY PACK PVU	CBS28-1 4377M	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C			
335000 RIGHT	FORWARD RIGHT EMERGENCY LIGHTING BATTERY PACK PVU	CBS28-1 3900M	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C			
341099	COPILOT TILT KNOB -- LNK	822-3163-020 4DKFK1	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
341001 NO. 1	AIR DATA COMPUTER ADC-3000	KMYF		822-1109-014 2FW1J	MTH 29-May-2015 HRS 2174.3 LDG 1406		O/C	0 0 0		
341001 NO. 2	AIR DATA COMPUTER ADC-3000	KMYF		822-1109-014 2FW9J	MTH 14-Jan-2016 HRS 2244.3 LDG 1515		O/C	0 0 0		
341001 STANDBY	AIR DATA COMPUTER ADC-3000	*CF		501-1890-04 1766	MTH 09-Oct-2006		O/C			
341003	AOA INDEXER	*CF		C12463-3 557	MTH 09-Oct-2006		O/C			
341004	AOA COMPUTER	*CF		C-13406-1 502	MTH 09-Oct-2006		O/C			
341006	AOA INDICATOR	*CF		C12405-1 83343	MTH 09-Oct-2006		O/C			
341007	AOA SENSOR	*CF		C-12717-1 1716	MTH 09-Oct-2006		O/C			
341008	BAROMETRIC SWITCH	IWA		GBC300-82 0744554	MTH 15-Nov-2010 HRS 996.7 LDG 564		O/C	0 0 0		
341010 AFT	RADIO ALT ANTENNA	*CF		S67-2002 54337549	MTH 09-Oct-2006		O/C			
341010 FORWARD	RADIO ALT ANTENNA	*CF		S67-2002 54337550	MTH 09-Oct-2006		O/C			
341030	TEMP PROBE SENSOR	*CF		0129G A65496	MTH 09-Oct-2006		O/C			
341034	RADIO ALT TRANSMITTER ALT-4000	MYF	09	822-0615-206 1286N	MTH 19-Dec-2019 HRS 3129.7 LDG 2166		O/C	0 0 0		
341098	PILOT BARO KNOB --	LNK		822-3163-010 4DKH2L	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
341098	COPILOT BARO KNOB --	LNK		822-3163-010 4DKH2M	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
341099	COPILOT BARO KNOB --	LNK		822-3163-020 4DKFK0	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
341099	PILOT TILT KNOB --			822-3163-020 4DKFK0	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
341101	IAPS CARD CAGE	LNK		822-2191-001 4CX731	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
341103 NO.1	CONFIG CNTRL STRAPPING UNIT	*CF		822-1363-002 28NRC	MTH 09-Oct-2006		O/C			
341103 NO.2	CONFIG CNTRL STRAPPING UNIT			822-1363-002 28NRD	MTH 09-Oct-2006		O/C	0		
341199	IMS-3500 --	LNK		822-299-201 4C6R4K	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342002 LEFT	AHRS COMPUTER AHC-3000	*CF	03	822-1110-002 26PPW	MTH 09-Oct-2006		O/C			
342002 RIGHT	AHRS COMPUTER AHC-3000	MYF	03	822-1110-002 49FMG6	MTH 07-Dec-2018 HRS 2946.2 LDG 2064		O/C			
342005 LEFT	FLT GUIDANCE COMPUTER *CF		01	822-1108-033 28GPD	MTH 09-Oct-2006		O/C			
342005 RIGHT	FLT GUIDANCE COMPUTER *CF		01	822-1108-033 28GPF	MTH 09-Oct-2006		O/C			
342006 LEFT	FLUX DETECTOR UNIT FDU-3000	*CF		822-1193-001 35103	MTH 09-Oct-2006		O/C			
342006 RIGHT	FLUX DETECTOR UNIT FDU-3000	*CF		822-1193-001 35088	MTH 09-Oct-2006		O/C			
342007 LEFT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 28M3L	MTH 09-Oct-2006		O/C			
342007 RIGHT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 28M3K	MTH 09-Oct-2006		O/C			
342008 LEFT	IAPS POWER SUPPLY PWR-3000	*CF	06	822-1137-001 29VNW	MTH 09-Oct-2006		O/C			
342008 RIGHT	IAPS POWER SUPPLY PWR-3000	*CF	06	822-1137-001 29VNR	MTH 09-Oct-2006		O/C			
342009	ENVIRONMENTAL CONTROL IEC-3001	*CF	03	822-1167-001 28P3Y	MTH 09-Oct-2006		O/C			
342010 LEFT	OPER CONFIG MODULE IWA			822-1484-228 3N3VB	MTH 15-Nov-2010 HRS 996.7 LDG 564		O/C	0 0 0		
342010 RIGHT	OPER CONFIG MODULE IWA			822-1484-228 3N3VV	MTH 15-Nov-2010 HRS 996.7 LDG 564		O/C	0 0 0		
342011 LEFT	I/O CONCENTRATOR IAPS MODULE IOC-4100	LNK	05	822-2065-001 4CX6V3	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
342011 RIGHT	I/O CONCENTRATOR IAPS MODULE IOC-4100	LNK	05	822-2065-001 4CX80L	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
342011	DETACHABLE CONFIG MODULE *CF			501-1803-153 1862	MTH 09-Oct-2006		O/C			
342031	STANDBY GYRO POWER SUPPLY PS-855A	PVU	08	501-1712-01 80807	MTH 03-Feb-2023 HRS 3554.1 LDG 2477		O/C			
342032	SECONDARY FLIGHT DISPLAY GH-3000	LGB		501-1741-2103 1357	MTH 19-Sep-2007 HRS 243		O/C	883		
342055 LEFT	DATA CONCENTRATOR UNIT DCU-3001	*CF		822-1483-250 27C6J	MTH 09-Oct-2006		O/C			
342055 RIGHT	DATA CONCENTRATOR UNIT DCU-3001	*CF		822-1483-250 27C7Y	MTH 09-Oct-2006		O/C			
342056 LEFT	AFD CONTROL DISPLAY PANEL LNK			822-2754-010 4DKH30	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342056 RIGHT	AFD CONTROL DISPLAY PANEL LNK			822-2754-010 4DKH2X	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
342301 LEFT	MODE SELECTOR KMYF	14		622-6209-020 23XBK	MTH 25-Sep-2014 HRS 2076.9 LDG 1291		O/C	0 0 0		
342301 RIGHT	MODE SELECTOR *CF	14		622-6209-020 28Y9T	MTH 09-Oct-2006		O/C			
342301	COURSE/HEADING PANEL MYF	01		822-1279-002 2FX7L	MTH 11-Nov-2011 HRS 1272 LDG 734		O/C	0 0 0		
342302 CENTER	ADAPTIVE FLIGHT DISPLAY			822-3065-001 4DC1HN	MTH 04-Oct-2018 HRS 2914.3 LDG 2042		O/C			
342302 LEFT	ADAPTIVE FLIGHT DISPLAY UNK			822-3065-001 4CVF81	MTH 13-Aug-2018 HRS 2886.1 LDG 2020		O/C			
342302 RIGHT	ADAPTIVE FLIGHT DISPLAY			822-3065-001 4CVF88	MTH 12-Sep-2018 HRS 2899.3 LDG 2032		O/C			
342303	COURSE PANEL CKP-3000	*CF	01	822-1281-002 27RGB	MTH 09-Oct-2006		O/C			
342304 CENTER	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY *CF			822-1140-101 29HTY	MTH 09-Oct-2006		O/C			
342304 LEFT	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY *CF			822-1140-101 29HVG	MTH 09-Oct-2006		O/C			
342304 RIGHT	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY *CF			822-1140-101 29HVB	MTH 09-Oct-2006		O/C			
343001	MARKER BEACON ANTENNA *CF			MB10-754 0344	MTH 09-Oct-2006		O/C			
343002	DUAL GLIDESLOPE COUPLER *CF			82-70-01 1762	MTH 09-Oct-2006		O/C			
343003	GLIDESLOPE ANTENNA *CF			44-70-01 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
344001	EGPWS COMPUTER MARK(V111) HONEYWELL	*CF	02	965-1206-011 5064	MTH 09-Oct-2006		O/C			
344002	WEATHER RADAR REC/XMTR ANTENNA RTA-852	*CF	38	622-8439-004 279DB	MTH 09-Oct-2006		O/C			
344011	STORMSCOPE PROCESSOR WX-1000E	ICT		78-8060-6086-5 JFP01100860	MTH 04-May-2007 HRS 150		O/C	2092		
344012	STORMSCOPE ANTENNA WX-1000E	ICT		78-8051-9200-8 81543	MTH 04-May-2007 HRS 150		O/C	0		
344013	SATELLITE DATALINK WT ANTENNA XMA-1000	*CF		822-2030-001 292LM	MTH 09-Oct-2006		O/C			
344014	SATELLITE DATALNK WT RECEIVER XMWR-1000	*CF		822-2031-002 292JC	MTH 09-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0110**
 Unit: **0110** Reg No: **N716NS**
 Airworthiness: **09-Oct-2006**
 Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345001 NO.1	FORWARD DME ANTENNA *CF			DMNI50-2-2 107887	MTH 09-Oct-2006		O/C			
345001 NO.2	AFT DME ANTENNA 85226	*CF		DMNI50-2-2 107474	MTH 09-Oct-2006		O/C			
345002 NO.1	LEFT DME TRANSCEIVER DME-4000	*CF	03	822-1466-001 26J9G	MTH 09-Oct-2006		O/C			
345002 NO.2	RIGHT DME TRANSCEIVER DME-4000	*CF	03	822-1466-001 26J9Y	MTH 09-Oct-2006		O/C			
345005 LEFT	NAVIGATION ANTENNA *CF			VT11-767-3 0353	MTH 09-Oct-2006		O/C			
345005 RIGHT	NAVIGATION ANTENNA *CF			VT11-767-3 0352	MTH 09-Oct-2006		O/C			
345020 NO.1	ADF 1 ANTENNA *CF			622-7383-101 28PML	MTH 09-Oct-2006		O/C			
345040 LEFT	DIVERSITY TRANSPONDER ANTENNA *CF			DMNI50-2-2 107885	MTH 09-Oct-2006		O/C			
345040 NO.1	TRANSPONDER ANTENNA *CF			DMNI50-2-2 108022	MTH 09-Oct-2006		O/C			
345040 NO.2	TRANSPONDER ANTENNA *CF			DMNI50-2-2 108017	MTH 09-Oct-2006		O/C			
345040 RIGHT	DIVERSITY TRANSPONDER ANTENNA *CF			DMNI50-2-2 107481	MTH 09-Oct-2006		O/C			
345041 NO. 1	TRANSPONDER PVU	27		622-9201-501 2910V	MTH 28-Jun-2022 HRS 3443 LDG 2382		O/C			
345041 NO. 2	TRANSPONDER TDR-94D	*CF	27	622-9210-008 2910P	MTH 09-Oct-2006		O/C			
345050	FMS GPS DISPLAY GPS-500	LNK	07	011-00562-10 45700194	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C			
345051 NO. 1	FMS GPS ANTENNA LNK			S67-1575-145 824-5048	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
345051 NO. 3	FMS-GPS ANTENNA LNK			CI 429-200 560966	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
345051	IRIDIUM/GPS PASSIVE ANTENNA IRIDIUM	KSDL		S67-1575-109 7427	MTH 06-Oct-2017 HRS 2666.6		O/C		2337.6	
345056 NO.1	GPS RECEIVER		4	822-2189-101 26WXX	MTH 27-Aug-2020 HRS 3215.7 LDG 2218		O/C	0 0 0		
345056 NO.2	GPS RECEIVER			822-2189-101 26WXP	MTH 27-Aug-2020 HRS 3215.7 LDG 2218		O/C	0 0 0		
345057 NO. 1	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4000	*CF	01	822-1465-001 278JM	MTH 09-Oct-2006		O/C			
345057 NO. 2	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4500	*CF	01	822-1579-001 29PXH	MTH 09-Oct-2006		O/C			
345061	TCAS PROCESSOR LNK		11	822-1294-032 153371	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
345062 BOTTOM	TCAS II ANTENNA *CF	622-8973-001 25GLD	MTH 09-Oct-2006		O/C			
345062 TOP	TCAS II ANTENNA *CF	622-8973-001 25GKV	MTH 09-Oct-2006		O/C			
345065	EXTERNAL - FSU COMPENSATION UNIT ECU-3000 *CF	822-1200-998 28M0D	MTH 09-Oct-2006		O/C			
345066	FSU UNIT *CF	822-1543-101 2B7B	MTH 09-Oct-2006		O/C			
345067 NO.1	RADIO INTERFACE UNIT RIU-4110 *CF	822-1864-002 278LV	MTH 09-Oct-2006		O/C			
345067 NO.2	RADIO INTERFACE UNIT RIU-4110 *CF	822-1864-002 278LV	MTH 09-Oct-2006		O/C			
345099	MULTIFUNCTION KEY PANEL UNK	822-2568-01 44XH5F	MTH 05-Oct-2018 HRS 2914.3 LDG 2042		O/C	0 0 0		
346023	CONTROLLER-CABIN BRIEF -- *CF	PBS250-2G5 252001659	MTH 09-Oct-2006		O/C			
346050	E.L. PANEL	9912631-9 002	MTH 28-Jun-2022 HRS 3452.5 LDG 2389		O/C			
346099 L/H	CURSOR CONTROL PANEL LNK	822-2754-010 4DKH30	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		O/C	0 0 0		
346099 R/H	CURSOR CONTROL PANEL MYF	822-2754-010 45C68Y	MTH 08-Mar-2018 HRS 2787.2 LDG 1954		O/C	0 0 0		
350005	OXYGEN REGULATOR *CF	172270-01 0902	MTH 09-Oct-2006		O/C			
350006	OXYGEN CYLINDER DOT E-10945 KHMZ	176276-50 1102701901	MTH 06-Aug-2021 HRS 3283.6 LDG 2270		180		30-Apr-2036	151 m 4 d
Manufacture Date: 13-Apr-2021								
350007	OXYGEN PRESSURE GAGE MD-97 *CF	C668512-0101 D0611151	MTH 09-Oct-2006		O/C			
351001	OXYGEN CONTROL VALVE *CF	P21007 1892	MTH 09-Oct-2006		O/C			
351002 COPILOT	OXYGEN MASK 9914067-41	MC10-16-101 119489	MTH 21-Aug-2018		72	0	31-Aug-2024	11 m 5 d
351002 PILOT	OXYGEN MASK 9914067-41	MC10-16-101 119636	MTH 24-Aug-2018		72	0	31-Aug-2024	11 m 5 d
361001 LEFT	PRECOOL TEMP SENSOR 9912584-3 *CF	27431501-10 5BB114	MTH 09-Oct-2006		O/C			
361001 RIGHT	PRECOOL TEMP SENSOR 9912584-3 *CF	27431501-10 5BB115	MTH 09-Oct-2006		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY LNK	9912624-1 T1619	MTH 16-Mar-2020 HRS 3178.9 LDG 2190		3200	0 0 0	6378.9	2731.4
361002 RIGHT	B/A PRECOOLER ASSEMBLY 9912624-1 LNK	8292-1 T1620	MTH 16-Mar-2020 HRS 3178.9 LDG 2190		3200	0 0 0	6378.9	2731.4
361003 LEFT	MODULATING VALVE 9912584-1 *CF	1H139-1 5BB41	MTH 09-Oct-2006		O/C			
361003 RIGHT	MODULATING VALVE 9912584-2 *CF	1H139-2 6BB48	MTH 09-Oct-2006		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
361005	PRESSURE SWITCH	*CF		P18M30 4102	MTH 09-Oct-2006		O/C			
361006 LEFT	OVERTEMP SWITCH 9914149-2	*CF		1173T181-2 5232	MTH 09-Oct-2006		O/C			
361006 RIGHT	OVERTEMP SWITCH 9914149-2	*CF		1173T181-2 5235	MTH 09-Oct-2006		O/C			
361007	B/A PRESSURE REGULATOR 9912510-1	*CF		1H75-18 6BB100	MTH 09-Oct-2006		O/C			
522001	INFLATABLE DOOR SEAL 9912075-4	*CF		S15501-4 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
53-00-00-960 NOSE LANDING GEAR 531003	NOSE LANDING GEAR ACTUATOR FITTING DISCARD	*CF		6511105-1 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		23900	0	23900	21354
53-00-00-961 LEFT NOSE LANDING GEAR 531004 : L	LEFT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD	*CF		5513056-7 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
53-00-00-961 RIGHT NOSE LANDING GEAR 531004 : R	RIGHT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD	*CF		5513056-8 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
530000	RADOME ASSEMBLY	KICT		6313101-847-1 732	MTH 31-May-2018 HRS 2829.4 LDG 1987		O/C			
561001 LEFT	LEFT WINDSHIELD ASSEMBLY 9912064-15	*CF		P00042-1 886	MTH 09-Oct-2006		O/C			
561001 RIGHT	RIGHT WINDSHIELD ASSEMBLY 9912064-16	*CF		93200-16 1552	MTH 09-Oct-2006		O/C			
561002 CABIN DOOR	WINDOW 9912207-8	*CF		93105-8 5248	MTH 09-Oct-2006		O/C			
561002 LEFT NO. 2	CABIN WINDOW 9912207-8	*CF		93105-8 5373	MTH 09-Oct-2006		O/C			
561002 LEFT NO. 3	CABIN WINDOW 9912207-8	*CF		93105-8 5411	MTH 09-Oct-2006		O/C			
561002 LEFT NO. 4	CABIN WINDOW 9912207-8	*CF		93105-8 5426	MTH 09-Oct-2006		O/C			
561002 LEFT NO. 5	CABIN WINDOW 9912207-8	*CF		93105-8 5179	MTH 09-Oct-2006		O/C			
561002 LEFT NO. 6	CABIN WINDOW 9912207-8	*CF		93105-8 4241	MTH 09-Oct-2006		O/C			
561002 LEFT NO. 7	CABIN WINDOW 9912207-8	*CF		93105-8 4234	MTH 09-Oct-2006		O/C			
561002 RIGHT NO. 1	CABIN WINDOW 9912207-8	*CF		93105-8 5371	MTH 09-Oct-2006		O/C			
561002 RIGHT NO. 2	CABIN WINDOW 9912207-8	*CF		93105-8 5365	MTH 09-Oct-2006		O/C			
561002 RIGHT NO. 3	CABIN WINDOW 9912207-8	*CF		93105-8 5363	MTH 09-Oct-2006		O/C			
561002 RIGHT NO. 4	CABIN WINDOW 9912207-8	*CF		93105-8 5362	MTH 09-Oct-2006		O/C			
561002 RIGHT NO. 5	CABIN WINDOW 9912207-8	*CF		93105-8 5343	MTH 09-Oct-2006		O/C			
561002 RIGHT NO. 6	CABIN WINDOW 9912207-8	*CF		93105-8 5464	MTH 09-Oct-2006		O/C			
561002 RIGHT NO. 7	CABIN WINDOW 9912207-8	*CF		93105-8 5341	MTH 09-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561003 COPILOT <i>561004 : R</i>	SIDE WINDOW	*CF		6311263-2 0923	MTH 09-Oct-2006		O/C			
561003 PILOT	SIDE WINDOW	*CF		6311263-1 0969	MTH 09-Oct-2006		O/C			
57-00-00-960 LEFT MAIN GEAR <i>571001 : L</i>	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD	*CF		6341324-1 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		15000	0	15000	12454
57-00-00-960 RIGHT MAIN GEAR <i>571001 : R</i>	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD	*CF		6341324-2 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		15000	0	15000	12454
57-00-00-961 LEFT MAIN LANDING GEAR AFT <i>571002 : L</i>	LEFT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD	*CF		6341326-5 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
57-00-00-961 LEFT MAIN LANDING GEAR FORWARD <i>571003 : L</i>	LEFT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD	*CF		6341325-1 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
57-00-00-961 RIGHT MAIN LANDING GEAR AFT <i>571002 : R</i>	RIGHT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD	*CF		6341326-6 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
57-00-00-961 RIGHT MAIN LANDING GEAR FORWARD <i>571003 : R</i>	RIGHT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD	*CF		6341325-2 SN-UNKNOWN	MTH 09-Oct-2006 LDG 0		12000	0	12000	9454
712002 LEFT ENGINE AFT <i>710001 : E1**L</i>	LEFT ENGINE AFT ISOLATOR MOUNT (OVERHAUL)	*CF		9912623-7 LM-605-SA11 LK1912	MTH 09-Oct-2006 HRS 0		8000	0	8000	4352.5
712002 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL)	*CF		9912623-6 LM-605-SA8 LK0403	MTH 09-Oct-2006 HRS 0		8000	0	8000	4352.5
712002 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL)	*CF		9912623-6 LM-605-SA8 LK0556	MTH 09-Oct-2006 HRS 0		8000	0	8000	4352.5
712002 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT (OVERHAUL)	*CF		9912623-8 LM-605-SA10 LK1905	MTH 09-Oct-2006 HRS 0		8000	0	8000	4352.5
712002 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL)	*CF		9912623-6 LM-605-SA8 LK0546	MTH 09-Oct-2006 HRS 0		8000	0	8000	4352.5
712002 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL)	*CF		9912623-6 LM-605-SA8 LK0524	MTH 09-Oct-2006 HRS 0		8000	0	8000	4352.5
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE FJ44-3A/9912614-1	*CF		67000-200 141227	MTH 09-Oct-2006		E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE FJ44-3A/9912614-1	*CF		67000-200 141228	MTH 09-Oct-2006		E/C			
720001 E1	FAN ROTOR	*CF		72036 AU21256	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
720001 E2	FAN ROTOR	*CF		72036 AU21256	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720002 E1	IP COMPRESSOR ROTOR *CF			69026 HW21364	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
720002 E2	IP COMPRESSOR ROTOR *CF			69026 HW21354	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
720003 E1	COMPLETE LP SHAFT ASSEMBLY *CF			66919 RX06RP293	MTH 09-Oct-2006		O/C			
720003 E2	COMPLETE LP SHAFT ASSEMBLY *CF			66919 RX06RP290	MTH 09-Oct-2006		O/C			
720004 E1	HIGH PRESSURE SHAFT *CF			64711 RX5RT818	MTH 09-Oct-2006		O/C			
720004 E2	HIGH PRESSURE SHAFT *CF			64711 RX5RT803	MTH 09-Oct-2006		O/C			
720005 E1	HP COMPRESSOR COVER *CF			69885 AU20106	MTH 09-Oct-2006		O/C			
720005 E2	HP COMPRESSOR COVER *CF			69885 AU20088	MTH 09-Oct-2006		O/C			
720006 E1	DIFFUSER CASE ASSEMBLY ICT			116099 AU20016	MTH 29-Aug-2010 HRS 963.5 LDG 540		O/C			
720006 E2	DIFFUSER CASE ASSEMBLY UNK			117777 AU21005	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	565.4 516		
720007 E1	1ST STAGE LP TURBINE NOZZLE UNK			114444 AU21261	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2033 1459		
720007 E2	1ST STAGE LP TURBINE NOZZLE ICT			114444 AU20838	MTH 01-Sep-2011 HRS 1225.4 LDG 700		O/C	2014.5 2609		
720008 E1	ACCESS DRIVE GEARBOX *CF			72715 AU20132	MTH 09-Oct-2006		O/C			
720008 E2	ACCESS DRIVE GEARBOX *CF			72715 AU20131	MTH 09-Oct-2006		O/C			
720015 E1	BALANCE PISTON UNK			115094 AU20848	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
720020 E1	COMBUSTOR MODULE ASSEMBLY UNK			116723 AU20969	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2022.9 1501		
720020 E2	COMBUSTOR MODULE ASSEMBLY UNK			116723 AU20590	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2018.2 1707		
722010 E1	IP (STAGE 1 & 2) VANE ASSEMBLY UNK			115569 AU20593	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	3908.7 3059		
722010 E2	IP (STAGE 1 & 2) VANE ASSEMBLY UNK			115569 AU20594	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	3908.7 3059		
723155 E1	1ST REDUCTION BEVEL GEAR SUPPORT BEARING UNK			120672 AU21228	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	592.7 583		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
723155 E2	1ST REDUCTION BEVEL GEAR SUPPORT BEARING	UNK		120672 AU20407	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2011.3 1458		
723165 E1	DEEP GROOVE-103 BALL BEARING	UNK		78321 JT-109502	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
723165 E2	DEEP GROOVE-103 BALL BEARING	UNK		78321 JT-109508	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
723170 E1	SPLIT INNER RING BALL BEARING	UNK		118017 JT-107843	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
723170 E2	SPLIT INNER RING BALL BEARING	UNK		118017 JT-107840	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
724035 E1	HP TURBINE COMBUSTER ASSEMBLY	UNK		113636 AU20969	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2022.9 1501		
724035 E2	HP TURBINE COMBUSTER ASSEMBLY	UNK		113636 AU20590	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2018.2 1707		
725101 E1	HP COMPRESSOR ROTOR	*CF		66055 HW21081	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
725101 E2	HP COMPRESSOR ROTOR	*CF		66055 HW21565	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
725102 E1	HP TURBINE ROTOR	UNK		111414 HW29566	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2022.9 1501		
725102 E2	HP TURBINE ROTOR	UNK		111414 HW25793	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	2022.8 1958		
725103 E1	HP TURBINE DISK	UNK		67093 HW29566	MTH 18-Aug-2014 HRS 2033 LDG 1264		8000	2022.9 1501	(7763)7763	5217
725103 E2	HP TURBINE DISK	UNK		67093 HW25793	MTH 18-Aug-2014 HRS 2033 LDG 1264		8000	2022.8 1958	(7306)7306	4760
725201 E1 NO.1	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725201 E2 NO.1	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725202 E1 NO.2	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725202 E2 NO.2	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725203 E1 NO.3	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725203 E2 NO.3	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725204 E1 NO.4	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725204 E2 NO.4	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725205 E1 NO.5	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725205 E2 NO.5	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725206 E1 NO.6	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725206 E2 NO.6	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725207 E1 NO.7	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725207 E2 NO.7	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725208 E1 NO.8	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725208 E2 NO.8	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725209 E1 NO.9	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725209 E2 NO.9	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725210 E1 NO.10	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725210 E2 NO.10	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725211 E1 NO.11	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725211 E2 NO.11	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725212 E1 NO.12	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725212 E2 NO.12	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725213 E1 NO.13	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725213 E2 NO.13	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725214 E1 NO.14	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725214 E2 NO.14	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725215 E1 NO.15	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725215 E2 NO.15	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725216 E1 NO.16	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725216 E2 NO.16	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725217 E1 NO.17	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725217 E2 NO.17	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725218 E1 NO.18	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725218 E2 NO.18	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725219 E1 NO.19	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725219 E2 NO.19	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725220 E1 NO.20	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725220 E2 NO.20	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725221 E1 NO.21	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725221 E2 NO.21	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725222 E1 NO.22	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725222 E2 NO.22	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725223 E1 NO.23	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725223 E2 NO.23	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725224 E1 NO.24	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725224 E2 NO.24	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code	Description		Part Number		C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
725225 E1 NO.25	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725225 E2 NO.25	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725226 E1 NO.26	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725226 E2 NO.26	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725227 E1 NO.27	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725227 E2 NO.27	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725228 E1 NO.28	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725228 E2 NO.28	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725229 E1 NO.29	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725229 E2 NO.29	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725230 E1 NO.30	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725230 E2 NO.30	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725231 E1 NO.31	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725231 E2 NO.31	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725232 E1 NO.32	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725232 E2 NO.32	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725233 E1 NO.33	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725233 E2 NO.33	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725234 E1 NO.34	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725234 E2 NO.34	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725235 E1 NO.35	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725235 E2 NO.35	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725236 E1 NO.36	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725236 E2 NO.36	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725237 E1 NO.37	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725237 E2 NO.37	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725238 E1 NO.38	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725238 E2 NO.38	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725239 E1 NO.39	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725239 E2 NO.39	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725240 E1 NO.40	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725240 E2 NO.40	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725241 E1 NO.41	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725241 E2 NO.41	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725242 E1 NO.42	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725242 E2 NO.42	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725243 E1 NO.43	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725243 E2 NO.43	HP TURBINE BLADE	UNK		78282 SN-UNKNOWN	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
725501 E1	1ST LP TURBINE DISK	*CF		72037 HW20898	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
725501 E2	1ST LP TURBINE DISK	*CF		72037 HW20885	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
725502 E1	2ND LP TURBINE DISK	*CF		66993 HW20635	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
725502 E2	2ND LP TURBINE DISK	*CF		66993 HW20618	MTH 09-Oct-2006 LDG 0		10000	0	(10000)10000	7454
726011 E1	ACCESSORY DRIVE GEARBOX HOUSING			ASSEMBLY PN SN-UNKNOWN	MTH 09-Oct-2006		O/C	0		
726011 E2	ACCESSORY DRIVE GEARBOX HOUSING			ASSEMBLY PN SN-UNKNOWN	MTH 09-Oct-2006		O/C	0		
726030 E1	CARBON FACE SEAL ASSEMBLY	UNK		68937 TX991E4	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
726030 E2	CARBON FACE SEAL ASSEMBLY	UNK		68937 TX992E4	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
726035 E2	RING SEAL ASSEMBLY	UNK		45075 TX966E2	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0110**
 Unit: **0110** Reg No: **N716NS**
 Airworthiness: **09-Oct-2006**
 Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
726040 E2	RING SEAL ASSEMBLY	UNK		45075 TX962E7	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
729904 E1	HP SHAFT SEAL FRONT RUNNER	UNK		78640 TX739E8	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
729904 E2	HP SHAFT SEAL FRONT RUNNER	UNK		78640 TX734E7	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
729905 E2	INNER GUIDED ROLLER BEARING	UNK		79027 JT-106581	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
729982 E2	SEAL ASSY, REAR, FUEL SLINGER	UNK		115094 AU20847	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
730001 LEFT ENGINE	FUEL PRESS SWITCH 9912033-2	*CF		1103P0448 7222	MTH 09-Oct-2006		O/C			
730001 RIGHT ENGINE	FUEL PRESS SWITCH 9912033-2	*CF		1103P0448 7243	MTH 09-Oct-2006		O/C			
732500 LEFT ENGINE	FADEC SOFTWARE-CP219.11.06	ICT		113537 CL6APW0426	MTH 05-Apr-2009 HRS 605		O/C	603		
732500 RIGHT ENGINE	FADEC			117790 CL6APW0643	MTH 02-Sep-2020 HRS 3215.7 LDG 2218		O/C	1578.1 1355		
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	ICT		1573-4 2128	MTH 14-Jan-2011 HRS 1047.9 LDG 596		O/C	1047.9 596		
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	ICT		1573-4 2122	MTH 14-Jan-2011 HRS 1047.9 LDG 596		O/C	1047.9 596		
730002 E1	FUEL NOZZLE ASSY			50817 BCC-00013166	MTH 03-Feb-2023 HRS 3554.1 LDG 2477		O/C			
730002 E2	FUEL NOZZLE ASSY			50817 BCC-00013163	MTH 03-Feb-2023 HRS 3554.1 LDG 2477		O/C			
732101 E1	FUEL DELIVERY UNIT	KIWA		119148 CL5APU0106	MTH 15-Jan-2013 HRS 1569.8 LDG 936		8000	3387 2593	(6182.8)6182.8	2535.3
732101 E2	FUEL DELIVERY UNIT	KIWA		119148 CL8ATW0113	MTH 15-Jan-2013 HRS 1569.8 LDG 936		8000	610.8 315	(8959)8959	5311.5
732301 E1	ELEC FUEL FILTER INDICATOR	UNK		57847 GE4220	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
732301 E2	ELEC FUEL FILTER INDICATOR	UNK		57847 GE3719	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C			
741001 E1 INBOARD	IGNITION EXCITER	*CF		73489 BL14360	MTH 09-Oct-2006		O/C			
741001 E1 OUTBOARD	IGNITION EXCITER	*CF		73489 BL14370	MTH 09-Oct-2006		O/C			
741001 E2 INBOARD	IGNITION EXCITER	*CF		73489 BL14362	MTH 09-Oct-2006		O/C			
741001 E2 OUTBOARD	IGNITION EXCITER	KSBA		73498 CK2301246	MTH 17-Jun-2023 HRS 3605.9 LDG 2517		O/C	0 0 0		
741002 E1	SHORT IGNITOR LEAD	*CF		50852 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
741002 E2	SHORT IGNITOR LEAD	*CF		50852 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
741003 E1	LONG IGNITOR LEAD	*CF		50853 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
741003 E2	LONG IGNITOR LEAD	*CF		50853 SN-UNKNOWN	MTH 09-Oct-2006		O/C			
741004 E1 INBOARD	IGNITOR			68032 CK-2202328	MTH 03-Feb-2023 HRS 3554.1 LDG 2477		O/C			
741004 E1 OUTBOARD	IGNITOR			68032 CK-000292	MTH 03-Feb-2023 HRS 3554.1 LDG 2477		O/C			
741004 E2 INBOARD	IGNITOR	KSBA		68032 CK-1801133	MTH 17-Jun-2023 HRS 3605.9 LDG 2517		O/C			
741004 E2 OUTBOARD	IGNITOR	KSBA		68032 CK-2300567	MTH 17-Jun-2023 HRS 3605.9 LDG 2517		O/C	0 0 0		
772001 LEFT NO. 1	ITT PROBE	*CF		62141 YYF013676	MTH 09-Oct-2006		O/C			
772001 LEFT NO. 2	ITT PROBE	*CF		62141 YYF013677	MTH 09-Oct-2006		O/C			
772001 LEFT NO. 3	ITT PROBE	*CF		62141 YYF013678	MTH 09-Oct-2006		O/C			
772001 LEFT NO. 4	ITT PROBE	*CF		62141 YYF013679	MTH 09-Oct-2006		O/C			
772001 LEFT NO. 5	ITT PROBE	*CF		62141 YYF013680	MTH 09-Oct-2006		O/C			
772001 LEFT NO. 6	ITT PROBE	*CF		62141 YYF013681	MTH 09-Oct-2006		O/C			
772001 RIGHT NO. 1	ITT PROBE	*CF		62141 YYF013688	MTH 09-Oct-2006		O/C			
772001 RIGHT NO. 2	ITT PROBE	*CF		62141 YYF013689	MTH 09-Oct-2006		O/C			
772001 RIGHT NO. 3	ITT PROBE	*CF		62141 YYF013690	MTH 09-Oct-2006		O/C			
772001 RIGHT NO. 4	ITT PROBE	*CF		62141 YYF013691	MTH 09-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
772001 RIGHT NO. 5	ITT PROBE	*CF		62141 YYF013692	MTH 09-Oct-2006		O/C			
772001 RIGHT NO. 6	ITT PROBE	*CF		62141 YYF013693	MTH 09-Oct-2006		O/C			
771001 E1	N1 DUAL MAGNETIC SPEED SENSOR	KIWA		57355 MD083974	MTH 19-Dec-2013 HRS 1840 LDG 1112		O/C			
771001 E2	N1 DUAL MAGNETIC SPEED SENSOR	KIWA		57355 MD084157	MTH 19-Dec-2013 HRS 1840 LDG 1112		O/C			
771002 E1	N2 DUAL MAGNETIC SPEED SENSOR	*CF		54831 MD087862	MTH 09-Oct-2006		O/C			
771002 E2	N2 DUAL MAGNETIC SPEED SENSOR	*CF		54831 MD088028	MTH 09-Oct-2006		O/C			
771003 E1	TT2 SENSOR	LGB		79646 GST3117	MTH 06-Dec-2007 HRS 306		O/C	0		
771003 E2	TT2 SENSOR	KMYF		118655EX GST-4647	MTH 21-Dec-2013 HRS 1841.1 LDG 1121		O/C			
772002 E1	ITT HARNESS ASSEMBLY	UNK		75378 YYF002781	MTH 18-Aug-2014 HRS 2033 LDG 1264		O/C	0 0 0		
793002 LEFT ENGINE	OIL PRESS SWITCH	*CF		S1103P89-3 2271	MTH 09-Oct-2006		O/C			
793002 RIGHT ENGINE	OIL PRESS SWITCH	*CF		S1103P89-3 2263	MTH 09-Oct-2006		O/C			
793003 LEFT ENGINE	OIL PRESS TRANSMITTER	KHMZ		APTE-304A-200G 7807-11-319	MTH 27-May-2021 HRS 3268.2 LDG 2260		O/C			
793003 RIGHT ENGINE	OIL PRESS TRANSMITTER	KHMZ		APTE-304A-200G 8375-7-29	MTH 27-May-2021 HRS 3268.2 LDG 2260		O/C			
792201 E1	LUBE OIL COOLER	*CF		59857 FC1421	MTH 09-Oct-2006		O/C			
792201 E2	LUBE OIL COOLER	*CF		59857 FC1420	MTH 09-Oct-2006		O/C			
792401 E1	LUBE AND SCAVENGE PUMP	KIWA		125142 MX20145	MTH 23-Nov-2016 HRS 2427.8 LDG 1700		5000	0 0 0	(7427.8)7427.8	3780.3
792401 E2	LUBE AND SCAVENGE PUMP	KIWA		125142 MX20217	MTH 23-Nov-2016 HRS 2427.8 LDG 1700		5000	0 0 0	(7427.8)7427.8	3780.3
793102 E1	OIL FILLER CAP	KIWA		123259 NSN	MTH 06-Jan-2016 HRS 2243.1 LDG 1513		O/C	0 0 0		
793102 E2	OIL FILLER CAP	KIWA		123259 NSN	MTH 06-Jan-2016 HRS 2243.1 LDG 1513		O/C	0 0 0		
801101 LEFT	STARTER GENERATOR	KICT		300SGL129Q 6581XL2	MTH 05-May-2019 HRS 3000.7 LDG 2090		1000	0 0 0	4000.7	353.2

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Components

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
801101	STARTER GENERATOR			300SGL129Q	MTH	27-Feb-2018		0		
RIGHT	9912125-2	LNK		3069XL2	HRS	2770.4	1000	0	3770.4	122.9
					LDG	1946		0		



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL 525B-99-01 R03	CESCOME PRICES (THIS SL CANCELS SL525B-99-01 R2 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 525B-99-03 R01	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 525B-99-03	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PERSONAL ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 525B-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 525B-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525B-99-03 R02	MISCELLANEOUS - TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 525B-99-08	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SB 560-00-0158	INSTALLATION OF TINNED COPPER BRAID			MTH	04-Oct-2018		-			Complete
	MOC : COMPLIED WITH									
SL 525B-05-03	TIME LIMITS/MAINTENANCE CHECKS - WING INSPECTION INTERVAL IMPLEMENTATION GRACE PERIOD			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
MOC :										
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
MOC :										
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
MOC :										
PSID WI-05-1000 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
PSID WI-05-1000 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
PSID WI-05-1000 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
PSID WI-05-1000 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
PSID WI-05-1003 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
MOC :										
PSID WI-05-1003 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
MOC :										
SL WI-05-1007-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1007-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-05-1007 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1007 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1045-CN E1	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL								
	CANCELLED								
	-								
	MOC :								
SL WI-05-1045-CN E2	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL								
	CANCELLED								
	-								
	MOC :								
SL WI-05-1045 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1045 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1095-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL								
	CANCELLED								
	-								
	MOC :								
SL WI-05-1095-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL								
	CANCELLED								
	-								
	MOC :								
SL WI-05-1095 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1095 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								
SL WI-05-1149 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	-								
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-05-1149 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL WI-05-1155 E1	TIME LIMITS/MAINTENANCE CHECKS - TIME EXTENSION OF MAJOR PERIODIC INSPECTION								
	MOC :								
SL WI-05-1155 E2	TIME LIMITS/MAINTENANCE CHECKS - TIME EXTENSION OF MAJOR PERIODIC INSPECTION								
	MOC :								
SB 525B-11-01 R01 11SB-01 : 525B1	ENGINE OIL DOOR PLACARD CHANGE ICT		RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		A/R			Complete
	MOC : COMPLIED WITH - CW DUE TO EARLIER REVISION HAS BEEN PCW.								
SB 525B-11-01 11SB-01	ENGINE OIL DOOR PLACARD CHANGE ICT		RECOMMENDED	MTH 14-Aug-2007 HRS 223		A/R			Complete
	MOC : COMPLIED WITH								
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL					-			
	MOC :								
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL					-			
	MOC :								
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL					-			
	MOC :								
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS RECOMMENDED					MTH	-		
	MOC :								
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL					-			
	MOC :								
SL CIL-20-01 R03- CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL CANCELLED					-			
	MOC :								
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL					-			
	MOC :								
SL 525B-20-01 R06	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL					A/R			
	MOC :								
SL 525B-20-05	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL INFORMATIONAL					-			
	MOC :								
SB 525B-21-03 21SB-03	TEMPERATURE SENSOR RELOCATION		OPTIONAL	MTH		-			
	MOC :								
SB 525B-21-04	AFT EVAPORATOR DRAIN HOSE IMPROVEMENT IWA		DISCRETIONARY	MTH 15-Nov-2010 HRS 996.7 LDG 564		A/R			Complete
	MOC : COMPLIED WITH - IAW THE SB ACCOMPLISHED AFT EVAPORATOR DRAIN HOSE IMPROVEMENT I.A.W. CESSNA SN525B-21-04.								



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
COM MC 525B-002	500 COMPRESSOR HOUR INSPECTION			INFORMATIONAL			-			
MOC :										
SL 525B-21-04	AIR CONDITIONING - PRESSURIZATION PRINTED CIRCUIT BOARD REPLACEMENT						-			
MOC :										
SL 525B-21-06	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT OPTIONAL						-			
MOC :										
SB 525B-23-01 <i>23SB-01</i>	RADIO TUNING UNIT (RTU) UPDATE LGB			RECOMMENDED	MTH 24-Oct-2007 HRS 271		A/R			Complete
MOC : COMPLIED WITH										
SB 525B-23-02 <i>23SB-02</i>	ACP-4110 AUDIO PANEL OUTPUT VOLUME ADJUSTMENT ICT			DISCRETIONARY	MTH 14-May-2008 HRS 411		A/R			Complete
MOC : COMPLIED WITH										
SB 525B-23-03	COMMUNICATIONS - ACP-4110 AUDIO PANEL LOCK-UP IMPROVEMENT KIWA			DISCRETIONARY	MTH 13-May-2011 HRS 1130.4 LDG 643		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB 525B-23-03 COMMUNICATIONS ACP-4110 AUDIO PANEL LOCK-UP IMPROVEMENT BY REPLACING AUDIO CONTROL PANELS COLLINS P/N 822-1861-030 VENDOR CHELTON P/N4110-002 WITH UNITS THAT HAVE INCORPORATED MOD 3, MOD 4, AND MOD 6 AND WERE TESTED PER SM 4110 REV. 4.05. UNITS WERE REIDENTIFIED TO P/N 822-1861-230 TO INDICATE INCORPORATION OF MODIFICATIONS.										
SB 525B-23-06	COMMUNICATIONS - AVIATOR 300 SATCOM ANTENNA REPLACEMENT OPTIONAL						-			
MOC :										
SL 525B-23-03	COMMUNICATIONS - SITA DATALINK FREQUENCY CHANGE FOR NORTH AMERICA INFORMATIONAL						-			
MOC :										
SL 525B-23-04	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE OPTIONAL						-			
MOC :										
SL 525B-23-05	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8 OPTIONAL						-			
MOC :										
SB 525B-24-06 <i>24SB-06</i>	AVIONICS EMERGENCY BUS RELAY IMPROVEMENT ICT			DISCRETIONARY	MTH 08-Feb-2009 HRS 570		A/R			Complete
MOC : COMPLIED WITH										
SB 525B-24-09	GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING KICT			MANDATORY	MTH 26-Apr-2013 HRS 1666 LDG 990		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525B-24-09; GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING, DATED FEBRUARY 15, 2013.										
SB 525B-24-12	ELECTRICAL POWER - JUMPER INSTALLATION IN THE COMPRESSOR ASSEMBLY RECOMMENDED			MTH			-			
MOC :										
COM MC 525B-013	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES INFORMATIONAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525B-25-04 25SB-04	RIGHT CABIN SIDE LEDGE ARM REST IMPROVEMENT SEE			OPTIONAL	MTH 13-Jan-2010 HRS 827		A/R			Complete
	MOC : COMPLIED WITH									
SB 525B-25-09	EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK OPTIONAL						-			
	MOC :									
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION OPTIONAL						-			
	MOC :									
SB CIB-25-02	EQUIPMENT/FURNISHINGS - BELTED TOILET SEAT INERTIA REEL MODIFICATION ICT			RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
	MOC : NOT APPLICABLE - NA PER AIRCRAFT SERIAL NUMBER.									
SL 525B-25-01 25SL-01	TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARY BUCKLE PLASTIC HANDLE ICT			MANDATORY	MTH 06-Feb-2008 HRS 329		A/R			Complete
	MOC : COMPLIED WITH									
SL 525B-25-05	EQUIPMENT/FURNISHINGS - TOILET DRIP TRAY INSTALLATION OPTIONAL						-			
	MOC :									
SB 525B-26-02 26SB-02	FORWARD BAGGAGE SMOKE DETECTOR DEACTIVATION *CF			DISCRETIONARY			-			
	MOC : - SERVICE BULLETIN ON HOLD.									
SB 525B-26-03 26SB-03	ANNUNCIATOR PANEL REPLACEMENT ICT			MANDATORY	MTH 14-Aug-2007 HRS 223		A/R			Complete
	MOC : COMPLIED WITH									
SB 525B-26-04	FORWARD SMOKE DETECTOR HEATER AND COVER INSTALLATION ICT			RECOMMENDED	MTH 31-Aug-2010 HRS 963.5 LDG 540		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SB525B-26-04; FORWARD SMOKE DETECTOR HEATER AND COVER INSTALLATION, DATED SEPTEMBER 25, 2009									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING KMYF			MANDATORY	MTH 15-Aug-2016 HRS 2350.4 LDG 1637 ACH 847		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH CIL-26-01R1 IAW SIL INSTRUCTIONS. NO DEFECTS FOUND.									
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING MANDATORY				MTH		-			
	MOC :									
SB 525B-27-02 R01	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT OPTIONAL						-			
	MOC :									
SB 525B-27-02 27SB-02	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT OPTIONAL				MTH		A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525B-27-03 R01	VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION	KICT		MANDATORY	MTH 09-Feb-2012 HRS 1328.3 LDG 772		A/R			Complete
MOC : COMPLIED WITH - REVISION 1 HAS NO EFFECT ON AIRCRAFT DUE TO ORIGINAL ISSUE BEING COMPLIED WITH.										
SB 525B-27-03	VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION	IWA		MANDATORY	MTH 15-Nov-2010 HRS 996.7 LDG 564		A/R			Complete
MOC : COMPLIED WITH - IAW THE SB ACCOMPLISHED VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION I.A.W. CESSNA SB525B-27-03.										
SL 525B-27-01 27SL-01	FLAP PUSHROD SAFETY WIRE INSPECTION	ICT		RECOMMENDED	MTH 06-Feb-2008 HRS 329		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL			-			
MOC :										
SL 525B-28-01 28SL-01	FUEL LINE CLEARANCE IMPROVEMENT	ICT		MANDATORY	MTH 08-Feb-2009 HRS 570		A/R			Complete
MOC : COMPLIED WITH										
SB 525B-29-03 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	ICT		MANDATORY	MTH 02-Sep-2011 HRS 1225.4 LDG 700		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525B-29-03 HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT; REVISION 1 DATED JUNE 6, 2011.										
SB 525B-29-03	HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	ICT		MANDATORY	MTH 31-Aug-2010 HRS 963.5 LDG 540		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525B-29-03; HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT, DATED MAY 07, 2010.										
SB 525B-29-04	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION			OPTIONAL			A/R			
MOC :										
SL 525B-29-01 29SL-01	HYDRAULIC RELIEF VALVE INLET NUT TORQUE INSPECTION	ICT		RECOMMENDED	MTH 14-Aug-2007 HRS 223		A/R			Complete
MOC : COMPLIED WITH										
SL 525B-29-02	HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION	KICT		RECOMMENDED	MTH 16-Aug-2017 HRS 2621.3 LDG 1847 ACH 1008.2		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL525B-29-02; ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION, DATED JUNE 13, 2017.										
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
MOC :										
SL 525B-30-02	ICE AND RAIN PROTECTION - WING ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE INSPECTION	ICT		MANDATORY	DAYS 22-Nov-2021 HRS 3327.4 LDG 2292		A/R			N/A
MOC : NOT APPLICABLE - NA PER AIRCRAFT SERIAL NUMBER.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION INFORMATIONAL									
	MOC :									
SL 525B-31-01 31SL-01	COCKPIT SWITCH INSPECTION ICT			RECOMMENDED	MTH 06-Feb-2008 HRS 329		A/R			Complete
	MOC : COMPLIED WITH									
SL 525B-31-03	TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001 KIWA			MANDATORY	MTH 10-Jan-2012 HRS 1307.7 LDG 758		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL525B-31-03 I.A.W. L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001. REWORK IS NOT REQUIRED DUE TO S/N.									
SB 525B-32-08 32SB-08	MAIN LANDING GEAR BRAKE HYDRAULIC AND PNEUMATIC LINE REPLACEMENT ICT			MANDATORY	MTH 26-Aug-2008 HRS 485		A/R			Complete
	MOC : COMPLIED WITH									
SB 525B-32-09 32SB-09	BRAKE METERING VALVE CABLE INSPECTION IWA			RECOMMENDED	MTH 15-Nov-2010 HRS 996.7 LDG 564		-			Complete
	MOC : COMPLIED WITH - IAW THE SB ACCOMPLISHED BRAKE METERING VALVE CABLE INSPECTION I.A.W. CESSNA SB525B-32-09.									
SB 525B-32-10	LANDING GEAR - NOSE LANDING GEAR ACTUATOR IMPROVEMENT DISCRETIONARY						A/R			
	MOC :									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL INFORMATIONAL						-			
	MOC :									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION KIWA			RECOMMENDED	MTH 19-Mar-2016 HRS 2258.3 LDG 1543		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH CIL 32-03. NO DEFECTS NOTED.									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL						-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION INFORMATIONAL						-			
	MOC :									
SL 525B-32-01 R01 32SL-01 : 525B1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION *CF			OPTIONAL	MTH		-			
	MOC :									
SL 525B-32-03 32SL-03	MAIN LANDING GEAR TIRE INFLATION PLACARD INSPECTION LGB			RECOMMENDED	MTH 06-Dec-2007 HRS 306		A/R			Complete
	MOC : COMPLIED WITH									
SL 525B-32-06 32SL-06	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION ICT			RECOMMENDED	MTH 11-Mar-2008 HRS 329		A/R			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525B-32-09 R02	EMERGENCY GEAR RELEASE INSPECTION	KIWA		MANDATORY	MTH 04-Feb-2011 HRS 1051.6 LDG 598		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL525B-32-09 R2 EMERGENCY GEAR RELEASE INSPECTION.										
SL 525B-32-14	LANDING GEAR - MAIN LANDING GEAR REPAIR			INFORMATIONAL			-			
MOC :										
SB 525B-33-01	LIGHTNING STRIKE IMPROVEMENT FOR THE LANDING LIGHTS	ICT		RECOMMENDED	MTH 28-Apr-2010 HRS 891.7 LDG 500		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525B-33-01, LIGHTNING STRIKE IMPROVEMENT FOR THE LANDING LIGHTS SERVICE BULLETIN DATED DECEMBER 14, 2007.										
SB 525B-33-03 33SB-03	RIGHT LANDING LIGHT RELAY/RESISTOR MOUNT BRACKET REPLACEMENT	ICT		RECOMMENDED	MTH 08-Feb-2009 HRS 570		A/R			Complete
MOC : COMPLIED WITH										
SB 525B-33-05	ELECTROLUMINESCENT PANEL MOUNTING IMPROVEMENT	MCO		MANDATORY	MTH 01-Nov-2012 HRS 1538.1 LDG 909		-			Complete
MOC : COMPLIED WITH										
SB 525B-33-07	LIGHTS - WING TIP LED LIGHT MODIFICATION			OPTIONAL			-			
MOC :										
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
MOC :										
SB 525B-34-01 R01 34SB-01 : 525B1	TERRAIN AWARENESS WARNING SYSTEM (TAWS) UPGRADE TO SOFTWARE LEVEL 1.13			OPTIONAL	MTH 29-Feb-2008		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE										
SB 525B-34-03 34SB-03	ENHANCED SURVEILLANCE TRANSPONDER UPGRADE			OPTIONAL	MTH 18-Sep-2007 HRS 243		A/R			N/A
MOC : NOT APPLICABLE - SB NOT APPLICABLE DUE TO COMPONENT PART NUMBER REFERENCED IN SB INSTALLED ORIGINALLY FROM THE FACTORY.										
SB 525B-34-04 R02 34SB-04 : 525B2	V-SPEED ENABLE AND SOFTWARE UPGRADE	ICT		RECOMMENDED	MTH 14-Aug-2007 HRS 223		A/R			Complete
MOC : COMPLIED WITH										
SB 525B-34-09 34SB-09	CURSOR CONTROL PANEL (CCP) HARDWARE UPGRADE TO MOD LEVEL 1	ICT		DISCRETIONARY	MTH 06-Feb-2008 HRS 329		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525B-34-17	COLLINS IFIS 6.0 SYSTEM SOFTWARE UPDATES	KMYF		OPTIONAL	MTH 31-Aug-2012 HRS 1508.4 LDG 886		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB525B-34-17. REMOVED PILOT'S & CO-PILOT'S AFD-3010, P/N 822-1084-123, S/N 2G74R & S/N 1WC7M RESPECTIVELY; AND AFD-3010E MFD, P/N 822-1753-123, S/N 2K83V AND SENT TO ROCKWELL COLLINS, INC. FOR MODIFICATION. RECEIVED ABOVE MODIFIED UNITS BACK FROM ROCKWELL COLLINS WITH NEW P/NS BUT SAME S/NS AS FOLLOWS: PILOT'S & CO-PILOT'S AFD-3010, P/N 822-1084-124, S/N 2G74R & S/N 1WC7M RESPECTIVELY; AND AFD-3010E MFD, P/N 822-1753-124, S/N 2K83V. REINSTALLED UNITS BACK IN AIRCRAFT AND PERFORMED REMAINING TESTING AND IFIS 6.0 UPGRADE PROCEDURE PER CESSNA SB 525B-34-17. AFM ALREADY HAS THE CORRECT REVISION SUPPLEMENT AS REQUIRED.										
SB 525B-34-18	R01 NAVIGATION - DBU-5000 DATABASE UNIT (FLASH MEMORY) SOFTWARE DATABASE LOADER			OPTIONAL			A/R			
MOC :										
SB 525B-34-19	R01 COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE			OPTIONAL			-			
MOC :										
SB 525B-34-19	R02 COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE			OPTIONAL			-			
MOC :										
SB 525B-34-19	R03 NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES			OPTIONAL			-			
MOC :										
SB 525B-34-19	COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE	IWA		OPTIONAL	MTH 15-Nov-2010 HRS 996.7 LDG 564		A/R			Complete
MOC : COMPLIED WITH - IAW THE SB ACCOMPLISHED COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE INSTALLATION I.A.W. CESSNA SB525B-34-19.										
SB 525B-34-21	NAVIGATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS II) SOFTWARE 7.1 UPGRADE	LNK		OPTIONAL	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			Complete
MOC : COMPLIED WITH										
SB 525B-34-22	ENHANCED SURVEILLANCE TRANSPONDER STRAPPING MODIFICATION			DISCRETIONARY	MTH		-			
MOC :										
SB 525B-34-23	TDR-94D TRANSPONDER UPGRADE			OPTIONAL			-			
MOC :										
SB 525B-34-26	R01 NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
MOC :										
SB 525B-34-26	R02 NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
MOC :										
SB 525B-34-26	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
MOC :										
SB 525B-34-38	R01 NAVIGATION - REACTIVE WINDSHEAR INSTALLATION			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB CIB-34-02	GPS-4000S SOFTWARE UPDATE KIWA			RECOMMENDED	MTH 19-Mar-2016 HRS 2258.3 LDG 1543		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED THE GPS 4000S SOFTWARE UPDATE IAW CIB-34-02 INSTRUCTIONS.										
SB CIB-34-03 R01	NAVIGATION - TEMPERATURE COMPENSATION FOR LNAV/VNAV - CANCELED CANCELED						-			
MOC :										
SL CIL-34-04	TDR-94/94D TRANSPONDER ALL-CALL KIWA			INFORMATIONAL	MTH 08-Oct-2014 HRS 2097.2 LDG 1307		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH VERIFICATION OF THE PROPER STRAPPING OF THE TDR-94/94D TRANSPONDER ALL CALL IAW CESSNA CIL-34-04.										
SB CIL-34-11	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ALT-4000-34-14, NAVIGATION - ALT 4000 POWER SUPPLY ROBUSTNESS IMPROVEMENT						-			
MOC : OPTIONAL										
SL 525B-34-09	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION KMYF			INFORMATIONAL	MTH 20-Jul-2016 HRS 2337.1 LDG 1620 ACH 847		-			Complete
MOC : COMPLIED WITH - CHANGED XMWR-1000 P/N 822-2031-002, S/N 292JC CONFIGURATION I/AW CESSNA CITATION SERVICE LETTER SL525B-34-09 AND THE ROCKWELL COLLINS SERVICE INFORMATION LETTER 523-0824070-001000.										
SL 525B-34-14	NAVIGATION - DISABLE FMS TEMPERATURE COMPENSATION AND IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES FOR LNAV/VNAV			MANDATORY	MTH 30-Nov-2020		-			N/A
MOC : NOT APPLICABLE										
SL CIL-35-01	TRANSMITTAL OF BE AEROSPACE SERVICE BULLETIN 118077-35-01 KIWA			MANDATORY	MTH 12-Mar-2014 HRS 1872.2 LDG 1155		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH 525B SL CIL-35-01, BE AEROSPACE SB 118077-35-01 NOT APPLICABLE.										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 KIWA			MANDATORY	MTH 19-Mar-2016 DAYS 2258.3 HRS 1543 LDG		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CIL-35-05 WITH AN EFFECTIVE DATE OF JANUARY 8 2016 BY VERIFYING THAT THE EFFECTED OXYGEN MASKS ARE NOT INSTALLED ON THIS AIRCRAFT IN ACCORDANCE WITH CIL-35-05. NO FURTHER ACTION IS REQUIRED.										
SL 525B-35-02 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 KIWA			MANDATORY	MTH 15-Jan-2013 HRS 1569.8 LDG 936		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 SERVICE LETTER IAW THE CESSNA 525B SL525B-35-02 R1										
SL 525B-35-02 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 KIWA			MANDATORY	MTH 15-Jan-2013 HRS 1569.8 LDG 936		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 SERVICE LETTER IAW THE CESSNA 525B SL525B-35-02 R2										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525B-35-02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KMYF		MANDATORY	MTH 15-Nov-2011 HRS 1272 LDG 734		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL525B-35-02 OXYGEN-TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-02 SERVICE LETTER INSPECTION ONLY.										
SB 525B-36-02 R01 PNEUMATIC - PRECOOLER EXHAUST IMPROVEMENT		KIWA		DISCRETIONARY	MTH 10-Jan-2012 HRS 1307.7 LDG 758		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH PNEUMATIC - PRECOOLER EXHAUST IMPROVEMENT I.A.W. SB525B-36-02-R1. UPDATED AIRCRAFT'S WEIGHT AND BALANCE.										
SB 525B-36-02	PRECOOLER EXHAUST IMPROVEMENT			DISCRETIONARY			A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED SUPERSEDED BY REVISION 1										
SB 525B-36-03 R01 PNEUMATIC - MOISTURE TRAP INSTALLATION				OPTIONAL			-			
MOC :										
SB 525B-36-03	PNEUMATIC - MOISTURE TRAP INSTALLATION			OPTIONAL			-			
MOC :										
SL 525B-36-01 R01 PNEUMATIC - PRECOOLER LIFE LIMIT				INFORMATIONAL			-			
MOC :										
SL 525B-36-01	PRECOOLER LIFE LIMIT			INFORMATIONAL			-			
MOC :										
SB 525B-52-01 R01 IMPROVEMENT FOR THE CABIN ENTRY STEPS				OPTIONAL	MTH		A/R			
<i>52SB-01 : 525B1</i>										
MOC :										
SB 525B-52-03 R01 CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION				OPTIONAL	MTH		A/R			
<i>52SB-03 : 525B1</i>										
MOC :										
ASL 525B-52-01	EMERGENCY DOOR INSPECTION			MANDATORY	MTH 06-Dec-2007 HRS 306		A/R			Complete
<i>52SLA01</i>	LGB									
MOC : COMPLIED WITH										
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION	KIWA		MANDATORY	MTH 19-Dec-2013 HRS 1840 LDG 1112		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED EMERGENCY DOOR INSPECTION IAW CIL-52-01.										
SL CIL-52-02	DOORS - EMERGENCY EXIT DOOR INSPECTION			INFORMATIONAL			-			
MOC :										
SL CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION	KHMZ		MANDATORY	MTH 11-Dec-2020 HRS 3244.9 LDG 2238		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER CIL-52-03, EMERGENCY ESCAPE HATCH INSPECTION. NO DEFECTS NOTED										
SB 525B-53-01	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S)	ICT		MANDATORY	MTH 04-May-2007 HRS 150		A/R			Complete
<i>53SB-01</i>										
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 525B-53-01 53SLA01	RELIEF TUBE CORROSION ICT			MANDATORY	MTH 04-Dec-2006 HRS 40		A/R			Complete
MOC : COMPLIED WITH										
ASL 525B-53-02 R04 53SLA02 : 525B4	RELIEF TUBE CORROSION INSPECTION ICT			MANDATORY	MTH 06-Feb-2008 HRS 329		A/R			Complete
MOC : COMPLIED WITH										
ASL 525B-53-02 R05 53SLA02 : 525B5	RELIEF TUBE CORROSION INSPECTION ICT			MANDATORY	MTH 06-Feb-2008 HRS 329		A/R			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.										
SL 525B-53-06 53SL-06	INTERCOSTAL DRAINAGE PATH INSPECTION ICT			RECOMMENDED	MTH 06-Feb-2010 HRS 844.7 LDG 470		A/R			Complete
MOC : COMPLIED WITH - .ACCOMPLISHED SL525B-53-06 INTERCOSTAL DRAINAGE PATH INSPECTION SERVICE LETTER DATED 27 OCT. 2009										
SL 525B-53-07	UPPER TAILCONE SKIN INSPECTION ICT			MANDATORY	MTH 31-Aug-2010 HRS 963.5 LDG 540		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL525B-53-07; UPPER TAILCONE SKIN INSPECTION, DATED JUNE 03, 2010.										
SB 525B-54-02	NACELLES/PYLONS - FORWARD ENGINE BEAM INSPECTION ACCESS PANEL INSTALLATION OPTIONAL						-			
MOC :										
SL 525B-54-01 R02 055401	PYLON INSPECTION ICT			RECOMMENDED	MTH 06-Feb-2010 HRS 844.7 LDG 470		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 3 WHICH CANCELLED THIS BULLETIN. SEE INSPECTION DOCUMENT 1 CODE A545002.										
SL 525B-54-01 R03	PYLON INSPECTION			CANCELLED			A/R			
MOC :										
SL 525B-54-01 54SL-01	PYLON STRUCTURE INSPECTION ICT			RECOMMENDED	MTH 06-Feb-2010 HRS 844.7 LDG 470		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL525B-54-01 REVISION 2 PYLON STRUCTURE INSPECTION DATED JANUARY 30, 2009.										
SL 525B-55-03 R01	STABILIZERS - VERTICAL STABILIZER BOLT TORQUE INSPECTION RECOMMENDED						-			
MOC :										
SL 525B-55-03	STABILIZERS - VERTICAL STABILIZER BOLT TORQUE INSPECTION RECOMMENDED						-			
MOC :										
SB 525B-57-02 R01	ANTI-ICE EXHAUST OUTLET IMPROVEMENT ICT			RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			Complete
MOC : COMPLIED WITH - CW DUE TO EARLIER REVISION HAS BEEN PCW.										
SB 525B-57-02	WINGS - ANTI-ICE EXHAUST OUTLET IMPROVEMENT KIWA			RECOMMENDED	MTH 08-Oct-2014 HRS 2097.2 LDG 1307		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH ANTI ICE EXHAUST OUTLET IMPROVEMENT IN ACCORDANCE WITH CITATION SB525B-57-02.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-70-1008 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									-
	MOC :									
SL WI-70-1008 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									-
	MOC :									
SB 525B-71-01 71SB-01	PT2/TT2 SENSOR INSTALLATION IMPROVEMENT ICT			MTH RECOMMENDED	06-Feb-2008 HRS 329		A/R			Complete
	MOC :	COMPLIED WITH								
SL 525B-71-08 R02	POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT ICT			MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
	MOC :	NOT APPLICABLE - NA PER AIRCRAFT SERIAL NUMBER.								
SL 525B-71-09 R01	POWER PLANT - ENGINE ISOLATOR MOUNTS INSPECTION EXTENSION OPTIONAL						-			
	MOC :									
SL 525B-71-09	POWER PLANT - ENGINE ISOLATOR MOUNTS INSPECTION EXTENSION (SUPERSEDED BY SL525B-71-09 R01) OPTIONAL						-			
	MOC :									
SL 44-71-153 E1	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING						-			
	MOC :									
SL 44-71-153 E2	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING						-			
	MOC :									
SL 44-71-198 E1	ENGINE - IP COMPRESSOR ROTOR RUB - ACCEPTABLE FOR CONTINUED USE						-			
	MOC :									
SL 44-71-198 E2	ENGINE - IP COMPRESSOR ROTOR RUB - ACCEPTABLE FOR CONTINUED USE						-			
	MOC :									
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-71-1319-CN E1	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-71-1319-CN E2	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-71-1319 E1	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1319 E2	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1541 E1	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1541 E2	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION INFORMATIONAL						-			
	MOC :									
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION INFORMATIONAL						-			
	MOC :									
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION INFORMATIONAL						-			
	MOC :									
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION INFORMATIONAL						-			
	MOC :									
SB FJ44-72-066 R03 E1	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04) RECOMMENDED						-			
	MOC :									
SB FJ44-72-066 R03 E2	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04) RECOMMENDED						-			
	MOC :									
SB FJ44-72-066 R06 E1	CARBON RING SEAL AND BEARING HOUSING - REPLACE ICT	RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292			-				N/A
	MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.									
SB FJ44-72-066 R06 E2	CARBON RING SEAL AND BEARING HOUSING - REPLACE ICT	RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292			-				N/A
	MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.									
SB FJ44-72-068 R03 E1	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-068 R04) OPTIONAL						-			
	MOC :									
SB FJ44-72-068 R03 E2	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-068 R04) OPTIONAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-070 R02 E1	CANCELLED - UPGRADE GEARBOX (4K SPRING-LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY SB FJ44-72-105 R05)			CANCELLED			-			
MOC :										
SB FJ44-72-070 R02 E2	CANCELLED - UPGRADE GEARBOX (4K SPRING-LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY SB FJ44-72-105 R05)			CANCELLED			-			
MOC :										
SB FJ44-72-075 R01 E1	GEARBOX P/N 78823 - INSPECTION ICT			MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		A/R			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-075 R01 E2	GEARBOX P/N 78823 - INSPECTION ICT			MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		A/R			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-078 R01 E1	ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R02)	UNK		OPTIONAL	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-078 R01 E2	ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R02)	UNK		OPTIONAL	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-078 R02 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-078 R02 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-078 R03 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK			OPTIONAL			-			
MOC :										
SB FJ44-72-078 R03 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK			OPTIONAL			-			
MOC :										
SB FJ44-72-085 R05 E1	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-72-085 R05 E2	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-72-085 R08 E1	IP BLEED VALVE - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-085 R08 E2	IP BLEED VALVE - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-086 R03 E1	ENGINE - BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-086 R03 E2	ENGINE - BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-093 R02 E1	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R03)			MANDATORY			-			Complete
MOC : COMPLIED WITH - PREVIOUSLY PREVIOUSLY COMPLIED WITH ORIGINAL BULLETIN FJ44-72-093										
SB FJ44-72-093 R02 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R03)			MANDATORY			-			Complete
MOC : COMPLIED WITH - PREVIOUSLY PREVIOUSLY COMPLIED WITH ORIGINAL BULLETIN FJ44-72-093										
SB FJ44-72-093 R10 E1	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R11)			MANDATORY			-			
MOC :										
SB FJ44-72-093 R10 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R11)			MANDATORY			-			
MOC :										
SB FJ44-72-093 R11 E1	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R12)			MANDATORY			-			
MOC :										
SB FJ44-72-093 R11 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R12)			MANDATORY			-			
MOC :										
SB FJ44-72-093 R12 E1	DIFFUSER CASE ASSEMBLY - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-72-093 R12 E2	DIFFUSER CASE ASSEMBLY - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-72-093 R13 E1	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE ICT			MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			Complete
MOC : COMPLIED WITH - CW DUE TO EARLIER REVISION HAS BEEN PCW.										
SB FJ44-72-093 R13 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE ICT			MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			Complete
MOC : COMPLIED WITH - CW DUE TO EARLIER REVISION HAS BEEN PCW.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-72-093 E1	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R01)	ICT	MANDATORY	MTH 31-Aug-2010 HRS 963.5 LDG 540		-				Complete
MOC : COMPLIED WITH - PERFORMED IDLE SPEED, VIBRATION SURVEY, STABILITY/ACCELERATION, PERFORMANCE CHECK, AND LEAK CHECKS AFTER COMPLETION OF SERVICE BULLETIN FJ44-72-093, BY WILLIAMS INTERNATIONAL REFERENCETR DATED AUGUST 29, 2010, ON THE LEFT ENGINE IAW WILLIAMS INTERNATIONAL FJ44-3A/3A-24 ENGINE M/M CHAPTER 71-00-00-760. ALL CHECKS WERE COMPLETED SATISFACTORY.										
SB FJ44-72-093 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R01)	ICT	MANDATORY	MTH 31-Aug-2010 HRS 963.5 LDG 540		-				Complete
MOC : COMPLIED WITH - PERFORMED IDLE SPEED, VIBRATION SURVEY, STABILITY/ACCELERATION, PERFORMANCE CHECK, AND LEAK CHECKS AFTER COMPLETION OF SERVICE BULLETIN FJ44-72-093 AND FJ44-77-011, BY WILLIAMSINTERNATIONAL REFERENCE MTR DATED AUGUST 29, 2010, ON THE RIGHT ENGINE IAW WILLIAMS INTERNATIONAL FJ44-3A/3A-24 ENGINE M/M CHAPTER 71-00-00-760. ALL CHECKS WERE COMPLETED SATISFACTORY										
SB FJ44-72-097 R01 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R02)		MANDATORY			-				
MOC :										
SB FJ44-72-097 R01 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R02)		MANDATORY			-				
MOC :										
SB FJ44-72-097 R02 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R03)		MANDATORY			-				
MOC :										
SB FJ44-72-097 R02 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R03)		MANDATORY			-				
MOC :										
SB FJ44-72-097 R03 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R04)	UNK	MANDATORY	MTH 18-Aug-2014 HRS 2033 LDG 1264		-				Complete
MOC : COMPLIED WITH										
SB FJ44-72-097 R03 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R04)	UNK	MANDATORY	MTH 18-Aug-2014 HRS 2033 LDG 1264		-				Complete
MOC : COMPLIED WITH										
SB FJ44-72-097 R04 E1	CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-151 R06)		MANDATORY			-				
MOC :										
SB FJ44-72-097 R04 E2	CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-151 R06)		MANDATORY			-				
MOC :										
SB FJ44-72-097 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01)		MANDATORY			-				
MOC :										
SB FJ44-72-097 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01)		MANDATORY			-				
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-105 R01 E1	ENGINE - UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R02)			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R01 E2	ENGINE - UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R02)			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R02 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R03)			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R02 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R03)			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R03 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R03 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R04 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R04 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R05 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R05 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL			-			
	MOC :									
SB FJ44-72-105 R06 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL	MTH		CSI			
	MOC :						CSI			
SB FJ44-72-105 R06 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL	MTH		CSI			
	MOC :						CSI			
SB FJ44-72-106 R03 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-106 R03 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-107 R02 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
MOC :										
SB FJ44-72-107 R02 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
MOC :										
SB FJ44-72-107 R05 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE ICT			RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-107 R05 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE ICT			RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-108 R01-CN E1	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) CANCELLED						-			
MOC :										
SB FJ44-72-108 R01-CN E2	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) CANCELLED						-			
MOC :										
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE UNK			RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE UNK			RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-110 E1	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE UNK			MANDATORY	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-110 E2	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE UNK			MANDATORY	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-122-CNSUPERSEDED - ENGINE - ACCESSORY DRIVE SHAFT - REPLACE E1	CANCELLED						-			
MOC :										
SB FJ44-72-122-CNSUPERSEDED - ENGINE - ACCESSORY DRIVE SHAFT - REPLACE E2	CANCELLED						-			
MOC :										
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE CANCELLED						-			
MOC :										
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE CANCELLED						-			
MOC :										
SB FJ44-72-124 R06 E1	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-124 R06 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-124 R07 E1	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-124 R07 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-124 R08 E1	HP TURBINE BLADES - REPLACE ICT			RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-124 R08 E2	HP TURBINE BLADES - REPLACE ICT			RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-124 R09 E1	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-124 R09 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-129 R01-CN E1	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE CANCELLED						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-129 R01-CN E2	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE CANCELED						-			
MOC :										
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02) RECOMMENDED						-			
MOC :										
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02) RECOMMENDED						-			
MOC :										
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION RECOMMENDED						-			
MOC :										
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION RECOMMENDED						-			
MOC :										
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-133 R01 E1	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED						-			
MOC :										
SB FJ44-72-133 R01 E2	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED						-			
MOC :										
SB FJ44-72-133 R02 E1	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED			HRS			CSI CSI		(5000)5000	1352.5
MOC :										
SB FJ44-72-133 R02 E2	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED			HRS			CSI CSI		(5000)5000	1352.5
MOC :										
SB FJ44-72-133 E1	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-133 E2	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01) RECOMMENDED						-			
MOC :										
SB FJ44-72-135 R01 E1	IDENTIFICATION PLATE - REPLACE MANDATORY			MTH HRS			DUE DUE DUE		(8000)8000	4352.5
MOC :										
SB FJ44-72-135 R01 E2	IDENTIFICATION PLATE - REPLACE MANDATORY			MTH HRS			DUE DUE DUE		(8000)8000	4352.5
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-140 R01 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			RECOMMENDED	MTH HRS		-		(5000)5000	1352.5
MOC :										
SB FJ44-72-140 R01 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION			RECOMMENDED	MTH HRS		-		(5000)5000	1352.5
MOC :										
SB FJ44-72-140 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY			-			
MOC :										
SB FJ44-72-140 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY			-			
MOC :										
SB FJ44-72-151 R05 E1	BEARING AND PINION ASSEMBLY - INSTALL			MANDATORY			-			
MOC :										
SB FJ44-72-151 R05 E2	BEARING AND PINION ASSEMBLY - INSTALL			MANDATORY			-			
MOC :										
SB FJ44-72-151 R06 E1	BEARING AND PINION ASSEMBLY - INSTALL	ICT		MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-151 R06 E2	BEARING AND PINION ASSEMBLY - INSTALL	ICT		MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-72-154 R01 E1	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)			RECOMMENDED			-			
MOC :										
SB FJ44-72-154 R01 E2	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)			RECOMMENDED			-			
MOC :										
SB FJ44-72-154 E1	1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-154 E2	1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)			RECOMMENDED			-			
MOC :										
SL 44-72-306 R1 E1	ENGINE – LP REAR BEARING SEAL RETAINER - REPLACE	UNK		RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SL 44-72-306 R1 E2	ENGINE – LP REAR BEARING SEAL RETAINER - REPLACE	UNK		RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 44-72-310 R4 E1	ENGINE - HP TURBINE BLADES - REPLACE	UNK		RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SL 44-72-310 R4 E2	ENGINE - HP TURBINE BLADES - REPLACE	ICT		RECOMMENDED	MTH 01-Sep-2011 HRS 1225.4 LDG 700		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB SL44-72-310										
SL 44-72-318 R2 E1	ENGINE - 1ST LP TURBINE NOZZLE - REPLACE	UNK		RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SL 44-72-318 R2 E2	ENGINE - 1ST LP TURBINE NOZZLE - REPLACE	ICT		RECOMMENDED	MTH 01-Sep-2011 HRS 1225.4 LDG 700		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB SL44-72-318										
SL 44-72-325 R04 E1	1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-325 R04 E2	1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-325 R05 E1	1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-325 R05 E2	1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-325 R06 E1	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-325 R06 E2	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-325 R07 E1	1ST LP TURBINE DISK - INSPECTION						CSI			
MOC :										
SL 44-72-325 R07 E2	1ST LP TURBINE DISK - INSPECTION						CSI			
MOC :										
SL 44-72-327 E1	SL44-72-327	UNK			MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SL 44-72-327 E2	SL44-72-327	UNK			MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SL 44-72-337 R1 E1	ENGINE - HP SHAFT - REPLACE						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 44-72-337 R1 E2	ENGINE - HP SHAFT - REPLACE						-			
	MOC :									
SL 44-72-382 E1	BLEED VALVE SHAFT - REPLACE	UNK			MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
	MOC :	COMPLIED WITH								
SL 44-72-382 E2	BLEED VALVE SHAFT - REPLACE	UNK			MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
	MOC :	COMPLIED WITH								
SL 44-72-429 E1	1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REPLACE	UNK			MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
	MOC :	COMPLIED WITH								
SL 44-72-429 E2	1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REPLACE	UNK			MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
	MOC :	COMPLIED WITH								
SL 44-72-466 E2	SL44-72-466	KIWA			MTH 23-Nov-2016 HRS 2427.8 LDG 1700		A/R			Complete
	MOC :	COMPLIED WITH - COMPLIED WITH WILLIAMS INTERNATIONAL FJ44-3A SERVICE LETTER SL44-72-466 ENGINE - OIL TANK CHECK VALVE - REPLACE DATED JUNE 3, 2013 ON RH ENGINE. NO DEFECTS NOTED.								
PSID WI-05-1000 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-72-1022 R01 E1	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1022 R01 E2	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1026 E1	FAN CASE - RUB INDICATIONS						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PSID WI-72-1026 E2	FAN CASE - RUB INDICATIONS						-			
	MOC :									
SB WI-72-1004 R04 -CN E1	1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)			CANCELLED			-			
	MOC :									
SB WI-72-1004 R04 -CN E2	1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)			CANCELLED			-			
	MOC :									
SB WI-72-1004 E1	1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY WISB-72-1004 R01)						-			
	MOC :									
SB WI-72-1004 E2	1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY WISB-72-1004 R01)						-			
	MOC :									
SB WI-72-1034 R01 E1	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY			-			
	MOC :									
SB WI-72-1034 R01 E2	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY			-			
	MOC :									
SB WI-72-1034 R02 E1	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY			-			
	MOC :									
SB WI-72-1034 R02 E2	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY			-			
	MOC :									
SB WI-72-1034 R03 E1	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY	MTH		MPI			
	MOC :						MPI			
SB WI-72-1034 R03 E2	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY	MTH		MPI			
	MOC :						MPI			
SB WI-72-1034 R04 E1	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY	MTH LDG		8000		(7763)7763	5217
	MOC :									
SB WI-72-1034 R04 E2	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY	MTH LDG		8000		(7306)7306	4760
	MOC :									
SB WI-72-1034 E1	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY			-			
	MOC :									
SB WI-72-1034 E2	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK			MANDATORY			-			
	MOC :									
SB WI-72-1037 R01 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R01 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R02 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE				MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-72-1037 R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2					MTH		-			
MOC :										
SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1				RECOMMENDED			CSI			
MOC :										
SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2				RECOMMENDED			CSI			
MOC :										
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1					MTH		-			
MOC :										
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2					MTH		-			
MOC :										
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1							-			
MOC :										
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2							-			
MOC :										
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			MPI			
MOC :										
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			MPI			
MOC :										
SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-72-1044 R01 BALANCE PISTON - REPLACE E1							-			
MOC :										
SB WI-72-1044 R01 BALANCE PISTON - REPLACE E2							-			
MOC :										
SB WI-72-1044 R02 BALANCE PISTON - REPLACE (SUPERSEDED BY SB FJ44-72-124 R09) E1							-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-72-1044 R02	BALANCE PISTON - REPLACE (SUPERSEDED BY SB FJ44-72-124 R09)									
E2							-			
	MOC :									
SB WI-72-1044 R03	BALANCE PISTON - REPLACE			RECOMMENDED			CSI			
E1										
	MOC :									
SB WI-72-1044 R03	BALANCE PISTON - REPLACE			RECOMMENDED			CSI			
E2										
	MOC :									
SB WI-72-1044	ENGINE - BALANCE PISTON - REPLACE			MTH			-			
E1										
	MOC :									
SB WI-72-1044	ENGINE - BALANCE PISTON - REPLACE			MTH			-			
E2										
	MOC :									
SL WI-72-1032-CN	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL									
E1				CANCELLED			-			
	MOC :									
SL WI-72-1032-CN	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL									
E2				CANCELLED			-			
	MOC :									
SL WI-72-1128	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL									
E1							-			
	MOC :									
SL WI-72-1128	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL									
E2							-			
	MOC :									
SL WI-72-1132-CN	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL									
E1				CANCELLED			-			
	MOC :									
SL WI-72-1132-CN	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL									
E2				CANCELLED			-			
	MOC :									
SL WI-72-1132	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL									
E1							-			
	MOC :									
SL WI-72-1132	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL									
E2							-			
	MOC :									
SL WI-72-1140	INDUCTION HEATING - REVISION TO ENGINE MANUAL									
E1							-			
	MOC :									
SL WI-72-1140	INDUCTION HEATING - REVISION TO ENGINE MANUAL									
E2							-			
	MOC :									
SL WI-72-1262	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL									
E1							-			
	MOC :									
SL WI-72-1262	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL									
E2							-			
	MOC :									
SB 525B-73-01	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT (FCU) FIELD REPLACEMENT									
				OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525B-73-02 LEFT 73SL-02	TRANSMITTAL OF WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-73-030R1, ENGINE AND FUEL CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06	ICT		RECOMMENDED MTH HRS	05-Apr-2009 605		A/R			Complete
MOC : COMPLIED WITH										
SL 525B-73-02 RIGHT 73SL-02	TRANSMITTAL OF WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-73-030R1, ENGINE AND FUEL CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06	ICT		RECOMMENDED MTH HRS	05-Apr-2009 605		A/R			Complete
MOC : COMPLIED WITH										
SB FJ44-73-030 R08 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R09)			MANDATORY			-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH SL525B-73-02 ON 04/05/2009.										
SB FJ44-73-030 R08 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R09)			MANDATORY			-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH SL525B-73-02 ON 04/05/2009										
SB FJ44-73-030 R09 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R10)	KMYF		MANDATORY MTH HRS LDG	03-Aug-2012 1485 876		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH AT ICT APRIL 05 2009.										
SB FJ44-73-030 R09 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R10)			MANDATORY			-			
MOC :										
SB FJ44-73-030 R12 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R13)	KMYF		MANDATORY MTH HRS LDG	03-Aug-2012 1485 876		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH BY ICT ON APRIL 5 2009										
SB FJ44-73-030 R13 E1	CANCELLED - ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06			CANCELLED			-			
MOC :										
SB FJ44-73-030 R13 E2	CANCELLED - ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06			CANCELLED			-			
MOC :										
SB FJ44-73-038 R03 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R04)			MANDATORY MTH			-			
MOC :										
SB FJ44-73-038 R03 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R04)			MANDATORY MTH			-			
MOC :										
SB FJ44-73-038 R04 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R05)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R04 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R05)			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-038 R05 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R06)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R05 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R06)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R06 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R07)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R06 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R07)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R07 E1	DUAL CHANNEL FADEC - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-73-038 R07 E2	DUAL CHANNEL FADEC - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-73-039 R02 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03)			MANDATORY			A/R			
MOC :										
SB FJ44-73-039 R02 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03)			MANDATORY			A/R			
MOC :										
SB FJ44-73-042 R03 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R03 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R04 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R04 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R05 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE	UNK		RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										
SB FJ44-73-042 R05 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE	UNK		RECOMMENDED	MTH 18-Aug-2014 HRS 2033 LDG 1264		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-043 R02 E1	ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD RECOMMENDED						-			
MOC :										
SB FJ44-73-043 R02 E2	ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD RECOMMENDED						-			
MOC :										
SB FJ44-73-044 R02 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R03)	KIWA		MANDATORY	MTH 15-Jan-2013 HRS 1569.8 LDG 936		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH "NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACEMENT" I.A.W. WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-73-044 R2.										
SB FJ44-73-044 R02 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R03)	KIWA		MANDATORY	MTH 15-Jan-2013 HRS 1569.8 LDG 936		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH "NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACEMENT" I.A.W. WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-73-044 R2.										
SB FJ44-73-044 R07 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE MANDATORY						-			
MOC :										
SB FJ44-73-044 R07 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE MANDATORY						-			
MOC :										
SB FJ44-73-044 R08 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE ICT			MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			Complete
MOC : COMPLIED WITH - PCW PER PART NUMBER INSTALLED.										
SB FJ44-73-044 R08 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE ICT			MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			Complete
MOC : COMPLIED WITH - PCW PER PART NUMBER INSTALLED.										
SB FJ44-73-044 R09 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE MANDATORY						-			
MOC :										
SB FJ44-73-044 R09 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE MANDATORY						-			
MOC :										
SB FJ44-73-061 E1	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) RECOMMENDED						-			
MOC :										
SB FJ44-73-061 E2	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) RECOMMENDED						-			
MOC :										
PSID WI-73-1008 R01 E1	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
PSID WI-73-1008 R01 E2	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG									
							-			
	MOC :									
SB WI-73-1002 R02 CANCELLED -CN E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
				CANCELLED			-			
	MOC :									
SB WI-73-1002 R02 CANCELLED -CN E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
				CANCELLED			-			
	MOC :									
SB WI-73-1002 R02 ENGINE FUEL AND CONTROL -CN E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)									
	LNK	MANDATORY	MTH	27-Feb-2018			-			Complete
			HRS	2770.4						
			LDG	1946						
	MOC : COMPLIED WITH									
SB WI-73-1002 R02 ENGINE FUEL AND CONTROL -CN E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)									
	LNK	MANDATORY	MTH	27-Feb-2018			-			Complete
			HRS	2770.4						
			LDG	1946						
	MOC : COMPLIED WITH									
SB WI-73-1007 R01 ENGINE FUEL AND CONTROL -CN E1	ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)									
							-			
	MOC :									
SB WI-73-1007 R01 ENGINE FUEL AND CONTROL -CN E2	ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)									
							-			
	MOC :									
SB WI-73-1008 R01 ENGINE FUEL AND CONTROL -CN E1	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED			-			
	MOC :									
SB WI-73-1008 R01 ENGINE FUEL AND CONTROL -CN E2	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED			-			
	MOC :									
SB WI-73-1008 R02 ENGINE FUEL AND CONTROL -CN E1	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED	MTH		DUE			
							DUE			
	MOC :									
SB WI-73-1008 R02 ENGINE FUEL AND CONTROL -CN E2	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED	MTH		DUE			
							DUE			
	MOC :									
SB WI-73-1008 R03 ENGINE FUEL AND CONTROL -CN E1	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED			-			
	MOC :									
SB WI-73-1008 R03 ENGINE FUEL AND CONTROL -CN E2	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED			-			
	MOC :									
SB WI-73-1008 R04 ENGINE FUEL AND CONTROL -CN E1	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED			-			
	MOC :									
SB WI-73-1008 R04 ENGINE FUEL AND CONTROL -CN E2	OIL COOLER TO FDU FUEL TUBE - REPLACE									
				RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-73-1008 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE MOC :			RECOMMENDED			-			
SB WI-73-1008 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE MOC :			RECOMMENDED			-			
SB WI-73-1009 R01 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :						-			
SB WI-73-1009 R01 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :						-			
SB WI-73-1009 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :						-			
SB WI-73-1009 R02 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :						-			
SB WI-73-1009 R03 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :						-			
SB WI-73-1009 R03 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :						-			
SB WI-73-1009 R04 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :			RECOMMENDED MTH			CSI CSI			
SB WI-73-1009 R04 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :			RECOMMENDED MTH			CSI CSI			
SB WI-73-1009 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :			RECOMMENDED			-			
SB WI-73-1009 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE MOC :			RECOMMENDED			-			
SB WI-73-1019-CN E1	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022) MOC :			SUPERSEDED			-			
SB WI-73-1019-CN E2	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022) MOC :			SUPERSEDED			-			
SB WI-73-1019 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022) MOC :						-			
SB WI-73-1019 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022) MOC :						-			
SB WI-73-1022 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 MOC :			NOT APPLICABLE			-			



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-73-1022 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01			NOT APPLICABLE			-			
	MOC :									
SB WI-73-1027 R01 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB WI-73-1027 R01 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB WI-73-1027 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB WI-73-1027 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB WI-73-1031 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01						-			
	MOC :									
SB WI-73-1031 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01						-			
	MOC :									
SL WI-73-1018-CN E1	CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG			CANCELLED			-			
	MOC :									
SL WI-73-1018-CN E2	CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG			CANCELLED			-			
	MOC :									
SL WI-73-1018 E1	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG						-			
	MOC :									
SL WI-73-1018 E2	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG						-			
	MOC :									
SL WI-73-1026 E1	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-73-1026 E2	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-73-1037 E1	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-73-1037 E2	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SB WI-74-1000 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	KICT		MANDATORY	MTH 08-Oct-2018 HRS 2917.5 LDG 2043		-			Complete
	MOC :									
	COMPLIED WITH - ACCOMPLISHED #1 ENGINE - IGNITION - IGNITER LEAD INSPECTION & CLAMPING ARRANGEMENT PER WISB-74-1000.									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-74-1000 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT KICT	MANDATORY	MTH 08-Oct-2018 HRS 2917.5 LDG 2043			-				Complete
MOC : COMPLIED WITH - ACCOMPLISHED #2 ENGINE - IGNITION - IGNITER LEAD INSPECTION & CLAMPING ARRANGEMENT PER WISB-74-1000.										
SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1		RECOMMENDED				-				
MOC :										
SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2		RECOMMENDED				-				
MOC :										
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1		RECOMMENDED	MTH HRS			-			(5000)5000	1352.5
MOC :										
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2		RECOMMENDED	MTH HRS			-			(5000)5000	1352.5
MOC :										
SB WI-75-1001 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE	RECOMMENDED				-				
MOC :										
SB WI-75-1001 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE	RECOMMENDED				-				
MOC :										
SB 525B-76-02	ENGINE CONTROLS - REMOVAL OF TRIM BOX WIRING OPTIONAL					A/R				
MOC :										
SB 525B-76-03 R01 ENGINE CONTROLS - FADEC CONNECTOR WASHER REMOVAL KMYF		RECOMMENDED	MTH 22-Jun-2011 HRS 1173.2 LDG 668			A/R				Complete
MOC : COMPLIED WITH - IAW THE SB COMPLIED WITH SB525B-76-03RI FADEC CONNECTOR WASHER REMOVAL.WORK PERFORMED I.A.W. SB INSTRUCTIONS.										
SB 525B-76-04	ENGINE CONTROLS - UPDATED FJ44-3A FULL AUTHORITY ENGINE CONTROL (FADEC) FIELD REPLACEMENT OPTIONAL					-				
MOC :										
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL CANCELLED					-				
MOC :										
SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL CANCELLED					-				
MOC :										
SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL					-				
MOC :										
SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL					-				
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-009 R01 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY SB FJ44-77-011 R18)			RECOMMENDED			-			N/A
	MOC : NOT APPLICABLE - DUE TO 115520 HARNESS ALREADY INSTALLED.									
SB FJ44-77-009 R01 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY SB FJ44-77-011 R18)			RECOMMENDED			-			N/A
	MOC : NOT APPLICABLE - DUE TO 115520 HARNESS ALREADY INSTALLED									
SB FJ44-77-011 R18 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION	ICT		MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			Complete
	MOC : COMPLIED WITH - CW DUE TO EARLIER REVISION HAS BEEN PCW.									
SB FJ44-77-011 R18 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION	ICT		MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			Complete
	MOC : COMPLIED WITH - CW DUE TO EARLIER REVISION HAS BEEN PCW.									
SB FJ44-77-011 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R01)	KMYF		SUPERSEDED	MTH 11-Aug-2016 HRS 2350.4 LDG 1637		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB FJ44-77-011 ON LEFT ENGINE. NO DEFECTS FOUND. WORK PERFORMED IAW SB INSTRUCTIONS.									
SB FJ44-77-011 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R01)	KMYF		SUPERSEDED	MTH 11-Aug-2016 HRS 2350.4 LDG 1637		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SBFJ44-77-011 IAW SB INSTRUCTIONS. NO DEFECTS FOUND.									
SB FJ44-77-013 R01 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-77-013 R01 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-77-013 R02 E1	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)			RECOMMENDED	MTH		-			
	MOC :									
SB FJ44-77-013 R02 E2	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)			RECOMMENDED	MTH		-			
	MOC :									
SB FJ44-77-013 R04 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
	MOC :									
SB FJ44-77-013 R04 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-013 R05 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R05 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R06 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R06 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R07 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R07 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R09 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED	MTH HRS		-		(5000)5000	1352.5
MOC :										
SB FJ44-77-013 R09 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED	MTH HRS		-		(5000)5000	1352.5
MOC :										
SB FJ44-77-013 E1	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 E2	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-009 R02 E1	ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-009 R02 E2	ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-009 R05 E1	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-79-009 R05 E2	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE	KIWA		MANDATORY			-			
MOC :										
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE	KIWA		MANDATORY			-			
MOC :										
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R05 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE	ICT		MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE	ICT		MANDATORY	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-79-013 R02 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R02 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R03 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)						-			
MOC :										
SB FJ44-79-013 R03 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)						-			
MOC :										
SB FJ44-79-013 R05 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE	ICT		RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-79-013 R05 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE	ICT		RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-T017 R01 E1	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST	ICT		RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SB FJ44-79-T017 R01 E2	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST	ICT		RECOMMENDED	MTH 22-Nov-2021 HRS 3327.4 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA PER ENGINE SERIAL NUMBER.										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2003-26-06	ANJUA AERONAUTIQUE SAFETY BELT AND RESTRAINT SYSTEMS (FORMERLY TRW REPA S.A., FORMERLY L'AIGLON)	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2012-08-07	2012-08-07	LNK			MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
AD 2007-19-12	SICMA AERO SEATS - 50XXX	LNK			MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 1974-20-10	EMERGENCY LOCATOR TRANSMITTER LEIGH SYSTEMS SHARC 7 SERIES	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 1990-09-08	IPECO TSO-C39A CREW SEATS	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 1998-25-10 R01 25AD-01 : 525R1	APPLIANCE AD - AIRCRAFT BELTS INC	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2005-07-27	AVIOINTERIORS S.P.A. SERIES 312 SEATS	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2005-20-26	AVIOINTERIORS S.P.A. (FORMERLY ALVEN), SERIES 312 BOX MOUNTED SEATS	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2006-17-13	RECARO AIRCRAFT SEATING GMBH & CO. (RECARO) MODEL 3410 SEATS	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2006-25-15	SICMA AERO SEAT: AMENDMENT 39-14856. DOCKET NO. FAA-2005-22959; DIRECTORATE IDENTIFIER 2005-NE-40-AD	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2007-04-15	SICMA AERO PASSENGER SEAT ASSEMBLIES. INSTALLED ON BUT NOT LIMITED TO AIRBUS A300, A310, A318, A319, A320, A321, A330, AND A340 SERIES AIRPLANES.	LNK	AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2010-02-06 (1)	VISUAL INSPECTION, TEMPORARY REPAIR, REPLACEMENT OF CENTRAL SPREADERS	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2010-02-06 (2)	INSTALL DOUBLERS ON NEW CENTRAL SPREADERS	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2010-02-06	SICMA AERO SEAT 90XX AND 92XX SERIES PASSENGER SEATS, INSTALLED ON, BUT NOT LIMITED TO ATR-GIE AVIONS DE TRANSPORT REGIONAL MODEL ATR42 AIRPLANES AND MODEL ATR72 AIRPLANES	LNK	AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2011-21-05	APPLIANCE AD - AVIOINTERIORS S.P.A. PASSENGER SEATS 12M()-(())(())()	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2011-21-08	APPLIANCE AD - SICMA AERO SEAT 88XX, 89XX, 90XX, 91XX, 92XX, 93XX, 95XX, AND 96XX SERIES PASSENGER SEAT ASSEMBLIES	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KICT	MANDATORY	MTH 01-Jun-2017 HRS 2562.3 LDG 1807 ACH 976.3		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-02 (G) GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-0002000-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2 EFFECTIVE DATE JUNE 12, 2015. THIS AD IS NOT APPLICABLE DUE TO AFFECTED SEATS ARE NOT INSTALLED.									
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KICT	MANDATORY	MTH 01-Jun-2017 HRS 2562.3 LDG 1807 ACH 976.3		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-02 (H) CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK EFFECTIVE DATE JUNE 12, 2015. THIS AD IS NOT APPLICABLE DUE TO AFFECTED SEATS ARE NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KICT	MANDATORY	MTH 01-Jun-2017 HRS 2562.3 LDG 1807 ACH 976.3		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-02 (I) REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2 EFFECTIVE DATE JUNE 12, 2015. THIS AD IS NOT APPLICABLE DUE TO AFFECTED SEATS ARE NOT INSTALLED.									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KICT	MANDATORY	MTH 01-Jun-2017 HRS 2562.3 LDG 1807 ACH 976.3		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-02 EQUIPMENT / FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION / REPLACEMENT EFFECTIVE DATE JUNE 12, 2015. THIS AD IS NOT APPLICABLE DUE TO AFFECTED SEATS ARE NOT INSTALLED.									
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	LNK		MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2017-22-02	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2018-19-15	EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2018-23-01 PARA (G)	INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)	PVU		MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2018-23-01 PARA (H)	INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2019-07-03 PARA (G)	REMOVE THE SEAT FROM THE AIRCRAFT AND PERFORM A DETAILED VISUAL INSPECTION; IF CORROSION OR OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT OR BEFORE (RE)INSTALLATION OF THE SEAT ON AN AIRCRAFT, AS APPLICABLE, REPAIR THE SEAT	PVU		MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2019-07-03 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEAT THAT HAS ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON ANY AIRCRAFT, UNLESS IT HAS PASSED AN INSPECTION IAW THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.B., OF ZODIAC SEATS FRANCE SB NO. 536-25-002, REVISION 3, DATED NOVEMBER 2, 2016	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2019-07-03 PARA (I)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.A., OF ZODIAC SEATS FRANCE SB NO. 536-25-004, REV. 0, DATED OCTOBER 19, 2017, CONSTITUTES A TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2019-07-03	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-08-01 PARA (G)	MODIFY THE AFFECTED PASSENGER SEAT AND RE-IDENTIFY EACH MODIFIED PASSENGER SEAT	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-08-01 PARA (H)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED RECARO MODEL PASSENGER SEAT ON ANY AIRCRAFT, UNLESS THE SEAT HAS BEEN MODIFIED AND RE-IDENTIFIED IN ACCORDANCE WITH PARAGRAPH (G)(2), (3), OR (4) OF THIS AD	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-08-01	APPLIANCE AD - EQUIPEMENT AND FURNISHINGS - MODIFICATION AND RE-IDENTIFICATION OF ALL AFFECTED RECARO AIRCRAFT SEATING GMBH & CO. KG MODEL PASSENGER SEATS	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-21-06 PARA (G)(1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (RESTATEMENT OF FAA 2017-22-02)	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-21-06 PARA (G)(2)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)	PVU			MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-21-06 PARA (G)(3)	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO AT TECHNICALSUPPORT@IPECO.COM	PVU		MANDATORY	DAYS 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-21-06 PARA (H)	DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C)(1)(I) OF THIS AD UNLESS THE SEAT IS MODIFIED AND RE-IDENTIFIED AS SPECIFIED IN PARAGRAPH (G)(1) OF THIS AD	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-21-06 PARA (H)	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-21-09 PARA (G)	INSPECT THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY; IF, DURING THE INSPECTION A LIFE VEST POUCH VELCRO STRIP IS FOUND DAMAGED OR WORN OR A LIFE VEST POUCH INSTALLATION IS NOT FOUND ACCEPTABLE, BEFORE FURTHER FLIGHT, REMOVE THE LIFE VEST POUCH FROM SERVICE AND REPLACE IT WITH A PART ELIGIBLE FOR INSTALLATION	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-21-09 PARA (I)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AVIOINTERIORS CENTAURUS ECONOMY CLASS PASSENGER SEAT WITH A P/N IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY HAS BEEN INSPECTED IN ACCORDANCE WITH PARAGRAPH (G)(1) OF THIS AD	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-21-09	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION / REPLACEMENT	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KHMZ		MANDATORY	MTH 27-May-2021		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE. THE AIRCRAFT SEATBELTS HAVE THE BLUE LOGO BUTTON.										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KHMZ		MANDATORY	MTH 27-May-2021		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE. THE AIRCRAFT SEATBELTS HAVE THE BLUE LOGO BUTTON.										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	KHMZ		MANDATORY	MTH 27-May-2021		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE. THE AIRCRAFT SEATBELTS HAVE THE BLUE LOGO BUTTON.										
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	KHMZ		MANDATORY	MTH 27-May-2021 HRS 3268.2 LDG 2260		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE. THE AIRCRAFT SEATBELTS HAVE THE BLUE LOGO BUTTON.										
FAA 2005-17-11 26AD-01	PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2010-04-16 PARA (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2010-04-16	TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2015-16-04	APPLIANCE AD - FIRE PROTECTION - MODIFY ALL KIDDE GRAVINER HAND-OPERATED FIRE EXTINGUISHERS HAVING PART NUMBERS 56412-001 (34H), 56411-001 (35H), AND 56412-002 (38H)	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2017-19-05 PARA (F)(1)	INSPECT EACH SIEMENS SMOKE DETECTOR, OR REVIEW YOUR MAINTENANCE RECORDS, TO DETERMINE IF AN AFFECTED DETECTOR IS INSTALLED	LNK		MANDATORY	DAYS 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2017-19-05 PARA (F)(2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURES 2 AND 3	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2017-19-05 PARA (F)(2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURE 4	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2017-19-05 PARA (F)(2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN PARAGRAPH (C)(2), SPECIFIED FIGURE 1	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-19-05 PARA (G)	DO NOT INSTALL ON ANY AIRPLANE A SMOKE DETECTOR WITH A MANUFACTURING DATE AND P/N LISTED IN FIGURE 2 OR 3 OR LISTED IN FIGURE 4 TO PARAGRAPH (F) OF THIS AD UNLESS THE DETECTOR IS MARKED "SIL PMC-26-002"	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2017-19-05	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2020-21-02	APPLIANCE AD - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2021-22-07	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT	PVU		MANDATORY	DAYS 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2022-01-03	APPLIANCE AD - FIRE PROTECTION - HAND-HELD FIRE EXTINGUISHERS - REPLACEMENT	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06)			MANDATORY			-			
MOC :										
FAA 2020-24-06	FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM - DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT			MANDATORY	MTH 22-Nov-2021 HRS 3334.6 LDG 2292		-			N/A
MOC : NOT APPLICABLE - NA DUE TO EQUIPMENT NOT INSTALLED.										
FAA 2008-19-01	APPLIANCE AD - HARCO LABS, INC. PITOT/AOA PROBES (PART NUMBERS 100435-39, 100435-39-001, 100435-40, AND 100435-40-001)						-			
MOC :										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	KBFL		MANDATORY	MTH 28-Dec-2021 HRS 3342.6 LDG 2301		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2021-23-12 DATED 12/9/21 BY REVISING THE LIMITATIONS SECTION OF THE AFM BY INCORPORATING THE LIMITATIONS SPECIFIED IN PARAGRAPH (G) OF AD.										
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)	KSBA		MANDATORY	MTH 12-Jul-2023 HRS 3620 LDG 2528		-			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	KSBA		MANDATORY	MTH 12-Jul-2023 HRS 3620 LDG 2528		-			Complete
MOC : COMPLIED WITH - INSERTED REQUIRED PLACARD IN AFM										
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	KSBA		MANDATORY	MTH 12-Jul-2023 HRS 3620 LDG 2528		-			Complete
MOC : COMPLIED WITH										
FAA 2006-18-08	APPLIANCE AD - GOODYEAR AVIATION TIRES, PART NUMBER 217K22-1, INSTALLED ON VARIOUS TRANSPORT CATEGORY AIRPLANES	LNK		AIRWORTHINESS	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 1995-22-01	APPLIANCE AD - AEROSPACE LIGHTING POWER UNIT	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 1997-05-03 R01 34AD-01 : 525R1	APPLIANCE AD - ALLIEDSIGNAL GNS-XLS & GNS-XL	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 1998-25-02 34AD-02 : 525	APPLIANCE AD - BFGOODRICH SKYWATCH SKY497	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2001-23-17 34AD-03 : 525A	APPLIANCE AD - GARMIN GNS 430	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2002-20-09 31AD-01 : 525A	APPLIANCE AD - COLLINS AFD-3010 AFD UNITS	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			Complete
MOC : COMPLIED WITH										
FAA 2004-08-15 34AD-02 : 525A	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2004-10-15 34AD-04 : 525A	APPLIANCE AD - GTX330/330D SOFTWARE UPGRADE	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			Complete
MOC : COMPLIED WITH										
FAA 2009-05-05	TO PREVENT CERTAIN CONDITIONS FROM EXISTING WHEN PFDS DISPLAY INCORRECT ATTITUDE, ALTITUDE, AND AIRSPEED INFORMATION	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2009-05-08	TRIMBLE OR FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUS GLOBAL POSITIONING SYSTEM (GPS) NAVIGATION SYSTEMS	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2009-08-01	TO PREVENT A SHIFT IN THE FMS COMPUTED POSITION	MTH	27-Feb-2018							N/A
	LNK	MANDATORY	HRS 2770.4							
			LDG 1946							
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	MTH	27-Feb-2018			A/R				N/A
	LNK	MANDATORY	HRS 2770.4							
			LDG 1946							
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2010-09-04	HONEYWELL INTERNATIONAL INC., PRIMUS EPIC AND PRIMUS APEX FLIGHTMANAGEMENT SYSTEMS, INSTALLED ON, BUT NOT LIMITED TO, EMPRESA BRASILEIRA DE AERONAUTICA S.A. (EMBRAER) MODEL ERJ 170 AND ERJ 190 AIRPLANES, AND PILATUS AIRCRAFT LTD. MODEL PC-12/47E AIRPLANES	MTH	27-Feb-2018							N/A
	LNK	AIRWORTHINESS	HRS 2770.4							
			LDG 1946							
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	MTH	24-Feb-2015							N/A
	KMYF	MANDATORY	HRS 2141.9							
			LDG 1360							
MOC : NOT APPLICABLE - AD 2012-02-08 AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS IS NOTAPPLICABLE TO THE HARDWARE INSTALLED IN THIS AIRCRAFT.										
FAA 2012-14-15 (G)	INCORPORATE LANGUAGE INTO THE LIMITATIONS SECTION OF THE AIRCRAFT FLIGHT MANUAL	MTH	27-Feb-2018							N/A
	LNK	MANDATORY	HRS 2770.4							
			LDG 1946							
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2012-14-15 (H)	FABRICATE AND INSTALL A PLACARD	DAYS	27-Feb-2018							N/A
	LNK	MANDATORY	HRS 2770.4							
			LDG 1946							
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2012-14-15	AIRWORTHINESS DIRECTIVES; HONEYWELL INTERNATIONAL, INC. GLOBAL NAVIGATION SATELLITE SENSORUNITS	MTH	27-Feb-2018							N/A
	LNK		HRS 2770.4							
			LDG 1946							
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	MTH	08-Oct-2014							Complete
	KIWA	MANDATORY	HRS 2097.2							
			LDG 1307							
MOC : COMPLIED WITH - COMPLIED WITH FAA AD2014-18-01 BY VERIFYING THE PROPER TYPE CODE STRAPPING.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	MTH	01-Jun-2017							N/A
	KICT	MANDATORY	HRS 2562.3							
			LDG 1807							
			ACH 976.3							
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-51-E AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD) - INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS, EFFECTIVE DATE JULY 1, 2015. THIS AD IS NOT APPLICABLE DUE TO AFFECTED DISPLAYS ARE NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	KICT	MANDATORY	MTH 01-Jun-2017 HRS 2562.3 LDG 1807 ACH 976.3		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-51 AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD) - INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS, EFFECTIVE DATE JULY 1, 2015. THIS AD IS NOT APPLICABLE DUE TO AFFECTED DISPLAYS ARE NOT INSTALLED.									
FAA 2017-11-11	APPLIANCE AD - NAVWORX, INC, AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS - REMOVE, DISABLE, OR REVISE SOFTWARE TO BROADCAST A SIL OF 0	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			Complete
MOC : COMPLIED WITH - COMPONENTS NOT INSTALLED									
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2018-03-04 PARA (G)	DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED	PVU	MANDATORY	DAYS 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2018-03-04 PARA (H)(1)	REPLACE AFFECTED PITOT PROBES	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2018-03-04 PARA (H)(2)	DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2019-01-02 PARA (G)(1)	DISABLE THE AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN FUNCTION IN EACH UNIT	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2019-01-02 PARA (G)(2)	REVISE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT IN ACCORDANCE WITH PARAGRAPH 5.2.C OF SB2018-01	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-01-02	APPLIANCE AD - NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-07-10 PARA (F)(1)	REMOVE THE AHRS UNIT FROM SERVICE	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-07-10 PARA (F)(2)	REMOVAL FROM SERVICE OF P/N 145130-7100 TERMINATES THE REQUIREMENTS OF AD 2010-26-09 (75 FR 81424, DECEMBER 28, 2010)	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-07-10 PARA (F)(3)	DO NOT INSTALL AN AHRS UNIT P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, OR 145130-7100 ON ANY AIRCRAFT	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-07-10	APPLIANCE AD - NAVIGATION - LITEF ATTITUDE HEADING AND REFERENCE SYSTEM (AHRS) - REMOVAL	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-12-09	APPLIANCE AD - NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)			SUPERSEDED	DAYS 11-Sep-2019 HRS 3092.2 LDG 2143		-			Complete
MOC : COMPLIED WITH - SOFTWARE INSTALLED HAS BEEN TESTED IN ACCORDANCE WITH BHE & ASSOCIATES, LTD. SERVICE BULLETIN 560-00-0165 REV A, 12AUG2019, SECTION 3.7. ALL CHECKED SATISFACTORY. THIS UPDATE LIFTS RESTRICTIONS DIRECTED BY AIRWORTHINESS DIRECTIVE 2019-12-09										
FAA 2019-13-03 PARA (G)	INSPECT THE TRANSPONDER INSTALLATION TO DETERMINE IF THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK	PVU		MANDATORY	DAYS 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-13-03 PARA (H)	DO NOT INSTALL AN AFFECTED TRANSPONDER ON ANY AIRCRAFT, UNLESS THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK AS DEFINED IN THIS AD	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2019-13-03	APPLIANCE AD - TRIG AVIONICS LTD. - NAVIGATION - TRANSPONDERS INSTALLATION - INSPECTION / MODIFICATION	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2020-10-05 PARA (G)	DISABLE TEMPERATURE COMPENSATION	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2020-10-05 PARA (H)	REVISE THE AIRPLANE FLIGHT MANUAL LIMITATIONS	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2020-16-08	APPLIANCE AD - ASPEN AVIONICS, INC. - EFD1000 FLIGHT DISPLAY SYSTEMS - AIRPLANE FLIGHT MANUAL - REVISION	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2020-18-51	APPLIANCE AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2021-05-17 PARA (G)(1) & (G) (2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)	UNK		MANDATORY	MTH 25-Mar-2021 HRS 3247.2 LDG 2241		-			N/A
MOC : NOT APPLICABLE - FDSA - 6500 PART NUMBERS NOT INSTALLED. BHE ASSOCIATES FUSION INSTALLED										
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE	UNK		MANDATORY	MTH 25-Mar-2021 HRS 3247.2 LDG 2241		-			N/A
MOC : NOT APPLICABLE - FDSA - 6500 PART NUMBERS NOT INSTALLED. BHE ASSOCIATES FUSION INSTALLED										
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE	UNK		MANDATORY	MTH 25-Mar-2021 HRS 3247.2 LDG 2241		-			N/A
MOC : NOT APPLICABLE - FDSA - 6500 PART NUMBERS NOT INSTALLED. BHE ASSOCIATES FUSION INSTALLED										
FAA 2021-05-17	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITATIONS / SOFTWARE UPGRADE	UNK		MANDATORY	MTH 25-Mar-2021 HRS 3247.2 LDG 2241		-			N/A
MOC : NOT APPLICABLE - FDSA - 6500 PART NUMBERS NOT INSTALLED. BHE ASSOCIATES FUSION INSTALLED										
FAA 2021-08-07 PARA (G)(1)	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A IAW AD PARAGRAPH (G) BY GPS P/N 822-2189-101 INSTALLED IN NO.1 AND NO.2 GPS RECEIVER POSITIONS. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-08-07 PARA (G)(2)	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A IAW AD PARAGRAPH (G) BY GPS P/N 822-2189-101 INSTALLED IN NO.1 AND NO.2 GPS RECEIVER POSITIONS. NO FURTHER ACTION REQUIRED.										
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A IAW AD PARAGRAPH (G) BY GPS P/N 822-2189-101 INSTALLED IN NO.1 AND NO.2 GPS RECEIVER POSITIONS. NO FURTHER ACTION REQUIRED.										
FAA 2021-08-15	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE	PVU		MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.										
AD 2007-26-11	INTERTECHNIQUE ZODIAC AIRCRAFT SYSTEMS: AMENDMENT 39-15313. DOCKET NO. FAA-2007-0374; DIRECTORATE IDENTIFIER 2007-SW-02-AD	LNK			MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 1999-08-21 35AD-01 : 525	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM C	ICT		MANDATORY	MTH 09-Oct-2006 HRS 10		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2009-21-10 R01	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN ASSEMBLIES INSTALLED IN THE AIRPLANE	LNK		MANDATORY	DAYS 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2010-11-05	INSPECT FOR AND REMOVE SUBSTANDARD OXYGEN CYLINDERS FROM AIRPLANE	LNK		MANDATORY	DAYS 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2011-01-09	B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) PART NUMBER 119003-11 INSTALLED ON VARIOUS TRANSPORT AIRPLANES	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2011-14-08	APPLIANCE AD - B/E AEROSPACE CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY	LNK		MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2011-14-08 EFFECTIVE DATE 19 AUG 2011 B/E AEROSPACE CONTINUOUS FLOW PASSENGER MASK IN-LINE FLOW INDICATORS BROKEN.										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KIWA	MANDATORY	MTH 19-Mar-2016 HRS 2258.3 LDG 1543		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2015-08-07 BY VERIFYING THAT EFFECTED O2 MASK HARNESSES ARE NOT INSTALLED ON THIS AIRCRAFT. REFERENCED INTERTECHNIQUE (ZODIAC AEROSPACE) SB MXH-35-240.									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KIWA	MANDATORY	MTH 19-Mar-2016 HRS 2258.3 LDG 1543		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2015-08-07 BY VERIFYING THAT EFFECTED O2 MASK HARNESSES ARE NOT INSTALLED ON THIS AIRCRAFT. REFERENCED INTERTECHNIQUE (ZODIAC AEROSPACE) SB MXH-35-240.									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KIWA	MANDATORY	MTH 19-Mar-2016 HRS 2258.3 LDG 1543		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2015-08-07 BY VERIFYING THAT EFFECTED O2 MASK HARNESSES ARE NOT INSTALLED ON THIS AIRCRAFT. REFERENCED INTERTECHNIQUE (ZODIAC AEROSPACE) SB MXH-35-240.									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KMYF	MANDATORY	MTH 17-Feb-2016 DAYS 2254.4 HRS 1534 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY PART NUMBER									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KMYF	MANDATORY	MTH 17-Feb-2016 DAYS 2254.4 HRS 1534 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY PART NUMBER									
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KMYF	MANDATORY	MTH 17-Feb-2016 DAYS 2254.4 HRS 1534 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY PART NUMBER									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KMYF	MANDATORY	MTH 17-Feb-2016 DAYS 2254.4 HRS 1534 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY PART NUMBER									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KMYF	MANDATORY	MTH 17-Feb-2016 HRS 2254.4 LDG 1534		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY PART NUMBER									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KMYF	MANDATORY	MTH 17-Feb-2016 HRS 2254.4 LDG 1534		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY PART NUMBER									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KIWA	MANDATORY	MTH 23-Nov-2016 HRS 2427.8 LDG 1700		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT PART NUMBER 119003-11 AMENDMENT 39-18547 EFFECTIVE DATE JULY 15, 2016 BY CONFIRMING THE EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT AT THIS TIME.									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KIWA	MANDATORY	MTH 23-Nov-2016 HRS 2427.8 LDG 1700		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT PART NUMBER 119003-11 AMENDMENT 39-18547 EFFECTIVE DATE JULY 15, 2016 BY CONFIRMING THE EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT AT THIS TIME.									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KIWA	MANDATORY	MTH 23-Nov-2016 HRS 2427.8 LDG 1700		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT PART NUMBER 119003-11 AMENDMENT 39-18547 EFFECTIVE DATE JULY 15, 2016 BY CONFIRMING THE EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT AT THIS TIME.									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KIWA	MANDATORY	MTH 23-Nov-2016 HRS 2427.8 LDG 1700		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT PART NUMBER 119003-11 AMENDMENT 39-18547 EFFECTIVE DATE JULY 15, 2016 BY CONFIRMING THE EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT AT THIS TIME.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE CREW MASKS P/N MC10-16-101 INSTALLED IN AIRCRAFT, IAW AD PARAGRAPH (G) PER ZODIAC AEROSPACE (SB) MC10-35-274 REV. 02 DATED JUNE 25 2014 P/N IS NOT LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A. (1). NO FURTHER ACTION REQUIRED									
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE CREW MASKS P/N MC10-16-101 INSTALLED IN AIRCRAFT, IAW AD PARAGRAPH (G) PER ZODIAC AEROSPACE (SB) MC10-35-274 REV. 02 DATED JUNE 25 2014 P/N IS NOT LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A. (1). NO FURTHER ACTION REQUIRED									
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE CREW MASKS P/N MC10-16-101 INSTALLED IN AIRCRAFT, IAW AD PARAGRAPH (G) PER ZODIAC AEROSPACE (SB) MC10-35-274 REV. 02 DATED JUNE 25 2014 P/N IS NOT LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A. (1). NO FURTHER ACTION REQUIRED									
FAA 2022-04-09 PARA (H) & (I)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF AN EFFECTED PART INSTALLED; IF INSTALLED, BEFORE FURTHER FLIGHT, DO A DETAILED INSPECTION FOR CORRECT SPACING OF THE GAP BETWEEN THE BOTTOM OF THE PACKING RETAINER AND TOP OF THE VALVE BODY AND PERFORM CORRECTIVE ACTIONS	PVU	MANDATORY	DAYS 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2022-04-09 PARA (J)	REPORT THE RESULTS OF THE INSPECTION	PVU	MANDATORY	DAYS 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2022-04-09	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECT / REPLACE	PVU	MANDATORY	MTH 25-Jun-2022 HRS 3443 LDG 2382		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 1990-07-08 R1	APPLIANCE AD - PREVENT SMOKE, FIRE, AND POSSIBLE ELECTRICAL SHOCK, OR ELECTROMAGNETIC INTERFERENCE TO FLIGHT CRITICAL OR ESSENTIAL SYSTEMS	LNK	MANDATORY	MTH 27-Feb-2018 HRS 2770.4 LDG 1946		-			N/A
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016				MTH 27-Feb-2018		-			N/A
		LNK		MANDATORY	HRS 2770.4					
					LDG 1946					
MOC : NOT APPLICABLE - COMPONENTS NOT INSTALLED										
FAA 2008-03-10	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE				MTH 11-Mar-2008		A/R			Complete
53AD-01		ICT		AIRWORTHINESS	HRS 329					
MOC : COMPLIED WITH										
FAA 2022-13-15	TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE				MTH		-			
E1				MANDATORY						
MOC :										
FAA 2022-13-15	TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE				MTH		-			
E2				MANDATORY						
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
00FO102	COCKPIT RELIEF TUBE FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			102 FO						
23FO188P 23FO188 : P	US AIRCRAFT PLACARDS FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			188P FO						
23FO36	LOCKING FUEL CAPS (EXCHANGE) FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			36 FO						
23FO501	MOBIL JET II OIL FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			501 FO						
23FO56E 23FO56 : E	PULSELIGHT SYSTEM(2401) W/INTERFACE TO TCAS II-PRECISE FL FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			56E FO						
23FO629S 23FO629 : S	WX-1000E LIGHTNING DETECTION L3 COMMUNICATIONS FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			629S FO						
23FO630D 23FO630 : D	BROADCAST GRAPHICAL WEATHER DISPLAY - COLLINS FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			630D FO						
23FO631	HF 9000 HIGH FREQUENCY COMM(PROV) COLLINS FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			631 FO						
23FO632G 23FO632 : G	SELCAL - COLLINS FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			632G FO						
23FO650	VOICE ANNUNCIATOR FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			650 FO						
23FO674D 23FO674 : D	PBS-250 PASGR BRIEFER - HEADSUP TECHNOLOGIES FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			674D FO						
23FO675G 23FO675 : G	AIRCELL ST-3100 FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			675G FO						
23FO675L 23FO675 : L	AIRCELL INTERCOM SWITCH FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			675L FO						
24FO186P 24FO186 : P	42 AMP HOUR LEAD ACID BATTERY CONCORDE (EX) FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			186P FO						
24FO655	ELECTRONIC CHARTS - JEPPESEN FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			655 FO						
25FO119E 25FO119 : E	SIDE FACING SEAT & CABINET FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			119E FO						
25FO130M 25FO130 : M	LEFT HAND BELTED TOILET FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			130M FO						
25FO634K 25FO634 : K	COCKPIT VOICE RECORDER FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			634K FO						
25FO729A 25FO729 : A	RAFFIA COLORED CKP/CABIN DOOR TRIM FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			729A FO						
27FO16C 27FO16 : C	STEEP APPROACH OPTION FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			16C FO						
34FO11A 34FO11 : A	PILOT'S ANGLE OF ATTACK INDEX-SAFELIGHT FACTORY OPTION				MTH 09-Oct-2006		-			
	*CF			11A FO						

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SUN AVIATION, LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0110**
Unit: **0110** Reg No: **N716NS**
Airworthiness: **09-Oct-2006**
Print Date: **26-Sep-2023 10:32AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3647.5	2546	25-Sep-2023	.4
ENG 1	3647.5	2546	25-Sep-2023	.4
ENG 2	3647.5	2546	25-Sep-2023	.4
AIR COND	1213.5		25-Sep-2023	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
34FO630B <i>34FO630 : B</i>	RTA-852 TURBULENCE DOPPLER RADAR - COLLINS (EX) FACTORY OPTION	*CF		630B FO	MTH 09-Oct-2006		-			
34FO635N <i>34FO635 : N</i>	TTR-4000 TCAS II COLLINS (EX) FACTORY OPTION	*CF		635N FO	MTH 09-Oct-2006		-			
34FO686Q <i>34FO686 : Q</i>	FMS 2 GARMIN GPS-500 FACTORY OPTION	*CF		686Q FO	MTH 09-Oct-2006		-			
34FO691H <i>34FO691 : H</i>	MARK VIII EGPWS -HONEYWELL (EX) FACTORY OPTION	*CF		691H FO	MTH 09-Oct-2006		-			
56FO900	REPL STND ENTRY DR STEPS W/BRAVO/ENCORE STYLE ENTR STPS FACTORY OPTION	*CF		900 FO	MTH 09-Oct-2006		-			