



DueList Report

PHENOM 300

S/N 50500547 N110AP

OWNER: SHOEAIR,LLC
ADDRESS: 2265 S RIVERBIRCH PLACE
IDAHO ID 83616

OPERATOR: SHOEAIR,LLC
ADDRESS: 2265 S RIVERBIRCH PLACE
IDAHO ID 83616

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: ALANE DORASCIENZI
EMAIL: ADORASCIENZI@CAMPSYSTEMS.COM

+1-514-636-2225 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PROJECTED: 6 MOS. to 25-DEC-2024

AIRCRAFT SERIAL/REGNO: 50500547/N110AP MODEL: PHENOM 300 MANUFACTURER: EMBRAER

CERTIFICATION DATE: 06-DEC-2019

LAST ACTUALS:

301.8 A/C HRS as of 19-DEC-2023
162 AFL as of 19-DEC-2023

PROJECTED:

392.05
204

ENGINE NO. 1 SERIAL/PART: PCE-DG1089/3072702 MODEL: PW535E MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 01-AUG-2019

LAST ACTUALS:

0 ENG. HRS 0 A/C HRS
0 ENC

303.5 ENG. HRS as of 07-JAN-2024
165 ENC as of 07-JAN-2024

PROJECTED:

393.75
207

ENGINE NO. 2 SERIAL/PART: PCE-DG1088/3072702 MODEL: PW535E MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 01-AUG-2019

LAST ACTUALS:

0 ENG. HRS 0 A/C HRS
0 ENC

303.5 ENG. HRS as of 07-JAN-2024
165 ENC as of 07-JAN-2024

PROJECTED:

393.75
207



Insufficient Items

Operator Review and Action Required

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023 Operator: SHOEAIR,LLC

Report Date: 25-Jun-2024

These tasks have insufficient information for calculating next due. Please provide the missing information (marked by ?) so that they can be setup properly. It is important to note that any task that has insufficient information, will not come due correctly unless the necessary information is provided by you.

PN & SN	Unit	Effective Date	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Disposition
35-02-01-004		RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER					Service ATA:35
	MOS	11-Jan-24	60			?	
	HRS						
	AFL						

ENTER MISSING DATE OF HYDROSTATIC CHECK _____

REF: AMM 35-02-01

Name: _____

Signature: _____

Cert.#: _____

Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



New Requirement/Flagged Items

Operator Review and Action Required

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023 Operator: SHOEAIR,LLC

Report Date: 25-Jun-2024

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
SB PW500-72-30579		NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SHIPPING CONTAINER, SERVICE BULLETIN					Bulletin ATA:72
	14-Jun-24	MOS	T:ESV	14-Jun-24	_____		CATEGORY 7
		HRS			_____		
		ENC			_____		
NEW REQUIREMENT ADDED ON 17-JUN-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: BULLETINS			
SB PW500-72-30579		NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SHIPPING CONTAINER, SERVICE BULLETIN					Bulletin ATA:72
	14-Jun-24	MOS	T:ESV	14-Jun-24	_____		CATEGORY 7
		HRS			_____		
		ENC			_____		
NEW REQUIREMENT ADDED ON 17-JUN-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: BULLETINS			

Name: _____ Signature: _____ Cert.# _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As
Of: 19-Dec-2023 Operator: SHOEAIR,LLC

Report Date: 25-Jun-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
24-36-01-005		FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015)						Service	ATA:24
PN:7639-34	MOS	6 (+1m/-1m)	Adj:-152d	19-Dec-23	19-Jan-24	19-Feb-24	OVD		
SN:G03166745	HRS			301.8					
	AFL			162					
REF: AMM 24-36-01									
FAA 2021-22-07		APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT						AD	ATA:26
	DAYS	180		19-Dec-23	16-Jun-24		OVD		
	HRS			301.8					
	AFL			162					
Disposition: MANDATORY REF: AD									
FAA 2023-21-04		INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.10 AVIONICS SOFTWARE AND CMC LOAD V5.20						AD	ATA:31
	MOS	T:6		EFF	11-Jun-24 *		OVD		
	HRS	T:300		EFF	629.57 *		327.8		
	AFL								
Disposition: MANDATORY REF: AD									
FAA 2023-22-11		REPLACEMENT OF THE AILERON AUTOPILOT SERVO MOUNT CLUTCH RETAINING BOLT AND WASHER						AD	ATA:22
	MOS	T:3		EFF	26-Mar-24 *		OVD		
	HRS	T:50		EFF	366.78 *		65		
	AFL								
Disposition: MANDATORY REF: AD									
24-36-01-005		FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)						Service	ATA:24
PN:7638-48P	MOS	6 (+1m/-1m)		19-Dec-23	19-Jun-24	19-Jul-24	TOL (+24 d)	25-Jun-2024(2)	
SN:G03208787	HRS			301.8					
	AFL			162					
REF: AMM 24-36-01									
25-62-01-001		VISUAL CHECK #1 FIRST AID KIT						Service	ATA:25
PN:019700-0001L	MOS	DUE		19-Dec-23	01-Sep-24 (M)		68 d	01-Sep-2024	
SN:UNKNOWN	HRS			301.8					
	AFL			162					
REF: AMM 25-62-01									
05-30-42		3200 FH/60 MO MAINTENANCE PACKAGE						Package	ATA:05
	MOS	60 (+1m/-1m)		06-Dec-19	06-Dec-24	06-Jan-25	164 d (+31)	06-Dec-2024	
	HRS	3200 (+30/-30)		0	3200	3230	2898.2 (+30)		
	AFL			0					
REF: SMR 05-30-42									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As
Of: 19-Dec-2023 Operator: SHOEAIR,LLC

Report Date: 25-Jun-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
05-30-84		60 MO MAINTENANCE PACKAGE						Package	ATA:05
	MOS	60 (+1m/-1m)		06-Dec-19	06-Dec-24	06-Jan-25	164 d (+31)	06-Dec-2024	
	HRS			0					
	AFL			0					
		REF: SMR 05-30-84							
34-15-00-002		SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS						Service	ATA:34
	MOS	60 (+1m/-1m)		06-Dec-19	06-Dec-24	06-Jan-25	164 d (+31)	06-Dec-2024	
	HRS			0					
	AFL			0					
		REF: AMM 34-15-00							
55-20-04-001		INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS						Service	ATA:55
	MOS	60		06-Dec-19	06-Dec-24		164 d	06-Dec-2024	
	HRS			0					
	AFL			0					
		REF: NDT PART 5 55-20-00							
Disposition: ALI									
55-20-04-002		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS						Service	ATA:55
	MOS	60		06-Dec-19	06-Dec-24		164 d	06-Dec-2024	
	HRS			0					
	AFL			0					
		REF: NDT PART 5 55-20-00							
Disposition: ALI									
55-40-04-002		INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS						Service	ATA:55
	MOS	60		06-Dec-19	06-Dec-24		164 d	06-Dec-2024	
	HRS			0					
	AFL			0					
		REF: NDT PART 5 55-40-00							
Disposition: ALI									
55-40-04-003		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS						Service	ATA:55
	MOS	60		06-Dec-19	06-Dec-24		164 d	06-Dec-2024	
	HRS			0					
	AFL			0					
		REF: NDT PART 5 55-40-00							
Disposition: ALI									
57-60-00-001		EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON						Service	ATA:57
	MOS	60		06-Dec-19	06-Dec-24		164 d	06-Dec-2024	
	HRS			0					
	AFL			0					
		REF: NDT PART 5 57-60-00							
Disposition: ALI									



Due List Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As
Of: 19-Dec-2023 Operator: SHOEAIR,LLC

Report Date: 25-Jun-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
SB 505-00-0026		GENERAL - W201 HARNESS ROUTING IMPROVEMENT, SERVICE BULLETIN						Bulletin ATA:00
	MOS	T:60			06-Dec-24 (M)		164 d	06-Dec-2024
	HRS							
	AFL							
Disposition: CATEGORY 02 - RECOMMENDED		REF: BULLETINS						
SB 505-55-0004 REV 01 PART II		ACCOMPLISH STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT, SERVICE BULLETIN AILERON MASS BALANCE AND ATTACHMENT PARTS REPLACEMENT						Bulletin ATA:55
	MOS	T:60		EFF	06-Dec-24 * (M)		164 d	06-Dec-2024
	HRS							
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
SB 505-55-0004 REV 01 PART III		ACCOMPLISH STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT, SERVICE BULLETIN RUDDER MASS BALANCE AND ATTACHMENT PARTS REPLACEMENT						Bulletin ATA:55
	MOS	T:60		EFF	06-Dec-24 * (M)		164 d	06-Dec-2024
	HRS							
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
051254		NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION						Package ATA:05
	MOS	12 (+30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024
	HRS	800 (+10%)		301.8	(1101.8)1100.1	1181.8	798.3 (+80)	
	ENC			162				
		REF: MM 05-20-00						
051254		NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION						Package ATA:05
	MOS	12 (+30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024
	HRS	800 (+10%)		301.8	(1101.8)1100.1	1181.8	798.3 (+80)	
	ENC			162				
		REF: MM 05-20-00						
22-11-00-001		FUNCTIONAL CHECK AILERON GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO						Service ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024
SN:1GK024921	HRS			301.8				
	AFL			162				
Disposition: AIRWORTHINESS		REF: AMM 22-11-00						
22-11-00-001		FUNCTIONAL CHECK ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO						Service ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024
SN:1GK026533	HRS			301.8				
	AFL			162				
Disposition: AIRWORTHINESS		REF: AMM 22-11-00						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As
Of: 19-Dec-2023 Operator: SHOEAIR,LLC

Report Date: 25-Jun-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
22-11-00-001		FUNCTIONAL CHECK RUDDER GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO						Service	ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024	
SN:1GK026554	HRS			301.8					
	AFL			162					
Disposition: AIRWORTHINESS		REF: AMM 22-11-00							
22-11-00-001		FUNCTIONAL CHECK TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT GSA 80 HIGH SPEED AUTOPILOT SERVO						Service	ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024	
SN:1GK026767	HRS			301.8					
	AFL			162					
Disposition: AIRWORTHINESS		REF: AMM 22-11-00							
25-61-00-001		OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM						Service	ATA:25
PN:S1821502-02	MOS	12		19-Dec-23	19-Dec-24		177 d	19-Dec-2024	
SN:LX1100862963	HRS			301.8					
	AFL			162					
		REF: AMM 25-61-00							
25-61-00-002		GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER						Service	ATA:25
PN:S1821502-02	MOS	12		19-Dec-23	19-Dec-24		177 d	19-Dec-2024	
SN:LX1100862963	HRS			301.8					
	AFL			162					
		REF: AMM 25-61-00							
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH BE AEROSPACE BATTERY)						Service	ATA:33
PN:7450LS-00	MOS	12		19-Dec-23	19-Dec-24		177 d	19-Dec-2024	
SN:00848M	HRS			301.8					
	AFL			162					
		REF: AMM 33-52-01							
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH BE AEROSPACE BATTERY)						Service	ATA:33
PN:7450LS-00	MOS	12		19-Dec-23	19-Dec-24		177 d	19-Dec-2024	
SN:005710	HRS			301.8					
	AFL			162					
		REF: AMM 33-52-01							
35-11-02-003		DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK						Service	ATA:35
PN:MC40-011	MOS	12 (+1m/-1m)		19-Dec-23	19-Dec-24	19-Jan-25	177 d (+31)	19-Dec-2024	
SN:B148094	HRS			301.8					
	AFL			162					
		REF: AMM 35-11-02							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As
Of: 19-Dec-2023 Operator: SHOEAIR,LLC

Report Date: 25-Jun-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
35-11-02-003		DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK							Service ATA:35
PN:MC40-011	MOS	12 (+1m/-1m)		19-Dec-23	19-Dec-24	19-Jan-25	177 d (+31)	19-Dec-2024	
SN:B148933	HRS			301.8					
	AFL			162					
REF: AMM 35-11-02									
71-00-00-760-823		NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	12 (+30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024	
	HRS	630 (+10%)		301.8	(931.8)930.1	994.8	628.3 (+63)		
	ENC			162					
REF: MM 71-00-00									
71-00-00-760-823		NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	12 (+30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024	
	HRS	630 (+10%)		301.8	(931.8)930.1	994.8	628.3 (+63)		
	ENC			162					
REF: MM 71-00-00									
72-00-02-810-801		NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	12		19-Dec-23	19-Dec-24		177 d	19-Dec-2024	
	HRS	630		301.8	(931.8)930.1		628.3		
	ENC			162					
REF: MM 72-00-02									
72-00-02-810-801		NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	12		19-Dec-23	19-Dec-24		177 d	19-Dec-2024	
	HRS	630		301.8	(931.8)930.1		628.3		
	ENC			162					
REF: MM 72-00-02									
73-10-05-212-801		NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	12 (+30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024	
	HRS			301.8					
	ENC			162					
REF: MM 73-10-05									
73-10-05-212-801		NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	12 (+30d)		19-Dec-23	19-Dec-24	18-Jan-25	177 d (+30)	19-Dec-2024	
	HRS			301.8					
	ENC			162					
REF: MM 73-10-05									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time