



Status Report

PHENOM 300

S/N 50500547 N110AP

OWNER: SHOEAIR,LLC
ADDRESS: 2265 S RIVERBIRCH PLACE
IDAHO ID 83616

OPERATOR: SHOEAIR,LLC
ADDRESS: 2265 S RIVERBIRCH PLACE
IDAHO ID 83616

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: ALANE DORASCIENZI
EMAIL: ADORASCIENZI@CAMPSYSTEMS.COM

+1-514-636-2225 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL / REGNO: 50500547/N110AP	MODEL: PHENOM 300	MANUFACTURER: EMBRAER
----------	---------------------------------	-------------------	-----------------------

CERTIFICATION DATE: 06-DEC-2019

LAST ACTUALS:
301.8 A/C HRS as of 19-DEC-2023
162 AFL as of 19-DEC-2023

ENGINE NO. 1	SERIAL / PART: PCE-DG1089/3072702	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
--------------	-----------------------------------	---------------	--

INSTALLED ON: 01-AUG-2019
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
303.5 ENG. HRS as of 07-JAN-2024
165 ENC as of 07-JAN-2024

ENGINE NO. 2	SERIAL / PART: PCE-DG1088/3072702	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
--------------	-----------------------------------	---------------	--

INSTALLED ON: 01-AUG-2019
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
303.5 ENG. HRS as of 07-JAN-2024
165 ENC as of 07-JAN-2024



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z210-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-41-00							PKG:87
Z210-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-41-00							PKG:87
Z220-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION							Service ATA:--
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-41-00							PKG:84
Z220-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-41-00							PKG:87
Z230-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:87
Z230-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:87
Z240-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z240-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION							Service ATA:--
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:84
Z310-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-43-00							PKG:87
Z310-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-43-00							PKG:87
Z320-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-43-00							PKG:87
Z320-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-43-00							PKG:87
Z330-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-44-00							PKG:87
Z330-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-44-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z340-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service ATA:--
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-44-00							PKG:84
Z340-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-44-00							PKG:87
Z410-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-46-00							PKG:87
Z410-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-46-00							PKG:87
Z430-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-46-00							PKG:87
Z430-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE							Service ATA:--
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-46-00							PKG:87
Z500-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service ATA:--
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-45-00							PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z500-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service ATA:--
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
				PROC. REF: AMM 05-45-00				PKG:84
Z700-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY							Service ATA:--
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
				PROC. REF: AMM 05-47-00				PKG:84
ATA 00 - INFORMATION								
00001	NO. 1 ENGINE - ADD CERT DATE							Service ATA:00
	MOS/MSC	31-Jul-19	-					
	HRS	0						
	ENC	0						
				PROC. REF: GENERIC NO REF				
00001	NO. 2 ENGINE - ADD CERT DATE							Service ATA:00
	MOS/MSC	31-Jul-19	-					
	HRS	0						
	ENC	0						
				PROC. REF: GENERIC NO REF				
EM55-210514-ALS	REVIEW EMBRAER PHENOM 300 - AMM - CHAPTER 04- REV. 14, DATED MAY 14TH, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
				PROC. REF: RCF 00				
EM55-211103-SMR	REVIEW EMBRAER PHENOM 300 - AMM 2757, SMR REV. 04, DATED NOV 3, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM55-220505-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED MAY 05/2022 FOR EMBRAER PHENOM 300							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-220630-CAMP ADJUSTMENT	REVIEW EMBRAER EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED JUN 30, 2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF -								
EM55-220812-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED AUG 12/2022 FOR MODEL EMB-505 - PHENOM 300							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-221017-AWL	REVIEW EMB-505 - PHENOM 300 AMM - PART IV - AIRWORTHINESS LIMITATIONS (AWL) REV 1 DATED OCT 17/2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-221103-SMR	REVIEW EMB-505 - PHENOM 300 AMM - PART III - SCHEDULE MAINTENANCE REQUIREMENTS (SMR) REV 5 DATED NOV 03/2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM55-230201-CAMP ADJUSTMENT	REVIEW EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED FEB 01, 2023							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
EM55-230216-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED FEB 16/2023 FOR EMB-505 - PHENOM 300							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-01	800 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)		800	830	498.2 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-01								PKG:1
051254	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	19-Dec-23	12 (+30d)		19-Dec-24	18-Jan-25	177 d (+30)	
	HRS	301.8	800 (+10%)		(1101.8) 1100.1	1181.8	798.3 (+80)	
	ENC	162						
PROC. REF: MM 05-20-00								PKG:1
051254	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	19-Dec-23	12 (+30d)		19-Dec-24	18-Jan-25	177 d (+30)	
	HRS	301.8	800 (+10%)		(1101.8) 1100.1	1181.8	798.3 (+80)	
	ENC	162						
PROC. REF: MM 05-20-00								PKG:1
05-30-10	1600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)		1600	1630	1298.2 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-10								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-20	2400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)		2400	2430	2098.2 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-20								PKG:20
05-30-40	3200 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19						
	HRS	0	3200 (+30/-30)		3200	3230	2898.2 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-40								PKG:40
05-30-42	3200 FH/60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19	60 (+1m/-1m)		06-Dec-24	06-Jan-25	164 d (+31)	
	HRS	0	3200 (+30/-30)		3200	3230	2898.2 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-42								PKG:42
05-30-50	5600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)		5600	5630	5298.2 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-50								PKG:50
05-30-60	6400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)		6400	6430	6098.2 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-60								PKG:60
05-30-80	12 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	19-Dec-23	12 (+1m/-1m)	Adj 24d	12-Jan-25	12-Feb-25	201 d (+31)	
	HRS	301.8						
	AFL	162						
PROC. REF: SMR 05-30-80								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-81	24 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	19-Dec-23	24 (+1m/-1m)	Adj 24d	12-Jan-26	12-Feb-26	566 d (+31)	
	HRS	301.8						
	AFL	162						
PROC. REF: SMR 05-30-81							PKG:81	
05-30-82	36 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	12-Jan-23	36 (+1m/-1m)	Adj -37d	06-Dec-25	06-Jan-26	529 d (+31)	
	HRS	221						
	AFL	108						
PROC. REF: SMR 05-30-82							PKG:82	
05-30-83	48 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	19-Dec-23	48 (+1m/-1m)	Adj -13d	06-Dec-27	06-Jan-28	1259 d (+31)	
	HRS	301.8						
	AFL	162						
PROC. REF: SMR 05-30-83							PKG:83	
05-30-84	60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19	60 (+1m/-1m)		06-Dec-24	06-Jan-25	164 d (+31)	
	HRS	0						
	AFL	0						
PROC. REF: SMR 05-30-84							PKG:84	
05-30-87	120 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19	120 (+1m/-1m)		06-Dec-29	06-Jan-30	1990 d (+31)	
	HRS	0						
	AFL	0						
PROC. REF: SMR 05-30-87							PKG:87	
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	06-Dec-19	T:120 (+1m/-1m)		06-Dec-29	06-Jan-30	1990 d (+31)	
	HRS	0						
	AFL	0						
PROC. REF: SMR 05-30-90							PKG:90	
05-50-00-210-802	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-802	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-803	NO. 1 ENGINE - ENGINE OVERTEMPERATURE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-803	NO. 2 ENGINE - ENGINE OVERTEMPERATURE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-804	NO. 1 ENGINE - ENGINE OVERSPEED							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-804	NO. 2 ENGINE - ENGINE OVERSPEED							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-805	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-805	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-806	NO. 1 ENGINE - LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-806	NO. 2 ENGINE - LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-807	NO. 1 ENGINE - DROPPED ENGINE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-807	NO. 2 ENGINE - DROPPED ENGINE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-808	NO. 1 ENGINE - HEAVY LANDING							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-808	NO. 2 ENGINE - HEAVY LANDING							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-809	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-809	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-810	NO. 1 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-810	NO. 2 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-811	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-811	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-812	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-812	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-813	NO. 1 ENGINE - LOSS OF OIL							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-813	NO. 2 ENGINE - LOSS OF OIL							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-814 ^U	NO. 1 ENGINE - CHIP DETECTOR LIGHT "ON"							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
05-50-00-210-814 ^U	NO. 2 ENGINE - CHIP DETECTOR LIGHT "ON"							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
05-50-00-210-815	NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-815	NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-816	NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-816	NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-817	NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-817	NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-818	NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-818	NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-819	NO. 1 ENGINE - FUEL FILTER CONTAMINATION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-819	NO. 2 ENGINE - FUEL FILTER CONTAMINATION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-820	NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-820	NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-821	NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-821	NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-822	NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-822	NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-823	NO. 1 ENGINE - FUEL CONTAMINATION							Service ATA:05
	MOS/MSC	31-Jul-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-823	NO. 2 ENGINE - FUEL CONTAMINATION							Service ATA:05
	MOS/MSC	31-Jul-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-824	NO. 1 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE							Service ATA:05
	MOS/MSC	31-Jul-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-824	NO. 2 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE							Service ATA:05
	MOS/MSC	31-Jul-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-01-210-801	LIGHTNING STRIKE - GENERAL VISUAL INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-01							
05-50-01-210-802	FORWARD FUSELAGE LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-01-210-803	CENTER FUSELAGE AND WING-TO-FUSELAGE FARING LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-01							
05-50-01-210-804	WINGS LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-01							
05-50-01-210-805	AFT FUSELAGE, TAIL CONE AND EMPENNAGE LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-01							
05-50-01-210-806	ENGINE NACELLE LIGHTNING STRIKE - GENERAL VISUAL INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-01							
05-50-02-200-801	HARD LANDING OR OFF-TEMPERATURE - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-02							
05-50-04-200-801	OVERSPEED - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-04							
05-50-06-200-801	LANDING GEAR DOWN OVERSPEED - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-06							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-07-200-801	FLAP EXTENDED OVERSPEED - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-07							
05-50-08-200-801	CABIN DEPRESSURIZATION - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-08							
05-50-09-200-801	ICE OR SNOW CONDITION - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-09							
05-50-10-200-801	HIGH-ENERGY STOP CONDITION - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-10							
05-50-11-200-801	LANDING GEAR FREE-FALL CONDITION - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-11							
05-50-12-200-801	OVERHEATED WHEELS - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-12							
05-50-13-200-801	WHEEL OVERSPEED - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-13							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-14-200-801	TIRE TREAD FAILURE - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-14							
05-50-15-200-801	TIRE BURST WITH LANDING GEAR FULLY RETRACTED - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-15							
05-50-16-200-801	ON-GROUND GALE EVENTS - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-16							
05-50-17-200-801	VOLCANIC ASH CONDITION - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-17							
05-50-18-200-801	LOAD FACTOR EXCEEDANCE - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-18							
05-50-19-200-801	TOILET OVERSERVICING - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-19							
05-50-20-200-801	SEVERE TURBULENCE - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-20							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-21-200-801	LANDING OVERWEIGHT - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-21							
05-50-26-200-801	SANDSTORM CONDITION - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-26							
05-50-27-200-801	AIRCRAFT NOISE AND VIBRATION- INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-27							
05-50-28-200-801	NLG INCORRECT TOWING - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-28							
05-50-29-200-801	FIRE EXTINGUISHING FOAM - INSPECTION							Service ATA:05
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-50-29							
H140-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE							Service ATA:05
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:87
H242-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE							Service ATA:05
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
H430-001 ^S		INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS						Service ATA:05
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-46-00						PKG:84		
H700-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS						Service ATA:05
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-47-00						PKG:84		
H700-002 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS						Service ATA:05
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-47-00						PKG:84		
H700-003 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING						Service ATA:05
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-47-00						PKG:84		
ATA 21 - AIR CONDITIONING								
21-01-01		RH INSC ILLUM PANEL						Component ATA:21
PN:441-44279-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1387	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-01-01, AMM 21-01-01								
21-20-03		NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY						Component ATA:21
PN:1300250-9	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1379	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01, AMM 21-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY							Component ATA:21
PN:1300250-9	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1389	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01, AMM 21-21-01								
21-20-05	GROUND COOLING FAN							Component ATA:21
PN:1133660-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:691	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-05, AMM 21-23-05								
21-21-02-001 ^S	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02								PKG:60
21-21-02-001 ^S	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02								PKG:60
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR							Component ATA:21
PN:100000-77	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:40995	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-03, AMM 21-23-03								
21-23-03	RAM AIR VALVE							Component ATA:21
PN:505-17170-401	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001031936	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-03, AMM 21-23-03								
21-23-03-002 ^S	OPERATIONAL CHECK OF RAM AIR VALVE							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-03								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-23-03-003 ^S	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-23-03							PKG:1
21-23-04-001 ^S	OPERATIONAL CHECK OF RAM AIR CHECK VALVES							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-23-04							PKG:60
21-23-05-001 ^S	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-23-05							PKG:10
21-24-01-001 ^S	OPERATIONAL CHECK OF IFE COOLING FAN							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-24-01							PKG:60
21-31-00-002 ^S	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-31-00							PKG:1
21-31-00-003 ^S	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-31-00							PKG:1
21-31-00-004 ^S	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-31-00							PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-00-005 ^S		OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL						Service ATA:21
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-00								PKG:50
21-31-01		(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT						Component ATA:21
PN:2119286-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2119286-01654	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01, AMM 21-31-01								
21-31-01-001		RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU)						Service ATA:21
PN:2119286-10	MOS	06-Dec-19						
SN:2119286-01654	HRS	0	5600 (+30/-30)		6000 (M)	6030	5698.2 (+30)	
	AFL	0						
PROC. REF: AMM 21-31-01								
21-31-02		OUTFLOW VALVE						Component ATA:21
PN:103922-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:103922-00577	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02, AMM 21-31-02								
21-31-02-001		RESTORATION (REPAIR) OF OUTFLOW VALVE						Service ATA:21
PN:103922-1	MOS	06-Dec-19						
SN:103922-00577	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
PROC. REF: AMM 21-31-02								
21-31-03		NEGATIVE PRESSURE RELIEF (NPR) VALVE						Component ATA:21
PN:130664-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:34163-0967	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03, AMM 21-31-03								
21-31-03-001 ^S		OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE						Service ATA:21
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-03								PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-04	PRESSURE RELIEF (PRV) VALVE							Component ATA:21
PN:103918-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:103918-00668	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-04, AMM 21-31-04								
21-31-04-001 ^S	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-04								
PKG:50								
21-41-01	BHS SHUT-OFF VALVE							Component ATA:21
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-01, AMM 21-41-01								
21-52-01	VCS COMPRESSOR DRIVE MODULE							Component ATA:21
PN:1133640-8	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:750	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01								
21-52-01-002	DISCARD OF COMPRESSOR DRIVE MODULE BELT							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	2000 (+30/-30)		2000	2030	1698.2 (+30)	
	AFL	0						
PROC. REF: AMM 21-52-01								
21-52-01-003 ^S	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-52-01								
PKG:1								
21-52-01-004	RESTORATION (OVERHAUL) COMPRESSOR							Service ATA:21
PN:1133640-8	MOS	06-Dec-19						
SN:750	HRS	0	2000 (+30/-30)		2000	2030	1698.2 (+30)	
	AFL	0						
PROC. REF: AMM 21-52-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-02	CDM COMPRESSOR MODULE							Component ATA:21
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01								
21-52-03	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE							Component ATA:21
PN:1133860-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00200	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-03, AMM 21-52-03								
21-52-03-001 ^S	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-52-03								PKG:1
21-52-04	FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER							Component ATA:21
PN:1133850-104	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1103	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-04, AMM 21-52-04, AMM 21-52-04, AMM 21-52-04								
21-52-05	COMPRESSOR DRIVE MODULE BELT							Component ATA:21
PN:PN	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
21-52-06-001 ^S	SERVICING OF VCS REFRIGERANT FLUID							Service ATA:21
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-17-00								PKG:80
21-52-08	AIR CONDITION CONDENSER ASSEMBLY							Component ATA:21
PN:1133760-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:682	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-08, AMM 21-52-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-08-001 ^S		GENERAL VISUAL INSPECTION OF VCS CONDENSER						Service ATA:21
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-52-08								PKG:10
21-52-09		AIR CONDITION MIX FLOW CONDENSER FAN						Component ATA:21
PN:1133720-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:694	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-09, AMM 21-52-09								
21-52-10		AIR CONDITION BLEED AIR HEAT EXCHANGER						Component ATA:21
PN:1320260-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:687	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-10, AMM 21-52-10								
21-61-00-001 ^S		OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM						Service ATA:21
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-61-00								PKG:1
21-61-01		ECS TEMPERATURE CONTROLLER						Component ATA:21
PN:1300670-6	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00754	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-01, AMM 21-61-01								
21-61-03		LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH						Component ATA:21
PN:1300450-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4429	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03		RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH						Component ATA:21
PN:1300450-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4436	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4477	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-04, AMM 21-61-04								
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4437	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-05, AMM 21-61-05								
21-61-06-001 ^S	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR							Service ATA:21
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-61-06								PKG:60
ATA 22 - AUTO FLIGHT								
22-11-00	GMC 715 GUIDANCE PANEL							Component ATA:22
PN:011-04214-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4WC000402	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-01, AMM 22-11-01								
22-11-00-001	FUNCTIONAL CHECK AILERON GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	19-Dec-23	12 (+30d/-30d)	19-Dec-24	18-Jan-25	177 d (+30)	AIRWORTHINESS	
SN:1GK024921	HRS	301.8						
	AFL	162						
PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	19-Dec-23	12 (+30d/-30d)	19-Dec-24	18-Jan-25	177 d (+30)	AIRWORTHINESS	
SN:1GK026533	HRS	301.8						
	AFL	162						
PROC. REF: AMM 22-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-00-001	FUNCTIONAL CHECK RUDDER GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	19-Dec-23	12 (+30d/-30d)		19-Dec-24	18-Jan-25	177 d (+30)	AIRWORTHINESS
SN:1GK026554	HRS	301.8						
	AFL	162						
PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT GSA 80 HIGH SPEED AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	19-Dec-23	12 (+30d/-30d)		19-Dec-24	18-Jan-25	177 d (+30)	AIRWORTHINESS
SN:1GK026767	HRS	301.8						
	AFL	162						
PROC. REF: AMM 22-11-00								
22-11-00-002 ^S	LUBRICATION OF SERVO ACTUATORS							Service ATA:22
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 22-11-00								
								PKG:80
22-11-00-003 ^S	DETAILED INSPECTION OF AUTOPILOT SERVO CABLE							Service ATA:22
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 22-11-00								
								PKG:42
22-11-01	TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO							Component ATA:22
PN:011-00877-21	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1A0007549	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-02	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO							Component ATA:22
PN:011-00878-20	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1A1022244	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-02	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO							Component ATA:22
PN:011-00878-20	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1A1024654	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-02	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO							Component ATA:22
PN:011-00878-20	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1A1024686	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-03	AILERON GSM 86 AUTOPILOT SERVO MOUNT							Component ATA:22
PN:011-01904-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1GK024921	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03								
22-11-06	ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT							Component ATA:22
PN:011-01904-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1GK026533	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-09	RUDDER GSM 86 AUTOPILOT SERVO MOUNT							Component ATA:22
PN:011-01904-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1GK026554	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-09, AMM 22-11-09								
22-11-12	TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT							Component ATA:22
PN:011-01904-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1GK026767	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-12, AMM 22-11-12								
ATA 23 - COMMUNICATIONS								
23-10-02 ^U	ANTENNA, DIRECTIONAL							Component ATA:23
PN:011-01346-00	MOS/MSC		O/C					
SN:124015181	HRS							
	AFL							
23-10-05 ^U	TRAFFIC PROCESSOR UNIT - GTS 8XXX							Component ATA:23
PN:011-02571-00	MOS/MSC		O/C					
SN:28P008711	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-10-06 ^U	ANTENNA, DIRECTIONAL							Component ATA:23
PN:011-01346-00	MOS/MSC		O/C					
SN:124015182	HRS							
	AFL							
23-11-03	KPA 1052 POWER AMPLIFIER							Component ATA:23
PN:APA3009-001-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:500313	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-03, AMM 23-11-03								
23-11-05	VHF 3 TRANSCEIVER							Component ATA:23
PN:011-02303-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:222005979	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-03, AMM 23-12-03								
23-12-01	VHF 1 (UPPER FUSELAGE) ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:322-6567	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-12-02	VHF 2 (LOWER FORWARD FUSELAGE) ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:322-6518	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-12-03	VHF 3 (LOWER AFT FUSELAGE) ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:322-6527	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-34-01	WLAN ACCESS POINT - WAP							Component ATA:23
PN:WAP3212-005-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000090	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-50-03	LH CONSOLE COCKPIT HAND MICROPHONE							Component ATA:23
PN:85-03-12369-04	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:536133	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
23-51-00-001 ^S	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE							Service ATA:23
	MOS	06-Dec-19						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 23-51-00								
								PKG:40
23-51-05	LEFT CONTROL PANEL							Component ATA:23
PN:441-40943-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1987	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-05, AMM 23-51-05								
23-51-05	RIGHT CONTROL PANEL							Component ATA:23
PN:441-40943-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1988	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-05, AMM 23-51-05								
23-61-00-001 ^S	FUNCTIONAL CHECK OF STATIC DISCHARGERS							Service ATA:23
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 23-61-00								
								PKG:83
ATA 24 - ELECTRICAL POWER								
24-01-01	LEFT CONSOLE CONTROL PANEL							Component ATA:24
PN:441-40929-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0993	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-01-01, AMM 24-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-01-02	4.3 PASSENGER CONTROL UNIT							Component ATA:24
PN:PSM2410-004-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000872	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
24-01-03	PCU CORE MODULE TWO							Component ATA:24
PN:PCS3009-201-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:500124	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-23-03, AMM 44-23-03								
24-31-01	NO. 1 ENGINE STARTER/GENERATOR							Component ATA:24
PN:400SG180Q	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:S01416XL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01								
24-31-01	NO. 2 ENGINE STARTER/GENERATOR							Component ATA:24
PN:400SG180Q	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:S01418XL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01								
24-31-01-001	NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017							Service ATA:24
PN:400SG180Q	MOS	06-Dec-19						
SN:S01416XL	HRS	0	800 (+30/-30)		1200 (M)	1230	898.2 (+30)	
	AFL	0						
PROC. REF: AMM 24-31-01								
24-31-01-001	NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017							Service ATA:24
PN:400SG180Q	MOS	06-Dec-19						
SN:S01418XL	HRS	0	800 (+30/-30)		1200 (M)	1230	898.2 (+30)	
	AFL	0						
PROC. REF: AMM 24-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)							Service ATA:24
PN:400SG180Q	MOS/MSC	06-Dec-19	N/A					
SN:S01416XL	HRS	0						
	AFL	0						
PROC. REF: AMM 24-31-01								
24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)							Service ATA:24
PN:400SG180Q	MOS/MSC	06-Dec-19	N/A					
SN:S01418XL	HRS	0						
	AFL	0						
PROC. REF: AMM 24-31-01								
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG550-12B	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:61803	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-02, AMM 24-31-02								
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG550-12B	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:61842	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-02, AMM 24-31-02								
24-31-07-001 ^S	RESTORATION (CLEANING) OF LH SHUNT GENERATOR							Service ATA:24
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 24-31-07								PKG:84
24-31-07-001 ^S	RESTORATION (CLEANING) OF RH SHUNT GENERATOR							Service ATA:24
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 24-31-07								PKG:84
24-36-01	AFT MAIN BATTERY							Component ATA:24
PN:7638-48P	MOS/MSC	19-Dec-23	H/T	TSN 0				
SN:G03208787	HRS	301.8		TSN 0				
	AFL	162		TSN 0				
PROC. REF: AMM 24-36-01, AMM 24-36-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-01	FORWARD MAIN BATTERY							Component ATA:24
PN:7639-34	MOS/MSC	12-Jan-23	H/T	TSN 0				
SN:G03166745	HRS	221		TSN 0				
	AFL	108		TSN 0				
PROC. REF: AMM 24-36-01, AMM 24-36-01								
24-36-01-003	DISCARD AFT MAIN BATTERY							Service ATA:24
PN:7638-48P	MOS	19-Dec-23	24 (+1m/-1m)		19-Dec-25	19-Jan-26	542 d (+31)	LIFE LIMIT
SN:G03208787	HRS	301.8						
	AFL	162	600 (+30/-30)		762	792	600 (+30)	
PROC. REF: AMM 24-36-01								
24-36-01-003	DISCARD FORWARD MAIN BATTERY							Service ATA:24
PN:7639-34	MOS	12-Jan-23	24 (+1m/-1m)		12-Jan-25	12-Feb-25	201 d (+31)	LIFE LIMIT
SN:G03166745	HRS	221						
	AFL	108	600 (+30/-30)		708	738	546 (+30)	
PROC. REF: AMM 24-36-01								
24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015)							Service ATA:24
PN:7638-48P	MOS/MSC		N/A					
SN:G03208787	HRS							
	AFL							
PROC. REF: AMM 24-36-01								
24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015)							Service ATA:24
PN:7639-34	MOS/MSC		N/A					
SN:G03166745	HRS							
	AFL							
PROC. REF: AMM 24-36-01								
24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)							Service ATA:24
PN:7638-48P	MOS	19-Dec-23	6 (+1m/-1m)		19-Jun-24	19-Jul-24	TOL (+24 d)	
SN:G03208787	HRS	301.8						
	AFL	162						
PROC. REF: AMM 24-36-01								
24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015)							Service ATA:24
PN:7639-34	MOS	19-Dec-23	6 (+1m/-1m)	Adj -152d	19-Jan-24	19-Feb-24	OVD	
SN:G03166745	HRS	301.8						
	AFL	162						
PROC. REF: AMM 24-36-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-02-001 ^S		OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)						Service ATA:24
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 24-36-02								PKG:60
24-50-01		PAX CAB DC/AC POWER SUPPLY 28VD INVERTER						Component ATA:24
PN:1215-30	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:003343	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-54-05, AMM 24-54-05								
24-50-02		PAX CAB DC/AC POWER SUPPLY 28VD INVERTER						Component ATA:24
PN:1215-30	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:003285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-54-05, AMM 24-54-05								
24-50-03		PAX CAB DC/AC POWER SUPPLY 28VD INVERTER						Component ATA:24
PN:1215-30	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:003289	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-54-05, AMM 24-54-05								
24-65-01		LEFT POWER DISTRIBUTION BOX						Component ATA:24
PN: SX7EG20-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0598	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-01, AMM 24-65-01								
24-65-02		RIGHT POWER DISTRIBUTION BOX						Component ATA:24
PN: SX7EG21-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0590	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-02, AMM 24-65-02								
24-65-04		NOSE POWER DISTRIBUTION BOX						Component ATA:24
PN: SX7EG22-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0595	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-04, AMM 24-65-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-01	COPILOT SEAT							Component ATA:25
PN:1419-04HM	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1441-1419	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01								
25-11-01	PILOT SEAT							Component ATA:25
PN:1419-03HM	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1440-1419	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01								
25-11-01-001 ^S	DETAILED INSPECTION COPILOT SEAT							Service ATA:25
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-11-01								PKG:20
25-11-01-001 ^S	DETAILED INSPECTION PILOT SEAT							Service ATA:25
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-11-01								PKG:20
25-11-01-002 ^S	DETAILED INSPECTION OF COCKPIT SEAT BELTS							Service ATA:25
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-11-01								PKG:20
25-21-01	PAX 2 - LH AFT FACE SEAT							Component ATA:25
PN:71204-11-107-ADADSBQAI	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:10189	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-01	PAX 3 - RH AFT FACE SEAT							Component ATA:25
PN:71204-12-207-ADADSBQAI	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:10188	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-01	PAX 6 - LH FWD FACE SEAT							Component ATA:25
PN:71203-11-107-ADADSBQAI	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:10344	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-01	PAX 7 - RH FWD FACE SEAT							Component ATA:25
PN:71203-12-107-ADADSBQAI	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:10345	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER SEATS							Service ATA:25
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-01								PKG:20
25-21-01-002 ^S	DETAILED INSPECTION OF PASSENGER SEAT BELTS							Service ATA:25
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-01								PKG:20
25-21-02	DIVAN							Component ATA:25
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-02, AMM 25-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-02-001 ^S	DETAILED INSPECTION DIVAN							Service ATA:25
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-02							PKG:40	
25-21-02-002 ^S	DETAILED INSPECTION DIVAN SEAT BELTS							Service ATA:25
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-02							PKG:40	
25-21-03	PAX 4 - LH FWD FACE SEAT							Component ATA:25
PN:71203-11-107-ADADSBQAI	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:10346	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-03	PAX 5 - RH FWD FACE SEAT							Component ATA:25
PN:71203-12-207-ADADSBQAI	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:10343	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-04	(DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY							Component ATA:25
PN:508358-415	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:A02MAY19-151	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-04, AMM 25-21-04								
25-21-04-001	RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) - NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY							Service ATA:25
PN:508358-415	MOS	01-May-19	84		01-May-26		675 d	
SN:A02MAY19-151	HRS							
	AFL							
PROC. REF: AMM 25-21-04, AMM 25-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-04-002	DISCARD OF SEAT BELT AIRBAG INFLATOR GAS CYLINDER							Service ATA:25
PN:PN	MOS	01-May-19	120		01-May-29		1771 d	LIFE LIMIT
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 25-21-04								
25-21-04-003	DETAILED VISUAL INSPECTION OF SEAT BELT AIRBAG ASSEMBLY							Service ATA:25
	MOS	19-Dec-23	48 (+1m/-1m)	Adj -6d	13-Dec-27	13-Jan-28	1266 d (+31)	
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 25-21-04								
25-21-04-004	OPERATIONAL CHECK OF SEAT BELT AIRBAG ASSEMBLY							Service ATA:25
	MOS	19-Dec-23	48 (+1m/-1m)	Adj -6d	13-Dec-27	13-Jan-28	1266 d (+31)	
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 25-21-04								
25-43-01-001 ^S	DETAILED VISUAL INSPECTION BELTED TOILET UNIT							Service ATA:25
	MOS	06-Dec-19						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-43-02								
								PKG:40
25-43-01-002 ^S	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT							Service ATA:25
	MOS	06-Dec-19						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-43-02								
								PKG:40
25-60-01	EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:S1821502-02	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:LX1100862963	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-01, AMM 25-61-01								
25-60-03	ELT ANTENNA							Component ATA:25
PN:S65-8282-406	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:401-3799	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-03, AMM 25-61-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:S1820506-01E	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:NSN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-01, AMM 25-61-01								
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM							Service ATA:25
PN:S1821502-02	MOS	19-Dec-23	12		19-Dec-24		177 d	
SN:LX1100862963	HRS	301.8						
	AFL	162						
PROC. REF: AMM 25-61-00								
25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:S1821502-02	MOS	19-Dec-23	12		19-Dec-24		177 d	
SN:LX1100862963	HRS	301.8						
	AFL	162						
PROC. REF: AMM 25-61-00								
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY							Service ATA:25
PN:S1820506-01E	MOS/MSC		DUE		01-Mar-25 (M)		249 d	LIFE LIMIT
SN:NSN	HRS							
	AFL							
PROC. REF: AMM 25-61-04								
25-61-05	CS144-A ELT/NAV INTERFACE MODULE							Component ATA:25
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-05, AMM 25-61-05								
25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACEMODULE							Service ATA:25
PN:PN	MOS	06-Dec-19	120		06-Dec-29		1990 d	
SN:UNKNOWN	HRS	0	16000		16000		15698.2	
	AFL	0						
PROC. REF: AMM 25-61-07								
25-62-01	#1 FIRST AID KIT							Component ATA:25
PN:019700-0001L	MOS/MSC	19-Dec-23	H/T	TSN 3				
SN:UNKNOWN	HRS	301.8		TSN 0				
	AFL	162		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-01-001	VISUAL CHECK #1 FIRST AID KIT							Service ATA:25
PN:019700-0001L	MOS/MSC	19-Dec-23	DUE		01-Sep-24 (M)		68 d	
SN:UNKNOWN	HRS	301.8						
	AFL	162						
			Expiry Date: : 01-Sep-24	PROC. REF: AMM 25-62-01				
25-62-02	COPILOT LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4688326	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	DIVAN NO. 1 LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766887	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	DIVAN NO. 2 LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766888	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 1 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766899	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 2 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766882	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 3 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766883	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02	NO. 4 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766884	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 5 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766885	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 6 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766886	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	PILOT LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4688332	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	TOILET PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L4766890	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST							Service ATA:25
PN:66601-505	MOS	01-Apr-19	120		01-Apr-29		1741 d	OVERHAUL
SN:L4688326	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF DIVAN NO. 1 LIFE VEST							Service ATA:25
PN:66601-105	MOS	06-Dec-19	120		06-Dec-29		1990 d	OVERHAUL
SN:L4766887	HRS	0						
	AFL	0						
PROC. REF: AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02-001	RESTORATION (OVERHAUL) OF DIVAN NO. 2 LIFE VEST							Service ATA:25
PN:66601-105	MOS	06-Dec-19	120		06-Dec-29		1990 d	OVERHAUL
SN:L4766888	HRS	0						
	AFL	0						
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST							Service ATA:25
PN:66601-105	MOS	01-Jun-19	120		01-Jun-29		1802 d	OVERHAUL
SN:L4766899	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST							Service ATA:25
PN:66601-105	MOS	01-Jun-19	120		01-Jun-29		1802 d	OVERHAUL
SN:L4766882	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST							Service ATA:25
PN:66601-105	MOS	01-Jun-19	120		01-Jun-29		1802 d	OVERHAUL
SN:L4766883	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST							Service ATA:25
PN:66601-105	MOS	01-Jun-19	120		01-Jun-29		1802 d	OVERHAUL
SN:L4766884	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST							Service ATA:25
PN:66601-105	MOS	01-Jun-19	120		01-Jun-29		1802 d	OVERHAUL
SN:L4766885	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST							Service ATA:25
PN:66601-105	MOS	01-Jun-19	120		01-Jun-29		1802 d	OVERHAUL
SN:L4766886	HRS							
	AFL							
PROC. REF: AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST							Service ATA:25
PN:66601-505	MOS	01-Apr-19	120		01-Apr-29		1741 d	OVERHAUL
SN:L4688332	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF TOILET LIFE VEST							Service ATA:25
PN:66601-105	MOS	01-Jun-19	120		01-Jun-29		1802 d	OVERHAUL
SN:L4766890	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-003 ^U	DISCARD TOILET PAX LIFE VEST							Service ATA:25
PN:66601-105	MOS/MSC	01-Jun-19	O/C					
SN:L4766890	HRS							
	AFL							
25-62-04-001 ^S	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER							Service ATA:25
	MOS	19-Dec-23	24 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 25-62-04								
PKG:81								
25-66-01	LIFE RAFT							Component ATA:25
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
25-66-01-001	RESTORATION LIFE RAFT (OVERHAUL)							Service ATA:25
PN:PN	MOS/MSC	06-Dec-19	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 25-66-01								
ATA 26 - FIRE PROTECTION								
26-11-01	LEFT ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-51-565/215C-5.1M	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:54634	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-11-01	RIGHT ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-51-565/215C-5.1M	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:54633	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01								
26-11-01-001 ^S	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 26-11-01								PKG:10
26-11-01-001 ^S	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 26-11-01								PKG:10
26-11-01-002 ^S	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 26-11-01								PKG:1
26-11-01-002 ^S	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 26-11-01								PKG:1
26-15-01	MODEL 602 SMOKE DETECTOR							Component ATA:26
PN:8930-223B60L014	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:28550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-15-01, AMM 26-15-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-01	ENGINE FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:33000073-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:91126A1	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-03, AMM 26-21-03								
26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL							Service ATA:26
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	2400 (+30/-30)		2400	2430	2098.2 (+30)	
	AFL	0						
PROC. REF: AMM 26-21-00								
26-21-01A	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL							Component ATA:26
PN:441-44278-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1374	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-01, AMM 26-21-01								
26-21-03-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:33000073-1	MOS	01-May-19	120		01-May-29		1771 d	AIRWORTHINESS
SN:91126A1	HRS							
	AFL							
PROC. REF: AMM 26-21-03								
26-21-05-001 ^S	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)							Service ATA:26
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 26-21-05								
26-21-07	NO. 1 CARTRIDGE							Component ATA:26
PN:30903962-1	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:0741YB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-07, AMM 26-21-07								
26-21-07	NO. 2 CARTRIDGE							Component ATA:26
PN:30903963-1	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1454YD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-07, AMM 26-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-07-001	DISCARD NO. 1 CARTRIDGE							Service ATA:26
PN:30903962-1	MOS	01-Jun-19	120		01-Jun-29		1802 d	LIFE LIMIT
SN:0741YB	HRS							
	AFL							
	Manufacture Date::		01-Jun-19	PROC. REF: AMM 26-21-07				
26-21-07-001	DISCARD NO. 2 CARTRIDGE							Service ATA:26
PN:30903963-1	MOS	01-Jun-19	120		01-Jun-29		1802 d	LIFE LIMIT
SN:1454YD	HRS							
	AFL							
	PROC. REF: AMM 26-21-07							
26-21-09-001 ^S	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING							Service ATA:26
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 26-21-09							PKG:20
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:P3APP003010A	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:012734	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 26-24-01, AMM 26-24-01							
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:P3APP003010A	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:012671	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 26-24-01, AMM 26-24-01							
26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS/MSC		N/A					
SN:012734	HRS							
	AFL							
	PROC. REF: AMM 26-24-01							
26-24-01-001	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS/MSC		N/A					
SN:012671	HRS							
	AFL							
	PROC. REF: AMM 26-24-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS	01-May-19	144		01-May-31		2501 d	LIFE LIMIT
SN:012734	HRS							
	AFL							
Manufacture Date:: 01-May-19 PROC. REF: AMM 26-24-01								
26-24-01-002	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS	01-May-19	144		01-May-31		2501 d	LIFE LIMIT
SN:012671	HRS							
	AFL							
Manufacture Date:: 01-May-19 PROC. REF: AMM 26-24-01								
26-24-01-003	DISCARD CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS/MSC		N/A					
SN:012734	HRS							
	AFL							
PROC. REF: AMM 26-24-01								
26-24-01-003	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS/MSC		N/A					
SN:012671	HRS							
	AFL							
PROC. REF: AMM 26-24-01								
26-24-01-004	WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS	05-Jan-23	24		05-Jan-25		194 d	
SN:012734	HRS	221						
	AFL	108						
PROC. REF: AMM 26-24-01								
26-24-01-004	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:P3APP003010A	MOS	05-Jan-23	24		05-Jan-25		194 d	
SN:012671	HRS	221						
	AFL	108						
PROC. REF: AMM 26-24-01								
ATA 27 - FLIGHT CONTROLS								
27-001	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS/MSC	06-Dec-19	N/A					
SN:1164	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-001	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS/MSC	06-Dec-19	N/A					
SN:1174	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-002	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS/MSC	06-Dec-19	N/A					
SN:2359	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-002	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS/MSC	06-Dec-19	N/A					
SN:2363	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-003	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS/MSC	06-Dec-19	N/A					
SN:2373	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-003	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS/MSC	06-Dec-19	N/A					
SN:2367	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-004	ROLL TRIM ACTUATOR							Component ATA:27
PN:470500-1005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:0575	HRS	0	12000	TSN 0	12000		11698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-02, AMM 27-14-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-005	YAW TRIM ACTUATOR							Component ATA:27
PN:470600-1005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:0575	HRS	0	12000	TSN 0	12000		11698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-24-02, AMM 27-24-02								
27-006	PITCH TRIM ACTUATOR							Component ATA:27
PN:467500-1003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:0592	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-41-01, AMM 27-41-01								
27-007	LEFT SPOILER ACTUATOR							Component ATA:27
PN:456800-1003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1133	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02								
27-007	RIGHT SPOILER ACTUATOR							Component ATA:27
PN:456800-1003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1132	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02								
27-008	ELECTRO - RUDDER GUST LOCK ACTUATOR							Component ATA:27
PN:SYLC-53058	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1977	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-70-01, AMM 27-70-01								
27-009	RUDDER BOOSTER ACTUATOR							Component ATA:27
PN:9125-3	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:0556T	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-23-02, AMM 27-23-02								
27-01-01	LEFT CONTROL WHEEL							Component ATA:27
PN:83912139	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01247	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-01-01	RIGHT CONTROL WHEEL							Component ATA:27
PN:83912141	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01187	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01								
27-01-02	LH PEDAL ASSEMBLY							Component ATA:27
PN:505-15420-427	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001037878	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-02, AMM 27-01-02								
27-01-03-001 ^S	LUBRICATION OF ROTARY BALL SPLINE							Service ATA:27
	MOS	19-Dec-23	24 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-21-00								PKG:81
27-010	LEFT TOGGLE LINK							Component ATA:27
PN:456870-1001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1250	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-65-02, AMM 27-65-02								
27-010	RIGHT TOGGLE LINK							Component ATA:27
PN:456870-1001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1249	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-65-02, AMM 27-65-02								
27-011	STICK PUSHER ACTUATOR							Component ATA:27
PN:9124-1	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:0598T	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-36-02, AMM 27-36-02								
27-012	POWER DRIVE UNIT							Component ATA:27
PN:467700-1003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:0600	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-07, AMM 27-51-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-013	LEFT FLAP POSITION SENSOR UNIT							Component ATA:27
PN:457310-1001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1192	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-013	RIGHT FLAP POSITION SENSOR UNIT							Component ATA:27
PN:457310-1001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1194	HRS	0	35000	TSN 0	35000		34698.2	
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-014	DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS/MSC	06-Dec-19	N/A					
SN:SSW1118	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	06-Dec-19						LIFE LIMIT
SN:SSW2236	HRS	0	35000		35000		34698.2	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	06-Dec-19						LIFE LIMIT
SN:SSW2283	HRS	0	35000		35000		34698.2	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS/MSC	06-Dec-19	N/A					
SN:SSW1116	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	06-Dec-19						LIFE LIMIT
SN:SSW2232	HRS	0	35000		35000		34698.2	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-014	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	06-Dec-19						LIFE LIMIT
SN:SSW2285	HRS	0	35000		35000		34698.2	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS	06-Dec-19						LIFE LIMIT
SN:SSW1118	HRS	0	35000		35000		34698.2	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	N/A					
SN:SSW2236	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	N/A					
SN:SSW2283	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS	06-Dec-19						LIFE LIMIT
SN:SSW1116	HRS	0	35000		35000		34698.2	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	N/A					
SN:SSW2232	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	N/A					
SN:SSW2285	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-016	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS	06-Dec-19						LIFE LIMIT
SN:1164	HRS	0	7200		7200		6898.2	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-016	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS	06-Dec-19						LIFE LIMIT
SN:1174	HRS	0	7200		7200		6898.2	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-017	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS	06-Dec-19						LIFE LIMIT
SN:2359	HRS	0	7200		7200		6898.2	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-017	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS	06-Dec-19						LIFE LIMIT
SN:2363	HRS	0	7200		7200		6898.2	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-018	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS	06-Dec-19						LIFE LIMIT
SN:2373	HRS	0	7200		7200		6898.2	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-018	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS	06-Dec-19						LIFE LIMIT
SN:2367	HRS	0	7200		7200		6898.2	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-03-01	NO. 1 ELECTRONICS FLIGHT CONTROL							Component ATA:27
PN:462900-1017	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2012	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-03-01, AMM 27-03-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL							Component ATA:27
PN:462900-1017	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2016	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-03-01, AMM 27-03-01								
27-03-01-002 ^S	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-03-01								
								PKG:50
27-03-01-003 ^S	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-03-01								
								PKG:50
27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	6098.2 (+30)	
	AFL	0						
PROC. REF: AMM 27-03-01								
27-04-01	TRIM ACTUATOR CONTROLLER							Component ATA:27
PN:475200-1009	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2102	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-04-01, AMM 27-04-01								
27-04-01-001 ^S	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01								
								PKG:50
27-04-01-002 ^S	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01								
								PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-00	AILERON CABLES ASSY.							Component ATA:27
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-02, AMM 27-11-02								
27-11-00-001 ^S	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-11-00								PKG:42
27-11-01	LEFT AILERON							Component ATA:27
PN:505-14721-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001042617	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-01, AMM 27-11-01								
27-11-01	RIGHT AILERON							Component ATA:27
PN:505-14719-409	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001038682	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-01, AMM 27-11-01								
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION							Service ATA:27
	MOS	15-Jan-21	60 (+1m/-1m)		15-Jan-26	15-Feb-26	569 d (+31)	
	HRS	42.93	3200 (+30/-30)		3242.93	3272.93	2941.1 (+30)	
	AFL	17						
PROC. REF: AMM 27-11-02								
27-11-02-001(INITIAL)	FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	15-Jan-21	-					
	HRS	42.93						
	AFL	17						
PROC. REF: AMM 27-11-02								
27-11-02-002 ^S	DETAILED INSPECTION OF AILERON CONTROL CABLES							Service ATA:27
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-11-02								PKG:42

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6000 (+30/-30)		6000	6030	5698.2 (+30)	
	AFL	0						
PROC. REF: AMM 27-14-03								
27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	6098.2 (+30)	
	AFL	0						
PROC. REF: AMM 27-14-02								
27-14-03	LEFT AILERON TAB							Component ATA:27
PN:505-14720-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001042315	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-03, AMM 27-14-03								
27-21-00	RUDDER CABLES ASSY.							Component ATA:27
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-21-02, AMM 27-21-02								
27-21-00-001 ^S	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-21-00								
PKG:42								
27-21-01	RUDDER ASSEMBLY							Component ATA:27
PN:505-39081-413	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001042594	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-21-01, AMM 27-21-01								
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION							Service ATA:27
	MOS	15-Jan-21	60 (+1m/-1m)		15-Jan-26	15-Feb-26	569 d (+31)	
	HRS	42.93	3200 (+30/-30)		3242.93	3272.93	2941.1 (+30)	
	AFL	17						
PROC. REF: AMM 27-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-02-001(INITIAL)		FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK						Service ATA:27
	MOS/MSC	15-Jan-21	-					
	HRS	42.93						
	AFL	17						
PROC. REF: AMM 27-21-02								
27-21-02-002 ^S		DETAILED INSPECTION OF RUDDER CONTROL CABLES						Service ATA:27
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-21-02								
PKG:42								
27-23-00-001 ^S		OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM						Service ATA:27
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-23-00								
PKG:10								
27-24-02-001		FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH						Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6000 (+30/-30)		6000	6030	5698.2 (+30)	
	AFL	0						
PROC. REF: AMM 27-24-03								
27-24-02-002		DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM						Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	6098.2 (+30)	
	AFL	0						
PROC. REF: AMM 27-24-02								
27-24-03		RUDDER TRIM TAB						Component ATA:27
PN:505-10450-409	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001042597	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-24-03, AMM 27-24-03								
27-26-01		VENTRAL RUDDER						Component ATA:27
PN:505-07540-417	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001048996	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-26-01, AMM 27-26-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-00	ELEVATOR CABLES ASSY							Component ATA:27
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-02, AMM 27-31-02								
27-31-00-001 ^S	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-31-00								PKG:42
27-31-01	RIGHT ELEVATOR							Component ATA:27
PN:505-11083-404	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001043606	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01, AMM 27-31-01								
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION							Service ATA:27
	MOS	15-Jan-21	60 (+1m/-1m)		15-Jan-26	15-Feb-26	569 d (+31)	
	HRS	42.93	3200 (+30/-30)		3242.93	3272.93	2941.1 (+30)	
	AFL	17						
PROC. REF: AMM 27-31-02								
27-31-02-001(INITIAL)	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	15-Jan-21	-					
	HRS	42.93						
	AFL	17						
PROC. REF: AMM 27-31-02								
27-31-02-002 ^S	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES							Service ATA:27
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-31-02								PKG:42
27-31-03	LEFT HAND ELEVATOR ASSEMBLY							Component ATA:27
PN:505-11083-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001043291	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03, AMM 27-31-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-03-001 ^S	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 27-31-03							PKG:50
27-31-03-002 ^S	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 27-31-03							PKG:50
27-31-05	MID CONTROL PANEL							Component ATA:27
PN:441-44280-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1378	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 23-51-05, AMM 23-51-05							
27-36-03-001 ^S	OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 27-36-03							PKG:10
27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	6098.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-41-01							
27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6000 (+30/-30)		6000	6030	5698.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-40-00							
27-41-01-003 ^S	LUBRICATION OF PITCH TRIM ACTUATOR							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 12-21-00							PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	6098.2 (+30)	
	AFL	0						
PROC. REF: AMM 27-41-01								
27-41-01-005 ^S	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-18-00								PKG:83
27-41-01-006 ^S	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-41-01								PKG:50
27-43-02	COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL							Component ATA:27
PN:441-44422-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1412	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 27-51-00								
27-51-01-001 ^S	LUBRICATION OF FLAP ACTUATORS BALL SCREWS							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-21-00								PKG:83
27-51-01-002	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-01-002	DETAILED INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-51-01							
27-51-01-002	DETAILED INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-51-01							
27-51-01-002	DETAILED INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-51-01							
27-51-01-002	DETAILED INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-51-01							
27-51-01-002	DETAILED INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-51-01							
27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	6898.2 (+30)	
	AFL	0						
	PROC. REF: AMM 27-51-01							
27-51-01-005 ^S	SERVICING OF FLAP ACTUATOR GEAR BOXES							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 12-18-00							

PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-01-900-801-01	LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475100-1013	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1164	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-02	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475100-1013	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1174	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-03	LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-2013	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:2359	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-04	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-2013	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:2363	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-05	LEFT NO. 1 INBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-1013	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:2373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-06	RIGHT NO. 1 INBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-1013	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:2367	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-05	LEFT INBOARD FLAP							Component ATA:27
PN:505-14334-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001050497	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-05	LEFT OUTBOARD FLAP							Component ATA:27
PN:505-14349-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001050499	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								
27-51-05	RIGHT INBOARD FLAP							Component ATA:27
PN:505-14334-406	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001040938	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								
27-51-05	RIGHT OUTBOARD FLAP							Component ATA:27
PN:505-14349-406	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001040933	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								
27-51-06-001 ^S	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-21-00								PKG:83
27-51-06-001 ^S	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-21-00								PKG:83
27-51-06-001 ^S	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-21-00								PKG:83
27-51-06-001 ^S	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-21-00								PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-001 ^S	LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 12-21-00							PKG:83
27-51-06-001 ^S	LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 12-21-00							PKG:83
27-51-06-002 ^S	DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 27-51-06							PKG:83
27-51-06-002 ^S	DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 27-51-06							PKG:83
27-51-06-002 ^S	DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 27-51-06							PKG:83
27-51-06-002 ^S	DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 27-51-06							PKG:83
27-51-06-002 ^S	DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 27-51-06							PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-002 ^S		DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT						Service ATA:27
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
				PROC. REF: AMM 27-51-06		PKG:83		
27-51-06-900-801-01		RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT						Component ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:SSW2285	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 27-51-06, AMM 27-51-06				
27-51-06-900-801-02		RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT						Component ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:SSW2232	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 27-51-06, AMM 27-51-06				
27-51-06-900-801-03		LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT						Component ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:SSW2283	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 27-51-06, AMM 27-51-06				
27-51-06-900-801-04		LEFT INBOARD FLAP FLEXIBLE 1 SHAFT						Component ATA:27
PN:457360-1005	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:SSW2236	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 27-51-06, AMM 27-51-06				
27-51-06-900-801-05		LEFT CENTER FLAP FLEXIBLE 2 SHAFT						Component ATA:27
PN:457360-1007	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:SSW1118	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 27-51-06, AMM 27-51-06				
27-51-06-900-801-06		RIGHT CENTER FLAP FLEXIBLE 2 SHAFT						Component ATA:27
PN:457360-1007	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:SSW1116	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 27-51-06, AMM 27-51-06				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER							Component ATA:27
PN:780501-9	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1957	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01, AMM 27-53-01								
27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS-INTERNAL							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 27-64-00								
27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 27-64-00								
27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL							Service ATA:27
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 7 27-64-00								
27-65-00-001 ^S	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-60-00								
								PKG:60
27-65-01-001 ^S	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)							Service ATA:27
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-65-00								
								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-66-01	NO. 1 CONTROL WHEEL POSITION SENSOR							Component ATA:27
PN:456896-1001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:381271	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-01, AMM 27-66-01								
27-66-01	NO. 2 CONTROL WHEEL POSITION SENSOR							Component ATA:27
PN:456896-1001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:381626	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-01, AMM 27-66-01								
27-66-02	LEFT SPOILER SURFACE POSITION SENSOR							Component ATA:27
PN:456897-1001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:390479	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-02, AMM 27-66-02								
27-66-02	RIGHT SPOILER SURFACE POSITION SENSOR							Component ATA:27
PN:456897-1001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:390484	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-02, AMM 27-66-02								
ATA 28 - FUEL								
28-11-00-001 ^S	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS							Service ATA:28
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 28-11-00								PKG:80
28-11-05	LEFT WING WATER DRAIN VALVE							Component ATA:28
PN:L83A13-628	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M29399	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-11-05	RIGHT WING WATER DRAIN VALVE							Component ATA:28
PN:L83A13-628	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M29404	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-11-07	LEFT WING DUMP VALVE							Component ATA:28
PN:V98A32-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M20811	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07								
28-11-07	RIGHT WING DUMP VALVE							Component ATA:28
PN:V98A32-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M20810	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07								
28-12-01-001 ^S	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA							Service ATA:28
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-01								PKG:1
28-12-03	LEFT FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M30151	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03								
28-12-03	RIGHT FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M30138	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03								
28-12-03-001 ^S	OPERATIONAL CHECK LEFT FLOAT VENT VALVE							Service ATA:28
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-12-03-001 ^S		OPERATIONAL CHECK RIGHT FLOAT VENT VALVE						Service ATA:28
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03								PKG:60
28-21-01		LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE						Component ATA:28
PN:L96-19-007P4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M28666	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-01		RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE						Component ATA:28
PN:L96-19-007P4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M28659	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-02		LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE						Component ATA:28
PN:P99C25-606P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L38538	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-02		RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE						Component ATA:28
PN:P99C25-606P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L38536	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-03		LEFT WING DC AUXILIARY BOOST PUMP CANISTER						Component ATA:28
PN:C93R25-606P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L43888	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-03		RIGHT WING DC AUXILIARY BOOST PUMP CANISTER						Component ATA:28
PN:C93R25-606P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L43893	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-05	LEFT WING JET PUMP FEED LINE							Component ATA:28
PN:T99A19-602	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L35563	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05								
28-21-05	RIGHT WING JET PUMP FEED LINE							Component ATA:28
PN:T99A19-602	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L38263	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05								
28-21-07	LEFT 0.75 SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M27260	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07	RIGHT 0.75 SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M27246	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-001	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM							Service ATA:28
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	800 (+30/-30)		800	830	498.2 (+30)	
	AFL	0						
PROC. REF: AMM 28-21-07								
28-21-07-001	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM							Service ATA:28
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	800 (+30/-30)		800	830	498.2 (+30)	
	AFL	0						
PROC. REF: AMM 28-21-07								
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR							Component ATA:28
PN:D97C00-644P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:C703057	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-08	LEFT WING 28 VDC SOV ACTUATOR							Component ATA:28
PN:D97C00-644P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:C703024	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR							Component ATA:28
PN:D97C00-644P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:C703040	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-09	LEFT WING SCAVENGER JET PUMP							Component ATA:28
PN:T99A19-603	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L38494	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-09, AMM 28-21-09								
28-21-09	RIGHT WING SCAVENGER JET PUMP							Component ATA:28
PN:T99A19-603	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L38492	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-09, AMM 28-21-09								
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE							Component ATA:28
PN:B97H19-608P2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:L38129	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-10, AMM 28-21-10								
28-21-10-001	OPERATIONAL CHECK OF FUEL XFEED VALVE							Service ATA:28
	MOS	06-Dec-19						
	HRS	0	12000 (+30/-30)		12000	12030	11698.2 (+30)	
	AFL	0						
PROC. REF: AMM 28-21-10								
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE							Component ATA:28
PN:L96-13-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M29020	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE							Component ATA:28
PN:L96-13-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M29023	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11								
28-21-13	INSC ILLUM PANEL							Component ATA:28
PN:441-42621-003	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1085	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-13, AMM 28-21-13								
28-23-01	REFUEL CONTROL PANEL							Component ATA:28
PN:742388-1-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:742388IN00687	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-01, AMM 28-23-01								
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE							Component ATA:28
PN:L94E31-653P3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M31696	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-03, AMM 28-23-03								
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE							Component ATA:28
PN:L94E31-653P3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M31703	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-03, AMM 28-23-03								
28-23-04-001 ^S	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER							Service ATA:28
	MOS	06-Dec-19						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-23-05								PKG:40
28-23-07	LEFT HIGH LEVEL SENSOR							Component ATA:28
PN:722860-2-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2526	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-07, AMM 28-23-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-23-07	RIGHT HIGH LEVEL SENSOR							Component ATA:28
PN:722860-2-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2518	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-07, AMM 28-23-07								
28-23-09	FUEL PORT AND CAP							Component ATA:28
PN:K97-63-613	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:M29679	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-09, AMM 28-23-09								
28-41-01	NO. 1 LEFT PROBE							Component ATA:28
PN:765896-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765896IN01204	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 1 RIGHT PROBE							Component ATA:28
PN:765896-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765896IN01255	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 LEFT PROBE							Component ATA:28
PN:765873-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765873IN01290	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 RIGHT PROBE							Component ATA:28
PN:765873-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765873IN01291	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 3 LEFT PROBE							Component ATA:28
PN:765874-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765874IN01276	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-01	NO. 3 RIGHT PROBE							Component ATA:28
PN:765874-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765874IN01282	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 4 LEFT PROBE							Component ATA:28
PN:765875-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765875IN01256	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 4 RIGHT PROBE							Component ATA:28
PN:765875-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:765875IN01274	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT							Component ATA:28
PN:738742-1-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:738790IN01443	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-05, AMM 28-41-05								
28-43-01	TEMPERATURE SENSOR							Component ATA:28
PN:798840-1-0	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:05744	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-43-01, AMM 28-43-01								
28-43-01-001 ^S	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR							Service ATA:28
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-43-01								
							PKG:60	
28-45-01	LEFT PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2239	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-45-01	RIGHT PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2247	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01								
ATA 29 - HYDRAULIC POWER								
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR							Component ATA:29
PN:3032763-003	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:MX822818	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02								
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:3032249-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:MX825602	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02								
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:3032249-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:MX821408	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02								
29-12-02-001 ^S	VISUAL CHECK OF MANIFOLD/ RESERVOIR							Service ATA:29
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 29-12-02								
29-12-02-002 ^S	OPERATIONAL CHECK LEFT EDP CHECK VALVE							Service ATA:29
	MOS	01-Jul-19						
	HRS	0	5600 (+30/-30)					
	AFL							
PROC. REF: AMM 29-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-12-02-002 ^S		OPERATIONAL CHECK RIGHT EDP CHECK VALVE						Service ATA:29
	MOS	01-Jun-19						
	HRS	0	5600 (+30/-30)					
	AFL							
PROC. REF: AMM 29-10-00								PKG:50
29-15-03		HYDRAULIC ACCUMULATOR						Component ATA:29
PN:11172-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:11172-0467	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-03, AMM 29-15-03								
29-15-03-001 ^S		SERVICING OF HYDRAULIC ACCUMULATOR						Service ATA:29
PN:11172-2	MOS	19-Dec-23	12 (+1m/-1m)					
SN:11172-0467	HRS	301.8						
	AFL	162						
PROC. REF: AMM 12-13-00								PKG:80
29-15-04		NO. 1 FSOV FIRE SHUT OFF VALVE						Component ATA:29
PN:3032428-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:AA714928	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-04, AMM 29-15-04								
29-15-04		NO. 2 FSOV FIRE SHUT OFF VALVE						Component ATA:29
PN:3032428-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:AA714945	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-04, AMM 29-15-04								
29-15-04-001		OPERATIONAL CHECK NO. 1 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE						Service ATA:29
PN:3032428-001	MOS	19-Dec-23	48 (+30d/-30d)	Adj -134d	07-Aug-27	06-Sep-27	1138 d (+30)	AIRWORTHINESS
SN:AA714928	HRS	301.8	3200 (+30/-30)		3501.8	3531.8	3200 (+30)	
	AFL	162						
PROC. REF: AMM 29-15-04								
29-15-04-001		OPERATIONAL CHECK NO. 2 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE						Service ATA:29
PN:3032428-001	MOS	19-Dec-23	48 (+30d/-30d)	Adj -134d	07-Aug-27	06-Sep-27	1138 d (+30)	AIRWORTHINESS
SN:AA714945	HRS	301.8	3200 (+30/-30)		3501.8	3531.8	3200 (+30)	
	AFL	162						
PROC. REF: AMM 29-15-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-15-05	PRIORITY VALVE							Component ATA:29
PN:2217-0030-401	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00083	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-05, AMM 29-15-05								
29-31-02-001 ^S	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE							Service ATA:29
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 29-31-02								PKG:50
ATA 30 - ICE AND RAIN PROTECTION								
30-01-01	MD INSC ILLUM PANEL							Component ATA:30
PN:441-45072-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1108	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-01-01, AMM 30-01-01								
30-12-00-001 ^S	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-10-00								PKG:60
30-12-01-001 ^S	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-12-01								PKG:60
30-12-02	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE							Component ATA:30
PN:RYLB-53534-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0725	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-02, AMM 30-12-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-12-02	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE							Component ATA:30
PN:RYLB-53534-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0730	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-02, AMM 30-12-02								
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8533-1-114	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8496-2-330	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8496-2-331	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8533-1-92	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8496-2-343	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8496-2-334	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-12-05-001 ^S	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 30-12-05							PKG:60
30-12-05-001 ^S	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 30-12-05							PKG:60
30-12-05-002 ^S	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 30-12-05							PKG:60
30-12-05-002 ^S	FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 30-12-05							PKG:60
30-21-01	LEFT ENGINE ANTI-ICE PRESUURE VALVE							Component ATA:30
PN:CW30-10040-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0000232	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 30-21-01, AMM 30-21-01							
30-21-01	RIGHT ENGINE ANTI-ICE PRESUURE VALVE							Component ATA:30
PN:CW30-10040-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0000231	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 30-21-01, AMM 30-21-01							
30-21-02	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-477F-1000-100GMOS/MSC		06-Dec-19	O/C	TSN 0				
SN:8613-12-492	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 30-21-02, AMM 30-21-02							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-477F-1000-100GMOS/MSC		06-Dec-19	O/C	TSN 0				
SN:8613-12-540	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02, AMM 30-21-02								
30-21-02-001	FUNCTIONAL CHECK OF LEFT ENGINE ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	12000 (+30/-30)		12000	12030	11698.2 (+30)	
	AFL	0						
PROC. REF: AMM 30-21-02								
30-21-02-001	FUNCTIONAL CHECK OF RIGHT ENGINE ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	12000 (+30/-30)		12000	12030	11698.2 (+30)	
	AFL	0						
PROC. REF: AMM 30-21-02								
30-21-02-720-801-A	TROUBLE SHOOTING ENGINE OPERATING PROBLEMS - ENGINE ANTI-ICING PRESSURE TRANSDUCER FUNCTIONAL CHECK							Service ATA:30
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 30-21-02								
30-21-03-001 ^S	BORESCOPE INSPECTION OF PICCOLO TUBE							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-21-03								PKG:50
30-21-04-001 ^S	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-21-00								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-31-00-002	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING							Service ATA:30
	MOS	19-Dec-23	24 (+1m/-1m)	Adj 24d	12-Jan-26	12-Feb-26	566 d (+31)	
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 30-30-00								PKG:81
30-41-01-002 ^S	DISCARD OF WINDSHIELD RAIN REPELLENT COATING							Service ATA:30
	MOS	12-Jan-23	12 (+1m/-1m)					
	HRS	221						
	AFL	108						
PROC. REF: AMM 30-41-01								PKG:80
30-41-01-003 ^S	FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE							Service ATA:30
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 30-41-01								PKG:80
30-42-00-001 ^S	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM							Service ATA:30
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-42-00								PKG:1
30-42-01	LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL							Component ATA:30
PN:EPM-112-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:03464	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-42-01	RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL							Component ATA:30
PN:EPM-112-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:03498	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-81-02	LEFT NOSE ICE DETECTOR							Component ATA:30
PN:0871LM3-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-81-02, AMM 30-81-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-30-02	CVDR ACCELEROMETER							Component ATA:31
PN:3001-01-111	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0619-DT4597N	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-05, AMM 31-31-05								
31-30-03	REAR CVDR IMPACT SWITCH							Component ATA:31
PN:5930-4-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8117	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-04, AMM 31-31-04								
31-31-00-002	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER)							Service ATA:31
	MOS	19-Dec-23	12 (+1m/-1m)	Adj 24d	12-Jan-25	12-Feb-25	201 d (+31)	
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 31-31-00								PKG:80
31-31-01	(CVR / CVDR) COCKPIT VOICE RECORDER							Component ATA:31
PN:5013-6100-50	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:002013751	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-01, AMM 31-31-01								
31-31-03	CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Component ATA:31
PN:266-E5542-00	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:ULB028908	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-03, AMM 31-31-03								
31-31-03-001	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Service ATA:31
PN:266-E5542-00	MOS/MSC		DUE		01-Dec-25 (M)		524 d	LIFE LIMIT
SN:ULB028908	HRS							
	AFL							
PROC. REF: AMM 31-31-03								
31-33-01	FDR - FLIGHT DATA RECORDER							Component ATA:31
PN:2100-2244-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:002009330	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-01, AMM 31-33-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-33-03	FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON							Component ATA:31
PN:266-E5542-00	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:ULB028550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-03, AMM 31-33-03								
31-33-03-001	DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED)							Service ATA:31
PN:266-E5542-00	MOS/MSC		DUE		01-Nov-25 (M)		494 d	LIFE LIMIT
SN:ULB028550	HRS							
	AFL							
PROC. REF: AMM 31-33-03								
31-33-04	FORWARD CVDR IMPACT SWITCH							Component ATA:31
PN:5930-4-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8121	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-04, AMM 31-33-04								
31-33-05	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Component ATA:31
PN:3K2222B	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:C1427	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-05, AMM 31-33-05								
31-33-05	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Component ATA:31
PN:3K2222B	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:C1426	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-05, AMM 31-33-05								
31-33-05-001 ^S	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Service ATA:31
PN:3K2222B	MOS	19-Dec-23	12 (+1m/-1m)					
SN:C1426	HRS	301.8						
	AFL	162						
PROC. REF: AMM 31-33-05								PKG:80
31-33-05-002 ^S	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Service ATA:31
PN:3K2222B	MOS	19-Dec-23	12 (+1m/-1m)					
SN:C1427	HRS	301.8						
	AFL	162						
PROC. REF: AMM 31-33-05								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-40-01	LH DCU UNIT							Component ATA:31
PN:011-01457-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:16907500	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01, AMM 31-41-01								
31-40-01	RH DCU UNIT							Component ATA:31
PN:011-01457-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:16907505	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01, AMM 31-41-01								
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-03711-40	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4SM005355	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05								
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-03711-40	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4SM005458	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05								
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL							Component ATA:31
PN:441-5430-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1003	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
31-42-00-001 ^S	OPERATIONAL CHECK OF HSDB SWITCH REVERSION							Service ATA:31
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-42-00								
							PKG:60	
31-50-01	(GEA 71) ENGINE AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-03682-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:497002671	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-03682-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:497002788	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-03682-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:497002647	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-61-00-001 ^S	OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)							Service ATA:31
PN:011-04187-10	MOS	06-Dec-19						
SN:4VS100434	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-61-00								PKG:40
31-61-00-001 ^S	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)							Service ATA:31
PN:011-04187-10	MOS	06-Dec-19						
SN:4VS100436	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-61-00								PKG:40
31-61-00-001 ^S	OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)							Service ATA:31
PN:011-04187-10	MOS	06-Dec-19						
SN:4VS100438	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-61-00								PKG:40
31-61-01	MFD (MULTI-FUNCTION FLIGHT DISPLAY)							Component ATA:31
PN:011-04187-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4VS100434	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01, AMM 31-61-01								
31-61-01	PFD 1 (PRIMARY FLIGHT DISPLAY)							Component ATA:31
PN:011-04187-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4VS100436	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01, AMM 31-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-61-01	PFD 2 (PRIMARY FLIGHT DISPLAY)							Component ATA:31
PN:011-04187-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4VS100438	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01, AMM 31-61-01								
31-61-06	NO. 1 BARO INSC ILLUMINATED PANEL							Component ATA:31
PN:441-44282-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1833	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-06, AMM 31-61-06								
31-61-06	NO. 2 BARO INSC ILLUMINATED PANEL							Component ATA:31
PN:441-44282-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1834	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-06, AMM 31-61-06								
316104-0101	PAX NO.1 GTC570 TOUCHSCREEN CONTROLLER							Component ATA:31
PN:011-03759-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4MT100511	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-04, AMM 31-61-04								
316104-0101	PAX NO.2 GTC570 TOUCHSCREEN CONTROLLER							Component ATA:31
PN:011-03759-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4MT100998	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-04, AMM 31-61-04								
ATA 32 - LANDING GEAR								
32-00-00-001 ^S	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR POLYURETHANE FILMS							Service ATA:32
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-00-20								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING							Component ATA:32
PN:2317-1201-503	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1767437/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING							Component ATA:32
PN:2317-1201-504	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1751232/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-003	LEFT PINTLE PIN							Component ATA:32
PN:2317-1101-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1757643/002	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-003	RIGHT PINTLE PIN							Component ATA:32
PN:2317-1101-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1747126/009	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-004	LEFT PINTLE PIN							Component ATA:32
PN:2317-1102-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1744416/010	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-004	RIGHT PINTLE PIN							Component ATA:32
PN:2317-1102-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1737995/003	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE							Component ATA:32
PN:2317-1103-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759848/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE							Component ATA:32
PN:2317-1103-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755327/008	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE							Component ATA:32
PN:2317-1107-005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755641/014	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		15138	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE							Component ATA:32
PN:2317-1107-005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1748600/005	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		15138	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN							Component ATA:32
PN:2317-1109-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1741390/012	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN							Component ATA:32
PN:2317-1109-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1766388/003	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT							Component ATA:32
PN:2317-1126-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1754824/006	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT							Component ATA:32
PN:2317-1126-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1768255/003	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10-00	LEFT MAIN LANDING GEAR							Component ATA:32
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
32-10-00	RIGHT MAIN LANDING GEAR							Component ATA:32
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
32-10-01	LEFT MAIN LANDING GEAR LEG STRUT ASSY							Component ATA:32
PN:2317-1100-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00563	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-10-01	RIGHT MAIN LANDING GEAR LEG STRUT ASSY							Component ATA:32
PN:2317-1100-406	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00562	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY							Component ATA:32
PN:2317-1500-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00580	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY							Component ATA:32
PN:2317-1500-406	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00571	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:2317-1502-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1725085/003	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		15138	
PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:2317-1502-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1725082/006	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		15138	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE							Component ATA:32
PN:2317-1503-005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1757601/005	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE							Component ATA:32
PN:2317-1503-005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755330/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT							Component ATA:32
PN:2317-1509-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1761907/005	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT							Component ATA:32
PN:2317-1509-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1761907/008	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-104	LEFT MAIN LANDING GEAR TRAILING ARM							Component ATA:32
PN:2317-1513-501	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1660761/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-105	RIGHT MAIN LANDING GEAR TRAILING ARM							Component ATA:32
PN:2317-1513-502	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1754497/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN							Component ATA:32
PN:2317-1505-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755565/017	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN							Component ATA:32
PN:2317-1505-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1760009/012	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-11-00-001 ^S	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR							Service ATA:32
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 32-11-00								PKG:80
32-11-00-003	LUBRICATION OF MAIN LANDING GEAR							Service ATA:32
	MOS	19-Dec-23	12 (+1m/-1m)	Adj 31d	19-Jan-25	19-Feb-25	208 d (+31)	
	HRS	301.8						
	AFL	162	650 (+30/-30)		812	842	650 (+30)	
PROC. REF: AMM 12-21-00								
32-11-01-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								
32-11-01-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-02-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								
32-11-02-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								
32-11-02-900-801-05	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Component ATA:32
PN:2117-3001-003	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1755655/006	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-06	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Component ATA:32
PN:2117-3001-003	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1755655/008	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-07	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:2117-3027-901	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:16973	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-08	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:2117-3027-901	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:17004	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-13	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:2117-3019-003	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1759109/011	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-02-900-801-14	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:2117-3019-003	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1759109/012	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-15	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:2117-3007-003	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1739820/019	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-16	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:2117-3007-003	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:1748484/008	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-03-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								
32-11-03-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								
32-11-03-004	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER							Service ATA:32
	MOS	19-Dec-23	12 (+1m/-1m)	Adj 31d	19-Jan-25	19-Feb-25	208 d (+31)	
	HRS	301.8						
	AFL	162	650 (+30/-30)		812	842	650 (+30)	
PROC. REF: AMM 12-14-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-04-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								
32-11-04-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-11-00								
32-20-01	NOSE LANDING GEAR							Component ATA:32
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-00								
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER							Component ATA:32
PN:2317-3000-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01280	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER							Component ATA:32
PN:2317-3000-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:2317-3011-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759823/004	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:2317-3011-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1744789/005	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:2317-3021-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1742612/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:2317-3021-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1741391/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-203	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:2317-3001-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755625/004	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:2317-3001-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755625/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT							Component ATA:32
PN:2317-3004-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759849/005	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT							Component ATA:32
PN:2317-3004-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1743703/010	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		16638	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-21-00-001 ^S	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR							Service ATA:32
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 32-21-00								

PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-00-003	LUBRICATION OF NOSE LANDING GEAR							Service ATA:32
	MOS	19-Dec-23	12 (+1m/-1m)	Adj 31d	19-Jan-25	19-Feb-25	208 d (+31)	
	HRS	301.8						
	AFL	162	650 (+30/-30)		812	842	650 (+30)	
PROC. REF: AMM 12-21-00								
32-21-01-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-21-00								
32-21-02	NLG RETRACTION ACTUATOR							Component ATA:32
PN:2117-1000-401	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00573	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-02, AMM 32-21-02								
32-21-03	NLG DOWNLOCK ACTUATOR							Component ATA:32
PN:2117-2000-401	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00573	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-03, AMM 32-21-03								
32-21-04-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-21-00								
32-21-05-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-05-004	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER							Service ATA:32
	MOS	19-Dec-23	12 (+1m/-1m)	Adj 24d	12-Jan-25	12-Feb-25	201 d (+31)	
	HRS	301.8						
	AFL	162	650 (+30/-30)		812	842	650 (+30)	
PROC. REF: AMM 12-14-03								
32-21-06-005 ^S	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER							Service ATA:32
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 32-21-06								
PKG:80								
32-21-09-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		06-Dec-29 *	06-Jan-30	1990 d (+31)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	11838 (+30)	
PROC. REF: AMM 32-21-00								
32-23-03	NLG DOOR - TORQUE TUBE ASSEMBLY							Component ATA:32
PN:505-19741-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001046378	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-300	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR							Component ATA:32
PN:2117-3000-409	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01223	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-300	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR							Component ATA:32
PN:2117-3000-409	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01229	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER							Component ATA:32
PN:2117-3034-501	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1760600/003	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER							Component ATA:32
PN:2117-3034-501	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1760602/003	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-302	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS/MSC	06-Dec-19	N/A					
SN:1755655/008	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-302	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS/MSC	06-Dec-19	N/A					
SN:1755655/006	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-303	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS/MSC	06-Dec-19	N/A					
SN:16973	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-303	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS/MSC	06-Dec-19	N/A					
SN:17004	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:2117-3008-901	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:87006/0003	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:2117-3008-901	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:87005/0025	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:2117-3009-007	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1730998/008	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:2117-3009-007	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759770/009	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-306	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS/MSC	06-Dec-19	N/A					
SN:1759109/012	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-306	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS/MSC	06-Dec-19	N/A					
SN:1759109/011	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-307	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS/MSC	06-Dec-19	N/A					
SN:1739820/019	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-307	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS/MSC	06-Dec-19	N/A					
SN:1748484/008	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:2117-3011-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1743726/016	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:2117-3011-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1743726/012	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:2117-3013-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1743727/008	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:2117-3013-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1764277/004	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-31-01	LANDING GEAR CONTROL LEVER							Component ATA:32
PN:827101-13	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0394	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-01, AMM 32-31-01								
32-31-04	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE							Component ATA:32
PN:7342-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0578T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04, AMM 32-31-04								
32-31-05	LH MLG UPLOCK BOX ASSY							Component ATA:32
PN:2617-1000-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01404	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-05, AMM 32-31-05								
32-31-05	NLG UPLOCK BOX ASSY							Component ATA:32
PN:2617-1000-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01399	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-05, AMM 32-31-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-31-05	RH MLG UPLOCK BOX ASSY							Component ATA:32
PN:2617-1000-404	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00725	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-05, AMM 32-31-05								
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT							Component ATA:32
PN:2117-3015-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759924/009	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT							Component ATA:32
PN:2117-3015-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1768960/010	HRS	0		TSN 0				
	AFL	0	12000	TSN 0	12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:MTMKS14ALGA1	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:01290	HRS	0		TSN 0				
	AFL	0	10500	TSN 0	10500		10338	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:MTMKS14ALGA1	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:01246	HRS	0		TSN 0				
	AFL	0	10500	TSN 0	10500		10338	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-312	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS	06-Dec-19						LIFE LIMIT
SN:16973	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-312	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS	06-Dec-19						LIFE LIMIT
SN:17004	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-313	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT							Component ATA:32
PN:2117-3029-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:02510	HRS	0		TSN 0				
	AFL	0	28000	TSN 0	28000		27838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-313	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT							Component ATA:32
PN:2117-3029-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:02529	HRS	0		TSN 0				
	AFL	0	28000	TSN 0	28000		27838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-314	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS	06-Dec-19						LIFE LIMIT
SN:1759109/012	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-314	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS	06-Dec-19						LIFE LIMIT
SN:1759109/011	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-315	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS	06-Dec-19						LIFE LIMIT
SN:1739820/019	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-315	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS	06-Dec-19						LIFE LIMIT
SN:1748484/008	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-316	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS	06-Dec-19						LIFE LIMIT
SN:1755655/008	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-316	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS	06-Dec-19						LIFE LIMIT
SN:1755655/006	HRS	0						
	AFL	0	12000		12000		11838	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM							Service ATA:32
	MOS	19-Dec-23	24 (+30d/-30d)		19-Dec-25	18-Jan-26	542 d (+30)	AIRWORTHINESS
	HRS	301.8	1600 (+30/-30)		1901.8	1931.8	1600 (+30)	
	AFL	162						
PROC. REF: AMM 32-35-00								
32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES							Service ATA:32
	MOS	19-Dec-23	24 (+30d/-30d)		19-Dec-25	18-Jan-26	542 d (+30)	AIRWORTHINESS
	HRS	301.8	1600 (+30/-30)		1901.8	1931.8	1600 (+30)	
	AFL	162						
PROC. REF: AMM 32-35-00								
32-35-02	CENTER FUSELAGE FREE FALL VALVE							Component ATA:32
PN:7343-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0583T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-35-02, AMM 32-35-02								
32-400	NOSE LANDING GEAR SHOCK STRUT							Component ATA:32
PN:2317-5100-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00577	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT							Component ATA:32
PN:2310-1144-005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:00966	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT							Component ATA:32
PN:2310-1173-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755549/003	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-06, AMM 32-21-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN							Component ATA:32
PN:2317-5105-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1654028/010	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-403	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN							Component ATA:32
PN:2317-5105-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1713404/002	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING							Component ATA:32
PN:2317-5301-503	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1757449/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER							Component ATA:32
PN:2117-4000-403	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:00622	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-06, AMM 32-21-06								
32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE							Component ATA:32
PN:2317-5101-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1749833/002	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK							Component ATA:32
PN:2317-5201-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759208/003	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK							Component ATA:32
PN:2317-5201-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759208/009	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-07, AMM 32-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN							Component ATA:32
PN:2317-6003-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1738201/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE							Component ATA:32
PN:2310-1165-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1716400/006	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-41-00	BRAKE CONTROL UNIT							Component ATA:32
PN:DAP00100-11	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:501760687	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01, AMM 32-41-01								
32-41-00-001 ^S	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM							Service ATA:32
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-00								
							PKG:50	
32-41-01	BRAKE CONTROL UNIT TRAY							Component ATA:32
PN:DAP00134-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1394	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01, AMM 32-41-01								
32-41-02	LH BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:Q3008	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:348889	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-02, AMM 32-41-02								
32-41-02	RH BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:Q3008	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:348932	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-02, AMM 32-41-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-02-001 ^S		OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-02								PKG:60
32-41-02-001 ^S		OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-02								PKG:60
32-41-02-002 ^S		FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	01-Nov-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-02								PKG:10
32-41-02-002 ^S		FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	01-Nov-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-02								PKG:10
32-41-06		LH MLG WHEEL SPEED TRANSDUCER						Component ATA:32
PN:DAP00103-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:052TB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06								
32-41-06		RH MLG WHEEL SPEED TRANSDUCER						Component ATA:32
PN:DAP00103-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:036TB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06								
32-41-07		BRAKE CONTROL MODULE						Component ATA:32
PN:DAP00101-02	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:052TG	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-07, AMM 32-41-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN							Component ATA:32
PN:57675-1	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:01321	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT							Component ATA:32
PN:2310-1183-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:00897	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK							Component ATA:32
PN:2317-5191-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759741/004	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-01, AMM 32-21-01, AMM 32-23-03, AMM 32-23-03								
32-43-00-001 ^S	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM							Service ATA:32
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-43-00								PKG:50
32-43-01-001 ^S	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM							Service ATA:32
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-43-00								PKG:50
32-43-02	PRESSURE SWITCH							Component ATA:32
PN:DAP00108-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:048SM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-03, AMM 29-12-03								
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR							Component ATA:32
PN:DAP00106-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:587	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-04, AMM 32-43-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-05	EMERGENCY/PARKING BRAKE VALVE							Component ATA:32
PN:DAP00107-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:047TC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-02								
32-43-08	THERMAL RELIEF VALVE							Component ATA:32
PN:DAP00110-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:739	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-08, AMM 32-43-08								
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE							Component ATA:32
PN:DAP00202-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:584	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-02, AMM 32-43-02								
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE							Component ATA:32
PN:2216-0001-401	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00971	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-11, AMM 32-43-11								
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE							Service ATA:32
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	800 (+30/-30)		800	830	498.2 (+30)	
	AFL	0						
PROC. REF: AMM 32-43-11								
32-45-00	LH MAIN WHEEL AND TIRE ASSY							Component ATA:32
PN:505-19517-611	MOS/MSC	19-Dec-23	O/C	TSR 0				
SN:5044JT	HRS	301.8		TSR 0				
	AFL	162		TSO 627, TSR 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-00	NOSE WHEEL AND TIRE ASSY							Component ATA:32
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-00	RH MAIN WHEEL AND TIRE ASSY							Component ATA:32
PN:505-19517-611	MOS/MSC	19-Dec-23	O/C	TSR 4				
SN:5164SL	HRS	301.8		TSR 0				
	AFL	162		TSO 375, TSR 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-01	LEFT MAIN WHEEL							Component ATA:32
PN:DAP00098-02	MOS/MSC	19-Dec-23	O/C	TSR 0				
SN:5044JT	HRS	301.8		TSR 0				
	AFL	162		TSO 627, TSR 0				
PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-01	RIGHT MAIN WHEEL							Component ATA:32
PN:DAP00098-02	MOS/MSC	19-Dec-23	O/C	TSR 4				
SN:5164SL	HRS	301.8		TSR 0				
	AFL	162		TSO 375, TSR 0				
PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY							Service ATA:32
PN:DAP00098-02	MOS	19-Dec-23						
SN:5044JT	HRS	301.8						
	AFL	162	T:1500 (+30/-30)	TAC 627	1035	1065	873 (+30)	
PROC. REF: AMM 32-45-00								
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY							Service ATA:32
PN:DAP00098-02	MOS	19-Dec-23						
SN:5164SL	HRS	301.8						
	AFL	162	T:1500 (+30/-30)	TAC 375	1287	1317	1125 (+30)	
PROC. REF: AMM 32-45-00								
32-45-02	LEFT MAIN WHEEL TIRE							Component ATA:32
PN:258K63-2	MOS/MSC	19-Dec-23	O/C	TSN 1				
SN:30790586	HRS	301.8		TSN 0				
	AFL	162		TSN 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-02	RIGHT MAIN WHEEL TIRE							Component ATA:32
PN:258K63-2	MOS/MSC	19-Dec-23	O/C	TSN 4				
SN:32000398	HRS	301.8		TSN 0				
	AFL	162		TSN 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-03	LH MLG HUB CAP							Component ATA:32
PN:DAP00131-02	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:114SH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-03, AMM 32-45-03								
32-45-03	RH MLG HUB CAP							Component ATA:32
PN:DAP00131-02	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:074SK	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-03, AMM 32-45-03								
32-45-11	NOSE WHEEL							Component ATA:32
PN:DAP00099-02	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:5030TF	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY							Service ATA:32
PN:DAP00099-02	MOS	06-Dec-19						
SN:5030TF	HRS	0						
	AFL	0	T:1500 (+30/-30)		1500	1530	1338 (+30)	
PROC. REF: AMM 32-45-00								
32-45-12	NOSE TIRE							Component ATA:32
PN:156E23-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:90772618	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-21	LH MLG CARBON BRAKE ASSY							Component ATA:32
PN:DAP00097-04	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:5083TB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21								
32-45-21	RH MLG CARBON BRAKE ASSY							Component ATA:32
PN:DAP00097-04	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:5092TB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-500	NOSE LANDING GEAR SHOCK ABSORBER							Component ATA:32
PN:2317-5170-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00582	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK							Component ATA:32
PN:2317-5227-501	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755237/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: GENERIC NO REF								
32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING							Component ATA:32
PN:2317-5113-005	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1759891/002	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: GENERIC NO REF								
32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER							Component ATA:32
PN:2317-5237-501	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1753631/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: GENERIC NO REF								
32-600	NOSE LANDING GEAR DRAG BRACE							Component ATA:32
PN:2317-6000-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00568	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-601	NOSE LANDING GEAR UPPER DRAG BRACE							Component ATA:32
PN:2317-6114-501	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1757808/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-602	NOSE LANDING GEAR LOWER DRAG BRACE							Component ATA:32
PN:2317-6201-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1755416/044	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-09, AMM 32-21-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN							Component ATA:32
PN:2317-6001-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1756504/003	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN							Component ATA:32
PN:2317-6001-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1756504/011	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-604	NOSE LANDING GEAR DRAG BRACE PIN							Component ATA:32
PN:2317-6003-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1738201/011	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-61-01	LH WING PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:53449	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:53351	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 1 NLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:53352	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:53448	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-01	NO. 2 NLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:53412	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:53450	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-700	NOSE LANDING GEAR LOCKING STAY							Component ATA:32
PN:2317-6500-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00566	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-701	NOSE LANDING GEAR UPPER LOCKING STAY							Component ATA:32
PN:2317-6521-003	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1756699/007	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-702	NOSE LANDING GEAR LOWER LOCKING STAY							Component ATA:32
PN:2317-6531-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1769845/003	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT							Component ATA:32
PN:2310-1734-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1628471/015	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT							Component ATA:32
PN:2310-1734-001	MOS	06-Dec-19		TSN 0				LIFE LIMIT
SN:1628471/005	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		11038	
PROC. REF: AMM 32-21-04, AMM 32-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-01-01	OVERHEAD LIGHTS CONTROL PANEL							Component ATA:33
PN:441-45393-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1076	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-01-01, AMM 33-01-01								
33-12-01	COCKPIT DIMMER							Component ATA:33
PN:81-01760-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1048	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-01, AMM 33-12-01								
33-12-02	INSC ILLUM - TEST PANEL							Component ATA:33
PN:441-42631-003	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1581	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02, AMM 33-12-02								
33-13-01	LH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY							Component ATA:33
PN:84075-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000533	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
33-13-01	RH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY							Component ATA:33
PN:84075-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
33-42-01	LH LWR FWD TAXI LIGHT ASSY							Component ATA:33
PN:81017-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000737	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01, AMM 33-42-01								
33-42-01	RH LWR FWD TAXI LIGHT ASSY							Component ATA:33
PN:81017-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000751	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01, AMM 33-42-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-47-01	LEFT LANDING LIGHT ASSY							Component ATA:33
PN:81017-5	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000749	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-47-01, AMM 33-47-01								
33-47-01	RIGHT LANDING LIGHT ASSY							Component ATA:33
PN:81017-6	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000726	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-47-01, AMM 33-47-01								
33-48-00	LEFT NO. 1 NAVIGATION LIGHT							Component ATA:33
PN:84004-7	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:001296	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								
33-48-00	LEFT NO. 2 NAVIGATION LIGHT							Component ATA:33
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								
33-48-00	RIGHT NO. 1 NAVIGATION LIGHT							Component ATA:33
PN:84004-7	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:001298	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								
33-48-00	RIGHT NO. 2 NAVIGATION LIGHT							Component ATA:33
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								
33-48-00-001	DISCARD LEFT NO. 1 NAVIGATION LIGHT							Service ATA:33
PN:84004-7	MOS	06-Dec-19						
SN:001296	HRS	0	12000 (+30/-30)		12000	12030	11698.2 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-48-00-001	DISCARD LEFT NO. 2 NAVIGATION LIGHT							Service ATA:33
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	12000 (+30/-30)		12000	12030	11698.2 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								
33-48-00-001	DISCARD RIGHT NO. 1 NAVIGATION LIGHT							Service ATA:33
PN:84004-7	MOS	06-Dec-19						
SN:001298	HRS	0	12000 (+30/-30)		12000	12030	11698.2 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								
33-48-00-001	DISCARD RIGHT NO. 2 NAVIGATION LIGHT							Service ATA:33
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	12000 (+30/-30)		12000	12030	11698.2 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								
33-48-00-002 ^S	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT							Service ATA:33
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								PKG:20
33-48-00-002 ^S	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT							Service ATA:33
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								PKG:20
33-48-00-002 ^S	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT							Service ATA:33
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								PKG:20
33-48-00-002 ^S	GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT							Service ATA:33
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-49-00	NO. 1 STROBE LIGHT							Component ATA:33
PN:84036-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000670	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02								
33-49-00	NO. 2 STROBE LIGHT							Component ATA:33
PN:84036-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:001247	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02								
33-49-00-001	DISCARD NO. 1 STROBE LIGHT							Service ATA:33
PN:84036-3	MOS	06-Dec-19						
SN:000670	HRS	0	8000 (+30/-30)		8000	8030	7698.2 (+30)	
	AFL	0						
PROC. REF: AMM 33-49-00								
33-49-00-001	DISCARD NO. 2 STROBE LIGHT							Service ATA:33
PN:84036-4	MOS	06-Dec-19						
SN:001247	HRS	0	8000 (+30/-30)		8000	8030	7698.2 (+30)	
	AFL	0						
PROC. REF: AMM 33-49-00								
33-49-00-002 ^S	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT							Service ATA:33
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-49-00								PKG:20
33-49-00-002 ^S	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT							Service ATA:33
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-49-00								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-52-01	EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR)							Component ATA:33
PN:7450LS-00	MOS/MSC	19-Dec-23	O/C	TSR 5				
SN:00848M	HRS	301.8		TSR 0				
	AFL	162		TSR 0				
PROC. REF: AMM 33-52-01, AMM 33-52-01								
33-52-01	EMERGENCY LIGHT BATTERY 2 (CENTER COMPT)							Component ATA:33
PN:7450LS-00	MOS/MSC	19-Dec-23	O/C	TSR 1				
SN:005710	HRS	301.8		TSR 0				
	AFL	162		TSR 0				
PROC. REF: AMM 33-52-01, AMM 33-52-01								
33-52-01-001	FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service ATA:33
PN:7450LS-00	MOS	19-Dec-23	12		19-Dec-24		177 d	
SN:00848M	HRS	301.8						
	AFL	162						
PROC. REF: AMM 33-52-01								
33-52-01-001	FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service ATA:33
PN:7450LS-00	MOS	19-Dec-23	12		19-Dec-24		177 d	
SN:005710	HRS	301.8						
	AFL	162						
PROC. REF: AMM 33-52-01								
33-52-01-002	FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH DLE BATTERY)							Service ATA:33
PN:7450LS-00	MOS/MSC		N/A					
SN:00848M	HRS							
	AFL							
PROC. REF: AMM 33-52-01								
33-52-01-002	FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH DLE BATTERY)							Service ATA:33
PN:7450LS-00	MOS/MSC		N/A					
SN:005710	HRS							
	AFL							
PROC. REF: AMM 33-52-01								
33-52-01-003	DISCARD OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR)							Service ATA:33
PN:7450LS-00	MOS/MSC		N/A					
SN:00848M	HRS							
	AFL							
PROC. REF: AMM 33-52-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-52-01-003	DISCARD OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT)							Service ATA:33
PN:7450LS-00	MOS/MSC		N/A					
SN:005710	HRS							
	AFL							
PROC. REF: AMM 33-52-01								
33-52-17-001 ^S	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED)							Service ATA:33
	MOS	06-Dec-19						
	HRS	0	1600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-52-17								
PKG:10								
ATA 34 - NAVIGATION								
34-00-02	TRANSPONDER RF RELAY							Component ATA:34
PN:D2-729B005	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:594807	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
34-00-03	NO.1 IASP SMART PROBE							Component ATA:34
PN:2015L-4B	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1348	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-07, AMM 34-15-07								
34-00-03	NO.2 IASP SMART PROBE							Component ATA:34
PN:2015L-4B	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1349	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-07, AMM 34-15-07								
34-10-01	RADIO ALTIMETER							Component ATA:34
PN:066-01153-0101	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:KRA405B-21198	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-02, AMM 34-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA							Component ATA:34
PN:S67-2002-45	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:553-10570	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-02, AMM 34-31-02								
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA							Component ATA:34
PN:S67-2002-45	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:553-11270	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-02, AMM 34-31-02								
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT							Component ATA:34
PN:C16786DA01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:C16786030078	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-01, AMM 34-11-01								
34-11-00-001	FUNCTIONAL CHECK OF (IESI) INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001)							Service ATA:34
PN:C16786DA01	MOS	19-Dec-23	24 (+1m/-1m)	Adj -90d	20-Sep-25	20-Oct-25	452 d (+30)	
SN:C16786030078	HRS	301.8						
	AFL	162						
PROC. REF: AMM 34-11-00								
34-11-02	PITOT/STATIC PROBE							Component ATA:34
PN:0856UT4	MOS/MSC	14-Sep-21	O/C	TSN 21				
SN:309468	HRS	119.1		TSN 119.1				
	AFL	52		TSN 52				
PROC. REF: AMM 34-11-02, AMM 34-11-02								
34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001)							Service ATA:34
PN:0856UT4	MOS	19-Dec-23	24 (+1m/-1m)	Adj -92d	18-Sep-25	18-Oct-25	450 d (+30)	
SN:309468	HRS	301.8						
	AFL	162						
PROC. REF: AMM 34-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-15-00-001 ^S	FUNCTIONAL CHECK OF AIR DATA SYSTEM							Service ATA:34
	MOS	19-Dec-23	24 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 34-15-00							PKG:81
34-15-00-002	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS							Service ATA:34
	MOS	06-Dec-19	60 (+1m/-1m)		06-Dec-24	06-Jan-25	164 d (+31)	
	HRS	0						
	AFL	0						
	PROC. REF: AMM 34-15-00							PKG:84
34-15-00-003	DETAILED INSPECTION OF IASP							Service ATA:34
	MOS	19-Dec-23	24 (+1m/-1m)	Adj 24d	12-Jan-26	12-Feb-26	566 d (+31)	
	HRS	301.8						
	AFL	162						
	PROC. REF: AMM 34-15-07							PKG:81
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM							Component ATA:34
PN:011-03732-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:45T002548	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 34-21-01, AMM 34-21-01							
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM							Component ATA:34
PN:011-03732-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:45T002552	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 34-21-01, AMM 34-21-01							
34-20-02	LEFT MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1CM025354	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 34-21-02, AMM 34-21-02							
34-20-02	RIGHT MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1CM026137	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 34-21-02, AMM 34-21-02							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-21-00-001 ^S		FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER						Service ATA:34
PN:011-00870-10	MOS	12-Jan-23	36 (+1m/-1m)					
SN:1CM025354	HRS	221						
	AFL	108						
PROC. REF: AMM 34-21-02								PKG:82
34-21-00-001 ^S		FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER						Service ATA:34
PN:011-00870-10	MOS	12-Jan-23	36 (+1m/-1m)					
SN:1CM026137	HRS	221						
	AFL	108						
PROC. REF: AMM 34-21-02								PKG:82
34-23-00		MAGNETIC COMPASS						Component ATA:34
PN:KCA0120W	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:BU6270519	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01, AMM 34-23-01								
34-23-00-001 ^S		FUNCTIONAL CHECK OF STANDBY COMPASS						Service ATA:34
PN:KCA0120W	MOS	12-Jan-23	36 (+1m/-1m)					
SN:BU6270519	HRS	221						
	AFL	108						
PROC. REF: AMM 34-23-00								PKG:82
34-30-01		LEFT VOR/LOC 2 & 3 BLADE ANTENNA						Component ATA:34
PN:S65-247170	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:173-6342	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03								
34-30-01		RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE						Component ATA:34
PN:S65-247170	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:173-6349	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03								
34-40-01		GDL-69A SATELLITE WEATHER AND RADIO RECEIVER						Component ATA:34
PN:011-03177-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:3NV004205	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01, AMM 34-57-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-40-02	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA							Component ATA:34
PN:013-00245-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:19530	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02								
34-40-02	FWD SEAT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA							Component ATA:34
PN:013-00245-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:18996	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02								
34-40-03	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA							Component ATA:34
PN:011-03997-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4RR001332	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01, AMM 34-42-01								
34-40-07	NOSE WEATHER RADAR ANTENNA							Component ATA:34
PN:117-00254-01	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:3443	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01, AMM 34-42-01								
34-43-02	LOWER TCAS L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:261-132853	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-02, AMM 34-43-02								
34-50-02	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:261-132544	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02								
34-50-02	TOP XPDR L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:261-130913	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-50-03	KN 63 DISTANCE MEASURING UNIT							Component ATA:34
PN:066-01070-0001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:43216	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01, AMM 34-51-01								
34-50-05	PHASING COUPLER							Component ATA:34
PN:SSPD-113-10	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:9847	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-01, AMM 34-32-01								
34-50-06	MARKER BEACON ANTENNA							Component ATA:34
PN:S35-1000-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:102-13595	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-04, AMM 34-32-04								
34-50-10	GSR 56 IRIDIUM UNIT							Component ATA:34
PN:011-02268-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1NZ008217	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-01, AMM 23-15-01								
34-50-11	IRIDIUM SATCOM ANTENNA							Component ATA:34
PN:S67-1575-109	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:430-16085	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-03, AMM 23-15-03								
34-50-12	GDL 59 DATALINK MANAGEMENT UNIT							Component ATA:34
PN:011-01746-03	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:57F000136	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-23-01, AMM 23-23-01								
34-50-13	WI-FI - DATALINK ANTENNA							Component ATA:34
PN:S65-5366-71S	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:258-6612	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-23-03, AMM 23-23-03, AMM 44-31-09, AMM 44-31-09, AMM 44-32-11, AMM 44-32-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-50-14	ADF ANTENNA							Component ATA:34
PN:622-7383-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4GPN7N	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-02, AMM 34-53-02								
34-50-15	ADF UNIT							Component ATA:34
PN:622-7382-101	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4G592X	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-01, AMM 34-53-01								
34-51-02	NO. 1 DME L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:261-132533	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02, AMM 34-51-02								
34-52-00	NO. 1 TRANSPONDER							Component ATA:34
PN:011-01997-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:20S010263	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-00	NO. 2 TRANSPONDER							Component ATA:34
PN:011-01997-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:20S010710	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM							Service ATA:34
PN:011-01997-00	MOS	08-Dec-23	24		08-Dec-25		531 d	
SN:20S010263	HRS							
	AFL							
PROC. REF: AMM 34-52-00								
34-52-00-001	FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM							Service ATA:34
PN:011-01997-00	MOS	08-Dec-23	24		08-Dec-25		531 d	
SN:20S010710	HRS							
	AFL							
PROC. REF: AMM 34-52-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-52-04	UPPER COAXIAL UNIT							Component ATA:34
PN:D2-729B005	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:594809	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-04, AMM 34-52-04								
34-53-01	ADF MOUNTING TRAY							Component ATA:34
PN:622-5212-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4FLF5T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-01, AMM 34-53-01								
ATA 35 - OXYGEN								
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE							Service ATA:35
	MOS	05-Jan-23	36 (+30d/-30d)	Adj -30d	06-Dec-25	05-Jan-26	529 d (+30)	AIRWORTHINESS
	HRS	221	2400 (+30/-30)		2621	2651	2319.2 (+30)	
	AFL	108						
PROC. REF: AMM 35-00-00								
35-01-00-001 ^S	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION							Service ATA:35
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 35-01-02								PKG:84
35-01-02	OXYGEN CYLINDER TRANSDUCER							Component ATA:35
PN:4441125-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8192-6-497	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-02, AMM 35-01-02								
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH							Component ATA:35
PN:P24151	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0715	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-05, AMM 35-01-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-01-06	OXYGEN SYSTEM CONTROL PANEL							Component ATA:35
PN:441-40945-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0997	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-06, AMM 35-01-06								
35-01-07	COCKPIT SENSOR							Component ATA:35
PN:P24099	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1159	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-07, AMM 35-01-07								
35-01-09	ALTITUDE COMPENSATING REGULATOR							Component ATA:35
PN:4421135-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:00973	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-09, AMM 35-01-09								
35-01-10	LOW PRESSURE OXYGEN VALVE							Component ATA:35
PN:4421132-109	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01114	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-10, AMM 35-01-10								
35-02-01	OXYGEN CYLINDER							Component ATA:35
PN:4441122-077	MOS/MSC	19-Dec-23	H/T	TSN 48				
SN:1038294203	HRS	301.8		TSN 301.8				
	AFL	162		TSN 162				
PROC. REF: AMM 35-02-01, AMM 35-02-01								
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR							Service ATA:35
PN:4441122-077	MOS	13-Dec-23	60		13-Dec-28		1632 d	
SN:1038294203	HRS							
	AFL							
PROC. REF: AMM 35-02-01								
35-02-01-003	DISCARD OF OXYGEN CYLINDER							Service ATA:35
PN:4441122-077	MOS	01-May-19	180		01-May-34		3597 d	LIFE LIMIT
SN:1038294203	HRS							
	AFL							
Manufacture Date:: 01-May-19 PROC. REF: AMM 35-02-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-02-01-004	RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER							Service ATA:35
	MOS		60		?		?	
	HRS							
	AFL							
PROC. REF: AMM 35-02-01								
35-02-05	OXYGEN PRESSURE REGULATOR							Component ATA:35
PN:172421-14	MOS/MSC	19-Dec-23	O/C	TSO 0				
SN:10347244603	HRS	301.8		TSO 0				
	AFL	162		TSO 0				
PROC. REF: GENERIC NO REF								
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX							Service ATA:35
	MOS	19-Dec-23	12 (+30d/-30d)	Adj 25d	13-Jan-25	12-Feb-25	202 d (+30)	AIRWORTHINESS
	HRS	301.8	800 (+30/-30)		1101.8	1131.8	800 (+30)	
	AFL	162						
PROC. REF: AMM 35-11-02								
35-11-01	COPILOT OXYGEN MASK STOWAGE BOX							Component ATA:35
PN:MXP603	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:SE110422	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-01	PILOT OXYGEN MASK STOWAGE BOX							Component ATA:35
PN:MXP603	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:SE108408	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-02	LEFT CREW OXYGEN MASK							Component ATA:35
PN:MC40-011	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:B148094	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-02, AMM 35-11-02								
35-11-02	RIGHT CREW OXYGEN MASK							Component ATA:35
PN:MC40-011	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:B148933	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-02, AMM 35-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-02-001	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK							Service ATA:35
PN:MC40-011	MOS/MSC	01-Nov-19	N/A					
SN:B148094	HRS	0						
	AFL							
PROC. REF: AMM 35-11-02								
35-11-02-001	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK							Service ATA:35
PN:MC40-011	MOS/MSC	01-Nov-19	N/A					
SN:B148933	HRS	0						
	AFL							
PROC. REF: AMM 35-11-02								
35-11-02-002	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK							Service ATA:35
PN:MC40-011	MOS	01-Mar-19	72 (+1m/-1m)		01-Mar-25	01-Apr-25	249 d (+31)	
SN:B148094	HRS	0	3600 (+30/-30)		3600	3630	3298.2 (+30)	
	AFL							
PROC. REF: AMM 35-11-02								
35-11-02-002	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK							Service ATA:35
PN:MC40-011	MOS	01-Apr-19	72 (+1m/-1m)		01-Apr-25	01-May-25	280 d (+30)	
SN:B148933	HRS	0	3600 (+30/-30)		3600	3630	3298.2 (+30)	
	AFL							
PROC. REF: AMM 35-11-02								
35-11-02-003	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK							Service ATA:35
PN:MC40-011	MOS	19-Dec-23	12 (+1m/-1m)		19-Dec-24	19-Jan-25	177 d (+31)	
SN:B148094	HRS	301.8						
	AFL	162						
PROC. REF: AMM 35-11-02								
35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK							Service ATA:35
PN:MC40-011	MOS	19-Dec-23	12 (+1m/-1m)		19-Dec-24	19-Jan-25	177 d (+31)	
SN:B148933	HRS	301.8						
	AFL	162						
PROC. REF: AMM 35-11-02								
35-11-04-001 ^S	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED)							Service ATA:35
	MOS	12-Jan-23	36 (+1m/-1m)					
	HRS	221						
	AFL	108						
PROC. REF: AMM 35-11-04								
PKG:82								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE							Service ATA:35
	MOS	05-Jan-23	36 (+30d/-30d)	Adj -30d	06-Dec-25	05-Jan-26	529 d (+30)	AIRWORTHINESS
	HRS	221	2400 (+30/-30)		2621	2651	2319.2 (+30)	
	AFL	108						
PROC. REF: AMM 35-21-00								
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE							Service ATA:35
	MOS	05-Jan-23	36 (+30d/-30d)	Adj -30d	06-Dec-25	05-Jan-26	529 d (+30)	AIRWORTHINESS
	HRS	221	2400 (+30/-30)		2621	2651	2319.2 (+30)	
	AFL	108						
PROC. REF: AMM 35-21-00								
35-21-01	AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:EB1-421048	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:D19061033	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	FWD SEAT ONE MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:EB1-421048	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:D19061035	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:EB2-421048	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:D19060215	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:EB2-421048	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:D19060216	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:EB2-421048	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:D19060219	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:EB2-421048	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:D19070122	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS							Service ATA:35
	MOS	12-Jan-23	36 (+1m/-1m)					
	HRS	221						
	AFL	108						
PROC. REF: AMM 35-21-01								
PKG:82								
35-21-02 ^U	ONE PASSENGER, MASK DEPLOYMENT SYST							Component ATA:35
PN:EB1-421048	MOS/MSC		O/C					
SN:D19061038	HRS							
	AFL							
35-31-01	PBE - PROTECTIVE BREATHING EQUIPMENT							Component ATA:35
PN:MR-10022NEMB	MOS/MSC	01-Apr-19	H/T	TSN 0				
SN:E1900852	HRS			TSN 0				
	AFL			TSN 0				
Manufacture Date:: 01-Apr-19 PROC. REF: AMM 35-31-01, AMM 35-31-01, AMM 35-31-01								
35-31-01-001	DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE)							Service ATA:35
PN:MR-10022NEMB	MOS	01-Apr-19	126 (+1m/-1m)		01-Oct-29	01-Nov-29	1924 d (+31)	LIFE LIMIT
SN:E1900852	HRS							
	AFL							
PROC. REF: AMM 35-31-01								
ATA 36 - PNEUMATIC								
36-00-00-710-801-A	TROUBLE SHOOT ENGINE OPERATING PROBLEMS - PNEUMATIC SYSTEM OPERATIONAL CHECK							Service ATA:36
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-00-00								
36-01-01	PNEUMATIC INSC ILLUM PANEL							Component ATA:36
PN:441-42633-002	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1571	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-01-01, AMM 36-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:RYLB-53505-5	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0800	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-01, AMM 36-11-01								
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:RYLB-53505-6	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0779	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-01, AMM 36-11-01								
36-11-01-001 ^S	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-01								PKG:20
36-11-01-002 ^S	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-00								PKG:1
36-11-02-001 ^S	DETAILED INSPECTION OF BLEED LINE WATER DRAINS							Service ATA:36
	MOS	19-Dec-23	24 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 36-11-02								PKG:81
36-11-03	AMS CONTROLLER							Component ATA:36
PN:SYLZ-53632-205	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0650A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-03, AMM 36-11-03								
36-11-04	NO. 1 ENGINE FAN AIR VALVE							Component ATA:36
PN:RYLB-53527-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1243	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-04, AMM 36-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-04	NO. 2 ENGINE FAN AIR VALVE							Component ATA:36
PN:RYLB-53527-2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1233	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-04, AMM 36-11-04								
36-11-04-001 ^S	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-04								
PKG:20								
36-11-05	LH INCONEL 625 BLEED PRE-COOLER							Component ATA:36
PN:381256000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:T0669	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-05, AMM 36-11-05								
36-11-05	RH INCONEL 625 BLEED PRE-COOLER							Component ATA:36
PN:381257000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:T0683	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-05, AMM 36-11-05								
36-11-06	CROSS BLEED VALVE							Component ATA:36
PN:RYLB-53506-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0564	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-06, AMM 36-11-06								
36-11-06-001 ^S	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-06								
PKG:1								
36-11-06-002 ^S	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-06								
PKG:60								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER							Component ATA:36
PN:APTE-479F-1000-200GMOS/MSC		06-Dec-19	O/C	TSN 0				
SN:8448-10-704	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-07, AMM 36-11-07								
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER							Component ATA:36
PN:APTE-479F-1000-200GMOS/MSC		06-Dec-19	O/C	TSN 0				
SN:8600-6-626	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-07, AMM 36-11-07								
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:103-00264	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01385	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:103-00264	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01395	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:103-00264	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01396	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:103-00264	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01399	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-08								
								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 36-11-08							PKG:60
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 36-11-08							PKG:60
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	06-Dec-19						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 36-11-08							PKG:60
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS							Service ATA:36
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	6098.2 (+30)	
	AFL	0						
	PROC. REF: AMM 36-21-01							
ATA 38 - WATER/WASTE								
38-33-07	WASTE DRAIN VALVE							Component ATA:38
PN:0218-0032-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:306934	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 38-33-07, AMM 38-33-07							
ATA 44 - CABIN SYSTEMS								
44-12-06 ^U	SUBWOOFER CABIN HIFI TWO							Component ATA:44
PN:SUB1814-004-000	MOS/MSC		O/C					
SN:000122	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
44-21-09	IFE INSC ILLUM PANEL							Component ATA:44
PN:441-44843-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1360	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-09, AMM 44-21-09								
44-21-12	HDMI / USB CABIN JACK MODULE							Component ATA:44
PN:ADT-1810-007-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000842	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-23-15, AMM 44-23-15								
44-21-14	RJ45 / USB CABIN JACK MODULE							Component ATA:44
PN:ADT-1810-005-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000736	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-23-07, AMM 44-23-07								
44-21-16	PAX 1 GMA 36 REMOTE AUDIO CONTROLLER							Component ATA:44
PN:011-04093-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4RK110377	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
44-21-16	PAX 2 GMA 36 REMOTE AUDIO CONTROLLER							Component ATA:44
PN:011-04093-00	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:4RK110387	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
44-21-23	NO. 1 WIRELESS HEADPHONE							Component ATA:44
PN:ADT1810-013-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000219	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
44-21-23	NO. 2 WIRELESS HEADPHONE							Component ATA:44
PN:ADT1810-013-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000223	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER							Component ATA:44
PN:BDP3009-203-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:500060	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-22-01, AMM 44-22-01								
44-22-02	LEFT AFT CABIN SPEAKER							Component ATA:44
PN:SPK4615-001-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000307	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-12-01, AMM 44-12-01								
44-22-02	LEFT FORWARD CABIN SPEAKER							Component ATA:44
PN:SPK4615-001-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000309	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-12-01, AMM 44-12-01								
44-22-02	RIGHT AFT CABIN SPEAKER							Component ATA:44
PN:SPK4615-001-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000310	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-12-01, AMM 44-12-01								
44-22-02	RIGHT FORWARD CABIN SPEAKER							Component ATA:44
PN:SPK4615-001-000	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000311	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-12-01, AMM 44-12-01								
44-22-03	NO. 1 10.4 INCH FOLD DOWN MONITOR-							Component ATA:44
PN:DIS0716-002-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:000109	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-22-03, AMM 44-22-03								
44-32-03	AIRCELL CONFIGURATION MODULE							Component ATA:44
PN:P14126	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1412619294	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-32-03, AMM 44-32-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
44-32-04 ^U		GOGO BIZ 4G TRANSCEIVER (5MCU, 2 AIRCARD)					Component	ATA:44
PN:P34110-002	MOS/MSC		O/C					
SN:3411000200714	HRS							
	AFL							
44-32-06 ^U		ASE 900 MHZ DUAL DIRECTIONAL ANTENNA					Component	ATA:44
PN:P35500	MOS/MSC		O/C					
SN:3550001904	HRS							
	AFL							
44-32-07 ^U		ASE 900 MHZ DUAL DIRECTIONAL ANTENNA					Component	ATA:44
PN:P35500	MOS/MSC		O/C					
SN:3550002069	HRS							
	AFL							
44-60-01		ETHERNET INTERFACE UNIT					Component	ATA:44
PN:EIU3009-201-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:500297	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-23-01, AMM 44-23-01								
44-60-02		ETHERNET ENCODER UNIT					Component	ATA:44
PN:EEU0910-201-001	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:500687	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-23-05, AMM 44-23-05								
ATA 52 - DOORS								
52-00-00		KEY LOCK KIT					Component	ATA:52
PN:505-09736-901	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:8MA005727DW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-10-00-001 ^S		INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE					Service	ATA:52
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 52-10-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-00-01A	PAX DOOR EQUIPPED MAIN DOOR ASSY							Component ATA:52
PN:505-09910-469	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001044541	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00, AMM 52-10-00								
52-10-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE							Service ATA:52
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 52-10-00								
PKG:84								
52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL							Service ATA:52
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 52-10-00								
52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL							Service ATA:52
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 52-10-00								
52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL							Service ATA:52
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 52-10-00								
52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL							Service ATA:52
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 52-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-20-001 ^S	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL							Service ATA:52
	MOS	19-Dec-23	12 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 52-10-20							PKG:80	
52-11-00-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 52-11-00							PKG:83	
52-11-00-003 ^S	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH							Service ATA:52
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-11-23							PKG:1	
52-13-00	MAIN DOOR BALANCE ASSY. GEAR SECTOR							Component ATA:52
PN:PN	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-13-01	MAIN DOOR BALANCE ASSY. PINION SHAFT							Component ATA:52
PN:PN	MOS/MSC	06-Dec-19	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-13-21-001 ^S	DISCARD OF SECTOR GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED)							Service ATA:52
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-21							PKG:50	
52-13-22	MAIN DOOR BALANCING MECHANISM							Component ATA:52
PN:PN	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-00, AMM 52-13-00, AMM 52-13-22, AMM 52-13-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-13-22-001 ^S	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE							Service ATA:52
PN:PN	MOS/MSC	06-Dec-19	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 52-13-22							PKG:1	
52-13-22-004 ^S	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES							Service ATA:52
	MOS	06-Dec-19						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-22							PKG:40	
52-13-23-001 ^S	DISCARD OF SHAFT PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED)							Service ATA:52
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-23							PKG:50	
52-20-00	EMERGENCY DOOR							Component ATA:52
PN:505-09700-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001044786	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-20-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE							Service ATA:52
	MOS/MSC	06-Dec-19	O/C					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 52-20-00								
52-20-01-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE							Service ATA:52
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 52-20-00, NDT PART 5 52-20-00							PKG:90	
52-20-01-01-901	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL							Service ATA:52
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 52-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-01-01-902	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL							Service ATA:52
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 52-20-00								
52-20-20-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 52-20-20								PKG:83
52-20-21-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR RUBBER SEAL							Service ATA:52
	MOS	19-Dec-23	24 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 52-20-21								PKG:81
52-31-20-001 ^S	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 52-31-20								PKG:83
52-32-20-001 ^S	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM							Service ATA:52
	MOS	19-Dec-23	48 (+1m/-1m)					
	HRS	301.8						
	AFL	162						
PROC. REF: AMM 52-32-20								PKG:83
ATA 53 - FUSELAGE								
53-00-00-001 ^S	GENERAL VISUAL INSPECTION OF FUSELAGE POLYURETHANE FILMS							Service ATA:53
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 53-00-20								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-05-00-001 ^S	DETAILED INSPECTION OF FUSELAGE DRAINS							Service ATA:53
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-05-00							PKG:84	
53-10-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00							PKG:90	
53-10-00-002	EXTERNAL GENERAL VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES							Service ATA:53
	MOS/MSC	06-Dec-19	O/C					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00							PKG:87	
53-10-00-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE							Service ATA:53
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00							PKG:87	
53-10-01-01-901	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00							PKG:87	
53-10-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00							PKG:87	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-02-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00								
53-10-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00								
53-10-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00								
53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00								
53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00								
53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00								PKG:90
53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-10-00								
53-10-07-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE							Service ATA:53
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00								PKG:84
53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS,DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL							Service ATA:53
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:15000		15000		14698.2	
	AFL	0	T:12000		12000		11838	
PROC. REF: NDT PART 5 53-10-00								
53-10-07-02-901	DETAILED INSPECTION OF WHEEL WEEL STRUCTURE. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - EXTERNAL							Service ATA:53
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:15000		15000		14698.2	
	AFL	0	T:12000		12000		11838	
PROC. REF: NDT PART 5 53-10-00								
53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WEEL STRUCTURE.							Service ATA:53
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:15000		15000		14698.2	
	AFL	0	T:12000		12000		11838	
PROC. REF: NDT PART 5 53-10-00								
53-11-00 ^U	FORWARD FUSELAGE ASSY							Component ATA:53
PN:507-01000-405	MOS/MSC	O/C						
SN:0001045997	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-11-01 ^U	CENTRAL FUSELAGE,ASSY-CTL FUS							Component ATA:53
PN:507-03500-415	MOS/MSC		O/C					
SN:0001041105	HRS							
	AFL							
53-11-02 ^U	ALIGNMENT,FUSELAGE JUNCTION							Component ATA:53
PN:507-08700-417	MOS/MSC		O/C					
SN:0001044064	HRS							
	AFL							
53-11-03 ^U	REAR FUSELAGE,ASSY							Component ATA:53
PN:507-06000-409	MOS/MSC		O/C					
SN:0001044093	HRS							
	AFL							
53-11-04 ^U	FUSELAGE,ASSY FUSLG COMPLETE							Component ATA:53
PN:507-09001-435	MOS/MSC		O/C					
SN:0001045998	HRS							
	AFL							
53-11-05 ^U	WING ASSY							Component ATA:53
PN:505-11900-455	MOS/MSC		O/C					
SN:0001045233	HRS							
	AFL							
53-11-06 ^U	WING ASSY-EQUIPED							Component ATA:53
PN:505-11984-407	MOS/MSC		O/C					
SN:0001048515	HRS							
	AFL							
53-11-07 ^U	WING JUNCTION							Component ATA:53
PN:505-12000-445	MOS/MSC		O/C					
SN:0001044458	HRS							
	AFL							
53-11-08 ^U	WING,HALF, ASSY							Component ATA:53
PN:505-12200-439	MOS/MSC		O/C					
SN:0001041416	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-11-09 ^U	WING,HALF,ASSY							Component ATA:53
PN:505-12200-440	MOS/MSC		O/C					
SN:0001039510	HRS							
	AFL							
53-14-00	NOSE RADOME							Component ATA:53
PN:5190-102-1	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:944	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-14-00, AMM 53-14-00								
53-20-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								
							PKG:90	
53-20-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								
							PKG:90	
53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90
53-20-05-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90
53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-06-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:84
53-20-06-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90
53-20-06-01-901	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-06-01-902	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:8750		8750		8448.2	
	AFL	0	T:7000		7000		6838	
PROC. REF: NDT PART 5 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-07-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-07-01-902	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-08-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90
53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-10-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-20-00								
53-30-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								PKG:90
53-30-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								PKG:90
53-30-01-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-02-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								
53-30-02-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:12500		12500		12198.2	
	AFL	0	T:10000		10000		9838	
PROC. REF: NDT PART 5 53-30-00								
53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-04-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								
PKG:90								
53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:10000		10000		9698.2	
	AFL	0	T:8000		8000		7838	
PROC. REF: NDT PART 5 53-30-00								
53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:12500		12500		12198.2	
	AFL	0	T:10000		10000		9838	
PROC. REF: NDT PART 5 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-07-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								PKG:90
53-30-07-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								PKG:90
53-30-07-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								
53-30-07-01-902	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL							Service ATA:53
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-08-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46							Service ATA:53
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: NDT PART 5 53-30-00							PKG:87
53-30-08-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46							Service ATA:53
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: NDT PART 5 53-30-00							PKG:90
ATA 54 - NACELLES/PYLONS								
54-00-00-001 ^S	GENERAL VISUAL INSPECTION OF PYLON POLYURETHANE FILMS							Service ATA:54
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 54-51-20							PKG:1
54-50-00-001 ^S	INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE							Service ATA:54
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: NDT PART 5 54-50-00							PKG:90
54-50-00-002 ^S	INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX							Service ATA:54
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: NDT PART 5 54-52-00, NDT PART 5 54-52-00							PKG:90
54-50-01-01-901	GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
	PROC. REF: NDT PART 5 54-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-02-01-901	GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 54-50-00								
54-50-03-001 ^S	EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE.							Service ATA:54
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 54-52-00								
PKG:84								
54-50-03-01-901	GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 54-52-00								
54-50-03-01-902	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 54-52-00								
54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 54-52-00								
54-50-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES							Service ATA:54
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 54-55-00								
PKG:87								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:15000		15000		14698.2	
	AFL	0	T:12000		12000		11838	
PROC. REF: NDT PART 6 54-55-00								
54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 54-55-00								
54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:15000		15000		14698.2	
	AFL	0	T:12000		12000		11838	
PROC. REF: NDT PART 5 54-55-00								
54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL							Service ATA:54
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:15000		15000		14698.2	
	AFL	0	T:12000		12000		11838	
PROC. REF: NDT PART 5 54-55-00								
ATA 55 - STABILIZERS								
55-00-00-001 ^S	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS							Service ATA:55
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 55-00-20								PKG:1
55-03-00	HORIZONTAL TAIL - EQUIPED							Component ATA:55
PN:505-10983-403	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001048328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-00	HORIZONTAL STABILIZER (COMPLETION)							Component ATA:55
PN:505-10700-421	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001044755	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
55-10-00-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								
							PKG:84	
55-10-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								
							PKG:84	
55-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								
							PKG:84	
55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-02-01-902	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								
								PKG:87
55-10-03-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								
								PKG:84
55-10-03-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-03-01-902	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-05-001 ^S	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS							Service ATA:55
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								
55-10-05-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-05-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 55-10-00								
55-10-05-02-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-05-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-05-04-901	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 55-10-00								
55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-08-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								PKG:84
55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-09-001	EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT							Service ATA:55
	MOS/MSC	06-Dec-19	O/C					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								
55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-09-01-902	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-10-10-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR TRIM-TAB FITTINGS							Service ATA:55
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								PKG:90
55-10-10-01-901	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-10-00								
55-20-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00								PKG:87
55-20-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-20-00								
55-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-20-00								
55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-20-00								
55-20-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-20-00								PKG:87
55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 55-20-00								
55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 8 55-20-00								
55-20-04-001	INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	06-Dec-19	60		06-Dec-24		164 d	ALI
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-04-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS							Service ATA:55
	MOS	06-Dec-19	60		06-Dec-24		164 d	ALI
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-20-00								
55-22-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB							Service ATA:55
	MOS	06-Dec-19	T:120					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-22-00								PKG:90
55-30-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								PKG:84
55-30-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER							Service ATA:55
	MOS	06-Dec-19	T:120					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								PKG:90
55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 55-30-00								
55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 55-30-00								
55-30-02-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								
PKG:84								
55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 55-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-02-05-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-03-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								PKG:87
55-30-03-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00, NDT PART 5 55-30-00								PKG:87
55-30-03-01-901	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-03-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-04-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								PKG:84
55-30-04-01-901	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER							Service ATA:55
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								PKG:84
55-30-05-01-901	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-30-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING							Service ATA:55
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-06-01-901	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-30-00								
55-40-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								
55-40-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-40-00								
55-40-01-01-902	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-40-00								
55-40-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								
55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-40-00								
55-40-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY							Service ATA:55
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								
55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL							Service ATA:55
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 55-40-00								
55-40-04-002	INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	06-Dec-19	60		06-Dec-24		164 d	ALI
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								
55-40-04-003	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	06-Dec-19	60		06-Dec-24		164 d	ALI
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								
55-42-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB							Service ATA:55
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-42-00								
ATA 56 - WINDOWS								
56-10-00	COPILOT HEATED GLASS WINDSHIELD ASSY							Component ATA:56
PN:NP-195301-6	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:19135H2919	HRS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
	AFL	0		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00								
56-10-00	PILOT HEATED GLASS WINDSHIELD ASSY							Component ATA:56
PN:NP-195301-5	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:19130H2379	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00								
56-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF SIDE WINDOWS PANE (BOTH SIDES)							Service ATA:56
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-12-00								
								PKG:84
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF COPILOT SIDE WINDOW ATTACHING BOLTS							Service ATA:56
PN:NP-195302-4	MOS	06-Dec-19						
SN:19135H2810	HRS	0	T:800 (+30/-30)	800	830	498.2 (+30)		
	AFL	0						
PROC. REF: AMM 56-10-00								
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF COPILOT WINDSHIELD ATTACHING BOLTS							Service ATA:56
PN:NP-195301-6	MOS	06-Dec-19						
SN:19135H2919	HRS	0	T:800 (+30/-30)	800	830	498.2 (+30)		
	AFL	0						
PROC. REF: AMM 56-10-00								
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF PILOT SIDE WINDOW ATTACHING BOLTS							Service ATA:56
PN:NP-195302-3	MOS	06-Dec-19						
SN:19099H9313	HRS	0	T:800 (+30/-30)	800	830	498.2 (+30)		
	AFL	0						
PROC. REF: AMM 56-10-00								
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF PILOT WINDSHIELD ATTACHING BOLTS							Service ATA:56
PN:NP-195301-5	MOS	06-Dec-19						
SN:19130H2379	HRS	0	T:800 (+30/-30)	800	830	498.2 (+30)		
	AFL	0						
PROC. REF: AMM 56-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE						Service ATA:56
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE						Service ATA:56
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE						Service ATA:56
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE						Service ATA:56
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90
56-10-03-01-901		SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL						Service ATA:56
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 56-10-00								
56-12-00		COPILOT ACRYLIC SIDE WINDOW						Component ATA:56
PN:NP-195302-4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:19135H2810	HRS	0	TSN 0					
	AFL	0	TSN 0					
PROC. REF: AMM 56-12-00, AMM 56-12-00								
56-12-00		PILOT ACRYLIC SIDE WINDOW						Component ATA:56
PN:NP-195302-3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:19099H9313	HRS	0	TSN 0					
	AFL	0	TSN 0					
PROC. REF: AMM 56-12-00, AMM 56-12-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-00	NO. 1 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:797070	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 10 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808268	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 11 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808270	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 2 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808271	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 3 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808295	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 4 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808296	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 5 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808297	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-00	NO. 6 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808299	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 7 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:808301	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 8 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:817026	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 9 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:856016	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE PASSENGER WINDOW PANELS							Service ATA:56
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-20-00								PKG:84
ATA 57 - WINGS								
57-00-00-001 ^S	GENERAL VISUAL INSPECTION OF WINGLET POLYURETHANE FILMS							Service ATA:57
	MOS	06-Dec-19						
	HRS	0	800 (+30/-30)					
	AFL	0						
PROC. REF: AMM 57-35-21								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-001 ^S		INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX						Service ATA:57
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00							PKG:90	
57-10-00-002 ^S		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN						Service ATA:57
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00							PKG:87	
57-10-01		LEFT WING LOWER SKIN						Component ATA:57
PN:505-12400-419	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001036620	HRS	0			TSN 0			
	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
57-10-01		RIGHT WING LOWER SKIN						Component ATA:57
PN:505-12400-420	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:0001036500	HRS	0			TSN 0			
	AFL	0			TSN 0			
PROC. REF: GENERIC NO REF								
57-10-01-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS						Service ATA:57
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-00-00							PKG:87	
57-10-01-01-901		DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL						Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-10-00								
57-10-02-002 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR						Service ATA:57
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00							PKG:90	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-02-01-901	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-10-00								
57-10-03-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR							Service ATA:57
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00								
57-10-03-01-901	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-10-00								
57-10-04-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-20-00								
57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-10-00								
57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL							Service ATA:57
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: NDT PART 5 57-10-00							PKG:87
57-10-07-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: NDT PART 5 57-10-00							PKG:84
57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
	PROC. REF: NDT PART 5 57-10-00							
57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
	PROC. REF: NDT PART 5 57-10-00							
57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
	PROC. REF: NDT PART 5 57-10-00							
57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
	PROC. REF: NDT PART 5 57-10-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-11-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00							PKG:84	
57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-10-00								
57-10-11-01-902	SPECIAL DETAILED INSPECTION (BOREScope) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-10-00								
57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:12500		12500		12198.2	
	AFL	0	T:10000		10000		9838	
PROC. REF: NDT PART 5 57-10-00								
57-50-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-50-00							PKG:84	
57-50-01-01-901	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-01-01-902	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:11250		11250		10948.2	
	AFL	0	T:9000		9000		8838	
PROC. REF: NDT PART 6 57-50-00								
57-50-01-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 57-50-00								
57-50-01-03-901	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-50-00								
57-50-01-04-901	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-50-00								
57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 57-50-00								
57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-20-00							PKG:84	
57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 57-50-00								
57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-50-00								
57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 57-50-00								
57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-50-00								
57-52-00-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP							Service ATA:57
	MOS	06-Dec-19	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-52-00							PKG:90	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-52-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-52-00							PKG:84	
57-52-01-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-52-00								
57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-52-00								
57-52-02-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-52-00								
57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:11250		11250		10948.2	
	AFL	0	T:9000		9000		8838	
PROC. REF: NDT PART 6 57-52-00								
57-52-04-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	06-Dec-19					AIRWORTHINESS	
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-52-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 57-52-00								
57-53-00-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE OUTBOARD FLAP							Service ATA:57
	MOS	06-Dec-19	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-53-00								PKG:87
57-53-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-53-00								PKG:84
57-53-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-53-00								
57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-53-00								
57-53-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-53-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:11250		11250		10948.2	
	AFL	0	T:9000		9000		8838	
PROC. REF: NDT PART 6 57-53-00								
57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-53-00								
57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-53-00								
57-53-04-03-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-53-00								
57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 6 57-53-00								
57-60-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON							Service ATA:57
	MOS	06-Dec-19	60		06-Dec-24		164 d	ALI
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-00-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON AND TAB							Service ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-60-00							PKG:84	
57-60-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-60-00								
57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-60-00								
57-60-01-02-901	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-60-00								
57-60-02-01-901	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-60-00								
57-60-02-02-901	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL							Service ATA:57
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:17500		17500		17198.2	
	AFL	0	T:14000		14000		13838	
PROC. REF: NDT PART 5 57-60-00								
57-60-04-001 ^U	INTERNAL DETAILED VISUAL INSPECTION OF AILERON MASS-BALANCE WEIGHTS AND ATTACHMENTS							Service ATA:57
	MOS/MSC	06-Dec-19	O/C					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
57-70-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS							Service	ATA:57
	MOS	06-Dec-19	60 (+1m/-1m)						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 5 57-70-00							PKG:84		
ATA 70 - STANDARD PRACTICES - ENGINES									
700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION							Service	ATA:70
	MOS/MSC	06-Dec-19	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 70-00-00									
700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION							Service	ATA:70
	MOS/MSC	06-Dec-19	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 70-00-00									
ATA 71 - POWER PLANT									
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS							Service	ATA:71
	MOS/MSC	06-Dec-19	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 70-00-00									
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS							Service	ATA:71
	MOS/MSC	06-Dec-19	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 70-00-00									
71-00-00-160-805	NO. 1 ENGINE - COMPRESSOR WASH							Service	ATA:71
	MOS/MSC	06-Dec-19	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 71-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-160-805	NO. 2 ENGINE - COMPRESSOR WASH							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-160-806	NO. 1 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-160-806	NO. 2 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-810	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-810	NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-814	NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-814	NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-760-817	NO. 1 ENGINE - DOWNLOAD ENGINE DCU DATA							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-817	NO. 2 ENGINE - DOWNLOAD ENGINE DCU DATA							Service ATA:71
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-823	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	19-Dec-23	12 (+30d)		19-Dec-24	18-Jan-25	177 d (+30)	
	HRS	301.8	630 (+10%)		(931.8) 930.1	994.8	628.3 (+63)	
	ENC	162						
PROC. REF: MM 71-00-00								
71-00-00-760-823	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	19-Dec-23	12 (+30d)		19-Dec-24	18-Jan-25	177 d (+30)	
	HRS	301.8	630 (+10%)		(931.8) 930.1	994.8	628.3 (+63)	
	ENC	162						
PROC. REF: MM 71-00-00								
71-11-00-001 ^S	GENERAL VISUAL INSPECTION OF UPPER MID COWL							Service ATA:71
	MOS	06-Dec-19						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 71-11-00								PKG:50
71-20-00	LEFT AFT ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:LK1501	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:LK2794	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:LK2817	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00	RIGHT AFT ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA4	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:LK1497	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00								
71-20-00	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:LK2870	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:LK2883	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT AFT MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA4	MOS/MSC	06-Dec-19	O/C					
SN:LK1501	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C					
SN:LK2794	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C					
SN:LK2817	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT AFT MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA4	MOS/MSC	06-Dec-19	O/C					
SN:LK1497	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C					
SN:LK2870	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	06-Dec-19	O/C					
SN:LK2883	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-21-01-01-901	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY							Service ATA:71
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:7500		7500		7198.2	
	AFL	0	T:6000		6000		5838	
PROC. REF: AMM 71-20-00								
71-22-01-01-901	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL							Service ATA:71
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:4500		4500		4198.2	
	AFL	0	T:3600		3600		3438	
PROC. REF: NDT PART 5 71-22-00, NDT PART 5 71-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-22-01-01-902	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY							Service ATA:71
	MOS	06-Dec-19						AIRWORTHINESS
	HRS	0	T:7500		7500		7198.2	
	AFL	0	T:6000		6000		5838	
PROC. REF: AMM 71-20-00								
71-31-00-001 ^S	DETAILED INSPECTION OF PYLON FIREWALL SEAL							Service ATA:71
	MOS	06-Dec-19						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 71-31-00								
PKG:20								
71-60-01	LEFT ENGINE AIR INLET							Component ATA:71
PN:505-43420-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:CPI555	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01								
71-60-01	RIGHT ENGINE AIR INLET							Component ATA:71
PN:505-43430-405	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:CPI555	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:3072702	MOS/MSC		E/C					
SN:PCE-DG1089	HRS							
WC#: 71.EN1	AFL							
PROC. REF: AMM 71-00-00, AMM 71-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:3072702	MOS/MSC		E/C					
SN:PCE-DG1088	HRS							
WC#: 71.EN2	AFL							
PROC. REF: AMM 71-00-00, AMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	19-Dec-23	12		19-Dec-24		177 d	
	HRS	301.8	630		(931.8) 930.1		628.3	
	ENC	162						
PROC. REF: MM 72-00-02								
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	19-Dec-23	12		19-Dec-24		177 d	
	HRS	301.8	630		(931.8) 930.1		628.3	
	ENC	162						
PROC. REF: MM 72-00-02								
ATA 72 - ENGINE								
72-00-00-000-802	NO. 1 ENGINE - LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL							Service ATA:72
PN:3073356-01	MOS/MSC	31-Jul-19	A/R					
SN:PKAAA827987	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
72-00-00-000-802	NO. 1 ENGINE - DISCARD GAS GENERATOR CASE							Service ATA:72
PN:3076150-01	MOS	06-Dec-19						
SN:RWA76F364	HRS	0						
	ENC	0	10000		(10000) 9997		9835	
PROC. REF: GENERIC NO REF								
72-00-00-000-802	NO. 2 ENGINE - LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL							Service ATA:72
PN:3073356-01	MOS/MSC	31-Jul-19	A/R					
SN:PKAAA827993	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
72-00-00-000-802	NO. 2 ENGINE - DISCARD GAS GENERATOR CASE							Service ATA:72
PN:3076150-01	MOS	06-Dec-19						
SN:RWA73F226	HRS	0						
	ENC	0	10000		(10000) 9997		9835	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-802 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-802 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-803 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-803 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-804 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
	PROC. REF: MM 72-00-00							PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-804 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-805 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-805 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-806 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-806 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-807 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-807 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-808 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-808 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-809 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-809 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-280-802	NO. 1 ENGINE - BORESCOPE INSPECT HP COMPRESSOR AND DIFFUSER EXIT DUCTS							Service ATA:72
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-280-802	NO. 2 ENGINE - BORESCOPE INSPECT HP COMPRESSOR AND DIFFUSER EXIT DUCTS							Service ATA:72
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-280-818	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	06-Dec-19	T:120 (+1m)		06-Dec-29	06-Jan-30	1990 d (+31)	
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-280-818	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	06-Dec-19	T:120 (+1m)		06-Dec-29	06-Jan-30	1990 d (+31)	
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-280-820 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								
72-00-00-280-820 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES							Service ATA:72
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								
72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS/MSC	06-Dec-19	BF/F					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS/MSC	06-Dec-19	BF/F					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-640-806	NO. 1 ENGINE - OIL ANALYSIS							Service ATA:72
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-640-806	NO. 2 ENGINE - OIL ANALYSIS							Service ATA:72
	MOS/MSC	06-Dec-19	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-01-810-822	NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)							Service ATA:72
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-01								
72-00-01-810-822	NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)							Service ATA:72
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-01								
72-00-51-030-002	NO. 1 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER							Service ATA:72
	MOS	31-Jul-19						LIFE LIMIT
	HRS	0	5000 (+100)		(5000) 4998.3 (M)	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 72-50-01, MM 72-50-01								
72-00-51-030-002	NO. 2 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER							Service ATA:72
	MOS	31-Jul-19						LIFE LIMIT
	HRS	0	5000 (+100)		(5000) 4998.3 (M)	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 72-50-01, MM 72-50-01								
72-60-01-212-801	NO. 1 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES							Service ATA:72
	MOS	06-Dec-19						
	HRS	0	1200 (+100)		(1200) 1198.3	1300	896.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
72-60-01-212-801	NO. 2 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES							Service ATA:72
	MOS	06-Dec-19						
	HRS	0	1200 (+100)		(1200) 1198.3	1300	896.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-02-212-801 ^U	NO. 1 ENGINE - DO AN INSPECTION OF ENGINE HYDRAULIC PUMP SHAFT SPLINES							Service ATA:72
	MOS	31-Jul-19						
	HRS	0	1200 (+100/-100)		(1200) 1198.3	1300	896.5 (+100)	
	ENC							
72-60-02-212-801 ^U	NO. 2 ENGINE - DO AN INSPECTION OF ENGINE HYDRAULIC PUMP SHAFT SPLINES							Service ATA:72
	MOS	27-Jul-19						
	HRS	0	1200 (+100/-100)		(1200) 1198.3	1300	896.5 (+100)	
	ENC							
720010	NO. 1 ENGINE - OVERHAUL							Service ATA:72
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
720010	NO. 2 ENGINE - OVERHAUL							Service ATA:72
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
720060	NO. 1 ENGINE - HOT SECTION INSPECTION							Service ATA:72
	MOS	06-Dec-19						
	HRS	0	2500 (+50)		(2500) 2498.3	2550	2196.5 (+50)	
	ENC	0						
PROC. REF: MM 72-00-00								
720060	NO. 2 ENGINE - HOT SECTION INSPECTION							Service ATA:72
	MOS	06-Dec-19						
	HRS	0	2500 (+50)		(2500) 2498.3	2550	2196.5 (+50)	
	ENC	0						
PROC. REF: MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
722001	NO. 1 ENGINE - OIL PUMP							Component ATA:72
PN:3073477-02	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:EC01A006A510	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-02, MM 79-20-02								
722001	NO. 2 ENGINE - OIL PUMP							Component ATA:72
PN:3073477-02	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:EC01A006A509	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-02, MM 79-20-02								
723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY							Component ATA:72
PN:3073356-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:PKAAA827987	HRS	0		TSN 0				
	ENC	0		TSN 0	(30000) 29997 (M)		29835	
	ACCCYC	0	30000	TSN 0				
PROC. REF: GENERIC NO REF								
723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY							Component ATA:72
PN:3073356-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:PKAAA827993	HRS	0		TSN 0				
	ENC	0		TSN 0	(30000) 29997 (M)		29835	
	ACCCYC	0	30000	TSN 0				
PROC. REF: GENERIC NO REF								
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR							Component ATA:72
PN:3073311-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:A004K21F	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 14997 (M)		14835	
	ACCCYC	0	15000	TSN 0				
PROC. REF: MM 72-30-01, MM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR							Component ATA:72
PN:3073311-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:A004HKCK	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 14997 (M)		14835	
	ACCCYC	0	15000	TSN 0				
PROC. REF: MM 72-30-01, MM 72-30-01								
723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR							Component ATA:72
PN:3073292-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:TXA1D7439	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 14997 (M)		14835	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REF								
723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR							Component ATA:72
PN:3073292-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:TXA1D7478	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 14997 (M)		14835	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REF								
723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3072981-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:A004H9XR	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3072981-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:A004H9XX	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3056210-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:EAAE000T297	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3056210-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:EAAE000T204	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:3075221-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:EDA1811P	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-30-02, MM 72-30-02								
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:3075221-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:EDA1810Y	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-30-02, MM 72-30-02								
723070	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY							Component ATA:72
PN:3079507-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HBA0444	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723070	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY							Component ATA:72
PN:3079617-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:A004HT0H	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723080	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY							Component ATA:72
PN:3076150-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:RWA76F364	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723080	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY							Component ATA:72
PN:3076150-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:RWA73F226	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723090	NO. 1 ENGINE - GAS GENERATOR DIFFUSER							Component ATA:72
PN:3073236-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:A004HK9L	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723090	NO. 2 ENGINE - GAS GENERATOR DIFFUSER							Component ATA:72
PN:3073236-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:A004HALC	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723095	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3052673-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:PKAAA828260	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723095	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3052673-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:PKAAA828255	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723110	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER							Component ATA:72
PN:3052668-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:AFD01E273	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723110	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER							Component ATA:72
PN:3052668-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:AFD01E040	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723120	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072571-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:MDA18005419	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723120	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072571-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:MDA18005424	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723130	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072572-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:MDA18004876	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723130	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072572-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:MDA18004873	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723140	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING							Component ATA:72
PN:3052737-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:LPA000025573	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723140	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING							Component ATA:72
PN:3052737-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:LPA000025245	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723150	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR							Component ATA:72
PN:3072574-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:EAAE000T061	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723150	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR							Component ATA:72
PN:3072574-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:EAAE000R440	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723160	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING							Component ATA:72
PN:3052670-02	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:FCN513245	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723160	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING							Component ATA:72
PN:3052670-02	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:FCN513246	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723170	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072280-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:PKAAA832148	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723170	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072280-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:PKAAA832141	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723180	NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:3052616-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:FCN511521	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723180	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:3052616-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:FCN511518	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053812-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:A004FX31	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053812-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:A004FX2Y	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053743-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:A004FWBR	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053743-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:A004FWBT	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724001	NO. 1 ENGINE - INNER COMBUSTION LINER							Component ATA:72
PN:3123695-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:A004HACE	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								
724001	NO. 2 ENGINE - INNER COMBUSTION LINER							Component ATA:72
PN:3123695-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:A004FTC9	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								
724002	NO. 1 ENGINE - OUTER COMBUSTION LINER							Component ATA:72
PN:3079976-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:A004H4BA	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								
724002	NO. 2 ENGINE - OUTER COMBUSTION LINER							Component ATA:72
PN:3079976-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:A004HH54	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								
724010	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY							Component ATA:72
PN:3075468-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:ACM222194680	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724010	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY							Component ATA:72
PN:3075468-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:ACM222194539	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK							Component ATA:72
PN:3053331-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:A004FMHX	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 9997 (M)		9835	
	ACCCYC	0	10000	TSN 0				
PROC. REF: MM 72-50-01, MM 72-50-01								
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK							Component ATA:72
PN:3053331-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:A004FOX0	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 9997 (M)		9835	
	ACCCYC	0	10000	TSN 0				
PROC. REF: MM 72-50-01, MM 72-50-01								
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3052661-01	MOS	31-Jul-19		TSN 0				LIFE LIMIT
SN:A004FFB7	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3052661-01	MOS	27-Jul-19		TSN 0				LIFE LIMIT
SN:A004F75N	HRS	0		TSN 0				
	ENC	0		TSN 0	(13500) 13497 (M)		13335	
	ACCCYC	0	13500	TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXA4998	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6533	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7488	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7496	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7498	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7507	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7555	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7556	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7564	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7617	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7628	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN1937	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7629	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7632	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7634	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7686	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7701	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7704	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7706	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7707	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7709	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN7712	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6469	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN8980	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN8983	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9001	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9005	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9010	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9030	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9032	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9092	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9094	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9101	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6479	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9103	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9156	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9161	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9170	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9177	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9180	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9184	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9243	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9246	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9253	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6485	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9310	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9312	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9313	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9317	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9321	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9322	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9331	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN9345	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP3801	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP3866	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6493	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP3920	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6499	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6507	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXN6516	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP3923	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP3926	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4060	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4082	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4152	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4155	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4875	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4878	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4883	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:HWXP4899	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0907	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0980	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0993	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0997	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0999	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1000	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1001	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1009	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1010	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1011	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1018	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0933	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1019	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1020	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1021	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1027	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1104	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1117	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1123	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1126	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1129	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1135	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0942	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR1139	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2663	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2664	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2667	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2672	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2689	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2862	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2872	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2875	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR2999	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0946	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3053	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3055	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3062	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3067	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3068	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3072	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3329	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3336	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3417	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3419	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0964	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3424	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3443	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3447	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3452	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3460	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3536	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3538	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3539	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3782	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3786	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0965	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3795	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0966	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0976	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR0979	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3799	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3810	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR3865	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR4440	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR4458	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR4462	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR4483	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR4674	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR4675	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:HWXR4705	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725015	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:3073355-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:EC01A006A510	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725015	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:3073355-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:FCN516616	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725020	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:3076552-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:RWA75F580	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-50-03								
725020	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:3076552-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:RWA75F480	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-50-03								
725025	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER							Component ATA:72
PN:3073353-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:MDA19008224	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725025	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER							Component ATA:72
PN:3073353-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:MDA19008222	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725030	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING							Component ATA:72
PN:3053163CL01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:PDAMXA5W01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725030	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING							Component ATA:72
PN:3053163CL01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:PDAMT3FN01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725035	NO. 1 ENGINE - TURBINE (CASTING) VANE RING							Component ATA:72
PN:3073821CL01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:PDAMTWNK01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725035	NO. 2 ENGINE - TURBINE (CASTING) VANE RING							Component ATA:72
PN:3073821CL01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:PDAMTDPM01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725040	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY							Component ATA:72
PN:3073262CL02	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:BHAMBLKK01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725040	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY							Component ATA:72
PN:3073262CL02	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:BHAMBTAN01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726010	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:3052549-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:FCN508555	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726010	NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:3052549-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:FCN514747	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726020	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:AEB0312184	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726020	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:AEB0312220	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726030	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:AEB0312194	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726030	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:AEB0312563	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726040	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:AEB0312195	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726040	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:AEB0312564	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726050	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:AEB0312197	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726050	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:AEB0312565	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726070	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY							Component ATA:72
PN:3078183-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:PKAAA812654	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726070	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY							Component ATA:72
PN:3078183-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:PKAAA812660	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726080	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT							Component ATA:72
PN:3072279-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:PKAAA826417	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726080	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT							Component ATA:72
PN:3072279-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:PKAAA826414	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726090	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING							Component ATA:72
PN:3072235-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:FAA1905514	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726090	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING							Component ATA:72
PN:3072235-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:FAA1905507	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726110	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:3052605-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:FAA1907794	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726110	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:3052605-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:FAA1907797	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726120	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING							Component ATA:72
PN:3052550-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:BB0305336	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726130	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072282-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:PKAAA826074	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726130	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072282-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:PKAAA826069	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727010	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3075013-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:KYAA025A839	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727010	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3075013-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:KYAA026A167	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727020	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3074835-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:KYAA026A197	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-70-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727020	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3074835-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:KYAA025A607	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-70-01								
ATA 73 - ENGINE FUEL AND CONTROL								
72-00-00-280-819 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								
PKG:1								
72-00-00-280-819 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 72-00-00								
PKG:1								
73-10-01-212-801	NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES							Service ATA:73
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
73-10-01-212-801	NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES							Service ATA:73
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES							Service ATA:73
	MOS	06-Dec-19						
	HRS	0						
	ENC	0	9900		(9900) 9897		9735	
PROC. REF: MM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES							Service ATA:73
	MOS	06-Dec-19						
	HRS	0						
	ENC	0	9900		(9900) 9897		9735	
PROC. REF: MM 73-10-04								
73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	19-Dec-23	12 (+30d)		19-Dec-24	18-Jan-25	177 d (+30)	
	HRS	301.8						
	ENC	162						
PROC. REF: MM 73-10-05								
73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	19-Dec-23	12 (+30d)		19-Dec-24	18-Jan-25	177 d (+30)	
	HRS	301.8						
	ENC	162						
PROC. REF: MM 73-10-05								
73-10-05-960-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	800 (+10%)		(800) 798.3	880	496.5 (+80)	
	ENC	0						
PROC. REF: MM 73-10-05, MM 73-10-05								
73-10-05-960-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	800 (+10%)		(800) 798.3	880	496.5 (+80)	
	ENC	0						
PROC. REF: MM 73-10-05, MM 73-10-05								
73-10-07-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 73-10-07								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-07-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 73-10-07								PKG:1
73-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT							Service ATA:73
PN:3071682-05	MOS	06-Dec-19						
SN:F85709	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 73-20-01								
73-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT							Service ATA:73
PN:3071682-05	MOS	06-Dec-19						
SN:F85679	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 73-20-01								
73-20-02-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 73-20-02								PKG:1
73-20-02-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 73-20-02								PKG:1
73-20-10-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS							Service ATA:73
PN:3073237-05	MOS	06-Dec-19						
SN:ADXBA001688	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-20-10-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS							Service ATA:73
PN:3073237-05	MOS	06-Dec-19						
SN:ADXBA001661	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
73-20-20-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES							Service ATA:73
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
73-20-20-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES							Service ATA:73
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
73-20-30-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:73
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
73-20-30-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:73
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
73-21-01	LEFT FADEC							Component ATA:73
PN:3073593-08	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2019061123	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-21-01, AMM 73-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-21-01	RIGHT FADEC							Component ATA:73
PN:3073593-08	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2019061812	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-21-01, AMM 73-21-01								
73-30-02-212-801 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 73-30-02								PKG:1
73-30-02-212-801 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR							Service ATA:73
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 73-30-02								PKG:1
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER							Component ATA:73
PN:8TJ300AAB2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:DT1198N	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01								
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER							Component ATA:73
PN:8TJ300AAB2	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:DT1196N	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01								
731005	NO. 1 ENGINE - FUEL FILTER							Component ATA:73
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-05								
731005	NO. 2 ENGINE - FUEL FILTER							Component ATA:73
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40617	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40627	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40628	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40618	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40619	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40620	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40622	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40623	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40624	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40625	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:DEAAB40626	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40567	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40595	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40597	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40569	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40570	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40579	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40580	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40582	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40585	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40590	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:DEAAB40591	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT							Component ATA:73
PN:3073593-08	MOS/MSC	01-Aug-19	O/C	TSN 0				
SN:2019061123	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-03, MM 73-20-03								
732001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT							Component ATA:73
PN:3073593-08	MOS/MSC	01-Aug-19	O/C	TSN 0				
SN:2019061812	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-03, MM 73-20-03								
732002	NO. 1 ENGINE - FUEL METERING UNIT (FMU)							Component ATA:73
PN:3071682-05	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:F85709	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-01, MM 73-20-01								
732002	NO. 2 ENGINE - FUEL METERING UNIT (FMU)							Component ATA:73
PN:3071682-05	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:F85679	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-01, MM 73-20-01								
732010	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:3073237-05	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:ADXBA001688	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02								
732010	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:3073237-05	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:ADXBA001661	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732030	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Component ATA:73
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732030	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Component ATA:73
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
733001	NO. 1 ENGINE - FUEL PRESSURE TRANSDUCER/SENSOR							Component ATA:73
PN:3073602-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:KLA01155	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-30-02, MM 73-30-02								
733001	NO. 2 ENGINE - FUEL PRESSURE TRANSDUCER/SENSOR							Component ATA:73
PN:3073602-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:KLA01173	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-30-02, MM 73-30-02								
ATA 74 - IGNITION								
74-00-01-750-801 ^S	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM							Service ATA:74
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-00-01								PKG:1
74-00-01-750-801 ^S	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM							Service ATA:74
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-00-01								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-10-01-212-801 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER						Service ATA:74
PN:31J2807-07	MOS	19-Dec-23	12 (+30d)					
SN:NNA19100123	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-10-01								PKG:1
74-10-01-212-801 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER						Service ATA:74
PN:31J2807-07	MOS	19-Dec-23	12 (+30d)					
SN:NNA19100127	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-10-01								PKG:1
74-20-01-212-801 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES						Service ATA:74
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-20-01								PKG:1
74-20-01-212-801 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES						Service ATA:74
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-20-01								PKG:1
74-20-02-210-801 ^S		NO. 1 ENGINE - VISUAL INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR						Service ATA:74
PN:PN	MOS	19-Dec-23	12 (+30d)					
SN:UNKNOWN	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-20-02								PKG:1
74-20-02-210-801 ^S		NO. 1 ENGINE - VISUAL INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR						Service ATA:74
PN:PN	MOS	19-Dec-23	12 (+30d)					
SN:UNKNOWN	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-20-02								PKG:1
74-20-02-210-801 ^S		NO. 2 ENGINE - VISUAL INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR						Service ATA:74
PN:PN	MOS	19-Dec-23	12 (+30d)					
SN:UNKNOWN	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-20-02								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-20-02-210-801 ^S NO. 2 ENGINE - VISUAL INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR								Service ATA:74
PN:PN	MOS	19-Dec-23	12 (+30d)					
SN:UNKNOWN	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 74-20-02								PKG:1
74-20-02-960-801 NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER								Service ATA:74
PN:PN	MOS/MSC	06-Dec-19	O/C					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: MM 74-20-02, MM 74-20-02								
74-20-02-960-801 NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER								Service ATA:74
PN:PN	MOS/MSC	06-Dec-19	O/C					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: MM 74-20-02, MM 74-20-02								
74-20-02-960-801 NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER								Service ATA:74
PN:PN	MOS/MSC	06-Dec-19	O/C					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: MM 74-20-02, MM 74-20-02								
74-20-02-960-801 NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER								Service ATA:74
PN:PN	MOS/MSC	06-Dec-19	O/C					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: MM 74-20-02, MM 74-20-02								
741001 NO. 1 ENGINE - EXCITER IGNITION								Component ATA:74
PN:31J2807-07	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:NNA19100123	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-10-01, MM 74-10-01								
741001 NO. 2 ENGINE - EXCITER IGNITION								Component ATA:74
PN:31J2807-07	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:NNA19100127	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-10-01, MM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742000	NO. 1 ENGINE - 5 O'CLOCK IGNITER							Component ATA:74
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-02, MM 74-20-02								
742000	NO. 2 ENGINE - 5 O'CLOCK IGNITER							Component ATA:74
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-02, MM 74-20-02								
742001	NO. 1 ENGINE - 7 O'CLOCK IGNITER							Component ATA:74
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-02, MM 74-20-02								
742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER							Component ATA:74
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-02, MM 74-20-02								
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD							Component ATA:74
PN:3127408-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:NNAS19030010	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD							Component ATA:74
PN:3127408-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:NNA17400049	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD							Component ATA:74
PN:3127408-02	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:NNA17400025	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD							Component ATA:74
PN:3127408-02	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:NNAS18360007	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								
ATA 75 - AIR								
75-30-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE							Service ATA:75
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 75-30-01								PKG:1
75-30-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE							Service ATA:75
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 75-30-01								PKG:1
75-30-01-212-802	NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR							Service ATA:75
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)	(5000) 4998.3	5100	4696.5 (+100)		
	ENC	0						
PROC. REF: MM 75-30-01								
75-30-01-212-802	NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR							Service ATA:75
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)	(5000) 4998.3	5100	4696.5 (+100)		
	ENC	0						
PROC. REF: MM 75-30-01								
75-30-01-212-803	NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE							Service ATA:75
PN:3053367-01	MOS	06-Dec-19						
SN:AHX0500983	HRS	0	5000 (+100)	(5000) 4998.3	5100	4696.5 (+100)		
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-01-212-803	NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE							Service ATA:75
PN:3053367-01	MOS	06-Dec-19						
SN:AHX0500984	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
75-30-01-900-802	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE							Component ATA:75
PN:3075987-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:TRAXY000141	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-900-802	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE							Component ATA:75
PN:3075987-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:TRAXY000142	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-900-803	NO. 1 ENGINE - LINEAR TRANSFORMER							Component ATA:75
PN:3071811-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:117032414	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-900-803	NO. 2 ENGINE - LINEAR TRANSFORMER							Component ATA:75
PN:3071811-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:117032408	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-801	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES							Service ATA:75
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-01-960-801	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES							Service ATA:75
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-802	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE							Service ATA:75
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-802	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE							Service ATA:75
	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-803	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
SN:117032414	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01								
75-30-01-960-803	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS/MSC	06-Dec-19	A/R					UNSCHEDULED MAINTENANCE CHECK
SN:117032408	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01								
75-30-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS	06-Dec-19						
SN:117032414	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS	06-Dec-19						
SN:117032408	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
75-30-20-212-801	NO. 1 ENGINE - REPLACED WITH NEW - THE BOV TORQUE MOTOR							Service ATA:75
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
75-30-20-212-801	NO. 2 ENGINE - REPLACED WITH NEW - THE BOV TORQUE MOTOR							Service ATA:75
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
750010	NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR							Component ATA:75
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-00-00								
750010	NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR							Component ATA:75
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-00-00								
753010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY							Component ATA:75
PN:3053367-01	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:AHX0500983	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753010	NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY							Component ATA:75
PN:3053367-01	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:AHX0500984	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01								
753020	NO. 1 ENGINE - BOV TORQUE MOTOR							Component ATA:75
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
753020	NO. 2 ENGINE - BOV TORQUE MOTOR							Component ATA:75
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 76 - ENGINE CONTROLS								
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY							Component ATA:76
PN:6990010-11	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:2012	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-11-01, AMM 76-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	12-Jan-23	36 (+30d)	Adj -37d	06-Dec-25	05-Jan-26	529 d (+30)	
	HRS	221	1600 (+100)		(1821) 1819.3	1921	1517.5 (+100)	
	ENC	108						
PROC. REF: MM 77-20-02								
77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	12-Jan-23	36 (+30d)	Adj -37d	06-Dec-25	05-Jan-26	529 d (+30)	
	HRS	221	1600 (+100)		(1821) 1819.3	1921	1517.5 (+100)	
	ENC	108						
PROC. REF: MM 77-20-02								
77-40-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT							Service ATA:77
PN:3075878-02	MOS	06-Dec-19						
SN:19068907	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
77-40-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT							Service ATA:77
PN:3075878-02	MOS	06-Dec-19						
SN:19069893	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
774001	NO. 1 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:3075878-02	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:19068907	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 77-40-01, MM 77-40-01								
774001	NO. 2 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:3075878-02	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:19069893	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 77-40-01, MM 77-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-10-02-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)							Service ATA:79
PN:3052640-04	MOS	06-Dec-19						
SN:0024349007	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
79-10-02-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)							Service ATA:79
PN:3052640-04	MOS	06-Dec-19						
SN:0024349008	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
79-20-00-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
79-20-00-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
79-20-01-210-801	NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER							Service ATA:79
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 79-20-01								
79-20-01-210-801	NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER							Service ATA:79
	MOS	06-Dec-19						
	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 79-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-20-01-960-801	NO. 1 ENGINE - DISCARD THE OIL FILTER							Service ATA:79
PN:PN	MOS	06-Dec-19						DISCARD
SN:UNKNOWN	HRS	0	800 (+10%)		(800) 798.3	880	496.5 (+80)	
	ENC	0						
PROC. REF: MM 79-20-01, MM 79-20-01								
79-20-01-960-801	NO. 2 ENGINE - DISCARD THE OIL FILTER							Service ATA:79
PN:PN	MOS	06-Dec-19						DISCARD
SN:UNKNOWN	HRS	0	800 (+10%)		(800) 798.3	880	496.5 (+80)	
	ENC	0						
PROC. REF: MM 79-20-01, MM 79-20-01								
79-30-01-210-801	NO. 1 ENGINE - EXAMINE - CHIP DETECTOR							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 79-30-01								
79-30-01-210-801	NO. 2 ENGINE - EXAMINE - CHIP DETECTOR							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: MM 79-30-01								
79-30-01-770-801 ^S	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 79-30-01								PKG:1
79-30-01-770-801 ^S	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 79-30-01								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-02-210-801 ^S	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH							Service ATA:79
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 79-30-02								PKG:1
79-30-02-210-801 ^S	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH							Service ATA:79
	MOS	19-Dec-23	12 (+30d)					
	HRS	301.8	800 (+10%)					
	ENC	162						
PROC. REF: MM 79-30-02								PKG:1
79-30-03-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - OIL TANK FILLER CAP							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
79-30-03-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - OIL TANK FILLER CAP							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
79-30-20-212-801	NO. 1 ENGINE - INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS)							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
79-30-20-212-801	NO. 2 ENGINE - INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS)							Service ATA:79
PN:PN	MOS	06-Dec-19						
SN:UNKNOWN	HRS	0	5000 (+100)		(5000) 4998.3	5100	4696.5 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR							Component ATA:79
PN:APTE-478A-1000-270D	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01120	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-05, AMM 79-31-05								
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR							Component ATA:79
PN:APTE-478A-1000-270D	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:01112	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-05, AMM 79-31-05								
790000	NO. 1 ENGINE - OIL FILTER							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-01, MM 79-20-01								
790000	NO. 2 ENGINE - OIL FILTER							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-01, MM 79-20-01								
790020	NO. 1 ENGINE - CHANGE OIL							Service ATA:79
	MOS/MSC	18-Nov-19	A/R					
	HRS	4.7						
	ENC	3						
PROC. REF: MM 72-00-00, MM 72-00-00								
790020	NO. 2 ENGINE - CHANGE OIL							Service ATA:79
	MOS/MSC	18-Nov-19	A/R					
	HRS	4.7						
	ENC	3						
PROC. REF: MM 72-00-00, MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792010	NO. 1 ENGINE - TEMPERATURE SENSOR							Component ATA:79
PN:ATS-9-800	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:111218-45	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
792010	NO. 2 ENGINE - TEMPERATURE SENSOR							Component ATA:79
PN:ATS-9-800	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:111218-30	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793001	NO. 1 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-30-01, MM 79-30-01								
793001	NO. 2 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-30-01, MM 79-30-01								
793003	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER							Component ATA:79
PN:3052640-04	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:0024349007	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-02, MM 73-10-02								
793003	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER							Component ATA:79
PN:3052640-04	MOS/MSC	27-Jul-19	O/C	TSN 0				
SN:0024349008	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-02, MM 73-10-02								
793004	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-30-02, MM 79-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500547 RegNo: N110AP HRS: 301.8 AFL: 162 As Of: 19-Dec-2023

25-Jun-2024 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793004	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-30-02, MM 79-30-02								
793020	NO. 1 ENGINE - OIL TANK FILLER CAP							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793020	NO. 2 ENGINE - OIL TANK FILLER CAP							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793025	NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS)							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793025	NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS)							Component ATA:79
PN:PN	MOS/MSC	31-Jul-19	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task