



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
053501	INSPECT/REPLACE PBE MASK INSPECTION			MTH HRS 6258 LDG 5068	04-Jun-2018		120		29-Feb-2028	30 m 28 d
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK			MTH HRS 7953.8 LDG 6462	21-Oct-2020		A/R			
055002	ACCOMPLISH OVERSPEED CHECK						A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK						A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK			MTH HRS 7153.6 LDG 5811	03-Sep-2019		A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK						A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK						A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK						A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK						A/R			
5-12-01 051201	INSPECTION DOCUMENT 01			MTH HRS 9759.7 LDG 7928	15-Sep-2023		450		10209.7	140.5
5-12-02 051202	INSPECTION DOCUMENT 02			MTH HRS 9759.7 LDG 7928	15-Sep-2023		900		10659.7	590.5
5-12-03 051203	INSPECTION DOCUMENT 03			MTH HRS 8886.1 LDG 7213	20-Jul-2022		1350		10236.1	166.9
5-12-04 051204	INSPECTION DOCUMENT 04			MTH HRS 8886.1 LDG 7213	20-Jul-2022		1800		10686.1	616.9
5-12-05 051205	INSPECTION DOCUMENT 05			MTH HRS 9297.1 LDG 7553	07-Feb-2023	23.1	3150		12470.2	2401
5-12-06 051206	INSPECTION DOCUMENT 06 KLGB			MTH HRS 10053 LDG 8150	01-Jul-2025		12		31-Jul-2026	11 m 30 d
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK) KLGB			C352TS G-97924755 MTH HRS 10053 LDG 8150	01-Jul-2025		12		31-Jul-2026	11 m 30 d
5-12-07 051207	INSPECTION DOCUMENT 07 KMYF			MTH HRS 10022.1 LDG 8122	18-Dec-2024		24		31-Dec-2026	16 m 30 d
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS 9367 LDG 7610	14-Mar-2023		60			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262004 051210 : FB	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)			9912048-6 81937B1	MTH 14-Mar-2023 HRS 9367 LDG 7610		60		31-Mar-2028	31 m 30 d
Hydro Check Date: 14-Mar-2023										
5-12-11 051211	INSPECTION DOCUMENT 11				MTH 22-Jul-2021 HRS 8196.2 LDG 6664		72		31-Jul-2027	23 m 30 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)			C352TS G-97924755	MTH 20-Jul-2023 HRS 9664.7 LDG 7853		72		31-Dec-2027	28 m 30 d
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 13-Dec-2019 HRS 7317.3 LDG 5955		144			
B262101 051212	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)			C352TS G-97924755	MTH 20-Jul-2023 HRS 9664.7 LDG 7853		144		31-Dec-2033	100 m 30 d
Hydro Check Date: 20-Dec-2021										
5-12-13 051213	INSPECTION DOCUMENT 13 KMYF				MTH 18-Dec-2024 HRS 10022.1 LDG 8122		12 450		31-Dec-2025 10472.1	4 m 30 d 402.9
5-12-14 051214	INSPECTION DOCUMENT 14 KMYF				MTH 18-Dec-2024 HRS 10022.1 LDG 8122		12 900		31-Dec-2025 10922.1	4 m 30 d 852.9
5-12-15 051215	INSPECTION DOCUMENT 15 KMYF				MTH 18-Dec-2024 HRS 10022.1 LDG 8122		24 1350		31-Dec-2026 11372.1	16 m 30 d 1302.9
5-12-16 051216	INSPECTION DOCUMENT 16				MTH 30-Dec-2022 HRS 9241.9 LDG 7504		36 1350		31-Dec-2025 10591.9	4 m 30 d 522.7
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK			29-10-00-720 HM50C-3 019B	MTH 30-Dec-2022 HRS 9241.9 LDG 7504		36 1350		31-Dec-2025 10591.9	4 m 30 d 522.7
5-12-17 051217	INSPECTION DOCUMENT 17 KLGB				MTH 01-Jul-2025 HRS 10053 LDG 8150		36 1800		31-Jul-2028 11853	35 m 30 d 1783.8
5-12-18 051218	INSPECTION DOCUMENT 18 KMYF				MTH 18-Dec-2024 HRS 10022.1 LDG 8122		36 2250		31-Dec-2027 12272.1	28 m 30 d 2202.9
5-12-20 051220	INSPECTION DOCUMENT 20				MTH 20-Dec-2023 HRS 9922.9 LDG 8061		48 2700		31-Dec-2027 12622.9	28 m 30 d 2553.7
5-12-21 051221	INSPECTION DOCUMENT 21 KMYF				MTH 18-Dec-2024 HRS 10022.1 LDG 8122		12		31-Dec-2025	4 m 30 d
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 20-Dec-2023 HRS 9922.9 LDG 8061		24			
B341001 AIRSPEED 051222 : A/S	CALIBRATION TEST INDICATOR 14 CFR PART 91.411			261440-1143 288581A	MTH 20-Dec-2023 HRS 9922.9 LDG 8061		24		31-Dec-2025	4 m 30 d
Calibration Date: 20-Dec-2023										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001 NO. 1 051222 : ADC	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	011-01110-00 43800525	MTH 20-Dec-2023 HRS 9922.9 LDG 8061		24		31-Dec-2025	4 m 30 d
Calibration Date: 20-Dec-2023								
B341001 NO. 2 051222 : ADC#2	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	011-01110-00 43800502	MTH 20-Dec-2023 HRS 9922.9 LDG 8061		24		31-Dec-2025	4 m 30 d
Calibration Date: 20-Dec-2023								
B341001 STANDBY 051222 : STDBY	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411	162350-1161 178837C	MTH 20-Dec-2023		24		31-Dec-2025	4 m 30 d
Calibration Date: 20-Dec-2023								
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)		MTH 20-Dec-2023 HRS 9922.9 LDG 8061		24		31-Dec-2025	4 m 30 d
B345000 LEFT 051222 : XPDR1	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	011-0079-21 84805801	MTH 20-Dec-2023		24		31-Dec-2025	4 m 30 d
Calibration Date: 20-Dec-2023								
B345000 RIGHT 051222 : XPDR2	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	011-00779-21 84805725	MTH 20-Dec-2023		24		31-Dec-2025	4 m 30 d
Calibration Date: 20-Dec-2023								
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	3-1640 0443	MTH		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)	3-1642 0194	MTH		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	3-1640 0346	MTH		A/R			
5-12-30 051230	INSPECTION DOCUMENT 30		MTH 04-Oct-2021 HRS 8438.6 LDG 6850		48 1800		31-Oct-2025 10238.6	2 m 30 d 169.4
5-12-31 051231	INSPECTION DOCUMENT 31		MTH 15-Sep-2023 HRS 9759.7 LDG 7928		450		10209.7	140.5
5-12-32 051232	INSPECTION DOCUMENT 32		MTH 20-Jul-2022 HRS 8886.1 LDG 7213		72 1800		31-Jul-2028 9013	35 m 30 d 853
5-12-35	INSPECTION DOCUMENT 35 KLGB		MTH 01-Jul-2025 HRS 10053 LDG 8150		6		31-Jan-2026	5 m 30 d
5-12-37	INSPECTION DOCUMENT 37		MTH 25-Sep-2019 HRS 7170 LDG 5819		7200		14370	4300.8
5-12-38	INSPECTION DOCUMENT 38 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) KLGB		MTH 01-Jul-2025 HRS 10053 LDG 8150		3			
B243000 051224B	CONCORDE (RG-390E) LEAD-ACID BATTERY FUNCTIONALCHECK (CAPACITY CHECK) KLGB	RG-390E/30 41299237	MTH 01-Jul-2025 HRS 10053 LDG 8150		3		31-Oct-2025	2 m 30 d
5-12-MA 0512MA	INSPECTION DOCUMENT MA		MTH 15-Sep-2023 HRS 9759.7 LDG 7928		500		10259.7	190.5

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-MB <i>0512MB</i>	INSPECTION DOCUMENT MB	MTH HRS LDG	15-Sep-2023 9759.7 7928		950		10709.7	640.5
5-12-MC <i>0512MC</i>	INSPECTION DOCUMENT MC	MTH HRS LDG	14-Mar-2023 9367 7610		4000		13367	3297.8
5-12-MD <i>0512MD</i>	INSPECTION DOCUMENT MD KMYF	MTH HRS LDG	18-Dec-2024 10022.1 8122		12		31-Dec-2025	4 m 30 d
5-12-ME <i>0512ME</i>	INSPECTION DOCUMENT ME	MTH HRS LDG	14-Mar-2023 9367 7610		36 1400		31-Mar-2026 10767	7 m 30 d 697.8
5-12-MF <i>0512MF</i>	INSPECTION DOCUMENT MF *CF	MTH HRS	21-Nov-2007 0		12000		12000	1930.8
5-12-MG <i>0512MG</i>	INSPECTION DOCUMENT MG	MTH HRS LDG	15-Sep-2023 9759.7 7928		2500		12259.7	2190.5
5-12-MH <i>0512MH</i>	INSPECTION DOCUMENT MH	MTH HRS LDG	22-Jul-2021 8196.2 6664		3400		11596.2	1527
5-12-MI <i>0512MI</i>	INSPECTION DOCUMENT MI *CF	MTH HRS	21-Nov-2007 0		12000		12000	1930.8
5-12-MJ <i>0512MJ</i>	INSPECTION DOCUMENT MJ UNK	MTH HRS LDG	08-Jan-2025 10028.2 8129		-			
5-12-MK <i>0512MK</i>	INSPECTION DOCUMENT MK UNK	MTH HRS LDG	17-Jun-2024 9994.2 8109		2500		12494.2	2425
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE	MTH HRS LDG	16-Feb-2024 9975.3 8101		A/R			
10-10-10-03	STORAGE - ZERO TO SEVEN DAYS	MTH	21-Nov-2007		A/R			
10-10-10-04	STORAGE - EIGHT TO THIRTY DAYS	MTH	21-Nov-2007		A/R			
10-10-10-05	STORAGE - THIRTY-ONE TO NINETY DAYS	MTH	21-Nov-2007		A/R			
10-10-10-06	STORAGE - NINETY-ONE DAYS AND OVER STORAGE	MTH	21-Nov-2007		A/R			
10-10-10-07	STORAGE - CABIN UPHOLSTERY AND CARPET STORAGE FOR HIGH HUMIDITY AREAS	MTH	21-Nov-2007		A/R			
10-20-00-03	MOORING	MTH	21-Nov-2007		A/R			
10-30-00-03	RESTORING - ZERO TO TWENTY-EIGHT DAYS	MTH	21-Nov-2007		A/R			
10-30-00-04	RESTORING - TWENTY-NINE DAYS TO NINETY DAYS	MTH	21-Nov-2007		A/R			
10-30-00-05	RESTORING - NINETY-ONE DAYS AND OVER	MTH	21-Nov-2007		A/R			
10-30-00-06	RESTORING - COLD SOAKED AIRPLANE RETURN TO SERVICE	MTH	21-Nov-2007		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH				DAYS 21-Nov-2007		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH				DAYS 21-Nov-2007		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH				DAYS 21-Nov-2007		A/R			
262003A LEFT 262003 : L	REPLACE FIRE EXT CARTRIDGE			AE13083-5 1032	MTH 16-Feb-2024 HRS 9975.3 LDG 8101		120	54	31-Aug-2029	48 m 30 d
262003A RIGHT 262003 : R	REPLACE FIRE EXT CARTRIDGE			AE13083-5 1016	MTH 16-Feb-2024 HRS 9975.3 LDG 8101		120	54	31-Aug-2029	48 m 30 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH 21-Nov-2007		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH 21-Nov-2007		A/R			
32-30-40-960 051208 : LG	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)			40005369-2 9529	MTH 12-Apr-2024 HRS 9975.3 LDG 8101		36		31-Jan-2027	17 m 30 d
Hydro Check Date: 30-Jan-2024										
32-40-00-960 051208 : EB	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)			40005399-1 11775	MTH 12-Apr-2024 HRS 9975.3 LDG 8101		36		31-Jan-2027	17 m 30 d
Hydro Check Date: 04-Jan-2024										
35-00-00-960 051210 : OXY	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST			4441073-040 450909601	MTH 23-Dec-2021 HRS 8552.6 LDG 6952		60		31-Oct-2026	14 m 30 d
Hydro Check Date: 21-Oct-2021										
71-00-10-2.4	BUILD UP ENGINE				MTH 21-Nov-2007		A/R			
71-00-10-2.5	CHANGE ENGINE CONFIGURATION FROM ONE SIDE TO THE OTHER				MTH 21-Nov-2007		A/R			
71-00-10-2.6	TEAR DOWN ENGINE				MTH 21-Nov-2007		A/R			
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION KMYF				MTH 18-Dec-2024 HRS 10026.1 LDG 8122		12 450		31-Dec-2025 (8222.1)10476.1	4 m 30 d 406.9
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION KMYF				MTH 18-Dec-2024 HRS 10026.4 LDG 8122		12 450		31-Dec-2025 (8272.4)10476.4	4 m 30 d 407.2
71-00-00-760-812 E1	CHECK NO.4 ENGINE CALIBRATION				MTH 08-Apr-2008 HRS 2254 LDG 1636		A/R			
71-00-00-760-812 E2	CHECK NO.4 ENGINE CALIBRATION				MTH 08-Apr-2008 HRS 2204 LDG 1584		A/R			
71-00-00-760-813 E1	CHECK NO.5 POWER ASSURANCE TEST				MTH 16-Feb-2024 HRS 9979.3 LDG 8102		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
71-00-00-760-813 E2	CHECK NO.5 POWER ASSURANCE TEST			MTH HRS LDG	16-Feb-2024 9979.6 5564		A/R			
710010 E1	COMPRESSOR DESALINATION WASH			MTH HRS LDG	16-Feb-2024 9979.3 8102		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
710010 E2	COMPRESSOR DESALINATION WASH			MTH HRS LDG	16-Feb-2024 9979.6 8102		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
710020 E1	COMPRESSOR PERFORMANCE RECOVERY WASH			MTH HRS LDG	16-Feb-2024 9979.3 8102		A/R			
710020 E2	COMPRESSOR PERFORMANCE RECOVERY WASH			MTH HRS LDG	16-Feb-2024 9979.6 8102		A/R			
72-00-00-290-804 E1	BORESCOPE INSPECTION			MTH HRS LDG	12-Mar-2024 9975.3 8101		A/R			
72-00-00-290-804 E2	BORESCOPE INSPECTION			MTH HRS LDG	12-Mar-2024 9975.3 8101		A/R			
72-00-00-290-805 E1	BORESCOPE INSPECTION FAN EXIT VANES			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-805 E2	BORESCOPE INSPECTION FAN EXIT VANES			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-290-806 E2	BORESCOPE INSPECTION HP COMPRESOR ROTOR			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-290-807 E1	BORESCOPE INSPECTION HP COMPRESSOR IMPELLER			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-807 E2	BORESCOPE INSPECTION HP COMPRESSOR IMPELLER			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-290-808 E1	BORESCOPE INSPECTION FUEL NOZZLES			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-808 E2	BORESCOPE INSPECTION FUEL NOZZLES			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-290-809 E1	BORESCOPE INSPECTION COMBUSTION CHAMBER LINER			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-809 E2	BORESCOPE INSPECTION COMBUSTION CHAMBER LINER			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-290-810 E1	BORESCOPE INSPECTION HP TURBINE VANE RING			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-810 E2	BORESCOPE INSPECTION HP TURBINE VANE RING			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-290-811 E1	BORESCOPE INSPECTION HP TURBINE BLADES			MTH HRS LDG	27-Oct-2023 9886.9 8030		300		(7932.9)10186.9	117.7
72-00-00-290-811 E2	BORESCOPE INSPECTION HP TURBINE BLADES			MTH HRS LDG	27-Oct-2023 9887.2 8030		300		(7983.2)10187.2	118
72-00-00-290-812 E1	BORESCOPE INSPECTION HP TURBINE SHROUD SEGMENTS			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-812 E2	BORESCOPE INSPECTION HP TURBINE SHROUD SEGMENTS			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-290-813 E1	BORESCOPE INSPECTION LP TURBINE BLADE			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-813 E2	BORESCOPE INSPECTION LP TURBINE BLADE			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-290-814 E1	BORESCOPE INSPECTION LP TURBINE VANE RING			MTH HRS LDG	15-Oct-2018 7033.92 5741		A/R			
72-00-00-290-814 E2	BORESCOPE INSPECTION LP TURBINE VANE RING			MTH HRS LDG	15-Oct-2018 7040.22 5741		A/R			
72-00-00-620-801- 01 E1	ENGINE PRESERVATION - 0 TO 7 DAYS			MTH	08-Apr-2008		-			
72-00-00-620-801- 01 E2	ENGINE PRESERVATION - 0 TO 7 DAYS			MTH	08-Apr-2008		-			
72-00-00-620-801- 02 E1	ENGINE PRESERVATION - 8 TO 28 DAYS			MTH	08-Apr-2008		-			
72-00-00-620-801- 02 E2	ENGINE PRESERVATION - 8 TO 28 DAYS			MTH	08-Apr-2008		-			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-620-801-03 E1	ENGINE PRESERVATION - 29 TO 90 DAYS				MTH 08-Apr-2008		-			
72-00-00-620-801-03 E2	ENGINE PRESERVATION - 29 TO 90 DAYS				MTH 08-Apr-2008		-			
72-00-00-620-801-04 E1	ENGINE PRESERVATION - 90 DAYS AND OVER				MTH 08-Apr-2008		-			
72-00-00-620-801-04 E2	ENGINE PRESERVATION - 90 DAYS AND OVER				MTH 08-Apr-2008		-			
72-00-00-620-804-01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-804-01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-804-02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 08-Apr-2008		A/R			
72-00-00-620-804-02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 08-Apr-2008		A/R			
72-00-00-620-804-03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 08-Apr-2008		A/R			
72-00-00-620-804-03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 08-Apr-2008		A/R			
72-00-00-620-805-01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-805-01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-805-02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-805-02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-806-01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-806-01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS				MTH 08-Apr-2008		A/R			
72-00-00-620-806-02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER				MTH 08-Apr-2008		A/R			
72-00-00-620-806-02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER				MTH 08-Apr-2008		A/R			
72-00-00-630-801 E1	ENGINE DEPRESERVATION PROCEDURE				MTH 08-Apr-2008		N/A			
72-00-00-630-801 E2	ENGINE DEPRESERVATION PROCEDURE				MTH 08-Apr-2008		N/A			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-630-804-01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH 08-Apr-2008		A/R			
72-00-00-630-804-01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH 08-Apr-2008		A/R			
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH 08-Apr-2008		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH 08-Apr-2008		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH 08-Apr-2008		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH 08-Apr-2008		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY			MTH 08-Apr-2008		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY			MTH 08-Apr-2008		A/R			
720000 E1	PERFORM ENGINE OVERHAUL UNK			MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
720000 E2	PERFORM ENGINE OVERHAUL UNK			MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION			MTH 23-Dec-2021 HRS 8200.2 LDG 6665		1750		(8127.9)10381.9	312.7
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION			MTH 23-Dec-2021 HRS 8200.5 LDG 6665		1750		(8183.6)10387.6	318.4
720003 E1	INSPECT LOW UTILIZATION ENGINE			MTH 11-Apr-2016 HRS 5993.1 LDG 4847		144		30-Apr-2028	32 m 29 d
720003 E2	INSPECT LOW UTILIZATION ENGINE			MTH 14-Apr-2016 HRS 5999.6 LDG 4847		144		30-Apr-2028	32 m 29 d
720020 E1	MONITORING OIL CONSUMPTION TREND			MTH 10-May-2012 HRS 3982.7		A/R			
720020 E2	MONITORING OIL CONSUMPTION TREND			MTH 08-Apr-2008		A/R			
721030 E1	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS		1750		(8127.9)10381.9	312.7
721030 E2	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS		1750		(8183.6)10387.6	318.4
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER			MTH 23-Dec-2021 HRS 8200.2 LDG 6665		1750		(8127.9)10381.9	312.7



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER				MTH 23-Dec-2021 HRS 8200.5 LDG 6665		1750		(8183.6)10387.6	318.4
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT KMYF				MTH 18-Dec-2024 HRS 10026.1 LDG 8122		12 900		31-Dec-2025 (8672.1)10926.1	4 m 30 d 856.9
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT KMYF				MTH 18-Dec-2024 HRS 10026.4 LDG 8122		12 900		31-Dec-2025 (8722.4)10926.4	4 m 30 d 857.2
731055 E1	REPLACE FUEL MANIFOLD			35C6160-01 DEAAAA66021	MTH 23-Dec-2021 HRS 8200.2 LDG 6665		1750		(8127.9)10381.9	312.7
731055 E2	REPLACE FUEL MANIFOLD			35C6160-01 DEAAAA66714	MTH 23-Dec-2021 HRS 8200.5 LDG 6665		1750		(8183.6)10387.6	318.4
732003 E1	ENGINE ELECTRONIC CONTROL (EEC) - TEST / VISUAL INSPECT PN SN-UNKNOWN				MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
732003 E2	ENGINE ELECTRONIC CONTROL (EEC) - TEST / VISUAL INSPECT 35C4035-03 06-131				MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
732105 E1	OVERHAUL FUEL METERING UNIT (F.M.U.) 8062-1109 15423402				MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
732105 E2	OVERHAUL FUEL METERING UNIT (F.M.U.) 8062-1109 15450007				MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH 35C5593-01 WDA135591				MTH 23-Dec-2021 HRS 8200.2 LDG 6665		1750		(8127.9)10381.9	312.7
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH 35C5593-01 WDA138181				MTH 23-Dec-2021 HRS 8200.5 LDG 6665		1750		(8183.6)10387.6	318.4
733030 E1	FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION 35C5593-01 WDA135591				MTH 23-Dec-2021 HRS 8200.2 LDG 6665		3500		(9446.2)11700.2	1631
733030 E2	FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION 35C5593-01 WDA138181				MTH 23-Dec-2021 HRS 8200.5 LDG 6665		3500		(9496.5)11700.5	1631.3
74-20-01-210-801 E1 LEFT	VISUAL INSPECTION LEFT IGNITER CABLE 35C0844-01 NSN				MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
74-20-01-210-801 E1 RIGHT	VISUAL INSPECTION RIGHT IGNITER CABLE 35C0799-01 NSN				MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
74-20-01-210-801 E2 LEFT	VISUAL INSPECTION LEFT IGNITER CABLE 35C0844-01 NSN				MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
74-20-01-210-801 E2 RIGHT	VISUAL INSPECTION RIGHT IGNITER CABLE 35C0799-01 NSN				MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
74-20-01-720-801 E1 LEFT	FUNTIONAL TEST LEFT IGNITER CABLE 35C0844-01 NSN				MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
74-20-01-720-801 E1 RIGHT	FUNTIONAL TEST RIGHT IGNITER CABLE			35C0799-01 NSN	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
74-20-01-720-801 E2 LEFT	FUNTIONAL TEST LEFT IGNITER CABLE			35C0844-01 NSN	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
74-20-01-720-801 E2 RIGHT	FUNTIONAL TEST RIGHT IGNITER CABLE			35C0799-01 NSN	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
74-20-02-220-801 E1 INBOARD	INSPECT INBOARD SPARK IGNITER			35C2353-02 WDA143866	MTH 15-Sep-2023 HRS 9882.1		3500		(11128.1)13382.1	3312.9
74-20-02-220-801 E1 OUTBOARD	INSPECT OUTBOARD SPARK IGNITER			35C2353-02 WDA144252	MTH 15-Sep-2023 HRS 9882.1		3500		(11128.1)13382.1	3312.9
74-20-02-220-801 E2 INBOARD	INSPECT INBOARD SPARK IGNITER			35C2353-02 WDA140962	MTH 23-Dec-2021 HRS 8200.5 LDG 6665		3500		(9496.5)11700.5	1631.3
74-20-02-220-801 E2 OUTBOARD	INSPECT OUTBOARD SPARK IGNITER			35C2353-02 WDA139267	MTH 15-Sep-2023 HRS 9764		3500		(11060)13264	3194.8
741011 E1	IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION			8408-6009 15389698	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
741011 E2	IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION			8408-6009 15372897	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
751010 E1	OVERHAUL BLEED VALVE ACTUATOR			8100-0015 15478273	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
751010 E2	OVERHAUL BLEED VALVE ACTUATOR			8100-0028 16104123	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
76-10-00-5.7	CUTOFF SWITCH RIGGING LEFT AND RIGHT				MTH 21-Nov-2007		A/R			
77-20-02-210-801 E1	VISUAL INSPECTION OF THE T6 THERMOCOUPLE WIRING HARNESS			35C0374-01 WDAAA000505	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
77-20-02-210-801 E2	VISUAL INSPECTION OF THE T6 THERMOCOUPLE WIRING HARNESS			35C0374-01 WDAAA000734	MTH 14-Apr-2016 HRS 5995.3 LDG 4846		3500		(8183.6)10383.3	314.1
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			35C0374-01 WDAAA000505	MTH 23-Dec-2021 HRS 8200.2 LDG 6665		1750		(8127.9)10381.9	312.7
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			35C0374-01 WDAAA000734	MTH 23-Dec-2021 HRS 8196.2 LDG 6664		1750		(8183.6)10383.3	314.1
79-30-02-720-801 E1	FUNCTIONAL TEST OIL FILTER IMPENDING BYPASS INDICATOR			35C4333-01 WDA00732	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
79-30-02-720-801 E2	FUNCTIONAL TEST OIL FILTER IMPENDING BYPASS INDICATOR			35C4333-01 WDA00942	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
790015 E1	REPLACE OIL FILTER ELEMENT				MTH 16-Feb-2024 HRS 9979.3 LDG 8102	-36	900		(8589.3)10843.3	774.1

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
790015 E2	REPLACE OIL FILTER ELEMENT				MTH 16-Feb-2024 HRS 9979.6 LDG 8102	-86.3	900		(8589.3)10793.3	724.1
791005 E1	OVERHAUL FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			10940J WA29209	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
791005 E2	OVERHAUL FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			10940J WA31112	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
792040 E1	OVERHAUL AIR COOLED OIL COOLER			35C2495-05 WA52744	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		3500		(8127.9)10381.9	312.7
792040 E2	OVERHAUL AIR COOLED OIL COOLER			35C2495-05 WA52735	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		3500		(8183.6)10387.6	318.4
794020 E1	REPLACE NO. 4 BEARING FRONT CARBON SEAL				MTH 23-Dec-2021 HRS 8200.2 LDG 6665		1750		(8127.9)10381.9	312.7
794020 E2	REPLACE NO. 4 BEARING FRONT CARBON SEAL				MTH 23-Dec-2021 HRS 8200.5 LDG 6665		1750		(8183.6)10387.6	318.4



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY. *CF			0113-12 1241	MTH 21-Nov-2007		O/C			
213001	KAPS II CONTROLLER			9912661-12 05024	MTH 04-Oct-2021 HRS 8438.6 LDG 6850		O/C			
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 856	MTH 21-Nov-2007		O/C			
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 857	MTH 21-Nov-2007		O/C			
215001	AIR CONDITIONING COMPRESSOR MODULE KMYF			1134146-6 1917A	MTH 13-Mar-2025 HRS 10040 LDG 8136		O/C	0 0 0		
215002	CONDENSOR ASSEMBLY 9912583-7 *CF			1134620-3 3399	MTH 21-Nov-2007		O/C			
215003	RECEIVER DRYER ASSY 9912583-3 *CF			1134275-1 1516	MTH 21-Nov-2007		O/C			
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 226	MTH 21-Nov-2007		O/C	0		
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 228	MTH 21-Nov-2007		O/C			
215005	VANE AXIAL BLOWER ASSY.			1250435-10 457	MTH 04-Jun-2018 HRS 6258 LDG 5068		O/C	4 0 0	11258	1188.8
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD KMYF			PN SN-UNKNOWN	MTH 13-Mar-2025 HRS 10040 LDG 8136 ACH 2314.5			0 0 0 0	3114.5	800
216000 LH	THERMAL ACTUATOR			PN-UNKNOWN SN-UNKNOWN	MTH 21-Oct-2020 HRS 7953.8 LDG 6462		O/C			
216000 RH	THERMAL ACTUATOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
221001 AILERON	GSA 80 TORQUE SERVO *CF			011-00877-00 66305042	MTH 21-Nov-2007		O/C			
221001 RUDDER	GSA 80 TORQUE SERVO			011-00877-00 66307565	MTH 09-Nov-2023 HRS 9892.3 LDG 8038		O/C	0 0 0		
221002 ELEVATOR	GSA 81 TORQUE SERVO			PN NOT INSTALLED	MTH 23-Jun-2019		O/C			
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO			011-00878-10 71309087	MTH 11-Jun-2022 HRS 8852.4 LDG 7190		O/C	0 0 0		
221003 AILERON	GSM 85A SERVO MOUNT LOWL			011-01904-00 1095091	MTH 12-Oct-2015 HRS 4548.6 LDG 3676 ACH 36		O/C	1479		
221003 ELEVATOR	GSM 85A SERVO MOUNT			011-02490-03 1GK025015	MTH 13-Feb-2020 HRS 7460.6 LDG 6065		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT			011-01436-A1 11305010	MTH 11-Jun-2022 HRS 8852.4 LDG 7190		O/C	0 0 0		
221003 RUDDER	GSM 85 SERVO MOUNT			011-02490-03 1GK025015	MTH 13-Feb-2020 HRS 7460.6 LDG 6065		O/C	0 0 0		
221004	GMC 710 AFCS CONTROLLER			011-01020-10 22009152	MTH 05-May-2023 HRS 9480.7 LDG 7705		O/C	0 0 0		
231002 NO. 1	GMA 1347D AUDIO PANEL OWL			011-01257-00 48401336	MTH 08-Jul-2009 HRS 520		O/C	0		
231002 NO. 2	GMA 1347D AUDIO PANEL *CF			011-01257-00 48401250	MTH 21-Nov-2007		O/C			
231003 NO. 1	VHF COMM ANTENNA			VHF10-829 755	MTH 22-Jun-2017 HRS 5675 LDG 4541		O/C	337.8 288		
231003 NO. 2	VHF COMM ANTENNA			VHF10-829 3228	MTH 06-Sep-2019 HRS 7153.6 LDG 5811		O/C			
231011	SAT PHONE ANTENNA			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
231101	HIGH FREQUENCY CONTROLLER			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
231102	HIGH FREQUENCY RECEIVER/ EXCITER			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
231103	HIGH FREQUENCY ANTENNA			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
231104	HIGH FREQUENCY POWER AMPLIFIER			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
243001 LEFT	DIGITAL GCU 9912682-1 OR 9912682-3	LOWL		51525-001F P2065	MTH 22-Dec-2015 HRS 4650.8 LDG 3752 ACH 36		O/C	0 0 0		
243001 RIGHT	DIGITAL GCU 9912682-3 OR 9912682-3	LOWL		51525-001F P3302	MTH 18-Jun-2010 HRS 1277 LDG 1029		O/C	0 0		
243002	EMER INST BATTERY KMYF			CBS24 01145	MTH 18-Dec-2024 HRS 10022.1 LDG 8122		O/C	0 0 0		
243007	MAIN SHIP BATTERY CONCORDE (LEAD ACID)			RG-390E/30 41299237	MTH 10-Nov-2023 HRS 9893.5 LDG 8039		O/C	0 0 0		
243015	RELAY DISCONNECT BATTERY S3155-1	*CF		A-931F CP-57140	MTH 21-Nov-2007		O/C			
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF			7018920-5 0204	MTH 21-Nov-2007		O/C			
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF			7018920-5 0206	MTH 21-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245003	FLAP CONTROL MODULE *CF			7018916-9 0181	MTH 21-Nov-2007		O/C			
245005 LEFT	ICE PROTECTION CONTROL *CF			7018917-9 0151	MTH 21-Nov-2007		O/C			
245005 RIGHT	ICE PROTECTION CONTROL			7018918-15 0109	MTH 09-Jun-2020 HRS 7586 LDG 6167		O/C	0 0 0		
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL *CF			7018919-9 0196	MTH 21-Nov-2007		O/C			
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL *CF			7018919-9 0199	MTH 21-Nov-2007		O/C			
245008	DOOR MONITOR- *CF			7018921-5 0160	MTH 21-Nov-2007		O/C			
245009	LANDING GEAR MONITOR- *CF			7018923-12 0101	MTH 21-Nov-2007		O/C			
245010 LEFT	START CONTROL LOWL			7018924-12 0138	MTH 18-Jun-2010 HRS 1277 LDG 1029		O/C	0 0		
245010 RIGHT	START CONTROL LOWL			7018924-12 131	MTH 18-Jun-2010 HRS 1277 LDG 1029		O/C	0 0		
245011	FLAP MONITOR- *CF			PN NOT INSTALLED	MTH 09-Aug-2013 HRS 3465.9 LDG 2749		O/C			
245012 LEFT	SPEEDBRAKE ASSY *CF			7018926-1 0238	MTH 21-Nov-2007		O/C			
245012 RIGHT	SPEEDBRAKE ASSY *CF			7018926-1 0237	MTH 21-Nov-2007		O/C			
245013	DIAGNOSTIC UNIT *CF			7018927-7 0171	MTH 21-Nov-2007		O/C			
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3 *CF			85-230-2 0638-446M2	MTH 21-Nov-2007		O/C			
245015	MASTER INTERIOR SSR UNIT			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245016 RIGHT	AVN BUS #1 SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245017 LEFT	AVN SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245018 RIGHT	AVN BUS #2 SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245019 LEFT	IGN #1 SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245019 RIGHT	IGN #1 SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245020 LEFT	IGN #2 SENSOR UZ107			10747P03E10 16129037	MTH 03-Jul-2020 HRS 7614.5 LDG 6192		O/C	0 0 0		
245020 RIGHT	IGN #2 SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245021	COCKPIT FAN SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245022	CABIN FAN SENSOR			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245023 LEFT	LH BOOST PUMP SENSOR	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245023 RIGHT	RH BOOST PUMP SENSOR	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245024	CONDENSER FAN SENSOR	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245025	DC-DC CONVERTER	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245026	AVN EMERG SENSOR	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245201 LEFT	CABIN ALTITUDE MODULE	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
245201 RIGHT	CABIN ALTITUDE MODULE	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
246030 LEFT	MULTI FUNCTION DISPLAY	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
246030 RIGHT	MULTI FUNCTION DISPLAY	PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
251001	GLARESHIELD ASSEMBLY *CF	4319027-9 98142-1	MTH 21-Nov-2007		O/C			
256001 CO-PILOT	LIFE VEST	P01074-207 18103000066	MTH 13-Dec-2019 HRS 7314.4 LDG 5953		120	11 0 0	31-Jan-2029	41 m 30 d
256001 NO. 1	LIFE VEST	P01074-207 18081770206	MTH 21-Jan-2021 HRS 8079.7 LDG 6566		120	0 0 0	01-Sep-2028	37 m 0 d
256001 NO. 2	LIFE VEST	P01074-207 18103000065	MTH 21-Jan-2021 HRS 8079.7 LDG 6566		120	24 0 0	31-Jan-2029	41 m 30 d
256001 NO. 3	LIFE VEST	P01074-207 19031750348	MTH 21-Jan-2021 HRS 8079.7 LDG 6566		120	21 0 0	30-Apr-2029	44 m 29 d
256001 NO. 4	LIFE VEST	P01074-207 19031750349	MTH 21-Jan-2021 HRS 8079.7 LDG 6566		120	21 0 0	30-Apr-2029	44 m 29 d
256001 NO. 5	LIFE VEST	A316101A001810 32921-232	MTH 20-Aug-2017 HRS 5870.7 LDG 4741		O/C	0 0 0		
256001 NO. 6	LIFE VEST	A316101A001810 32921-228	MTH 26-Aug-2018 HRS 6501.9 LDG 5252		O/C	0 0 0		
256001 PILOT	LIFE VEST	P01074-207 19031750352	MTH 21-Jan-2021 HRS 8079.7 LDG 6566		120	21 0 0	30-Apr-2029	44 m 29 d
256002	ELT BATTERY	452-0133 394372-011	MTH 16-Sep-2022 HRS 9039.3 LDG 7339		60	7 0 0	21-Feb-2027	18 m 20 d
256004	ELT ANTENNA *CF	110-340 151213	MTH 21-Nov-2007		O/C			
256007 256001	ELT PROCESSOR C406N	453-5060 03900	MTH 21-Nov-2007		O/C			
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1	3001-212-1004/455-9 208207	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		O/C	6258 5305		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1	3001-212-1004/455-9 208303	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		O/C	6258 5305		
262001	FIRE EXTINGUISHER BOTTLE	9912048-6 81937B1	MTH 14-Mar-2023 HRS 9367 LDG 7610		O/C	0 0 0		
262003 LEFT	FIRE EXT CARTRIDGE	AE13083-5 1032	MTH 16-Feb-2024 HRS 9975.3 LDG 8101		120	54	31-Aug-2029	48 m 30 d
Manufacture Date: 01-Aug-2019								
262003 RIGHT	FIRE EXT CARTRIDGE	AE13083-5 1016	MTH 16-Feb-2024 HRS 9975.3 LDG 8101		120	54	31-Aug-2029	48 m 30 d
Manufacture Date: 01-Aug-2019								
262004	PORTABLE FIRE EXTINGUISHER	C352TS G-97924755	MTH 20-Jul-2023 HRS 9664.7 LDG 7853		O/C	0 0 0		
271001 LEFT	CONTROL WHEEL ASSY *CF	4319065-1 1041	MTH 21-Nov-2007		O/C	0		
271001 RIGHT	CONTROL WHEEL ASSY *CF	4319065-2 1146	MTH 21-Nov-2007		O/C	0		
271002 --	ELEVATOR TRIM TAB ACTUATOR	PN SN-UNKNOWN	MTH 21-Nov-2007		H/T H/T	0		
273001	RUDDER TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 NSN	MTH 21-Nov-2007		O/C	0		
273002	AILERON TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 0112	MTH 21-Nov-2007		O/C	0		
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1 LEO	MP50Y-1 188	MTH 04-Aug-2011 HRS 2253 LDG 1847		O/C	563		
275002 LEFT	FLAP ACTUATOR 9912640-1	41013930-105 0279	MTH 08-Apr-2015 HRS 4063.6 LDG 3323 ACH 36		O/C	0 0 0		
275002 RIGHT	FLAP ACTUATOR 9912640-2	41013930-106 0208	MTH 08-Apr-2015 HRS 4063.6 LDG 3323 ACH 36		O/C	0 0 0		
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY	9914344-59 1032	MTH 20-Jul-2022 HRS 8886.1 LDG 7213		O/C	0 0 0		
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY 9914344-52 *CF	140527-5200 07010134	MTH 21-Nov-2007		O/C	0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-2 IRA	41014070-103 0667	MTH 10-Dec-2009 HRS 972		O/C	0 0		
276001 RIGHT	SPEED BRAKE ACTUATOR 9912641-3	41014070-106 542198	MTH 27-Dec-2023 HRS 9922.9 LDG 8061		O/C			
282001 LEFT	PRIMARY EJECTOR 9912190-5	LR45300A C1284	MTH 21-Nov-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0044**
 Unit: **0044** Reg No: **N300VR**
 Airworthiness: **21-Nov-2007**
 Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282001 RIGHT	PRIMARY EJECTOR 9912190-5	*CF		LR45300A C1300	MTH 21-Nov-2007		O/C	0		
282002	TRANSFER VALVE 9914103-6	*CF		ZSV57 07-05311159	MTH 21-Nov-2007		O/C	0		
282003 LEFT	DC FUEL PUMP 9912553-1	*CF		1C7-23 6BC141	MTH 21-Nov-2007		O/C	0		
282003 RIGHT	DC FUEL PUMP 9912553-1	*CF		1C7-23 6BC140	MTH 21-Nov-2007		O/C	0		
282004 L1	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C281	MTH 21-Nov-2007		O/C	0		
282004 L2	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C388	MTH 21-Nov-2007		O/C	0		
282004 R1	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C305	MTH 21-Nov-2007		O/C	0		
282004 R2	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C292	MTH 21-Nov-2007		O/C	0		
282005 LEFT	VALVE-FUEL MOTOR 9912014-3	*CF		AV24B1507 AA118225	MTH 21-Nov-2007		O/C	0		
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3	*CF		AV24B1507 AA114129	MTH 21-Nov-2007		O/C	0		
284001 L1	FUEL PROBE 9912664-1	*CF		020-251-001 0218	MTH 21-Nov-2007		O/C	0		
284001 L2	FUEL PROBE 9912664-2	*CF		020-251-002 0223	MTH 21-Nov-2007		O/C	0		
284001 L3	FUEL PROBE 9912664-3	*CF		020-251-003 0216	MTH 21-Nov-2007		O/C	0		
284001 L4	FUEL PROBE 9912664-4	*CF		020-251-004 0217	MTH 21-Nov-2007		O/C	0		
284001 L5	FUEL PROBE 9912664-5	*CF		020-251-005 0232	MTH 21-Nov-2007		O/C	0		
284001 R1	FUEL PROBE 9912664-1	*CF		020-251-001 0207	MTH 21-Nov-2007		O/C	0		
284001 R2	FUEL PROBE 9912664-2	LOWL		020-251-002 1104	MTH 09-Aug-2013 HRS 3465.9 LDG 2749		O/C	0 0 0		
284001 R3	FUEL PROBE 9912664-3			020-251-003 0446	MTH 09-Jun-2023 HRS 9563.2 LDG 7778		O/C	3484.23 3047		
284001 R4	FUEL PROBE 9912664-4	*CF		020-251-004 0220	MTH 21-Nov-2007		O/C	0		
284001 R5	FUEL PROBE 9912664-5	*CF		020-251-005 0238	MTH 21-Nov-2007		O/C	0		
284002	SIGNAL CONDITIONER 9912664-6			367-350-001 1302	MTH 07-Feb-2017 HRS 5349.8 LDG 4309		O/C			
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2			HM50C-3 019B	MTH 04-Mar-2019 HRS 6740.4 LDG 5463		O/C	0 0 0		
291002	HYDRAULIC CHECK VALVE *CF			CV02-267 NSN	MTH 21-Nov-2007		O/C	0		
291003	HYDRAULIC SYS PRESSURE GAUGE *CF			19940933-1 NSN	MTH 21-Nov-2007		O/C	0		
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4	*CF		80665 NSN	MTH 21-Nov-2007		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291007	HYDRAULIC MANIFOLD 9912657-14	*CF		8257-3 0085	MTH 21-Nov-2007		O/C	0		
291008	HYDRAULIC RELIEF VALVE 9912657-2	*CF		2672 0057	MTH 21-Nov-2007		O/C	0		
291009	BRAKE PRESSURE SWITCH 9912657-3			80664 0570	MTH 16-Nov-2023 HRS 9906.3 LDG 8048		O/C	0 0 0		
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5	*CF		4251 NSN	MTH 21-Nov-2007		O/C	0		
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7	*CF		4252 NSN	MTH 21-Nov-2007		O/C	0		
291011	HYDRAULIC DUMP VALVE 9912657-15	*CF		9625-1 NSN	MTH 21-Nov-2007		O/C	0		
291012	HYDRAULIC RESERVOIR ASSEMBLY *CF			7017005-24 NSN	MTH 21-Nov-2007		O/C	0		
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2	*CF		7550-2 0174	MTH 21-Nov-2007		O/C	0		
301001 LEFT	WING DE-ICE BOOT 9912662-17			P35-4D5317-17 NDP0170	MTH 05-May-2020 HRS 7554 LDG 6139		O/C	1991 1670		
301001 RIGHT	WING DE-ICE BOOT 9912662-18			P35-4D5317-18 NDX0720	MTH 12-Nov-2020 HRS 7962.7 LDG 6469		O/C	42 0 0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT 9912662-3			P29S4D5317-05 NDO9520	MTH 05-May-2020 HRS 7554 LDG 6139		O/C	0 0 0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT 9912662-4			P29S4D5317-06 MZN500	MTH 05-May-2020 HRS 7554 LDG 6139		O/C	7554 6139		
301004 L1	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4386A	MTH 21-Nov-2007		O/C	0		
301004 L2	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4402A	MTH 21-Nov-2007		O/C	0		
301004 L3	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4423A	MTH 21-Nov-2007		O/C	0		
301004 R1	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4415A	MTH 21-Nov-2007		O/C	0		
301004 R2	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4392A	MTH 21-Nov-2007		O/C	0		
301004 R3	DE-ICE PRESSURE SWITCH			1106P55-1 12193A	MTH 30-Jan-2020 HRS 7447.9 LDG 6056		O/C	0 0 0		
301004	VERT DE-ICE BOOT 9912662-13			P29S4D5317-13 NDV2260	MTH 05-May-2020 HRS 7554 LDG 6139		O/C	35 0 0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY *CF			5285-00-3 1245	MTH 21-Nov-2007		O/C	0		
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY *CF			5285-00-3 1305	MTH 21-Nov-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
302002 LEFT	TEMP SWITCH			1173T0759 5232	MTH 08-Apr-2015 HRS 4063.6 LDG 3323		O/C	2818.9 2492		
302002 RIGHT	TEMP SWITCH	*CF		1173T0759 4111	MTH 21-Nov-2007		O/C	0		
304001 L1	DE-ICE VALVE	*CF		3D2353-06 N071743	MTH 21-Nov-2007		O/C	0		
304001 L2	DE-ICE VALVE	*CF		3D2353-06 N072415	MTH 21-Nov-2007		O/C	0		
304002 LEFT	WINDSHIELD CONTROLLER	LOWL		7098108-1 0508A	MTH 12-Oct-2015 HRS 4548.6 LDG 3676 ACH 36		O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER	LOWL		7098108-1 0238A	MTH 08-Apr-2015 HRS 4063.6 LDG 3323 ACH 36		O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY	*CF		7041020-5 38	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY	*CF		7041020-6 36	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
321001	NOSE LANDING GEAR TRUNNION			7042020-1 32325373	MTH 20-Dec-2023 HRS 9922.9 LDG 8061		O/C	0 0 0		
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY	LOWL		7041050-4 39M	MTH 23-Nov-2011 HRS 2391.4 LDG 1969		12000	1969	12000	3840
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY			7041050-5 26081549C	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		12000	1 0 0	18664	10504
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY			7041030-1 142	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		20000	3047	23617	15457
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY			7041030-4 RH0068	MTH 02-May-2022 HRS 8723.3 LDG 7096		20000	0 0	27096	18936
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK	*CF		6327504-6 1538	MTH 21-Nov-2007		O/C	0		
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK	*CF		6327504-6 1719	MTH 21-Nov-2007		O/C	0		
322002	NOSE GEAR FORK & PISTON ASSEMBLY	*CF		7042040-1 NSN	MTH 21-Nov-2007		O/C			
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR	*CF		9912655-1 FA100036-001 FA100036-1-0078	MTH 21-Nov-2007 LDG 0		12000	0	12000	3840
322010 LEFT	MAIN LANDING GEAR HYDRAULIC ACTUATOR			9912653-5 FA100104-001 FA100104-1-0156	MTH 01-Mar-2018 HRS 6252.1 LDG 5064		12000	4638 3718	13346	5186
322010 RIGHT	MAIN LANDING GEAR HYDRAULIC ACTUATOR	*CF		9912653-6 FA100105-001 FA100091-1-0006	MTH 21-Nov-2007 LDG 0		12000	0 0	12000	3840
322011	NOSE LANDING GEAR ACTUATOR	*CF		9912654-2 FA100087-001 FA100087-1-0044	MTH 21-Nov-2007 LDG 0		12000	0 0	12000	3840

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
322202	SHIMMY DAMPER *CF	7042030-2 NSN	MTH 21-Nov-2007		O/C			
322205 NOSE	LANDING GEAR STRUT ASSEMBLY LOWL	7042010-4 037	MTH 23-Nov-2011 HRS 2391.4 LDG 1969		20000	1969	20000	11840
322206 NOSE	LANDING GEAR DRAG BRACE ASSY *CF	7042120-1 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
323001 LEFT	LANDING GEAR ASSEMBLY *CF	7041010-5 38	MTH 21-Nov-2007		O/C	0		
323001 RIGHT	LANDING GEAR ASSEMBLY *CF	7041010-6 36	MTH 21-Nov-2007		O/C	0		
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE 9914678-3	40005369-2 9529	MTH 12-Apr-2024 HRS 9975.3 LDG 8101		288		31-Dec-2041	196 m 30 d
Manufacture Date: 01-Dec-2017								
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE 9914678-4	40005399-1 11775	MTH 12-Apr-2024 HRS 9975.3 LDG 8101		288	0 0	30-Nov-2047	267 m 29 d
Manufacture Date: 01-Nov-2023								
323003	EMER BLOW DOWN BTL PRESSURE GAUGE *CF	19940931-1 NSN	MTH 21-Nov-2007		O/C	0		
324001 LEFT	MAIN LANDING GEAR TIRE 9912646-1	021-523-0 2354T00380	MTH 15-Sep-2023 HRS 9759.7 LDG 7928		O/C	0 0 0		
324001 RIGHT	MAIN LANDING GEAR TIRE 9912646-1	021-523-0 2161T00320	MTH 27-Oct-2023 HRS 9882.9 LDG 8029		O/C	0 0 0		
324002	NOSE LANDING GEAR TIRE 9912649-1	079-606-0 1210T00138	MTH 25-Jul-2023 HRS 9678.3 LDG 7864		O/C	0 0 0		
324003 LEFT	MAIN LANDING GEAR WHEEL 9912645-1	3-1640 0443	MTH 15-Sep-2023 HRS 9759.7 LDG 7928		O/C	3323.6 2687		
324003 RIGHT	MAIN LANDING GEAR WHEEL 9912645-1	3-1640 0346	MTH 27-Oct-2023 HRS 9882.9 LDG 8029		O/C			
324004 NOSE	NOSE LANDING GEAR WHEEL 9912648-1	3-1642 0194	MTH 25-Jul-2023 HRS 9678.3 LDG 7864		O/C			
324005 LEFT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	2-1706-1 0328	MTH 27-Oct-2023 HRS 9882.9 LDG 8029		O/C	0 0 0		
324005 RIGHT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	2-1706-1 0753	MTH 29-Jun-2023 HRS 9608.1 LDG 7815		O/C	0 0 0		
324006 LEFT	SHUTTLE VALVE *CF 9914689-4	5145-1 0107	MTH 21-Nov-2007		O/C	0		
324006 RIGHT	SHUTTLE VALVE *CF 9914689-4	5145-1 0094	MTH 21-Nov-2007		O/C	0		
324007	BRAKE METERING VALVE 9912650-2 *CF	84-62 0077	MTH 21-Nov-2007		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324101 LEFT	WHEEL SPEED SENSOR			9912650-5 1044	MTH 11-Oct-2022		O/C	0		
324101 RIGHT	WHEEL SPEED SENSOR			466-23-1 9912650-5	MTH 18-May-2010 HRS 1208 LDG 976		O/C	0 0		
324101	PARKING BRAKE VALVE			98433-1 9912388-10	MTH 21-Nov-2007		O/C	0		
324102	ANTISKID CONTROL UNIT			9912650-1 302829405	MTH 04-Oct-2022 HRS 9082.7 LDG 7372		O/C	8220.4 6622		
324103	ANTISKID CONTROL VALVE			211-134-1 9912650-6	MTH 21-Nov-2007		O/C	0		
324104	EMERGENCY BRAKE VALVE			72298 9912651-1	MTH 21-Nov-2007		O/C	0		
324105	EMER BRAKE BOTTLE PRESSURE GAUGE			19940931-1 -	MTH 21-Nov-2007		O/C	0		
325001	BUNGE ASSEMBLY			7042072-9 NSN	MTH 21-Nov-2007		O/C			
334001 LEFT	POWER SUPPLY			9912677-3 001179	MTH 08-Sep-2020 HRS 7859.2 LDG 6387		O/C	0 0 0		
334001 RIGHT	POWER SUPPLY			9912677-3 001173	MTH 13-Dec-2019 HRS 7314.4 LDG 5953		O/C	95.1 74		
334002	GROUND RECOGNITION LIGHT			84003-2 9912679-3	MTH 21-Nov-2007		O/C	0		
334003 LEFT	ANTI-COLLISION LIGHT			9912679-7 001301	MTH 05-May-2020 HRS 7554 LDG 6139		8000	5 0 0	15554	5484.8
334003 RIGHT	ANTI-COLLISION LIGHT			84056-2 / 9912679-8 000789	MTH 05-May-2020 HRS 7554 LDG 6139		8000	3 0 0	15554	5484.8
341001	SWAAT UNIT			0863B2 9912689-1	MTH 21-Nov-2007		O/C	0		
341002 NO. 1	GDC 74B AIRDATA SYSTEM			011-01110-00 43800525	MTH 21-Nov-2007		O/C	0		
341002 NO. 2	GDC 74B AIRDATA SYSTEM			011-01110-00 43800502	MTH 21-Nov-2007		O/C	0		
341003 NO. 1	GTP 59 OAT PROBE SYSTEM			011-00978-00 47908541	MTH 21-Nov-2007		O/C	0		
341003 NO. 2	GTP 59 OAT PROBE SYSTEM			011-00978-00 47908540	MTH 21-Nov-2007		O/C	0		
341004 LEFT	PITOT PROBE			0851LN 9912678-1	MTH 21-Nov-2007		O/C	0		
341004 RIGHT	PITOT PROBE			0851LN 9912678-1	MTH 21-Nov-2007		O/C	0		
342001 STANDBY	ALTIMETER			162350-1161 S3100-465 178837C	MTH 27-Dec-2021 HRS 8552.6 LDG 6952		O/C	7242 5913		
342002 AIRSPEED	INDICATOR			261440-1143 288581A	MTH 21-Nov-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE			011-00831-00 46711839	MTH 05-Oct-2023 HRS 9822.7 LDG 7979		O/C	0 0 0		
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE	*CF		011-00831-00 46706492	MTH 21-Nov-2007		O/C	0		
342003	MAGNETIC COMPASS	*CF		S2800-821 6073091	MTH 21-Nov-2007		O/C	0		
342004 NO. 1	GDU 1040A DISPLAY	LOWL		011-00916-00 86800574	MTH 25-Jul-2012 HRS 2787.1 LDG 2293		O/C	0 0 0		
342004 NO. 2	GDU 1040A DISPLAY	LOWL		011-00916-00 86800407	MTH 08-Apr-2015 HRS 4063.6 LDG 3323 ACH 36		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT	*CF	1	011-00868-10 42007313	MTH 21-Nov-2007		O/C	0		
342005 NO. 2	GRS 77 AHRS UNIT	*CF	1	011-00868-10 42007306	MTH 21-Nov-2007		O/C	0		
342006 NO. 1	GMU 44 MAGNETOMETER			011-00870-00 47507188	MTH 09-Jun-2023 HRS 9563.2 LDG 7778		O/C	0 0 0		
342006 NO. 2	GMU 44 MAGNETOMETER			011-00870-00 47510210	MTH 04-Jun-2018 HRS 6258 LDG 5068		O/C	6872.6 5432		
342007	GDU 1500 MFD UNIT	*CF		011-01108-00 43200699	MTH 21-Nov-2007		O/C	0		
342008	ATTITUDE INDICATOR			4200-21	MTH 08-Apr-2015		O/C	0		
	S3100-513	LOWL		E08-10028	HRS 4063.6 LDG 3323 ACH 36		O/C	0 0 0		
344001	GWX 68 WEATHER RADAR			011-00883-20 47203114	MTH 14-Jun-2017 HRS 5652.4 LDG 4569		O/C			
344002	GARMIN GDL-69A DATA LINK	*CF		011-00987-00 47758081	MTH 21-Nov-2007		O/C	0		
344005 LEFT	(KRA-405B) RADAR ALTIMETER ANTENNA			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
344005 RIGHT	(KRA-405B) RADAR ALTIMETER ANTENNA			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
344006	(KRA-405B) RADAR ALTIMETER			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
345001	GPS/WAAS/XM ANTENNA	*CF		013-00245-00 5014	MTH 21-Nov-2007		O/C	0		
345002 RIGHT	TRANSPONDER			011-00779-21 84805725	MTH 04-Oct-2021 HRS 8438.6 LDG 6850		O/C			
345003 LEFT	TRANSPONDER			011-0079-21 84805801	MTH 04-Jun-2018 HRS 6258 LDG 5068		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345004	GCU 475 FLIGHT MGMT CONTROL UNIT			010-00359-10 21806201	MTH 11-Jun-2022 HRS 8852.4 LDG 7190		O/C	0 0 0		
345005	ADF RECEIVER			013-00166-00 2766	MTH 23-May-2023 HRS 9528.5 LDG 7750		O/C			
345006	ADF ANTENNA			AN3500 05074	MTH 12-Nov-2020 HRS 7962.7 LDG 6469		O/C	13 0 0		
345007	MARKER BEACON ANTENNA *CF			MB10-754-2 0031	MTH 21-Nov-2007		O/C	0		
345008	GLIDE SLOPE ANTENNA *CF			RGS10-48 12501	MTH 21-Nov-2007		O/C	0		
345009 LEFT	L-BAND TRANSPONDER ANTENNA LOWL			L10-611-14 3884	MTH 23-Nov-2011 HRS 2391.4 LDG 1969		O/C	0 0 0		
345009 RIGHT	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 0467	MTH 21-Nov-2007		O/C	0		
345009 UPPER	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 0463	MTH 21-Nov-2007		O/C	0		
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 0433	MTH 21-Nov-2007		O/C	0		
345010	VOR/LOC ANTENNA *CF			VT10-767-3 0376	MTH 21-Nov-2007		O/C			
345011	KN63 DME TRANSCEIVER *CF	1		066-01070-0001 31315	MTH 21-Nov-2007		O/C	0		
345013	RMI CONVERTER ICT			013-00167-00 0858	MTH 23-Oct-2008 HRS 73		O/C	0		
345014	GPS/WAAS/ ANTENNA			013-00244-00 14844	MTH 23-Dec-2021 HRS 8552.6 LDG 6952		O/C	46 0 0		
345015	DME ANTENNA *CF			L10-611-14 0442	MTH 21-Nov-2007		O/C	0		
346010	TAS PROCESSOR *CF			066-01152-0101 KTA810-1597	MTH 21-Nov-2007		O/C	0		
346011 BOTTOM	TAS ANTENNA *CF			L10-611-14 0453	MTH 21-Nov-2007		O/C	0		
346011 TOP	TAS ANTENNA LOWL			071-01599-0100 UKN	MTH 12-Jun-2015 HRS 4197.2 LDG 3425 ACH 36		O/C	1621		
346013	TCAS II ANTENNA			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT			011-01105-01 15W014952	MTH 04-Jun-2018 HRS 6258 LDG 5068		O/C	0 0 0		
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT			011-01105-01 15W007795	MTH 22-Jun-2017 HRS 5675 LDG 4541		O/C	337.8 288		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
350001	OXYGEN BOTTLE			4441073-040 450909601	MTH 23-Dec-2021 HRS 8552.6 LDG 6952		180	0	31-Mar-2026	7 m 30 d
Manufacture Date: 01-Mar-2011										
350002	OXYGEN PRESSURE GAUGE C668512-0101	*CF		MD97-1 EO7-10087	MTH 21-Nov-2007		O/C			
351001 LEFT	CREW OXYGEN MASK			9914067-41 SE27598	MTH 01-Apr-2021 HRS 8174.7 LDG 6644		72	3 0 0	31-Jan-2027	17 m 30 d
351001 RIGHT	CREW OXYGEN MASK			9914067-41 99059	MTH 15-Sep-2023 HRS 9759.7 LDG 7928		72	0 0 0	30-Sep-2029	49 m 29 d
361001 LEFT	PRECOOLER			7014214-49 SN-UNKNOWN	MTH 21-Oct-2020 HRS 7953.8 LDG 6462		O/C	0 0		
361001 RIGHT	PRECOOLER			7014214-49 T1205	MTH 23-Jul-2021 HRS 8196.2 LDG 6664		O/C	0 0 0		
361002 LEFT	VARIABLE VENTURI VALVE ASSY			2601-34 0523A	MTH 04-Jun-2018 HRS 6258 LDG 5068		O/C	0 0 0		
361002 RIGHT	VARIABLE VENTURI VALVE ASSY *CF			2601-34 0128A	MTH 21-Nov-2007		O/C			
361003	SERVICE AIR REGULATOR ASSY *CF			9912510-2 3B012	MTH 21-Nov-2007		O/C			
361004 LEFT	B/A SHUTOFF VALVE			5253-00-3 1964B	MTH 04-Jun-2018 HRS 6258 LDG 5068		O/C	0 0 0		
361004 RIGHT	B/A SHUTOFF VALVE			5253-00-3 2753B	MTH 15-Jan-2020 HRS 7415.4 LDG 6031		O/C	4 0 0		
361101 R1	DE-ICE VALVE	*CF		3D2353-06 NO71760	MTH 21-Nov-2007		O/C	0		
361101 R2	DE-ICE VALVE	*CF		3D2353-06 NO72484	MTH 21-Nov-2007		O/C	0		
522001	CABIN DOOR SEAL	*CF		S-22560-3 9912674-3 069	MTH 21-Nov-2007		O/C			
522002	ESCAPE HATCH SEAL	*CF		S-22561 9912675-1 049	MTH 21-Nov-2007		O/C			
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY *CF			7013022-3 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY *CF			7013022-4 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY *CF			7013022-11 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY *CF			7013022-10 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
533100	AFT PRESSURE BULKHEAD WEB BOND ASSEMBLY PN SN-UNKNOWN				MTH 21-Nov-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
534101 FWD	ENGINE BEAM *CF	7012061-3 0044	MTH 21-Nov-2007		O/C			
552001 LEFT	ELEVATOR ASSEMBLY *CF	7034001-7 -	MTH 21-Nov-2007		O/C			
552001 RIGHT	ELEVATOR ASSEMBLY *CF	7034001-8 0000023	MTH 21-Nov-2007		O/C			
553001	VERTICAL STABILIZER ASSY *CF	7031001-801-7 -	MTH 21-Nov-2007		O/C			
561001 LEFT	WINDSHIELD ASSY, (LH) KMYF	9912745-13 23132H4968	MTH 30-Oct-2024 HRS 10022.1 LDG 8122		O/C	0 0 0		
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912745-6 *CF	P03100-6 00293	MTH 21-Nov-2007		O/C			
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1 *CF	93310-1 1175	MTH 21-Nov-2007		O/C			
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2 *CF	93310-2 1170	MTH 21-Nov-2007		O/C			
562003 L1	CABIN WINDOW 9912747-10 *CF	93320-10 1189	MTH 21-Nov-2007		O/C			
562003 L2	CABIN WINDOW 9912747-10 *CF	93320-10 1221	MTH 21-Nov-2007		O/C			
562003 L3	CABIN WINDOW 9912747-10 *CF	93320-10 1191	MTH 21-Nov-2007		O/C			
562003 R1	CABIN WINDOW 9912747-10 *CF	93320-10 1214	MTH 21-Nov-2007		O/C			
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-10 *CF	93320-10 1284	MTH 21-Nov-2007		O/C			
562003 R3	CABIN WINDOW 9912747-10 *CF	93320-10 1188	MTH 21-Nov-2007		O/C			
572001 LEFT WING	FWD SPAR *CF	7022022-1 45541	MTH 21-Nov-2007		O/C			
572001 RIGHT WING	FWD SPAR *CF	7022022-2 45542	MTH 21-Nov-2007		O/C			
572002 LEFT WING	REAR SPAR *CF	7022032-3 45552	MTH 21-Nov-2007		O/C			
572002 RIGHT WING	REAR SPAR *CF	7022032-4 45545	MTH 21-Nov-2007		O/C			
572003 LEFT WING	MAIN SPAR *CF	7022027-1 -	MTH 21-Nov-2007		O/C			
572003 RIGHT WING	MAIN SPAR *CF	7022027-2 -	MTH 21-Nov-2007		O/C			
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF	7041165-5 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF	7041165-6 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF	7041155-9 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF	7041155-10 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY *CF	7041175-5 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY *CF	7041175-6 NSN	MTH 21-Nov-2007 LDG 0		20000	0	20000	11840
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1 *CF	7051001-1 22	MTH 21-Nov-2007		O/C			
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM	9912647-1 LK2666	MTH 14-Mar-2023 HRS 9367 LDG 7610		4000	0 0 0	13367	3297.8

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM			9912647-1 LK2665	MTH 14-Mar-2023 HRS 9367 LDG 7610		4000	0 0 0	13367	3297.8
712001 RIGHT	ENG CHANNEL-FWD MOUNT *CF			7051001-2 51	MTH 21-Nov-2007		O/C			
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1			LM-471-SA11 2659	MTH 14-Mar-2023 HRS 9367 LDG 7610		4000	0 0 0	13367	3297.8
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM			9912647-1 2662	MTH 14-Mar-2023 HRS 9367 LDG 7610		4000	0 0 0	13367	3297.8
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY			9912647-3 LK2784	MTH 12-Nov-2020 HRS 7962.7 LDG 6469		8000	4 0 0	15962.7	5893.5
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY			9912647-3 LK2785	MTH 12-Nov-2020 HRS 7962.7 LDG 6469		8000	4 0 0	15962.7	5893.5
712003 AFT	ENGINE BEAM *CF			7012066-2 0044	MTH 21-Nov-2007		O/C			
712003 LEFT	AFT ENGINE MOUNT CHANNEL *CF			7051001-3 52	MTH 21-Nov-2007		O/C			
712003 RIGHT	AFT ENGINE MOUNT CHANNEL *CF			7051001-4 56	MTH 21-Nov-2007		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE			35C0510-01 PCE-LB0147	MTH 16-May-2021 HRS 4667 LDG 3775		E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE			35C0510-01 PCE-LB0148	MTH 16-May-2021 HRS 4667 LDG 3775		E/C			
72-30-02-900-801 E1	FAN CASE			35C4881-01 SN-UNKNOWN	MTH 11-Apr-2016		O/C	0		
72-30-02-900-801 E2	FAN CASE			35C3657-01 KUA06984	MTH 08-Apr-2008		O/C	0		
72-40-01-900-801 E1	COMBUSTION CHAMBER LINER			35C4281-01 A004TPEC	MTH 16-Oct-2020 HRS 7863.4 LDG 6397		O/C	0 0 0		
72-40-01-900-801 E2	COMBUSTION CHAMBER LINER			35C4281-01 A004FTT8	MTH 16-Oct-2020 HRS 7866.7 LDG 6397		O/C	0 0 0		
72-50-03-900-801 E2	HP TURBINE SUPPORT CASE			35C2368-01 RWA17B768	MTH 08-Apr-2008		O/C	0		
72-50-05-900-801 E2	LP TURBINE VANE RING			35C3442CL01 HLA742A326	MTH 08-Apr-2008		O/C	0		
720010 E1	FAN ROTOR	UNK		35C1940-01 TXA1B4143	MTH 11-Apr-2016 HRS 5993.1 LDG 4847 ACCC YC		10500	3739.1 3211 3211	(10500)12136	3976 3976
720010 E2	FAN ROTOR	UNK		35C1940-01 TXA1B2774	MTH 13-Apr-2016 HRS 5999.6 LDG 4847 ACCC YC		10500	3795.6 3263 3263	(10500)12084	3924 3924



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
721010 E1	HP TURBINE DISK	35C3921-01 FRAEPYYA16	MTH 23-Dec-2021 HRS 8200.2 LDG 6665 ACCC YC			0 0 0 5250	(10279)11915	3755 3755
721010 E2	HP TURBINE DISK	35C3921-01 FRAEPYYA23	MTH 23-Dec-2021 HRS 8200.5 LDG 6665 ACCC YC			0 0 0 5250	(10331)11915	3755 3755
721020 E1	LP TURBINE DISK	35C2372-01 A00298P5	MTH 10-Apr-2016 HRS 5993.1 LDG 4847 ACCC YC			3739.1 3211 3211 10500	(10500)12136	3976 3976
721020 E2	LP TURBINE DISK	35C2372-01 A0028DEB	MTH 13-Apr-2016 HRS 5999.6 LDG 4847 ACCC YC			3795.6 3263 3263 10500	(10500)12084	3924 3924
723010 E1	IMPELLER AND SHAFT ASSEMBLY	35C4888-01 A0028H9F	MTH 10-Apr-2016 HRS 5993.1 LDG 4847 ACCC YC			3211 3211 10500	(10500)12136	3976 3976
723010 E2	IMPELLER AND SHAFT ASSEMBLY	35C4888-01 A0027Y5C	MTH 13-Apr-2016 HRS 5999.6 LDG 4847 ACCC YC			3795.6 3263 3263 10500	(10500)12084	3924 3924
725010 E1	HP COMPRESSOR ROTOR	35C3661-01 TXA1B4109	MTH 10-Apr-2016 HRS 5993.1 LDG 4847 ACCC YC			3739.1 3211 3211 10500	(10500)12136	3976 3976
725010 E2	HP COMPRESSOR ROTOR	35C3661-01 TXA1B4244	MTH 13-Apr-2016 HRS 5999.6 LDG 4847 ACCC YC			3795.6 3263 3263 10500	(10500)12084	3924 3924
726010 E1	AGB STARTER MAGNETIC SEAL	PN-UNKNOWN SN-UNKNOWN	MTH 23-Dec-2021 HRS 8200.2 LDG 6665		1750	0 0 0	(8127.9)10381.9	312.7
726010 E2	AGB STARTER MAGNETIC SEAL	PN-UNKNOWN SN-UNKNOWN	MTH 23-Dec-2021 HRS 8200.5 LDG 6665		1750	0 0 0	(8183.6)10387.6	318.4
730001 LEFT	ENGINE FUEL PRESSURE SWITCH	1103P0448 7994	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		O/C			
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH	1103P0448 8043	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		O/C	6258 5305		
733001 LEFT	FUEL FLOW TRANSMITTER	TFF1573-4 0740-019	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		O/C	6258 5305		
733001 RIGHT	FUEL FLOW TRANSMITTER	TFF1573-4 AAA1712	MTH 05-May-2023 HRS 9480.7 LDG 7705		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
73-20-02-900-801 E1	ELECTRICAL WIRING HARNESS			35C3943-03 WDAAL000201	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		H/T H/T H/T H/T	0 0 0 0		
73-20-02-900-801 E2	ELECTRICAL WIRING HARNESS			35C3943-03 WDAAL001575	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		H/T H/T H/T H/T			
731050 E1	FUEL MANIFOLD			35C6160-01 DEAAAA66021	MTH 23-Dec-2021 HRS 8200.2 LDG 6665		O/C	9 0 0		
731050 E2	FUEL MANIFOLD			35C6160-01 DEAAAA66714	MTH 23-Dec-2021 HRS 8200.5 LDG 6665		O/C	8 0 0		
732101 E1	FUEL METERING UNIT (F.M.U.) UNK			8062-1109 15423402	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		H/T H/T H/T H/T	0 0 0 0		
732101 E2	FUEL METERING UNIT (F.M.U.) UNK			8062-1109 15450007	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		H/T H/T H/T H/T	0 0 0 0		
733010 E1	FUEL FILTER IMPENDING BYPASS SWITCH			35C5593-01 WDA135591	MTH 23-Dec-2021 HRS 8200.2 LDG 6665		O/C	0 0 0		
733010 E2	FUEL FILTER IMPENDING BYPASS SWITCH			35C5593-01 WDA138181	MTH 23-Dec-2021 HRS 8200.5 LDG 6665		O/C	0 0 0		
741001 E1	IGNITION EXCITER UNK			8408-6009 15389698	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		O/C			
741001 E2	IGNITION EXCITER UNK			8408-6009 15372897	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		O/C			
741002 E1 LEFT	IGNITER CABLE			35C0844-01 NSN	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		O/C	3739.1 3211		
741002 E2 LEFT	IGNITER CABLE			35C0844-01 NSN	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		O/C	3795.6 3263		
741003 E1 RIGHT	IGNITER CABLE			35C0799-01 NSN	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		O/C	3739.1 3211		
741003 E2 RIGHT	IGNITER CABLE			35C0799-01 NSN	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		O/C	3795.6 3263		
741004 E1 INBOARD	SPARK IGNITER			35C2353-02 WDA143866	MTH 15-Sep-2023 HRS 9882.1		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
741004 E2 INBOARD	SPARK IGNITER			35C2353-02 WDA140962	MTH 23-Dec-2021 HRS 8200.5 LDG 6665		O/C	0 0 0		
741005 E1 OUTBOARD	SPARK IGNITER			35C2353-02 WDA144252	MTH 15-Sep-2023 HRS 9882.1		O/C	0 0		
741005 E2 OUTBOARD	SPARK IGNITER			35C2353-02 WDA139267	MTH 15-Sep-2023 HRS 9764		O/C	0 0		
751003 E1	BLEED VALVE ACTUATOR UNK			8100-0015 15478273	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		H/T H/T H/T	0 0 0		
751003 E2	BLEED VALVE ACTUATOR UNK			8100-0028 16104123	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		H/T H/T H/T	0 0 0		
76-10-00-2.3	THROTTLE QUADRANT ASSEMBLY			PN SN-UNKNOWN	MTH 21-Nov-2007		O/C	0		
761001 E1	FADEC 9912637-2			35C4035-03 07-284	MTH 23-Dec-2021 HRS 8200.2 LDG 6665		O/C	4217.5 3506		
761001 E2	FADEC 9912637-2			35C4035-03 06-131	MTH 23-Dec-2021 HRS 8200.5 LDG 6665		O/C	5714.4		
77-20-02-900-801 E1	T6 THERMOCOUPLE WIRING HARNESS			35C0374-01 WDAAA000505	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		O/C			
77-20-02-900-801 E2	T6 THERMOCOUPLE WIRING HARNESS			35C0374-01 WDAAA000734	MTH 14-Apr-2016 HRS 5995.3 LDG 4846		O/C			
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.) UNK			10940J WA29209	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		H/T H/T H/T	0 0 0		
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.) UNK			10940J WA31112	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		H/T H/T H/T	0 0 0		
792030 E1	AIR COOLED OIL COOLER			35C2495-05 WA52744	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		H/T H/T H/T	0 0 0		
792030 E2	AIR COOLED OIL COOLER			35C2495-05 WA52735	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		H/T H/T H/T	0 0 0		
793001 E1	OIL TEMP SENSOR *CF			102-00083 06313	MTH 08-Apr-2008		O/C	0		
793001 E2	OIL TEMP SENSOR *CF			102-00083 06278	MTH 08-Apr-2008		O/C	0		
793002 E1	OIL PRESSURE TRANSMITER			APTE-304A-250G 8448-7-554	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		O/C	1159.3 924		



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
793002 E2	OIL PRESSURE TRANSMITER	APTE-304A-250G 7365-10-560	MTH 22-Jul-2021 HRS 8196.2 LDG 6664		O/C	6258 5305		
793010 E1	CHIP COLLECTOR	35C0412-01 AB0216	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		O/C	3739.1 3211		
793010 E2	CHIP COLLECTOR	35C0412-01 AB1036	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		O/C	0 0 0		
793050 E1	OIL FILTER IMPENDING BYPASS INDICATOR	35C4333-01 WDA00732	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		O/C			
793050 E2	OIL FILTER IMPENDING BYPASS INDICATOR	35C4333-01 WDA00942	MTH 14-Apr-2016 HRS 5999.6 LDG 4847		O/C	0 0 0		
801000 LEFT	STARTER GENERATOR	MG94E-1 742D	MTH 18-Dec-2024 HRS 10022.1 LDG 8122		1500	0	11522.1	1452.9
801000 RIGHT	STARTER GENERATOR	9912676-1 1027D	MTH 17-Oct-2022 HRS 9103.3 LDG 7390		1500	0 0 0	10603.3	534.1



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)	INFORMATIONAL	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
	MOC : NOT APPLICABLE							
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)	RECOMMENDED			-			
	MOC :							
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)	RECOMMENDED	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1							
SB 510-03-01	CONVERSION FROM FAA (US) TO EASA CERTIFICATION	OPTIONAL	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
	MOC : NOT APPLICABLE							
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW	INFORMATIONAL			-			
	MOC :							
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)	INFORMATIONAL	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
	MOC : NOT APPLICABLE - CANCELLED							
SL 510-99-03 99SL-03	TUBE ASSEMBLY SLEEVE INSPECTION	RECOMMENDED	MTH 23-Oct-2008 HRS 73		A/R			Complete
	ICT							
	MOC : COMPLIED WITH							
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS	INFORMATIONAL			A/R			
	MOC :							
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION	INFORMATIONAL			A/R			
	MOC :							
SL 510-05-01 REV 01	TIME LIMITS/MAINTENANCE CHECKS - LANDING GEAR LIFE LIMIT EXEMPTION	INFORMATIONAL	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER							
SL 510-05-01	LANDING GEAR LIFE LIMIT EXEMPTION (SUPERSEDED BY SL510-05-01 REV 01)	SUPERSEDED	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1							
SL 510-11-01	INSPECTION OF THE LOWER SPEED BRAKE PLACARD	RECOMMENDED	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER.							
SL 510-11-02	POWER J-BOX PLACARD INSPECTION	RECOMMENDED	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER.							



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-11-03	PLACARDS AND MARKINGS - BRAKE ACCUMULATOR PLACARD INSPECTION									
			RECOMMENDED	MTH 08-Mar-2024		A/R			N/A	
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - BY SERIAL NUMBER.										
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)									
			INFORMATIONAL	MTH 08-Mar-2024		-			N/A	
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS									
			INFORMATIONAL			-				
MOC :										
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)									
			INFORMATIONAL	MTH 08-Mar-2024		-			N/A	
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2										
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									
			RECOMMENDED	MTH 08-Mar-2024		-			Complete	
				HRS 9975.3						
				LDG 8101						
MOC : COMPLIED WITH - PER NO REPORTS FROM CREW										
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)									
			INFORMATIONAL			-				
MOC :										
SL CIL-20-01 REV 01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 02)									
			INFORMATIONAL	MTH 08-Mar-2024		-			N/A	
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2										
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL									
			INFORMATIONAL			-				
MOC :										
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01)									
			INFORMATIONAL	MTH 08-Mar-2024		-			N/A	
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.										
SL 510-20-01 REV 01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 02)									
			INFORMATIONAL	MTH 08-Mar-2024		-			N/A	
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2										
SL 510-20-01 REV 02	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 03)									
			INFORMATIONAL	MTH 08-Mar-2024		A/R			N/A	
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 3										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-20-01 REV 03	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 04)									
		INFORMATIONAL	MTH	08-Mar-2024			A/R			N/A
			HRS	9975.3						
			LDG	8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 4										
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)									
		INFORMATIONAL	MTH	08-Mar-2024			A/R			N/A
			HRS	9975.3						
			LDG	8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 5										
SL 510-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 01)									
		INFORMATIONAL	MTH	08-Mar-2024			-			N/A
			HRS	9975.3						
			LDG	8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL									
		INFORMATIONAL					-			
MOC :										
SL 510-21-01 21SL-01	COMPRESSOR ISOLATOR MOUNT INSPECTION		MTH	23-Oct-2008			A/R			Complete
	ICT	RECOMMENDED	HRS	73						
MOC : COMPLIED WITH										
SL 510-21-02 REV 01	CABIN ALTITUDE MODULE INSPECTION		MTH	08-Mar-2024			A/R			N/A
		MANDATORY	HRS	9975.3						
			LDG	8101						
MOC : NOT APPLICABLE - BY SERIAL NUMBER. APPLICABLE TO -0061 THRU -0181										
SL 510-21-02	CABIN ALTITUDE MODULE INSPECTION (SUPERSEDED BY SL510-21-02 REV 01)									
		MANDATORY	MTH	08-Mar-2024			A/R			N/A
			HRS	9975.3						
			LDG	8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT									
		RECOMMENDED	MTH	20-Feb-2020			-			N/A
MOC : NOT APPLICABLE - BY PART NUMBER INSTALLED										
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT									
		OPTIONAL					-			
MOC :										
ASL 510-22-01 22ASL01	AUTOPILOT SERVO GUARD PIN INSPECTION		MTH	23-Oct-2008			A/R			Complete
	ICT	MANDATORY	HRS	73						
MOC : COMPLIED WITH										
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT		MTH				A/R			
		OPTIONAL								
MOC : DECLINED - NOT OF INTEREST										
SL 510-24-02	AFT PRESSURE BULKHEAD CONNECTOR INSPECTION		MTH	08-Mar-2024			A/R			N/A
		RECOMMENDED	HRS	9975.3						
			LDG	8101						
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SL 510-24-03 24SL-03	CREW ALERTING SYSTEM (CAS) ELECTRICAL WIRING INSPECTION									
	ICT	MANDATORY	MTH	23-Oct-2008			A/R			Complete
			HRS	73						
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-24-04 REV 01	LEFT CIRCUIT BREAKER PANEL PINS INSPECTION/REPLACEMENT	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SL 510-24-04	LEFT CIRCUIT BREAKER PANEL PINS INSPECTION/REPLACEMENT (SUPERSEDED BY SL510-24-04 REV 01)	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.								
SL 510-24-06 24SL-06	FUSE LIMITER INSPECTION IRA	MANDATORY	MTH 16-Sep-2009 HRS 749		-			Complete
MOC : COMPLIED WITH								
SL 510-24-07	PRINTED CIRCUIT BOARD INSPECTION	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SL 510-24-08 REV 01	STARTER/GENERATOR INSPECTION LOWL	MANDATORY	MTH 18-Jun-2010 HRS 1277 LDG 1029		A/R			Complete
MOC : COMPLIED WITH - IAW THE SB COMPLIED WITH VIA APPLICATION OF ORIGINAL RELEASE OF SL24-08 ON 29 DEC 2009								
SL 510-24-08 24SL-08	STARTER/GENERATOR INSPECTION (SUPERSEDED BY SL510-24-08 REV 01) OWL	SUPERSEDED	MTH 30-Dec-2009 HRS 1017		-			Complete
MOC : COMPLIED WITH								
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION MANDATORY		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER. APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.								
SL 510-24-11 REV 01	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION MANDATORY		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01) MANDATORY		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER. APPLICABLE TO SERIAL NUMBERS 510-0153 THRU 51-0279, -0281 THRU -0285, -0291 THRU -0294, AND -0296 ONLY.								
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION MANDATORY		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER. APPLICABLE TO SERIAL NUMBERS 510-0253 THRU 510-0323 ONLY.								
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION LOWL	MANDATORY	MTH 23-Nov-2011 HRS 2391.4 LDG 1969		A/R			Complete
MOC : COMPLIED WITH - PERFORMED SL510-24-13								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION									
				MANDATORY	DAYS 10-May-2017		-			Complete
					HRS 5563					
					LDG 4469					
	MOC : COMPLIED WITH									
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01)									
				MANDATORY	DAYS 10-May-2017		-			Complete
					HRS 5563					
					LDG 4469					
	MOC : COMPLIED WITH									
STC SA02653LA	REPLACEMENT OF ORIGINAL EQUIPMENT MAIN BATTERY WITH CONCORDE RG-390E/30 VALVE REGULATED LEAD-ACID BATTERY IN ACCORDANCE WITH MASTER DRAWING LIST 5-0598, REVISION A, DATED 3/22/2017, OR LATER FAA APPROVED REVISIONS.									
				STC-SUPPLEMENTALMTH			-			
				TYPE CERTIFICATE	HRS					
					LDG					
	MOC :									
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT									
				OPTIONAL	MTH		A/R			
	MOC : DECLINED - NOT OF INTEREST									
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER									
				DISCRETIONARY	MTH		A/R			
	MOC : DECLINED - NOT OF INTEREST									
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS									
				OPTIONAL	MTH		-			
	MOC : DECLINED - NOT OF INTEREST									
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION				DAYS 18-Jun-2010		A/R			Complete
				LOWL	MANDATORY					
					HRS 1277					
					LDG 1029					
	MOC : COMPLIED WITH - PERFORMED SI25-02									
SL 510-25-03 REV 01	EQUIPMENT/FURNISHINGS - CREW SEAT INSPECTION				MTH 08-Mar-2024		-			N/A
				MANDATORY	HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY SERIAL NUMBER									
SL 510-25-03	EQUIPMENT/FURNISHINGS - CREW SEAT INSPECTION (SUPERSEDED BY SL510-25-03 REV 01)									
				SUPERSEDED	MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY SERIAL NUMBER									
SB 510-27-01 27SB-01	AILERON SHIELD SEALANT REVISION			MANDATORY	MTH 16-Sep-2009		-			Complete
		IRA			HRS 749					
	MOC : COMPLIED WITH									
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION				MTH 19-Mar-2013		-			Complete
				LOWL	RECOMMENDED					
					HRS 3135					
					LDG 2482					
	MOC : COMPLIED WITH - PERFORMED SB510-27-02									
ASL 510-27-01	ELEVATOR AUTOPILOT CABLE INSPECTION				DAYS		A/R			Complete
				MANDATORY						
	MOC : COMPLIED WITH - PCW									



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-27-01 27SL-01	FLAP ACTUATOR INSTALLATION SETSCREW INSPECTION ICT			RECOMMENDED	MTH 23-Oct-2008 HRS 73		A/R			Complete
MOC : COMPLIED WITH										
SL 510-27-02 27SL-02	CONTROL YOKE ASSEMBLY TIE STRAP INSPECTION ICT			MANDATORY	MTH 23-Oct-2008 HRS 73		A/R			Complete
MOC : COMPLIED WITH										
SL 510-27-05 27SL-05	FLAP ACTUATOR INSPECTION IRA			MANDATORY	MTH 16-Sep-2009 HRS 749		-			Complete
MOC : COMPLIED WITH										
SL 510-27-06 REV 01	RUDDER PUSHROD INSPECTION			MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE.										
SL 510-27-06	RUDDER PUSHROD INSPECTION (SUPERSEDED BY SL510-27-06 REV 01)			MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.										
SL 510-27-08	ELEVATOR TRIM CHAIN INSPECTION			MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE.										
SB 510-28-02 28SB-02	LOCKING FUEL CAP INSTALLATION			OPTIONAL	MTH		A/R			
MOC : DEFERRED - NOT OF INTEREST.										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS INFORMATIONAL						-			
MOC :										
SL 510-28-01 28SL-01	LEFT AND RIGHT FUEL PROBE WIRE BUNDLE ASSEMBLY INSPECTION IRA			MANDATORY	MTH 16-Sep-2009 HRS 749		A/R			Complete
MOC : COMPLIED WITH										
SB 510-29-01	HYDRAULIC SYSTEM NOISE REDUCTION			OPTIONAL	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE.										
SB 510-29-02	REPLACEMENT OF THE HYDRAULIC PACK ASSEMBLY RECOMMENDED				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE.										
SB 510-30-01	WINDSHIELD CONTROLLER WIRING HARNESS INSTALLATION OPTIONAL				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER.										
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT DISCRETIONARY				MTH		-			
MOC : DECLINED - NOT OF INTEREST AND ALSO CHECK REQUIREMENT.										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-30-02	ICE AND RAIN PROTECTION - PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT (SUPERSEDED BY 510-30-02 REV 01)									
			DISCRETIONARY	MTH			-			
MOC : DECLINED - NOT OF INTEREST.										
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT									
			DISCRETIONARY	MTH			A/R			
MOC : DECLINED - NOT OF INTEREST										
SB 510-30-03	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT (SUPERSEDED BY 510-30-03 REV 01)									
			DISCRETIONARY	MTH	08-Mar-2024		A/R		N/A	
				HRS	9975.3					
				LDG	8101					
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.										
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT									
			MANDATORY	MTH	08-Mar-2024		A/R		N/A	
				HRS	9975.3					
				LDG	8101					
MOC : NOT APPLICABLE - BY SN.										
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION									
	LOWL		MANDATORY	MTH	28-Nov-2012		-		Complete	
				HRS	3017.6					
				LDG	2381					
MOC : COMPLIED WITH - PERFORMED SB510-30-05										
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT									
			RECOMMENDED	MTH			-			
MOC : DEFERRED										
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)									
			RECOMMENDED	MTH	08-Mar-2024		-		N/A	
				HRS	9975.3					
				LDG	8101					
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.										
ASL 510-30-02 30ASL02	WATER SEPARATOR DRAIN CAP									
	MTO		MANDATORY	MTH	07-Apr-2008		A/R		Complete	
				HRS	39					
MOC : COMPLIED WITH										
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES									
			INFORMATIONAL	MTH	08-Mar-2024		-		N/A	
				HRS	9975.3					
				LDG	8101					
MOC : NOT APPLICABLE - NOTED.										
SL CIL-30-01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY CIL-30-01 REV 01)									
			INFORMATIONAL	MTH	08-Mar-2024		-		N/A	
				HRS	9975.3					
				LDG	8101					
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.										
SL 510-30-01 REV 01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 02)									
			INFORMATIONAL	MTH	08-Mar-2024		A/R		N/A	
				HRS	9975.3					
				LDG	8101					
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2.										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-30-01 REV 02	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 03)									
			INFORMATIONAL	MTH 08-Mar-2024			A/R			N/A
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 3.										
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)									
			INFORMATIONAL	MTH 08-Mar-2024			A/R			N/A
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 4.										
SL 510-30-01 REV 04	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 05)									
			INFORMATIONAL	MTH 08-Mar-2024			A/R			N/A
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 5										
SL 510-30-01 REV 05	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 06)									
			INFORMATIONAL	MTH 08-Mar-2024			A/R			N/A
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 6										
SL 510-30-01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 01)									
			INFORMATIONAL	MTH 08-Mar-2024			A/R			N/A
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.										
SB 510-31-01 31SB-01	MASTER CAUTION WARNING LIGHT WIRING MODIFICATION									
	ICT		DISCRETIONARY	MTH 23-Oct-2008			A/R			Complete
				HRS 73						
MOC : COMPLIED WITH										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION									
			INFORMATIONAL				-			
MOC :										
SL 510-31-02	COCKPIT SWITCH INSPECTION									
			MANDATORY	MTH 08-Mar-2024			A/R			N/A
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE.										
SL 510-31-03	COCKPIT SWITCH WIRE BUNDLE ASSEMBLY (WBA) INSPECTION									
			MANDATORY	MTH 08-Mar-2024			A/R			N/A
				HRS 9975.3						
				LDG 8101						
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO AIRCRAFT SERIAL NUMBERS -0156 THRU -0164, -0167 THRU -0191, -0193 THRU -0215, -0218 THRU -0220, -0223, -0225 THRU -0227.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION									
			INFORMATIONAL				-			
MOC :										
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION									
			INFORMATIONAL				-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-32-02 REV 01 <i>32SL-02 : 510R1</i>	EMERGENCY GEAR RELEASE INSPECTION	LSZH		MANDATORY	MTH 19-Apr-2010 HRS 1128 LDG 906		A/R			Complete
MOC : COMPLIED WITH - PERFORMED IN ACCORDANCE WITH SL510-32-02 REV.1 INSTRUCTIONS.										
SL 510-32-02	EMERGENCY GEAR RELEASE INSPECTION (SUPERSEDED BY SL510-32-02 REV 01)			MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1.										
SL 510-32-03 <i>32SL-03</i>	RIGHT BRAKE STOP BRACKET INSPECTION	LSZH		MANDATORY	MTH 19-Apr-2010 HRS 1128 LDG 906		A/R			Complete
MOC : COMPLIED WITH - PERFORMED INSPECTION IN ACCORDANCE WITH SL510-32-03 INSTRUCTIONS. FOUND FASTENERS INSTALLED AS REQUIRED.										
SL 510-32-04	NOSE LANDING GEAR (NLG) UPLOCK BRACKET CORROSION REPAIR						A/R			
MOC :										
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION	LOWL		RECOMMENDED	MTH 28-Nov-2012 HRS 3017.6 LDG 2381		-			Complete
MOC : COMPLIED WITH - PERFORMED SL510-32-05										
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION			MANDATORY	DAYS 31-Mar-2017 HRS 5430 LDG 4374		-			Complete
MOC : COMPLIED WITH										
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY			MANDATORY	DAYS 28-Jul-2017 HRS 5803.4 LDG 4712		-			Complete
MOC : COMPLIED WITH										
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT			OPTIONAL	MTH		-			
MOC : DECLINED - NOT OF INTEREST.										
SB 510-34-01	TRAFFIC ADVISORY SYSTEM INSTALLATION			OPTIONAL	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SB 510-34-02 <i>34SB-02</i>	HARDWARE AND SOFTWARE UPDATE FOR GARMIN G1000 AVIONICS	ICT		MANDATORY	MTH 23-Oct-2008 HRS 73		A/R			Complete
MOC : COMPLIED WITH										
SB 510-34-05	DUAL DIVERSITY TRANSPONDER INSTALLATION			OPTIONAL	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-34-08	GARMIN TRANSPONDER HARDWARE IMPROVEMENT MANDATORY	MTH	08-Mar-2024		A/R			N/A
			HRS 9975.3					
			LDG 8101					
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SB 510-34-09 34SB-09	GARMIN G1000 SOFTWARE VERSION 010-00435-16 UPGRADE OWL	RECOMMENDED	MTH 14-May-2009		-			Complete
			HRS 345					
MOC : COMPLIED WITH								
SB 510-34-10 34SB-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION OPTIONAL	MTH			A/R			
MOC : DEFERRED - AT OPERATOR CONVENIENCE								
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE LOWL	MANDATORY	MTH 23-Nov-2011		A/R			Complete
			HRS 2391.4					
			LDG 1969					
MOC : COMPLIED WITH - PERFORMED GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE SERVICE BULLETIN								
SB 510-34-11	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE (SUPERSEDED BY 510-34-11 REV 01) LOWL	MANDATORY	MTH 23-Nov-2011		A/R			Complete
			HRS 2391.4					
			LDG 1969					
MOC : COMPLIED WITH - PERFORMED GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE SERVICE BULLETIN								
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT LOWL	MANDATORY	MTH 28-Feb-2012		-			Complete
			HRS 2519.3					
			LDG 2076					
MOC : COMPLIED WITH - PERFORMED 510-34-12 R1								
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01) LOWL	MANDATORY	MTH 28-Feb-2012		-			Complete
			HRS 2519.3					
			LDG 2076					
MOC : COMPLIED WITH - PERFORMED 510-34-12								
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE LOWL	MANDATORY	MTH 28-Nov-2012		-			Complete
			HRS 3017.6					
			LDG 2381					
MOC : COMPLIED WITH - PERFORMED SB510-34-14								
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRS SOFTWARE UPDATE MANDATORY	MTH	04-Dec-2016		-			Complete
			HRS 5287.2					
			LDG 4262					
MOC : COMPLIED WITH								
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02) OPTIONAL	MTH	08-Dec-2016		-			Complete
			HRS 5286.4					
			LDG 4291					
MOC : COMPLIED WITH								
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03) OPTIONAL	MTH			-			Complete
MOC : COMPLIED WITH - PCW								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE									
			OPTIONAL	MTH	08-Dec-2016		-			Complete
				HRS	5287.2					
				LDG	4262					
	MOC : COMPLIED WITH									
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE									
			RECOMMENDED	MTH	22-Jul-2021		-			Complete
				HRS	8196.2					
				LDG	6664					
	MOC : COMPLIED WITH									
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE									
			INFORMATIONAL	MTH	04-Dec-2016		-			Complete
				HRS	5287.2					
				LDG	4262					
	MOC : COMPLIED WITH									
SL 510-34-02	GARMIN GRS 77 ATTITUDE HEADING REFERENCE SYSTEM (AHRS)									
			INFORMATIONAL	MTH	08-Mar-2024		A/R			N/A
				HRS	9975.3					
				LDG	8101					
	MOC : NOT APPLICABLE - BY SERIAL NUMBER									
SL 510-34-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING									
34SL-03		OWL	INFORMATIONAL	MTH	10-Mar-2009		A/R			Complete
				HRS	210					
	MOC : COMPLIED WITH									
SL 510-34-04	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0816									
34SL-04		ICT	MANDATORY	MTH	27-Oct-2008		A/R			Complete
				HRS	74					
	MOC : COMPLIED WITH									
SL 510-34-09	GROUNDING STRIP INSPECTION									
34SL-09		LSZH	MANDATORY	MTH	19-Apr-2010		A/R			Complete
				HRS	1128					
				LDG	906					
	MOC : COMPLIED WITH - CHECKED INSTALLATION OF GROUNDING STRIP IN ACCORDANCE WITH SL510-34-09 INSTRUCTIONS.									
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A									
			INFORMATIONAL				A/R			
	MOC :									
SL 510-34-14	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0941 REV A. ERRONEOUS GWX SERVICE MESSAGE MAY BE DISPLAYED									
			INFORMATIONAL	MTH	23-Nov-2011		A/R			Complete
				HRS	2391.4					
				LDG	1969					
	MOC : COMPLIED WITH									
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1									
		LOWL	RECOMMENDED	MTH	23-Nov-2011		A/R			Complete
				HRS	2391.4					
				LDG	1969					
	MOC : COMPLIED WITH - ALRREADY DONE MOD 1 FOUND INSTALLED									
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE									
			INFORMATIONAL				A/R			
	MOC :									
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSUE									
			INFORMATIONAL				A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA	INFORMATIONAL			A/R			
MOC :								
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS	INFORMATIONAL			A/R			
MOC :								
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS	INFORMATIONAL			A/R			
MOC :								
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION	MTH 04-Dec-2016			-			Complete
	INFORMATIONAL	HRS 5287.2						
		LDG 4262						
MOC : COMPLIED WITH								
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL	INFORMATIONAL			-			
MOC :								
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT	RECOMMENDED MTH			-			Complete
MOC : COMPLIED WITH - STANDARD SD CARD INSTALLED								
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS	INFORMATIONAL			-			
MOC :								
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM)	INFORMATIONAL	MTH 08-Mar-2024		-			N/A
		HRS 9975.3						
		LDG 8101						
MOC : NOT APPLICABLE - NO LONGER APPLICABLE WHEN SB510-34-18 IS INCORPORATED.								
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG	INFORMATIONAL			-			
MOC :								
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS)	INFORMATIONAL			-			
MOC :								
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	MANDATORY	DAYS 08-Mar-2024		-			N/A
		HRS 9975.3						
		LDG 8101						
MOC : NOT APPLICABLE - OXYGEN MASK PART NUMBERS ARE NOT PART OF THE SL.								
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02)	MANDATORY	MTH 28-Feb-2012		-			Complete
	LOWL		HRS 2519.3					
			LDG 2076					
MOC : COMPLIED WITH - PERFORMED SL510-35-01 R1								
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	MANDATORY	MTH		-			Complete
MOC : COMPLIED WITH - PCW								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)	LOWL		MANDATORY	MTH 28-Feb-2012 HRS 2519.3 LDG 2076		-			Complete
MOC : COMPLIED WITH - PERFORMED SL510-35-01										
SB 510-52-01	IMPROVEMENT TO THE DOOR FRAME PROXIMITY SWITCH			RECOMMENDED	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SB 510-52-03 52SB-03	NOSE BAGGAGE DOOR HINGE IMPROVEMENT	ICT		RECOMMENDED	MTH 23-Oct-2008 HRS 73		A/R			Complete
MOC : COMPLIED WITH										
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION			DISCRETIONARY	MTH		A/R			
MOC : DECLINED - NOT OF INTEREST										
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT			MANDATORY	DAYS 19-Mar-2020 HRS 7554 LDG 6139		-			Complete
MOC : COMPLIED WITH										
SL 510-52-01 REV 01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION			MANDATORY	MTH 19-Apr-2010 HRS 1128 LDG 906		A/R			Complete
MOC : COMPLIED WITH - PERFORMED INSPECTION IN ACCORDANCE WITH SL510-52-01 REV.1 INSTRUCTIONS										
SL 510-52-01 52SL-01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION (SUPERSEDED BY SL510-52-01 REV 01)	IRA		SUPERSEDED	MTH 16-Sep-2009 HRS 749		-			Complete
MOC : COMPLIED WITH										
SL 510-52-02	CABIN DOOR FAIRING FASTENER INSPECTION			MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SL 510-52-03 52SL-03	DOOR FRAME CORNER FASTENER INSPECTION	LSZH		MANDATORY	MTH 19-Apr-2010 HRS 1128 LDG 906		A/R			Complete
MOC : COMPLIED WITH - PERFORMED INSPECTION IN ACCORDANCE WITH SL510-52-03 INSTRUCTIONS.										
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR			INFORMATIONAL			A/R			
MOC :										
SL 510-52-05	DOORS - CABIN ENTRY DOOR HINGE SHIELD INSPECTION			RECOMMENDED	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT			MANDATORY	DAYS 13-Dec-2019 HRS 7314.4 LDG 5953		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-53-01 53SB-01	AFT CABIN STRUCTURE INSPECTION LSZH	MANDATORY	DAYS 19-Apr-2010 HRS 1128 LDG 906			A/R				Complete
MOC : COMPLIED WITH - PEFORMED INSPECTION IN ACCORDANCE WITH SB510-53-01 INSTRUCTIONS.										
ASL 510-53-02 53ASL02	TAILCONE SEALANT INSPECTION (SUPERSEDED BY ASL510-53-02 REV 01) ICT	MANDATORY	MTH 23-Oct-2008 HRS 73			-				Complete
MOC : COMPLIED WITH										
SL 510-53-01 53SL-01	FORWARD PRESSURE BULKHEAD INSPECTION ICT	RECOMMENDED	MTH 23-Oct-2008 HRS 73			A/R				Complete
MOC : COMPLIED WITH										
SL 510-53-03	FUSELAGE - DRAIN HOLE INSPECTION LSZH	MANDATORY	MTH 19-Apr-2010 HRS 1128 LDG 906			A/R				Complete
MOC : COMPLIED WITH - PERFORMED INSPECTION IN ACCORDANCE WITH SL510-53-03 INSTRUCTIONS.FOUND DRAIN HOLE ASSEMBLY INSTALLED AS REQUIRED.										
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS	DISCRETIONARY	MTH 04-Jun-2018 HRS 6258 LDG 5068			-				Complete
MOC : COMPLIED WITH										
SB 510-54-01	PYLON SKIN IMPROVEMENTS (NOT RELEASED) (SUPERSEDED BY 510-54-01 REV 01)		MTH 08-Mar-2024 HRS 9975.3 LDG 8101			-				N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
ASL 510-54-01 54ASL01	PYLON RAM AIR DUCT VISUAL INSPECTION ICT	MANDATORY	MTH 23-Oct-2008 HRS 73			A/R				Complete
MOC : COMPLIED WITH										
SL 510-55-01 55SL-01	HORIZONTAL STABILIZER RIB INSPECTION LSZH	MANDATORY	MTH 19-Apr-2010 HRS 1128 LDG 906			A/R				Complete
MOC : COMPLIED WITH - PERFORMED IN ACCORDANCE WITH SL510-55-01 INSTRUCTIONS.										
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02) SUPERSEDED		MTH			-				Complete
MOC : COMPLIED WITH - PCW										
SL 510-55-02 REV 02	HORIZONTAL STABILIZER SEALANT INSPECTION	MANDATORY	DAYS 14-Jan-2013 HRS 3055.9 LDG 2415			A/R				Complete
MOC : COMPLIED WITH - PCW										
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01) LOWL	MANDATORY	DAYS 26-Nov-2010 HRS 1732 LDG 1400			A/R				Complete
MOC : COMPLIED WITH - PERFORMED SEALING OF HORIZONTAL STABILISER IN ACCORDANCE WITH CESSNA INSTRUCTIONS PROVIDED TO GLOBEAIR PRIOR TO OFFICIAL RELEASE OF SL510-55-02.										
SB 510-56-01	WINDSHIELD SCREW SEALING IMPROVEMENT	MANDATORY	DAYS 08-Mar-2024 HRS 9975.3 LDG 8101			A/R				N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-56-02 56SB-02	CABIN WINDOW FROST PANE MODIFICATION LSZH	DISCRETIONARY	MTH 19-Apr-2010 HRS 1128 LDG 906		A/R			Complete
MOC : COMPLIED WITH - PERFORMED MODIFICATION IN ACCORDANCE WITH SB510-56-02 INSTRUCTIONS.								
SL 510-56-01 56SL-01	WINDSHIELD WIRE BUNDLE ASSEMBLY INSPECTION IRA	MANDATORY	MTH 16-Sep-2009 HRS 749		A/R			Complete
MOC : COMPLIED WITH								
SL 510-57-01 REV 01 57SL-01 : 510R1	FLAP HINGE INSPECTION IRA	MANDATORY	MTH 16-Sep-2009 HRS 749		-			Complete
MOC : COMPLIED WITH								
SL 510-57-01	FLAP HINGE INSPECTION (SUPERSEDED BY SL510-57-01 REV 01) SUPERSEDED		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SL 510-57-02	WINGS - FLAP ACTUATOR BOLT REPLACEMENT MANDATORY		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE								
COM MC 510-006	510 MODEL COMMUNIQUE - PRATT & WHITNEY SERVICE BULLETIN 63112				-			
MOC :								
SB PW600-72- 63000 R01 E1	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS CATEGORY 11		MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72- 63000 R01 E2	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS CATEGORY 11		MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72- 63000 E1	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS (SUPERSEDED BY PW600-72-63000 R01) CATEGORY 11		MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72- 63000 E2	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS (SUPERSEDED BY PW600-72-63000 R01) CATEGORY 11		MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72- 63001 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 6		MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72- 63001 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 6		MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72- 63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5		MTH 08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72- 63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5		MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE			CATEGORY 9	MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE			CATEGORY 9	MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING			CATEGORY 5	MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING			CATEGORY 5	MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD										
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE			CATEGORY 9	MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE			CATEGORY 9	MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD										
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY			CATEGORY 7	MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY			CATEGORY 7	MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD										
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 8	MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 8	MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD										
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 7	MTH 08-Mar-2024 HRS 9979.3 LDG 8102		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 7	MTH 08-Mar-2024 HRS 9979.6 LDG 8102		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01)			CATEGORY 6	MTH 18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01)			CATEGORY 6	MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7	MTH 08-Mar-2024 HRS 9975.3 LDG 8101			-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7	MTH 08-Mar-2024 HRS 9975.3 LDG 8101			-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS CATEGORY 7				-			
MOC :								
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS CATEGORY 7				-			
MOC :								
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) CATEGORY 7	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) CATEGORY 7	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY CATEGORY 6				-			
MOC :								
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY CATEGORY 6				-			
MOC :								
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01) CATEGORY 9	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01) CATEGORY 9	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63021 E1	INSPECTION/CORRECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING CATEGORY 6	MTH 08-Mar-2024 HRS 9979.3 LDG 8102			-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SB PW600-72-63021 E2	INSPECTION/CORRECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING CATEGORY 6	MTH 08-Mar-2024 HRS 9979.6 LDG 8102			-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02) CATEGORY 7	MTH			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02) CATEGORY 7	MTH			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01) CATEGORY 7	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01) CATEGORY 7	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING CATEGORY 7	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING CATEGORY 7	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER CATEGORY 7	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER CATEGORY 7	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9	MTH 18-Dec-2007			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9	MTH 22-Dec-2007			-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63027 R01 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8	MTH	18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63027 R01 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8	MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01) CATEGORY 8	MTH	18-Dec-2007		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01) CATEGORY 8	MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63028 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01) CATEGORY 5	MTH	18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63028 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01) CATEGORY 5	MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01) CATEGORY 7	MTH	18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63031 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01) CATEGORY 7	MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7	MTH	08-Mar-2024		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7	MTH	08-Mar-2024		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER								
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8	MTH	18-Dec-2007		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8	MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT BUILD								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH			-			
MOC :										
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH			-			
MOC :										
SB PW600-72-63037 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01) CATEGORY 7			MTH	08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63037 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01) CATEGORY 7			MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY *CF CATEGORY 7			MTH			-			
MOC :										
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY *CF CATEGORY 7			MTH			-			
MOC :										
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY *CF CATEGORY 7			MTH			-			
MOC :										
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63043 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02) *CF CATEGORY 6			MTH			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2										
SB PW600-72-63043 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02) *CF CATEGORY 6			MTH			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63043 R02 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER	UNK		CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63043 R02 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER	UNK		CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY			CATEGORY 6	MTH 08-Mar-2024 HRS 9979.3 LDG 8102		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY			CATEGORY 6	MTH 08-Mar-2024 HRS 9979.6 LDG 8102		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER										
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)			CATEGORY 7	MTH 08-Mar-2024 HRS 9979.3 LDG 8102		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)			CATEGORY 7	MTH 08-Mar-2024 HRS 9979.6 LDG 8102		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63051 R01 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)	EGHH		CATEGORY 7	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - P&W SB 63051R1 INCORPORATED BY P&WC AS PART OF HSI.										
SB PW600-72-63051 R01 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)	EGHH		CATEGORY 7	MTH 15-Feb-2013 HRS 4248 LDG 3376		-			Complete
MOC : COMPLIED WITH - SB 630510 R1 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										
SB PW600-72-63051 R02 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R03)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63051 R02 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R03)	CATEGORY 6			-			
MOC :								
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES	CATEGORY 6			-			
MOC :								
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES	CATEGORY 6			-			
MOC :								
SB PW600-72-63051 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01)	CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63051 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01)	CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF	CATEGORY 7	MTH 08-Mar-2024 HRS 9979.3 LDG 8102		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 63085								
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF	CATEGORY 7	MTH 08-Mar-2024 HRS 9979.6 LDG 8102		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 63085								
SB PW600-72-63052 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01)	CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63052 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01)	CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS	CATEGORY 7			-			
MOC :								
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS	CATEGORY 7			-			
MOC :								
SB PW600-72-63053 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)	CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63053 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)	CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER	CATEGORY 7	MTH		-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER	EGHH		CATEGORY 7	MTH 15-Feb-2013 HRS 4248 LDG 3376		-			Complete
MOC : COMPLIED WITH - SB 63057 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
MOC :										
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
MOC :										
SB PW600-72-63059 R01 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R02)			CATEGORY 6			-			
MOC :										
SB PW600-72-63059 R01 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R02)			CATEGORY 6			-			
MOC :										
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY				MTH 11-Jun-2012 HRS 9378.7 LDG 3158		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT SHOP VISIT ENGINE REPAIR										
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY				MTH 15-Feb-2013 HRS 4243.7 LDG 3375		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT SHOP VISIT FOR ENGINE REPAIR										
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)	EGHH		CATEGORY 6	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - P&W SB63059 INCORPORATED BY P&WC AS PART OF HSI.										
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)	EGHH		CATEGORY 6	MTH 15-Feb-2013 HRS 4248 LDG 3376		-			Complete
MOC : COMPLIED WITH - SB63059 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL	EGHH			MTH 20-Jul-2012 HRS 3982.7 LDG 3159		A/R			Complete
MOC : COMPLIED WITH - P&W SB63062R1 INCORPORATED BY P&WC AS PART OF HSI.										
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL	EGHH			MTH 15-Feb-2013 HRS 4248 LDG 3376		A/R			Complete
MOC : COMPLIED WITH - SB63062 R1 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										
SB PW600-72-63062 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63062 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01) CATEGORY 7 MTH				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET CATEGORY 8				-			
MOC :								
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET CATEGORY 8				-			
MOC :								
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02) EGHH CATEGORY 6 MTH 20-Jul-2012 HRS 3982.7 LDG 3159				A/R			Complete
MOC : COMPLIED WITH - P&W SB63064R1 INCORPORATED BY P&WC AS PART OF HSI.								
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02) EGHH CATEGORY 6 MTH 15-Feb-2013 HRS 4248 LDG 3376				A/R			Complete
MOC : COMPLIED WITH - SB63064 R1 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.								
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY MTH 20-Jul-2012 HRS 3978.7 LDG 3158				-			Complete
MOC : COMPLIED WITH - P&W SB63064R1 INCORPORATED BY P&WC AS PART OF HSI								
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY MTH 15-Feb-2013 HRS 4243.7 LDG 3375				-			Complete
MOC : COMPLIED WITH - SB63064 R1 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR								
SB PW600-72-63064 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01) CATEGORY 6 MTH				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63064 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01) CATEGORY 6 MTH				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF CATEGORY 7				-			
MOC :								
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF CATEGORY 7				-			
MOC :								
SB PW600-72-63065 E1	TURBOFAN ENGINE - NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF (SUPERSEDED BY PW600-72-63065 R01) CATEGORY 7 MTH 08-Mar-2024 HRS 9979.3 LDG 8102				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63065 E2	TURBOFAN ENGINE - NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF (SUPERSEDED BY PW600-72-63065 R01) CATEGORY 7	MTH 08-Mar-2024 HRS 9979.6 LDG 8102			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER EGHH	CATEGORY 7	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - P&W SB63066 INCORPORATED BY P&WC AS PART OF HSI.								
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER CATEGORY 7	MTH			-			
MOC :								
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY UNK	CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		A/R			Complete
MOC : COMPLIED WITH								
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY UNK	CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		A/R			Complete
MOC : COMPLIED WITH								
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY EGHH	CATEGORY 6	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		A/R			Complete
MOC : COMPLIED WITH - P&W SB63070 INCORPORATED BY P&WC AS PART OF HSI.								
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY EGHH	CATEGORY 6	MTH 17-Apr-2012 HRS 3932.7 LDG 3107		A/R			Complete
MOC : COMPLIED WITH - SB63070 CARRIED OUT BY P&WC AS PART OF HSI.								
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING UNK	CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING UNK	CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01) CATEGORY 7	MTH			A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01) CATEGORY 7	MTH			A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6				-			
MOC :								
SB PW600-72-63074 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY	MTH	11-Jun-2012		-			Complete
		HRS	3982.7					
		LDG	3159					
MOC : COMPLIED WITH								
SB PW600-72-63074 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY UNK	MTH	13-Apr-2016		-			Complete
		HRS	5999.6					
		LDG	4847					
MOC : COMPLIED WITH								
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) UNK	MTH	11-Apr-2016		-			Complete
		HRS	5993.1					
		LDG	4847					
MOC : COMPLIED WITH								
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) UNK	MTH	13-Apr-2016		-			Complete
		HRS	5999.6					
		LDG	4847					
MOC : COMPLIED WITH								
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6	MTH	11-Apr-2016		-			Complete
		HRS	5993.1					
		LDG	4847					
MOC : COMPLIED WITH - AT SHOP VISIT OF OH.								
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6	MTH	14-Apr-2016		-			Complete
		HRS	5999.6					
		LDG	4847					
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH								
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6	MTH			A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6	MTH			A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7				A/R			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH										
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH										
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL	EGHH		CATEGORY 5	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		A/R			Complete
MOC : COMPLIED WITH - P&W SB63081R1 INCORPORATED BY P&WC AS PART OF HSI.										
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 5	MTH		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB63083										
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5	MTH		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63081 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5	MTH		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7	MTH 06-Nov-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT SHOP VISIT ENGINE REPAIR										
SB PW600-72-63083 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7	MTH 11-Jun-2012 HRS 3932.7 LDG 3107		-			Complete
MOC : COMPLIED WITH - INCORPORATED AT SHOP VISIT ENGINE REPAIR										
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)	EGHH		CATEGORY 7	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - P&W SB63083 INCORPORATED BY P&WC AS PART OF HSI.										
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)	EGHH		CATEGORY 7	MTH 17-Apr-2012 HRS 3932.7 LDG 3107		-			Complete
MOC : COMPLIED WITH - SB63083 CARRIED OUT BY P&WC AS PART OF HSI.										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
MOC :										
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
MOC :										
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63087 R01 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R02)			CATEGORY 3	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2										
SB PW600-72-63087 R01 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R02)			CATEGORY 3	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2										
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	HUR		CATEGORY 3	MTH 17-Sep-2012 HRS 4081 LDG 3240		-			Complete
MOC : COMPLIED WITH - P&WC SB PW600-72-63087 R2 CARRIED OUT.										
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	HUR		CATEGORY 3	MTH 17-Sep-2012 HRS 4201.7 LDG 3331		-			Complete
MOC : COMPLIED WITH - P&WC SB PW600-72-63087 R2 CARRIED OUT.										
SB PW600-72-63087 E1	REPLACEMENT/MODIFICATION OF - ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R01)			CATEGORY 3	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63087 E2	REPLACEMENT/MODIFICATION OF - ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R01)			CATEGORY 3	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02) CATEGORY 6 MTH				A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB PW600-72-63089 R01 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02) CATEGORY 6 MTH				A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF UNK CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF UNK CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01) CATEGORY 6 MTH				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63089 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01) CATEGORY 6 MTH				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7 MTH				A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 63087								
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7 MTH				A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 63087								
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6 MTH				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6 MTH				-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847			-			Complete
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH								
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847			-			Complete
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)	UNK		CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)	UNK		CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET	UNK		CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET	UNK		CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH										
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01)	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01)			CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF	EGHH		CATEGORY 7	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - P&W SB63095 INCORPORATED BY P&WC AS PART OF HSI.										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF	EGHH		CATEGORY 7	MTH 17-Apr-2012 HRS 3932.7 LDG 3107		-			Complete
MOC : COMPLIED WITH - SB63095 CARRIED OUT BY P&WC AS PART OF HSI.										
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
MOC :										
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
MOC :										
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)				MTH 08-Mar-2024 HRS 9979.3 LDG 8102		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)				MTH 08-Mar-2024 HRS 9979.6 LDG 8102		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3			-			
MOC :										
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3	MTH		-			
MOC :										
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5			-			
MOC :										
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY	EGHH		CATEGORY 5	MTH 15-Feb-2013 HRS 4248 LDG 3376		-			Complete
MOC : COMPLIED WITH - SB63098 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
MOC :										
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63101 R01 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 R01 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
	MOC :									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
	MOC :									
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
	MOC :									
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
	MOC :									
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH	UNK			MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
	MOC :									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH	UNK			MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
MOC :										
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
MOC :										
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
MOC :										
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
MOC :										
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
MOC :										
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
MOC :										
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7						-			
MOC :										
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7						-			
MOC :										
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
MOC :								
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
MOC :								
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
MOC :								
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5	MTH 16-Oct-2020 HRS 7861.1 LDG 6396			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5	MTH 16-Oct-2020 HRS 7866.7 LDG 6397			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5	MTH 11-Apr-2016 HRS 5993.1 LDG 4847			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5	MTH 11-Apr-2016			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING CATEGORY 3	MTH 27-Feb-2019 HRS 7354.6 LDG 6018			-			N/A
MOC : NOT APPLICABLE - AS SB63105 IS NOT INCORPORATED								
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING CATEGORY 3	MTH 27-Feb-2019 HRS 7304.6 LDG 5966			-			N/A
MOC : NOT APPLICABLE - AS SB63105 IS NOT INCORPORATED								
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL CATEGORY 3	MTH 22-Jul-2021 HRS 8200.2 LDG 6665			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL CATEGORY 3	MTH 29-Jun-2023 HRS 9612.4 LDG 7816			-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL CATEGORY 7				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL CATEGORY 7			MTH 26-Aug-2022 HRS 8991.5 LDG 7297			-			Complete
MOC : COMPLIED WITH - DURING FCB-WP-130										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 5						-			
MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 5						-			
MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 7						-			
MOC :										
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 7						-			
MOC :										
ASB PW600-72-A63071 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02) UNK CATEGORY 3			MTH 11-Apr-2016 HRS 5993.1 LDG 4847			A/R			Complete
MOC : COMPLIED WITH										
ASB PW600-72-A63071 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02) EGHH CATEGORY 3			MTH 19-Feb-2010 HRS 3034 LDG 2367			A/R			Complete
MOC : COMPLIED WITH - A63071 R1 COMPLETED.										
ASB PW600-72-A63071 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE CATEGORY 3			MTH 11-Apr-2016 HRS 5993.1 LDG 4847			-			Complete
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH										
ASB PW600-72-A63071 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE CATEGORY 3			MTH 19-Feb-2010 HRS 3034 LDG 2322			-			Complete
MOC : COMPLIED WITH - AT SHOP VISIT FOR OH										
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						A/R			
MOC :										
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						A/R			
MOC :										
ASL 510-73-01 LEFT 73ASL01 : L	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE LOWL MANDATORY			MTH 27-Oct-2009 HRS 892 LDG 706			A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH VIA APPLICATION OF SB63069										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 510-73-01 RIGHT 73ASL01 : R	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	LOWL		MANDATORY	MTH 27-Oct-2009 HRS 892 LDG 706		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH VIA APPLICATION OF SB63069										
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	LOWL		MANDATORY	MTH 08-Jan-2010 HRS 1019 LDG 817		A/R			Complete
MOC : COMPLIED WITH - ASL510.73.02 COMPLIED WITH VIA APPLICATION OF PWC SB 63071										
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	LOWL		MANDATORY	MTH 08-Jan-2010 HRS 1019 LDG 817		A/R			Complete
MOC : COMPLIED WITH - ASL510-73-02 COMPLIED WITH VIA APPLICATION OF PWC SB63071										
SB PW600-1007- 63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY S/N										
SB PW600-1007- 63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8				MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY S/N										
SB PW600-72- 63067 E2	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY EGHH CATEGORY 7				MTH 17-Apr-2012 HRS 3932.7 LDG 3107		-			Complete
MOC : COMPLIED WITH - P&W SB63067 CARRIED OUT BY P&WC AS PART OF HSI.										
SB PW600-72- 63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE UNK CATEGORY 6				MTH 11-Apr-2016 HRS 5993.1 LDG 4847		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72- 63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE EGHH CATEGORY 6				MTH 15-Feb-2013 HRS 4248 LDG 3376		A/R			Complete
MOC : COMPLIED WITH - SB63073 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										
SB PW600-72- 63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) UNK CATEGORY 7				MTH 11-Apr-2016 HRS 5993.1 LDG 4847		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72- 63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) UNK CATEGORY 7				MTH 13-Apr-2016 HRS 5999.6 LDG 4847		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) UNK		MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) UNK		MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01) CATEGORY 6		MTH		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63080 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01) CATEGORY 6		MTH		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72-63082 E1	INSPECTION OF BYPASS-DUCT FUEL FAIRING EGHH CATEGORY 5		MTH 20-Jul-2012 HRS 3982.7 LDG 3159		A/R			Complete
MOC : COMPLIED WITH - P&W SB63082 INCORPORATED BY P&WC AS PART OF HSI.								
SB PW600-72-63082 E2	INSPECTION OF BYPASS-DUCT FUEL FAIRING EGHH CATEGORY 5		MTH 17-Apr-2012 HRS 3932.7 LDG 3107		A/R			Complete
MOC : COMPLIED WITH - SB63082 CARRIED OUT BY P&WC AS PART OF HSI.								
ASB PW600-72-A63061 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02) CATEGORY 3		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
ASB PW600-72-A63061 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02) CATEGORY 3		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 3		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB63087								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)	CATEGORY 3	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB63087								
ASB PW600-72-A63061 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	CATEGORY 3	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
ASB PW600-72-A63061 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	CATEGORY 3	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
ASB PW600-72-A63069 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R02)	CATEGORY 3	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
ASB PW600-72-A63069 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R02)	CATEGORY 3	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
ASB PW600-72-A63069 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R03)	CATEGORY 3	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 3								
ASB PW600-72-A63069 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R03)	CATEGORY 3	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 3								
ASB PW600-72-A63069 R03 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	CATEGORY 2	MTH 08-Mar-2024 HRS 9979.3 LDG 8102		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB63071								
ASB PW600-72-A63069 R03 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	CATEGORY 2	MTH 08-Mar-2024 HRS 9979.6 LDG 8102		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB63071								
ASB PW600-72-A63069 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R01)	HUR CATEGORY 3	MTH 03-Nov-2009 HRS 3033		-			Complete
MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW600-72-A63069 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R01)	HUR		CATEGORY 3	MTH 03-Nov-2009 HRS 2983		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN			CATEGORY 7	MTH 08-Apr-2008		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN			CATEGORY 7	MTH 22-Dec-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 8	MTH 08-Apr-2008		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 8	MTH 22-Dec-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63011 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-73-63011 R01)			CATEGORY 8	MTH		-			N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1									
SB PW600-73-63011 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-73-63011 R01)			CATEGORY 8	MTH		-			N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1									
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 7	MTH 08-Apr-2008		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 7	MTH 22-Dec-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT			CATEGORY 8	MTH 08-Apr-2008		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT			CATEGORY 8	MTH 22-Dec-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7	MTH 08-Apr-2008		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7	MTH 22-Dec-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 7	MTH 08-Apr-2008		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 7	MTH 22-Dec-2007		-			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01)			CATEGORY 8	MTH 08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01)			CATEGORY 8	MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-73-63115 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7	MTH		-			
MOC :										
SB PW600-73-63115 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7	MTH		-			
MOC :										
SB PW600-73-63115 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7			-			
MOC :										
SB PW600-73-63115 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER UNK	CATEGORY 7	MTH		-			
MOC :								
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER UNK	CATEGORY 7	MTH		-			
MOC :								
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS UNK	CATEGORY 6	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH								
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS UNK	CATEGORY 6	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH								
SB PW600-75-63054 R01 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) UNK	CATEGORY 7	MTH		-			
MOC :								
SB PW600-75-63054 R01 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) UNK	CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH								
SB PW600-75-63054 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) UNK	CATEGORY 7	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-75-63054 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) UNK	CATEGORY 7	MTH		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB 510-76-01 REV 01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 (SUPERSEDED BY 510-76-01 REV 02) MANDATORY	MTH			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 LOWL MANDATORY	MTH 28-Nov-2012 HRS 3017.6 LDG 2381			-			Complete
MOC : COMPLIED WITH - PRFORMED SB510-76-01 R2								
SB 510-76-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 (SUPERSEDED BY 510-76-01 REV 01) MANDATORY	MTH			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB 510-76-02	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT RECOMMENDED	MTH			-			
MOC :								
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS UNK	CATEGORY 8	MTH 08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8	MTH	22-Dec-2007		-			Complete
MOC : COMPLIED WITH								
SB 510-79-02	OIL TEMPERATURE PROBE O-RING REPLACEMENT RECOMMENDED	MTH HRS LDG	08-Mar-2024 9975.3 8101		A/R			N/A
MOC : NOT APPLICABLE - BY S/N								
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT OPTIONAL				-			
MOC :								
SL 510-79-01 79SL-01	OIL PRESSURE TRANSMITTER INSPECTION IRA MANDATORY	MTH HRS	16-Sep-2009 749		-			Complete
MOC : COMPLIED WITH								
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION LOWL MANDATORY	DAYS HRS LDG	22-Apr-2011 2002 1641		A/R			Complete
MOC : COMPLIED WITH - PERFORMED OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION								
SL 510-79-03 REV 01	OIL - OIL TRANSDUCER AND CONNECTOR REPLACEMENT MANDATORY	MTH HRS LDG	08-Mar-2024 9975.3 8101		-			N/A
MOC : NOT APPLICABLE - BY S/N								
SL 510-79-03	OIL - OIL TRANSDUCER AND CONNECTOR REPLACEMENT (SUPERSEDED BY SL510-79-03 REV 01) MANDATORY	MTH HRS LDG	08-Mar-2024 9975.3 8101		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL				-			
MOC :								
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL				-			
MOC :								
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL	MTH			A/R			
MOC :								
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL	MTH			A/R			
MOC :								
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SB PW600-72- 63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	UNK		CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72- 63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	UNK		CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72- 63068 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01)			RECOMMENDED	MTH		-			N/A
	MOC :	NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72- 63068 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01)			RECOMMENDED	MTH		-			N/A
	MOC :	NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72- 63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)				MTH 08-Mar-2024 HRS 9979.3 LDG 8102		-			N/A
	MOC :	NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-72- 63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)				MTH 08-Mar-2024 HRS 9979.6 LDG 8102		-			N/A
	MOC :	NOT APPLICABLE - SUPERSEDED BY REVISION 1								
SB PW600-79- 63008 R01 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R02)			CATEGORY 5	MTH 18-Dec-2007		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-79- 63008 R01 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R02)			CATEGORY 5	MTH 22-Dec-2007		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-79- 63008 R02 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS			CATEGORY 5	MTH 18-Dec-2007		-			Complete
	MOC :	COMPLIED WITH - AT MANUFACTURE								
SB PW600-79- 63008 R02 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS			CATEGORY 5	MTH 22-Dec-2007		-			Complete
	MOC :	COMPLIED WITH - AT MANUFACTURE								

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-79-63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)				MTH 08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)				MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				MTH 08-Apr-2008		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				MTH 22-Dec-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-79-63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER UNK			CATEGORY 7	MTH 11-Apr-2016 HRS 5993.1 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-79-63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER UNK			CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH EGHH			CATEGORY 7	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - P&W SB63046 INCORPORATED BY P&WC AS PART OF HSI.										
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH UNK			CATEGORY 7	MTH 13-Apr-2016 HRS 5999.6 LDG 4847		-			Complete
MOC : COMPLIED WITH										
SB PW600-79-63047 R02 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03) EGHH			CATEGORY 3	MTH 20-Jul-2012 HRS 3982.7 LDG 3159		-			Complete
MOC : COMPLIED WITH - P&W SB63047R2 INCORPORATED BY P&WC AS PART OF HSI.										
SB PW600-79-63047 R02 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03) EGHH			CATEGORY 3	MTH 15-Feb-2013 HRS 4248 LDG 3376		-			Complete
MOC : COMPLIED WITH - SB 63047 R2 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										
SB PW600-79-63047 R03 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS CATEGORY 3				MTH 08-Mar-2024 HRS 9979.3 LDG 8102		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY TO THE POST-SB63055 ACOC CONFIGURATION										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-79-63047 R03 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS			CATEGORY 3	MTH 08-Mar-2024 HRS 9979.6 LDG 8102		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY TO THE POST-SB63055 ACOC CONFIGURATION										
SB PW600-79-63047 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)				MTH 10-Mar-2008		-			Complete
MOC : COMPLIED WITH - INCORPORATED										
SB PW600-79-63047 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)				MTH 10-Mar-2008		-			Complete
MOC : COMPLIED WITH - PCW										
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM			RECOMMENDED	MTH 16-Sep-2018 HRS 6533.7 LDG 5278		-			Complete
MOC : COMPLIED WITH										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2007-0256-CN	APPLIANCE AD - ATA 25 - CANCELLED: EQUIPMENT / FURNISHINGS - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION / REPLACEMENT	CANCELLED	MTH 08-Nov-2022 HRS 9143.3 LDG 7427		-			N/A
MOC : NOT APPLICABLE - AD CANCELLED								
EASA 2013-0020 R03 (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER	MANDATORY	MTH 08-Mar-2024		-			N/A
MOC : NOT APPLICABLE								
EASA 2013-0020 R03 (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD	MANDATORY	MTH 08-Mar-2024		-			N/A
MOC : NOT APPLICABLE								
EASA 2013-0020 R03 (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE	MANDATORY	MTH 08-Mar-2024		-			N/A
MOC : NOT APPLICABLE								
EASA 2013-0020 R03 (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD	MANDATORY	MTH 08-Mar-2024		-			N/A
MOC : NOT APPLICABLE - N/A								
EASA 2013-0020 R03	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT (SUPERSEDED BY 2013-0020 R04)	MANDATORY	MTH 08-Mar-2024		-			N/A
MOC : NOT APPLICABLE								
EASA 2013-0020 R04 (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD	MANDATORY	MTH 01-Jul-2014 HRS 3913.7 LDG 3131		-			N/A
MOC : NOT APPLICABLE								
EASA 2013-0020 R04 (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE	MANDATORY	MTH 01-Jul-2014 HRS 3913.7 LDG 3131		-			N/A
MOC : NOT APPLICABLE								
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT	MANDATORY	MTH 01-Jul-2014 HRS 3913.7 LDG 3131		-			N/A
MOC : NOT APPLICABLE								
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)	MANDATORY	DAYS 09-Mar-2020		-			N/A
MOC : NOT APPLICABLE - DUE TO NEW PART								
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION	MANDATORY	MTH 09-Mar-2020		-			N/A
MOC : NOT APPLICABLE - DUE TO NEW PART								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN AFFECTED PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART	MANDATORY	MTH 09-Mar-2020		-			N/A
	MOC : NOT APPLICABLE - DUE TO NEW PART							
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE	MANDATORY	MTH 04-Nov-2019		-			N/A
	MOC : NOT APPLICABLE - DUE TO NEW PART							
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT	MANDATORY	MTH 04-Nov-2019		-			N/A
	MOC : NOT APPLICABLE - DUE TO NEW PART							
EASA 2021-0137	APPLIANCE AD - EQUIPMENT / FURNISHINGS - PILOT AND CO-PILOT SEATS / LONGITUDINAL LOCKING SYSTEM PINS - MEASUREMENT / ADJUSTMENT	MANDATORY	MTH 15-Nov-2021 HRS 8529.9 LDG 6931		-			N/A
	MOC : NOT APPLICABLE - APPLICABILITY: 191 SERIES PILOT SEATS, HAVING PART NUMBER (P/N) 19101-00-00, AND 191 SERIES CO-PILOT SEATS, HAVING P/N 19102-00-00							
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	MANDATORY	MTH 08-Jan-2025 HRS 10028.2 LDG 8129		12		08-Jan-2026	5 m 7 d Complete
	MOC : COMPLIED WITH							
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	MANDATORY			-			
	MOC :							
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	MANDATORY			-			
	MOC :							
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	MANDATORY	MTH		-			
	MOC :							
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	MANDATORY	MTH		-			
	MOC :							
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	MANDATORY			-			
	MOC :							
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	MANDATORY			-			
	MOC :							
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	MANDATORY	MTH		-			
	MOC :							
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	MANDATORY	MTH		-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	MANDATORY			-			
MOC :								
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	MANDATORY			-			
MOC :								
LBA D-2018-234	APPLIANCE AD - EQUIPMENT / FURNISHINGS - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REMOVAL FROM SERVICE	MANDATORY			-			
MOC :								
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED								
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED								
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED								
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED								
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED								
EASA 2016-0024	FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED								
EASA 2021-0185 R01	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT	MANDATORY	DAYS 08-Nov-2022 HRS 9143.3 LDG 7427		-			N/A
MOC : NOT APPLICABLE - N/A BY PN.								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
EASA 2021-0185 R02	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION/REPLACEMENT			MANDATORY	MTH 27-Oct-2023 HRS 9882.9 LDG 8029	-				N/A
MOC : NOT APPLICABLE - HAFEX HAND-HELD FIRE EXTINGUISHER, HAVING PART NUMBER (P/N) P3APP003010A, P/N P3APP003010B OR P/N P3APP003010C, ALL SERIAL NUMBERS (S/N).										
EASA 2021-0185	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT			MANDATORY	DAYS 08-Nov-2022 HRS 9143.3 LDG 7427	-				N/A
MOC : NOT APPLICABLE - BY PN										
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS	LOW		MANDATORY	MTH 17-Nov-2012 HRS 3015 LDG 2379	A/R				N/A
MOC : NOT APPLICABLE - N/A										
FAA 2010-04-16 PARA (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT	LOWL		MANDATORY	DAYS 15-May-2010 HRS 1200 LDG 969	A/R				N/A
MOC : NOT APPLICABLE										
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER	LOWL		MANDATORY	DAYS 15-May-2010 HRS 1200 LDG 969	A/R				N/A
MOC : NOT APPLICABLE										
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI	LOWL		MANDATORY	MTH 15-May-2010 HRS 1200 LDG 969	A/R				N/A
MOC : NOT APPLICABLE										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS			MANDATORY		-				
MOC :										
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)	UNK		MANDATORY	MTH 17-Jun-2024 HRS 9994.2 LDG 8109	-				N/A
MOC : NOT APPLICABLE - BY AIRCRAFT SERIAL 510-0044										
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	UNK		MANDATORY	MTH 17-Jun-2024 HRS 9994.2 LDG 8109	-				N/A
MOC : NOT APPLICABLE - BY AIRCRAFT SERIAL 510-0044										
FAA 2023-10-02	INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	UNK		MANDATORY	MTH 17-Jun-2024 HRS 9994.2 LDG 8109	-				N/A
MOC : NOT APPLICABLE - BY AIRCRAFT SERIAL 510-0044										



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH									
			MANDATORY		DAYS 28-Jul-2017		-			Complete
					HRS 5803.6					
					LDG 4686					
	MOC : COMPLIED WITH - PCW IAW SL510-32-08									
EASA 2010-0003 R02 (1)	VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO 0 (ZERO) OR 1, AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94() SIL 07-2.		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2010-0003 R02 (2)	EXEMPTIONS: DASSAULT AEROPLANES		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2010-0003 R02 (3)	EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2010-0003 R02 (4)	EXEMPTIONS: SAAB 2000 AEROPLANES		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2010-0003 R02 (5)	EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2010-0003 R02 (6)	EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B; AND CESSNA MODEL 525, 525A, 525B, 560; 560XL		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2010-0003 R02 (7)	EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)		MANDATORY		MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
	MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.									



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.								
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.								
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.								
EASA 2015-0093	APPLIANCE AD - NAVIGATION & ATTITUDE HEADING REFERENCE SYSTEM & MODIFICATION / REPLACEMENT	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.								
EASA 2022-0024	APPLIANCE AD - ATA 34 - NAVIGATION - FLIGHT MANAGEMENT COMPUTER 2 / NAVIGATION MODULES - OPERATIONAL LIMITATIONS / AMENDMENT	MANDATORY	DAYS 08-Nov-2022 HRS 9143.3 LDG 7427		-			N/A
MOC : NOT APPLICABLE - BY P/N.								
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.								
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.								
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT MODEL.								
EASA 2012-0254 PARA (1)	INSPECT/CHECK OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT (SUPERSEDED BY 2012-0254 R01) OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N	MANDATORY	DAYS 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY PN & SN								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2012-0254 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT (SUPERSEDED BY 2012-0254 R01) AFFECTED OXYGEN MASK REGULATOR	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY PN & SN								
EASA 2012-0254 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT (SUPERSEDED BY 2012-0254 R01) AIRCRAFT FLIGHT MANUAL (AFM)	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY PN & SN								
EASA 2012-0254 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT (SUPERSEDED BY 2012-0254 R01) EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY PN & SN								
EASA 2012-0254	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT (SUPERSEDED BY 2012-0254 R01)	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - BY PN & SN								
EASA 2014-0142 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445952 WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								
EASA 2014-0142 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								
EASA 2014-0142 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD.	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								
EASA 2014-0142 R01 (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS	MANDATORY	MTH 12-May-2016		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0142 R01 (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD	MANDATORY	MTH 12-May-2016		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								
EASA 2014-0142 R01 (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD	MANDATORY	MTH 12-May-2016		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								
EASA 2014-0142 R01	APPLIANCE AD - OXYGEN & OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE & IDENTIFICATION / REPLACEMENT	MANDATORY	MTH 12-May-2016		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								
EASA 2014-0142	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT (SUPERSEDED BY 2014-0142 R01)	MANDATORY	MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			N/A
MOC : NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274.								
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAAAD 2017-18-12	MANDATORY	MTH		-			
MOC :								
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY			-			
MOC :								
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH		-			
MOC :								
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAAAD 2017-18-12	MANDATORY			-			
MOC :								
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY			-			
MOC :								
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY			-			
MOC :								
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.				-			
MOC :								
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	MANDATORY			-			
MOC :								
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS		MTH 08-Mar-2024 HRS 9975.3 LDG 8101		-			
MOC : DEFERRED - NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274								



CESCOM 10 - Aircraft Status Report

Owner: **PINNACLE LEGAL, P.C.**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0044**
Unit: **0044** Reg No: **N300VR**
Airworthiness: **21-Nov-2007**
Print Date: **01-Aug-2025 12:24PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	10069.2	8160	31-Jul-2025	.22
ENG 1	7815.2	6524	31-Jul-2025	.13
ENG 2	7865.2	6576	31-Jul-2025	.13
AIR COND	2314.5		31-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD									
				MANDATORY	MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
MOC : NOT APPLICABLE - NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274										
FAA 2018-21-14	OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT									
				MANDATORY	MTH 08-Mar-2024		-			N/A
					HRS 9975.3					
					LDG 8101					
MOC : NOT APPLICABLE - NOT APPLICABLE - N/A AS OUR MASKS PN MC10-16-101 ARE NOT PART OF ZODIAC AEROSPACE SB MC10-35-274										
TCCA CF-2010-03 E1	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR									
	UNK			MANDATORY	MTH 11-Apr-2016		-			Complete
					HRS 5993.1					
					LDG 4847					
MOC : COMPLIED WITH										
TCCA CF-2010-03 E2	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR									
	UNK			MANDATORY	MTH 13-Apr-2016		-			Complete
					HRS 5999.6					
					LDG 4847					
MOC : COMPLIED WITH										
FAA 2010-17-06 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
	EGHH			MANDATORY	MTH 19-Feb-2010		-			Complete
					HRS 3084					
					LDG 2419					
MOC : COMPLIED WITH - FAA AD 2010-17-06 COMPLIED WITH BY COMPLETION OF ASL510-73-02 AND PWASB63071 ON NO1 ENGINE										
FAA 2010-17-06 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
	EGHH			MANDATORY	MTH 15-Feb-2013		-			Complete
					HRS 4248					
					LDG 3376					
MOC : COMPLIED WITH - AD 2010-17-06 COMPLIED WITH BY P&WC AS PART OF ENGINE REPAIR.										